

Response

to Main Document

Achim Mueller/SCHUSKF
07/12 01:08 AM

Subject: Raceway Qualification Test with Pre-Damaged THU2 BTF-0065

Response to: Inspection and Test Reports

Category:



el021209.doc

SKF 001793

**Raceway Qualification Test with Pre-Damaged THU2 BTF-0065**

SKF GmbH
Gunner-Wester-Str.12
D-97419 Schweinfurt, Germany
Tel.: +49 (9721) 56-0

Ohne unsere Genehmigung darf dieser Bericht weder vervielfältigt, noch dritten Personen oder Konkurrenzfirmen mitgeteilt werden (§1 des Gesetzes vom 9.September 1965).

Without prior consent this report must neither be copied nor communicated to a third party or competitors (§1, act of 9th September, 1965).

Requested by		
Project		
Reported by	Supervised by	Approved by
Achim Müller/ATT-PK		A. Stubenrauch / ATT
Copies to		
Michael D. Lewis Achim Müller Archiv	ADNA ATT-PK MWI	SKF NATC SKF Schweinfurt SKF Schweinfurt

st02t209 1496576kB

Achim Müller

SKF 001794



Content	Test Description	page 3
	Test Results	page 3
	Conclusion	page 4

Tabellen und Bilder

Key words: Truck Hub Unit, Raceway Qualification Test, Damage



Test Description


A THU has been pre-damaged due to non rotation during assembly (see report ST02T207). This bearing was then put on a THU test rig and run under "Raceway Qualification Test" conditions.

These test conditions are chosen such, that heavy but realistic corner loads, which may occur under normal operation, are simulated. The dominant loading condition (85% of the test time) simulates + 0.25 g cornering load. Road recordings ("Service Condition Recordings...", NL93T035, G.-J. Scheers) are proposing that this condition occurs with a percentage of less than 0.3% under linehaul service. It is assumed that during city delivery, a similar cornering condition is present for less than 2% of the total service life of a vehicle.

Based on this information it is a safe assumption that every hour of test time, the test rig operates at 500 rpm, simulates approximately 2650 miles of operation under city delivery condition, while it represents more than 8000 miles under linehaul conditions.

Test Results

The reported bearing was operating for 395 hours when a vibration level, which was twice as high as the base level of the already damaged bearing was measured. These 395 hours would be already equivalent to approximately 1,000,000 miles of city delivery condition. Upon inspection small damages on the inboard outer ring raceways were detected (see picture 1).



Picture 1: circumferential operation traces and scratches on rwt, predamaged THU outer ring raceway

During a Design Verification Test, these scratches would have been evaluated as bearing damage, and the test would have been terminated.

Since the target of this test was to demonstrate the feasibility of a 50,000 miles inspection interval, it has been decided to continue the test instead of investigating the observed damage in detail.

Upon restarting of the test, the bearing was overloaded by mistake. The overload was such that a axial load equivalent to approximately 1 g was acting on the THU. The bearing was immediately heavily damaged on the raceways and inner ring guiding flanges (see picture 2). Nevertheless the test was continued with this, now excessively, damaged bearing.



Picture 2: THU cone after overload

The bearing is operating since then for 32.5 hours under the earlier described test condition. The test time would translate into approximately 86,000 miles of field operation under city delivery conditions.

During the test, inboard and outboard inner ring temperatures were recorded (see table 1). After test termination, the axial endplay of the Truck Hub Unit was determined to be 0.315 mm.

Test Time [h]	Inboard inner ring temp. [°C]	Outboard inner ring temp. [°C]
6	130	not recorded
11.6	150	130
18.7	165	133
25	180	140
28.4	180	140
32.5	190	150

Table 1: Inner ring temperatures

Conclusion

From the above result it is concluded, that a damage caused by a wrong assembly method (i.e. no rotation during clamping) will not immediately affect the bearing performance. It is, however, to be expected that such damage will reduce the potential service life of a Truck Hub Unit.

The heavy bearing damage caused by mistake would have been noticed during a "Basic Inspection" of the wheel end. The wheel would have been considered as rotating rough and noisy. Continuing the test for another 32.5 hours (equivalent to 86,000 miles under city delivery condition) shows that the chosen 50,000 miles interval between two "Basic Inspections" is sufficient to detect bearing damages prior to a safety critical condition of the wheel end.



Report No.: ST 02 T 209 Updated: Mar 11, 2003 Total Pages: 5

Page # 4

Response
to Main Document

Achim Mueller/SCH/SKF
07/17 01:22 AM

Subject: Raceway Qualification "Water Contaminated Grease"
Response to: Inspection and Test Reports
Category:



s1021210.doc

SKF 001799



Raceway Qualification Test on BTF-0065 with "Water Contaminated Grease"



SKF GmbH
Gunner-Wester-Str.12
D-97419 Schweinfurt, Germany
Tel.: +49 (9721) 56-0

Ohne unsere Genehmigung darf dieser Bericht weder vervielfältigt, noch dritten Personen oder Konkurrenzfirmen mitgeteilt werden (§1 des Gesetzes vom 9. September 1965).

Without prior consent this report must neither be copied nor communicated to a third party or competitors (§1, act of 9th September, 1965).

Requested by		
Project		
Reported by	Supervised by	Approved by
Achim Müller/ATT-PK		A. Stubenrauch / ATT
Copies to		
Michael D. Lewis Achim Müller Archiv	ADNA ATT-PK MWI	SKF NATC SKF Schweinfurt SKF Schweinfurt

st02t210 1460736kB

Achim Müller



Content	Objective	page 3
Test Bearings	page 3	
Test Rig	page 3	
Test Description	page 3	
Test Conditions	page 4	
Test Results	page 5	
Bearing Condition	page 5	
Conclusion	page 6	

Tabellen und Bilder

Key words: Truck Hub Unit, water contamination, raceway qualification,



1. Objective

To demonstrate the performance of a THU with water ingress under Raceway Qualification Test Conditions.

2. Test Bearings

Test Bearing: BTF-0065 manufactured by Aiken USA


Customer: ArvinMeritor

Application: 13200 lbs Front Steer Axle

3. Test Rig

The test was performed on SKF Truck Hub Unit test rig THU4 in Schweinfurt, Germany. A principle sketch of the test rig is shown below.

Picture 1: Principle sketch of the THU test rig



Two bearing units are running at the same time. Radial and lateral load are applied with hydraulic cylinders as under road running conditions.

Radial load is applied independently to each unit, lateral load is applied via a single rod to both units at the same time. The lateral load, applied at a loading radius equivalent to the tire radius, creates a moment load in the unit.

The spindles are equipped with thermocouples to measure the bearing temperature. Also the rig support bearing temperature and vibration level for alert stop are measured.



Rotational speed and loads are electronically controlled and monitored.

A picture of the THU test rig is shown below in picture 2.



Picture 2: Truck Hub Unit test rig

4. Test Description

This test is designed to evaluate the raceway fatigue life of the tested THU under severe but realistic conditions. The conditions have been chosen to accelerate the test while ensuring a realistic failure mode. The test does not determine the L_{10} life of the test THU since not enough bearings are tested for such an evaluation.

5. Test conditions

5.1 Test Target

Two units will be tested until failure or max $2 \cdot L_{10}$. In this case $L_{10} = 208$ hours. L_{10} is calculated using SKF computer program BEACON assuming the load cycle below.

5.2 Load Conditions



Time [sec.]	Acceleration (g)	F_{rad} (kN)	F_{flat} (kN)
102	0.25	40.4	10.1
3	0	29.4	0
12	-0.25	18.5	-4.6
3	0	29.4	0

5.3 Assembly Conditions

Load line from vehicle inside (LLP): 62.5mm
 Wheel radius: 533mm
 Clamp force of the inner rings: 80 kN
 Speed: 500 min⁻¹
 Cooling: air cooling equivalent 100km/h
 Temperature measuring points: measured in the spindles under the raceways with thermocouples

5.4 Remarks

Both bearings were lubricated with 61 grams of grease in which 1.5% of water (0.9 gram) were dispersed. One bearing was equipped with an R-SAFE type seal, the other with a garter seal. After 37.5 hours of operation, the rig was stopped and a grease sample was taken from the bearing with the R-SAFE seal. The amount of water in the grease dropped to 0.3%, i.e. water is evaporating during operation.

The missing amount of grease was substituted and 5 grams of water were injected to the inboard inner ring retaining flange. The earlier mentioned test cycle was run for 14 hours continuously, followed by a standstill period of 10 hours.

6. Test Results


After the addition of the aforementioned 5 grams of water, the test bearing completed 14 hours of operation and the following standstill period. Upon restart of the operation, it was noticed that the bearing temperature increased steadily, indicating a bearing damage (see picture 3).



SKF GmbH

BTF-0065B (6to Front Wheel)

Run with 5 ml water at the inner side

19.06.2002
D. Schleyer
Sg. Wasser

Picture 3: Temperature recording indicating bearing damage after standstill period

The bearing was run for additional 4.5 hours until it was decided to terminate the test.

7. Bearing conditions after the test

After disassembly and cleaning of the bearing, the inboard inner ring of the unit shows several shallow spells (see picture 4). The appearance of the roller raceways is shiny.



Picture 4: Spalled inboard inner ring raceway (the arrow indicates the sense of rotation)

Grease samples were taken from both units. It was determined that the bearing with the garter seal showed only traces of water. The amount of water in the spalled unit was reduced to approximately 1.5 grams only.

8. Conclusions

The damage of the spalled unit has the same appearance as damages of bearings returned from the field (see ST02T206). This confirms that even relatively small amounts of water, entering a Truck Hub Unit will cause major damage in a short time.

It could furthermore be demonstrated that water, which entered the bearing, eventually evaporates during operation. This can explain the presence of salt and other minerals in bearings returned from the field, without obvious water content in the lubricant.

Response
to Mailbox Request

Achim.Mueller@SCHSKF
07/07/06 44 AM

Subject: Stud Assembly Test
Response to: Inspection and Test Reports
Category:



st0211.doc

SKF 001807



3

Report No.: Supplement ST02T205

Page # 1

Updated: Mar 11, 2003 Total Pages:

AIR LEAK TEST

Additional Investigations



SKF GmbH
Gunnar-Wester-Str.12
D-97419 Schweinfurt, Germany
Tel.: +49 (9721) 56-0

Ohne unsere Genehmigung darf dieser Bericht weder vervielfältigt, noch dritten Personen oder Konkurrenzfirmen mitgeteilt werden (§1 des Gesetzes vom 9.September 1965).

Without prior consent this report must neither be copied nor communicated to a third party or competitors (§1, act of 9th September, 1965).

Requested by		
Project		
Reported by	Supervised by	Approved by
Achim Müller/ATT-PK		A. Stubenrauch / ATT
Copies to		
Michael D. Lewis Achim Müller Archiv	ADNA ATT-PK MWI	SKF NATC SKF Schweinfurt SKF Schweinfurt

st02t205supplement 458752kB

Achim Müller

SKF 001808



3

Report No.: Supplement ST02T205
Page # 1

Updated: Mar 11, 2003 Total Pages:

Content	Purpose	page 3
	Test Description	page 3
	Test Results	page 3
	Conclusion	page 3

Tabellen und Bilder**Key words:** Truck Hub Unit, Air Leak Test,



3

Report No.: Supplement ST02T205
Page # 2

Updated: Mar 11, 2003 Total Pages:

Test Description


Additional air leak tests as described in ST02T205 have been performed on an original ArvinMeritor wheel end assembly using the O-ring, which is in use in the series assembly since April 2000. For comparison, the same test was performed on a European trailer axle wheel end assembly (see picture 1) without additional sealing.

Test Results

Neither of the two wheel end assemblies showed any air leak along the spindle and knuckle side face.

Conclusion

This test proves the effectiveness of the O-ring, which was introduced by ArvinMeritor to be assembled onto the front wheel spindle. It also proves that European wheel ends do not exhibit the potential leak path along the knuckle side face and the spindle due to their different manufacturing process (see picture 1).



Response

to Main Document

Achim Mueller/SCH/SKF
07/24/04:03 AM

Subject: Report about Outboard Outer Ring Spalls

Response to: Inspection and Test Reports

Category:



UB186_02.doc 186-02.pdf

SKF 001811

BU Trucks Product DesignTranslation of
"Untersuchungsbefund Nr. 186/02"**Purpose of the Investigation**

Evaluation of bearing damage, spalls on outboard outer ring raceways.

Results**1. Macroscopic Investigation****1.1 THU 9/8282****1.1.1 Outboard Outer Ring Raceway**

The raceway exhibits several non-uniform distributed brinelling marks. From these marks, axially oriented spalls are originating (see picture 1). The marks show signs of "false brinelling" and contact corrosion. The honed surface structure is still visible outside the axial marks.

At both ends of the overrolled area of the raceway fine corrosion pittings are detectable. Most pittings are at the large raceway diameter, they are distributed equally around the circumference.

The large raceway diameter of the raceway exhibits plastic deformation in circumferential direction. This appears to be caused by edge stresses in the rolling contact.

1.1.2 Inboard Outer Ring Raceway

The raceway exhibits no spalls. The honing structure is still visible. At both ends of the raceway corrosion pittings are detectable. There are less pittings than on the outboard side.

1.1.3 Area between the Raceways

No corrosion pittings are detectable between the raceways.

1.1.4 Inner Rings and Rollers

Outboard: Indentations due to overrolled metallic particles, abrasive wear, no corrosion, honing structure still visible.
Inboard: Abrasive wear, no corrosion, honing structure still visible.

1.2 THU 9/8284**1.2.1 Outboard Outer Ring Raceway**

Several shallow spalls are found on the raceway. The honing structure is still visible. Some areas, which are oriented axially, are completely smoothed.

At both ends of the overrolled area of the raceway fine corrosion pittings are detectable. Most pittings are found at the large raceway diameter.

The large raceway diameter of the raceway exhibits plastic deformation with pittings in circumferential direction. This appears to be caused by edge stresses in the rolling contact.

1.2.2 Inboard Outer Ring Raceway

BU Trucks Product Design

Translation of

Structure	AFIT 2 ... 4	AFIT 2 ... 4 Untersuchungsbefund Nr. 186/02"
-----------	--------------	--

Conclusion

Both Truck Hub Units exhibit spalls at the outboard outer ring raceway. Brinelling marks and smoothings, caused by "false brinelling" are the starting points of these spalls. The brinelling marks are partially accompanied by corrosion. The formation of brinelling marks is obviously supported by the water content of the lubricant.

In the area of the end of the contact zone at the large diameter of both outer ring raceways of the Truck Hub Units, corrosion pittings are equally distributed around the circumference. This indicates a corrosive reaction during operation. The intensity of corrosion pittings is highest at the large raceway diameter of the outboard raceway and is reduced towards the inboard side. Water enters obviously the bearing from its outboard side.

The edge loading of the raceways is a secondary damage mode.



Untersuchungsbefund Nr. 186/02

Datum: 2002-07-11

Seite 1 von 9

Angefordert von: Herrn A. Müller, ATT-PK

P- Nr.: 148/02

Teile: 2 THU
Type: BTF-0052
Bezeichnung der Lager: 9/8282
9/8284 "Ryder, Big springs, TX, R.S."

Werkstoff: OR:SAE 1055 M
Wärmebehandlung:
OR-Laufbahn: induktiv gehärtet
Rollen: einsatzgehärtet

Zweck der Untersuchungen:

Schadensfalluntersuchung. Schälungen auf den flanschseitigen OR-Laufbahnen.

Ergebnisse:

1. Makroskopische Beurteilung

1.1 THU 9/8282

1.1.1 OR-Laufbahn flanschseitig

Auf der Laufbahn befinden sich mehrere Standrillen in verschiedenen Abständen. Die Standrillen sind Ausgang von in axialer Richtung ausgedehnten Schälungen (siehe Bild 1). Die Standrillen zeigen Merkmale von "false brinelling" und Korrosion im Stillstand. Die Honrillen sind außerhalb der Standrillen noch gut erkennbar.

Zu beiden Laufspurenenden hin erkennt man im überlauften Bereich unter der Stereolupe feine Lochfraßkorrosion. Diese ist im Gebiet am großen Durchmesser am stärksten. Diese Korrosion ist über den Umfang gleichmäßig verteilt.

Am flanschseitigen Rand der Laufspur befindet sich in Umfangsrichtung eine Spur plastischer Deformation. Sie scheint durch Kantenlauf von Rollen erzeugt worden zu sein.

1.1.2 OR-Laufbahn inboard

Die Laufbahn zeigt keine Schälungen. Die Honrillen sind gut erhalten.

Unter der Stereolupe erkennt man im Gebiet zu beiden Laufspurenenden umlaufende Lochfraßkorrosion. Diese ist deutlich schwächer als auf der flanschseitigen Laufbahn.

1.1.3 Mittelschulter

Auf der Mittelschulter befinden sich Korrosionsspuren.

1.1.4 Innenringe und Rollen

Outbordeitig: Metallabriebindrückungen, keine Korrosion, abrissver Verschleiß, Honrillen noch gut sichtbar.

Inboardseitig: keine Korrosion, abrissver Verschleiß, Honrillen noch gut sichtbar.

1.2 THU 9/8284

1.2.1 OR-Laufbahn flanschseitig

Auf der Laufbahn befinden sich einzelne flache Schälungen. Die Honrillen sind sichtbar. Es existieren aber Gänge mit völliger Glättung, die überwiegend axial orientiert sind.

Zu beiden Laufspurenenden hin erkennt man unter der Stereolupe feine Lochfraßkorrosion. Sie ist am großen Durchmesser stärker ausgeprägt.

Am flanschseitigen Rand der Laufspur befindet sich in Umfangsrichtung eine Spur plastischer Deformation mit Pits. Sie stammt offensichtlich vom Kantenlauf von Rollen.

verfasst:
STW 3 / NI / Wo

Kopien an:
ATT-PK, STW, STW3

Im Gebiet der Laufspuränder beider OR-Laufbahnen der THUs ist Lochfraßkorrosion gleichmäßig in Umfangrichtung verteilt. Dies deutet auf Korrosion im Lauf. Die Lochfraßkorrosion weist am großen Laufbahndurchmesserende flanschseitig die höchste Intensität auf und nimmt zum inboard hin ab. Die Wasserzufuhr kommt demnach vom Outboard.

Der Kantenlauf der Rollen flanschseitig ist ein konkurrenzender Ausfallmechanismus.

THU 9/8282 - OR Laufbahn flanschseitig**Bild 1**

THU 9/8282 - OR Laufbahn flanschseitig




Bild 2: Rillen auf Laufbahn




Bild 3: Detail von Bild 2

THU 9/8262 - OR Laufbahn flanschseitig





Bild 4: Bildung einer Schälung



Bild 5: Detail von Bild 4

THU 9N8282 - OR Laufbahn flanschseitig**Bild 6: Lochfraßkorrosionen****Bild 7: Detail von Bild 5**

THU 9/B284 - OR Laufbahn flanschseitig




Bild 8: Kantenlaufspur





Bild 9: Detail von Bild 7

THU 9/8284 - OR Laufbahn flanschseitig**Bild 10: Detail von Bild 7**

THU 9/8284 - OR Laufbahn flanschseitig




Bild 11: Staubverteilung




Bild 12: Detail von Bild 11

Response

to Response

Bruce Weeks/AMER/SKF
07/24/08:30 AM

Subject: OB Outer Ring Spalls - Report with Translated Picture Captions

Response to: Report about Outboard Outer Ring Spalls

Category:



UB186_02 with captions.doc

SKF 001824

BU Trucks Product DesignTranslation of
"Untersuchungsbefund Nr. 186/02"**Purpose of the Investigation**

Evaluation of bearing damage, spalls on outboard outer ring raceways.

Results**1. Macroscopic Investigation****1.1 THU 9/8282****1.1.1 Outboard Outer Ring Raceway**

The raceway exhibits several non-uniform distributed brinelling marks. From these marks, axially oriented spalls are originating (see picture 1). The marks show signs of "false brinelling" and contact corrosion. The honed surface structure is still visible outside the axial marks.

At both ends of the overrolled area of the raceway fine corrosion pittings are detectable. Most pittings are at the large raceway diameter, they are distributed equally around the circumference.

The large raceway diameter of the raceway exhibits plastic deformation in circumferential direction. This appears to be caused by edge stresses in the rolling contact.

1.1.2 Inboard Outer Ring Raceway

The raceway exhibits no spalls. The honing structure is still visible. At both ends of the raceway corrosion pittings are detectable. There are less pittings than on the outboard side.

1.1.3 Area between the Raceways

No corrosion pittings are detectable between the raceways.

1.1.4 Inner Rings and Rollers

Outboard: Indentations due to overrolled metallic particles, abrasive wear, no corrosion, honing structure still visible.
Inboard: Abrasive wear, no corrosion, honing structure still visible.

1.2 THU 9/8284**1.2.1 Outboard Outer Ring Raceway**

Several shallow spalls are found on the raceway. The honing structure is still visible. Some areas, which are oriented axially, are completely smoothed.

At both ends of the overrolled area of the raceway fine corrosion pittings are detectable. Most pittings are found at the large raceway diameter.

The large raceway diameter of the raceway exhibits plastic deformation with pittings in circumferential direction. This appears to be caused by edge stresses in the rolling contact.

1.2.2 Inboard Outer Ring Raceway

BU Trucks Product Design

Translation of

Structure	AFIT 2 ... 4	AFIT 2 ... 4 Untersuchungsbefund Nr. 186/02"
-----------	--------------	--

Conclusion

Both Truck Hub Units exhibit spalls at the outboard outer ring raceway. Brinelling marks and smoothings, caused by "false brinelling" are the starting points of these spalls. The brinelling marks are partially accompanied by corrosion. The formation of brinelling marks is obviously supported by the water content of the lubricant.

In the area of the end of the contact zone at the large diameter of both outer ring raceways of the Truck Hub Units, corrosion pittings are equally distributed around the circumference. This indicates a corrosive reaction during operation. The intensity of corrosion pittings is highest at the large raceway diameter of the outboard raceway and is reduced towards the inboard side. Water enters obviously the bearing from its outboard side.

The edge loading of the raceways is a secondary damage mode.

Picture Captions:

Picture 1 -- Brinelling on Raceway (Comment at side is direction of rotation)

Picture 2 -- Close up of picture 1

Picture 3 -- Further close up of picture 2

Picture 4 -- Initiation of Spall

Picture 5 -- close up of Picture 4 (showing intercrystalline fracture, not sub-surface)

Picture 6 -- Corrosion Pitting

Picture 7 -- Close up of Picture 6 (note that German version is in error stating this is close up of picture 5)

Picture 8 -- Small Etch on Raceway

Picture 9 -- Close up of Picture 8

Picture 10 -- Further Close up of Picture 9

Picture 11 -- Distribution of Over-rolled Dust

Picture 12 -- Close up of Picture 11

Response
to Main Document

Achim Mueller/SCH/ SKF
07/26 02:47 AM

Subject: Static Water Splash Test
Response to: Inspection and Test Reports
Category:



st021212.doc

SKF 001828



STATIC WATER SPLASH TEST ON ARVINMERITOR K NUCKLE



SKF GmbH
Gunner-Wester-Str. 12
D-97419 Schweinfurt, Germany
Tel.: +49 (9721) 56-0

Ohne unsere Genehmigung darf dieser Bericht weder vervielfältigt, noch dritten Personen oder Konkurrenzfirmen mitgeteilt werden (§1 des Gesetzes vom 9. September 1965).

Without prior consent this report must neither be copied nor communicated to a third party or competitors (§1, act of 9th September, 1965).

Requested by		
Project		
Reported by	Supervised by	Approved by
Achim Müller/ATT-PK		A. Stubearnsch / ATT
Copies to		
Michael D. Lewis Achim Müller Archiv	ADNA ATT-PK MWI	SKF NATC SKF Schweinfurt SKF Schweinfurt

st02l212 5795840kB

Achim Müller

SKF 001829



Content	Purpose	page 3
	Test Description	page 3
	Test Results	page 3
	Conclusion	page 7

Tabellen und Bilder

Key words: Truck Hub Unit, Water Splash Test, ArvinMeritor, Knuckle



Purpose of the Test

The purpose of this static test was to prove if water may enter the joint between a Truck Hub Unit's inner ring and the knuckle side face of ArvinMeritor's front steer axle.

Test Description

A Truck Hub Unit BTF-0065 was assembled onto a new knuckle of an ArvinMeritor front steer axle. A torque of 800 Nm (590 ft-lbs) was applied to the inner lock nut. The specified minimum clamp torque is 680 Nm (680 Nm). The outer lock nut was clamped to specification.

The knuckle is then installed horizontally to a rig. To achieve some temperature variation, the Truck Hub Unit was set into rotation by means of a driving belt. Simple tap water was then sprayed onto the joint between knuckle and inner ring side face (see picture 1).



Picture 1: Static Water Splash Test set up

The rotational speed of the unit was set to be 800 rpm during "dry" periods, while it was 300 rpm during time periods with water splash. The duration of each time period was set to be 30 minutes.



Two different assemblies were tested: one with an O-ring in the joint, a second without this seal. The first test was run for 16 "water splash cycles", the second for 13. Temperatures at the outer ring (inboard side) were determined to be around 25°C during water splash, and around 60°C without.

The following pictorial depicts the appearance of the knuckle side face after each test and the bearing side face and bore after the test without the O-ring.




Picture 2: Appearance of the knuckle side face (top) after water splash test with O-ring. Water intrusion along the milling traces is visible.



Report No.: ST 02 T 212 Updated: Mar 11, 2003 Total Pages: 9

Page # 4



Picture 3: Appearance of the knuckle side face (bottom) after water splash test with O-ring. Water is collected in the cavity between spindle, O-ring and bearing side face.



Report No.: ST 02 T 212 Updated: Mar 11, 2003 Total Pages: 9

Page # 5




Picture 4: Appearance of knuckle side face (top) after water splash test without O-ring. Corrosion marks are now visible on the spindle



Report No.: ST 02 T 212 Updated: Mar 11, 2003 Total Pages: 9


Page # 6



Picture 5: Appearance of knuckle side face (bottom) after water splash test without O-ring. Virtually all milling marks are indicating water intrusion.



Picture 6: Bearing side face (bottom) after water splash test without O-ring. The complete chamfer exhibits corrosion marks.



Picture 7: Bearing bore after water splash test without O-ring. Corrosion stains are distributed around the complete circumference.

Conclusion

This test proves the potential water leak path between the knuckle and inner ring side faces and along the stub axle. It is to be assumed that the risk of water intrusion is increasing, when dynamic loading conditions like cornering and/or braking are applied.

The test also proves the performance of a sealed (O-ring) joint.

Response

to Main Document

Achim Mueller/SCHWEKF
09/08 02:06 AM

Subject: Water Splash Test on European Wheel Assembly

Response to: Inspection and Test Reports

Category:



sauerwaternplash.do

SKF 001838

BU Trucks Product Design**Purpose of the Test**

The purpose of this static test was to prove that water may not enter the joint between a Truck Hub Unit's inner ring and the axle side face of SAF's (Sauer Achsenfabrik) trailer axle.

Test Description

A Truck Hub Unit BTF-0056 was assembled onto a new wheel end spindle of an SAF trailer axle. The bearing was clamped with 80 kN.

The knuckle is then installed horizontally to a rig. To achieve some temperature variation, the Truck Hub Unit is set into rotation by means of a driving belt. Simple tap water is then sprayed onto the joint between axle and inner ring side face (see picture 1).



Picture 1: Water Splash on joint between Truck Hub Unit (top) and axle (bottom)

The rotational speed was set to be 800 rpm during "dry" periods, while it was 300 rpm during time periods with water splash. The duration of each time period was set to be 30 minutes.

Test Results

Only one assembly without O-ring in the joint was tested for 13 "water splash cycles". The temperature variation was between 30°C and 65°C.

Upon disassembly, no corrosion was found in the joint between THU and axle (see pictures 2 to 4).

SKF

BU Trucks Product Design

**Static water Splash Test on SAF
Axe**



Picture 2: Top view on axle side face and transition to spindle






BU Trucks Product Design

Picture 3: Side view on axle side face and transition to spindle

Static water Splash Test on SAF

Axle



Picture 3: Bearing side face. The crescent shaped reddish corrosion trace indicates the outer diameter of the axle side face

Conclusion

This test proves that water does not easily enter the joint between axle and bearing side face (if at all). Water, which is splashed onto said joint, will flow along the outer diameter of the contact zone between inner ring and axle and eventually drip off.

Discussion

Main Topic:
Bernd Stephan/SCA-HQ/SP
07/01 02:48 AM

Subject: Letter from ARM to Ryder
Category:

This is the letter that ARM submitted to Ryder today.

As you can see, instead of identifying a rifle shot. They mentioned that they are going to focus on a detection device. They formatted the letter this way because it very quickly became obvious that a few parts could turn into many parts.

Notice that timing is aggressive for the vibration detection.

Forwarded by Robert J Bondy/DET/SKF on 06/28/2002 10:48 AM

Thomas.Sanko@ArvinMeritor.com on 06/28/2002 10:39:46 AM



To: robert.j.bondy@skf.com
CC:
Subject: Ryder letter

<<TS61702Response.doc>>

Tom Sanko
Product Manager-Drivelines & Front Axles
248-435-1573
248-435-1968 fax
thomas.sanko@arvinmeritor.com



TS61702Response.doc

June 26, 2002

Mr. Jim Cald
Ryder
Logistics & Transportation
Solutions Worldwide
3600 NW 82 Avenue
Miami, FL 33186-0829

Dear Mr. Cald:

During our meeting in Miami on June 14th, a team led by Mr. Jerry Thrift requested a proposal from Meritor regarding the FF981 hubs in service on approximately 38,000 Ryder trucks. The concern was the number of hub failures being experienced at mileages less than the 750,000 mile warranty and the inability of the current inspection methods performed at various Ryder locations to adequately detect progressing bearing deterioration during regularly scheduled preventive maintenance.

We were asked to review vehicle data subsequently provided by Ryder against our own records of axle shipments and recommend a target population of trucks on which the hubs would be replaced at no expense to Ryder. An e-mail from Mr. George Bowers dated 6/13/02 detailed Ryder's expectations for this program.

First let me update you on the current status of our investigation and other activities.

1. Our investigation of the data so far does not identify a "rifle shot" population of trucks that we would propose Ryder remove from service. However, we are continuing to review the data.
2. We recognize that our test procedure TP-0251 is subject to technician skill.
3. We are developing an electronic diagnostic device to remove all operator subjectivity. The device has been used in the lab and on a vehicle in our garage. This assessment provides conclusive results enabling one to easily distinguish a hub in "good" condition from one in a state of some distress. The comparison was made between a new hub and one that resulted in disagreement among personnel during the inspections performed in LaVergne, TN. We invite you to our facility in Troy, MI for a demonstration as early as next week if your schedule permits. Alternatively, we can transport the device with a technician to any Ryder location of your choice.
4. We plan to have the prototype model developed into production units by the end of September 2002.

Upon availability of production models of the diagnostic tool, quantities sufficient to stock each Ryder location will be provided free of charge along with any necessary training.

From that point forward, inspections would be performed with this tool in conjunction with TP-0251.

SKF 001843

We believe this to be a reasonable and equitable approach to the current problem and look forward to your concurrence to begin as soon as possible. If we can determine a "target" population on which to focus our prototype inspection process we can accelerate the preventive maintenance at those locations.

Sincerely,

T. M. Sanko
Product Manager
CVS Front Axle / Driveline
ArvinMeritor, Inc.

SKF 001844

TS61702Response.doc

Name Robert J Bondy/DET/SKF

E-mail

Phone

Role

Goals

Other

Discussion

Mail To/From:
Robert J Bondy/DET/ SKF
06/05 05:39 PM

Subject: Ryder Tennessee letter
Category: PLB



Robert J Bondy
06/05/2002 05:27 PM

To: Richard W Frett/ELG/SKF@SKF, Timothy D Gifford/KOP/SKF@SKF
cc:
Subject: Information: Hub Review In Tennessee

----- Forwarded by Robert J Bondy/DET/SKF on 06/05/2002 05:27 PM -----



Robert J Bondy
06/04/2002 11:03 AM

To: Bernd Stephan/SCH/SKF@SKF, Arno Stubenrauch/SCH/SKF@SKF
cc:
Subject: Information: Hub Review In Tennessee

Bernd:

I've already copied Bruce, Bill and Mike

Please make sure to read the last part of the Ryder Expectations of ARM™ Please ask that your group bring
> with them plans to address rapid replacement of our unitized hubs."

Regards,

bob

----- Forwarded by Robert J Bondy/DET/SKF on 06/04/2002 11:00 AM -----
Dale.Bell@ArvinMeritor.com on 06/03/2002 04:54:39 PM

----- Original Message -----
To: robert.j.bondy@skf.com
cc:
Subject: FW: Hub Review In Tennessee

> -----Original Message-----
> From: Rosenthal, Robert
> Sent: Monday, June 03, 2002 3:13 PM
> To: Sanko, Thomas; Bell, Dale
> Cc: Mejaly, Joseph
> Subject: FW: Hub Review In Tennessee

SKF D01846

>
> For your information.
> We need to give them facts, on how long hubs will run after detection of a
> spall.
> Rosey
>
> -----Original Message-----
> From: McLendon, Bruce
> Sent: Monday, June 03, 2002 1:24 PM
> To: Rosenthal, Robert; Pan, J
> Cc: Hyatt, Jeffrey; Comer, Danny
> Subject: FW: Hub Review In Tennessee
>
> Read the following request from Ryder Bruce
>
> -----Original Message-----
> From: John_N_Murphy@ryder.com@AU TO
> Sent: Friday, May 31, 2002 4:19 PM
> To: mclendbe@meritorauto.com
> Cc: Jerry_F_Thrift@ryder.com; George_Bowers@ryder.com;
> Harry_F_Ryder@ryder.com; Patrick_Porter@ryder.com
> Subject: Hub Review In Tennessee
>
> Bruce, I had the opportunity to speak with both Harry Ryder and Patrick
> Porter this afternoon. From the information provided to me I am convinced
> that our maintenance practices are correct and the issue at hand is
> product
> quality.
> It appears that the issue at hand now is that a technician may or may not
> be able to feel the spalling bearings during PM inspection. In addition,
> SKF and Arvin-Meritor do not know the mean time to failure once spalling
> begins.
> The failure rate which Ryder is seeing is raising at an alarming rate. I
> know we have a meeting set up for the week of June 10th. The purpose of
> my
> writing is to make sure that Arvin-Meritor understands the expectation of
> the upcoming meeting.
> During our next meeting Ryder is not expecting to hear more on the length
> and duration of tests that are currently underway. The time has come for
> a
> more proactive approach to this issue. Please ask that your group bring
> with them plans to address rapid replacement of our unitized hubs.
> Regards,
> John Murphy

Discussion

Main Topic
Class
Rehmberg/GHQ/GOT/SKF
05/30 08:20 AM

Subject: Report to ARM
Category: Information

Updated version as of 2002-05-31



THU2 report to ARM 4.ppt

SKF 001848

Main failure causes identified

- **SKF**
 - CFW seal leakage
 - R-safe seal leakage
 - Stud hardness
- **ARM**
 - Water intrusion along the spindle
 - Mounting without rotating
 - Stud replacements

SKF 001649

SKF

CFW seal cause sheet

- **Cause:** IR Seal failure / not sealing properly
- **Effect:** Unacceptable higher indication on premature seal failure rate in North America environment.
- **Parts:**
 - Affects CFW parts made 1997 through April 2000
 - Replaced by improved R-safe from May 2000 onwards
- **Findings**
 - Grease used as lubricant. Less grease does not mean it can't perform what it was intended to do.
 - Grease fill (in cavity between lips) amount less in Aiken compared to Luechow
 - might lead to early failures due to less contamination resistance
 - Luechow fill 1.5 g (remain 0.8 g after assembly)
 - Aiken fill 0.3 g
 - No spec's on grease fill from Freudenberg
 - Grease fill is used primarily for reducing seal lip wear
 - Average seal life shorter in NA compared to Europe
 - Operating differences ?
 - Maintenance differences ?
 - CFW seal pumping action reduces effect over time
 - Abnormal events 1999 (week 17,18,19) ?
 - In Aiken (production)
 - at ARM (design, mounting etc)
 - Failure rate <1% lead to change from CFW to R-Safe seal
 - >1 % water will break down the grease function
- **Conclusions**
 - Different grease fill
 - Study show no effect on seal wear
 - Statistics to support statement
 - water immersion will reduce life if
 - Statistics to support statement
 - Question to ARM: How much water will normally spray on the bearing ?
 - Question to ARM: What's the extent of high pressure cleaning
- **Recommendations**
 - Retrofit pop-out bolt from Wabash
 - To be checked by the driver min once per day
 - To be used in combination with ABS signal warning

SKF 001850

SKF

R-safe seal cause sheet

- Cause: IR Seal failure / not sealing properly
- Effect: Unacceptable higher indication on premature seal failure rate in North America environment.
- Parts
 - Affects R-Safe parts made after April 2000
- Findings
 - Molding defects
 - fill not completed on one lip or both lips / de-flashing not complete
 - 8 claimed parts returned from ARM
 - 6 showed defects on both lips
 - The other 2 was not seal related
 - Water intrusion only possible when both lips are defect
 - Defects on the seal lips are run out under operation due to wear
 - have seen on samples that at least one lip is repaired within 100.000 miles
 - Defect rate found is < 2% of both lips
 - note: The findings are from inspection of the last production lot. However the scrap rate was the same for the other production lots Samples from the other production lots will be checked for verification.
 - Lack of warranty data update from ARM
 - 100 % air test already implemented in Elgin
 - Conclusions
 - Water intrusion could happen if:
 - Both lips defected
 - Water flooding at early mileage (before lip repair itself)
 - Rig test on pre-damaged bearings shows residual life in excess of 80.000 miles.
 - Recommendations
 - Retrofit pop-out bolt (see for CFW)
 - Implement 3 extra inspections
 - at 50, 100 and 150 thousand miles
 - Complete instrumental road test for verification
 - Seal material change (high temperature)

SKF 001851

SKF

Stud hardness cause sheet

- **Cause:** Studs with hardness out of spec, incl high hardness variation
- **Effect:** Fractures occurring at low mileages or during re-torque of wheel nuts
- **Parts**
 - Affects studs from supplier Ingersoll. Delivery started Feb 2001
- **Findings**
 - Bolts delivered outside SKF spec's 500+ HV 0,3.
 - SKF spec's In Vickers 0,3
 - NATC uses video monitoring equipment
 - Ingersoll measures with manual equipment
 - Correlation issues between NATC and Ingersoll
 - Affects shipment lot #4, and possibly #3 & #5
 - Pending proper 8D report from Ingersoll
 - MascotTech bolts from 1997 with >500,000 miles up to 456 HV 0,3
 - **Conclusions**
 - Ingersoll have not a capable HT process
 - Measurement principles different
 - SKF key spec on surface hardness
 - Ingersoll measurement principle focus core
 - Difficult translation between two meas. principles
 - **Recommendations**
 - Temporary deviation to be issued to Ingersoll for slight increase in surface hardness
 - Revalidate Mascotech as supplier with new heat treat process

SKF 001852

SKF

Leave out for now

Unhardened IR raceway

cause sheet

- **Cause:** Unhardened IR raceway
- **Effect:** Early spalling
- **Parts**
 - Affects bearings during Q1 2000
- **Findings**
 - 20 bearings with unhardened inner rings returned from field
 - Early spalling started
- **Conclusions**
 - Heat Treatment process not working properly for a short period of time
 - No further returns received after corrective actions.
 - Root cause identified and fixed.
- **Recommendations**
 - Case closed

SKF 001853

SKF

Water intrusion along the spindle cause sheet

- **Cause:** water ingress in the bearing
- **Effect:** Unacceptable higher indication on premature seal failure rate in North America environment.
- **Parts**
 - Affect units before August 2001
- **Findings**
 - Traces of corrosion proving that water intrudes along the spindle into the bearing.
 - Investigations on 30 returned units from the field, previously thought to be seal failures show in 21 cases actual failures due to water intrusion along the spindle.
 - ARM introduced an O-ring August 2001
- **Conclusions**
 - Incidents like this considerably less in European environment
 - Possibly the spindle rigidity not sufficient
 - ARM's introduction of O-ring improved the problem
- **Recommendations**
 - Do FEA of assemblies of ARM and Europe for benchmarking.
 - Introduce pop-out bolt from Wabash

SKF 001854

SKF

Mounting without rotating OR cause sheet

- **Cause:** Damage raceways during mounting
- **Effect:** Insufficient life for 1 million miles
- **Parts**
 - Affects units from 1997 through June 2001
- **Findings**
 - Nicks found on OR raceways during installation
 - Rotation is part of SKF mounting instructions
 - ARM introduced automatic rotation device in their assembly June 2001
- **Conclusions**
 - ARM introduction of automatic device was made to ensure proper mounting.
- **Recommendations**
 - Introduce pop-out bolt from Wabash

SKF 001855

SKF


Improper replacement of Studs cause sheet

- **Cause:** Units damaged due to improper stud removal and insertion
- **Effect:** Insufficient life for 1 million miles
- **Parts**
 - Potentially affects certain percentage of units during life of the product
- **Findings**
 - Heavy marks on studs, suggesting they have been inserted with hammer / sledge hammer
- **Conclusions**
 - Potentially could introduce impact damages on the raceways
- **Recommendations**
 - More investigations needed
 - Use SKF maintenance procedure on how to do this.

SKF 001866

SKF

P-Chart - All ARM Returns by Service Date




SKF 001857

Steer THU Warranty Return Percent of claims

(based on 530 claims in SKF database as of 12/31/2001)

To be updated



SKF 001858

SKF


Response
to Main Document

Robert J Bondy/DET/SKF
06/31 09:05 AM

Subject: Freightliner Discussion may 31 presentation
Response to: Report to ARM
Category: Information


FLINER disc.ppt

- The Data
 - Returned Material Review



Miscellaneous:

- 5.1% Removal damage (reason for removal not given; not apparent)
- 2.9% Water intrusion along spindle
- 2.2% hub cap lost
- 2% inner come
- 1.6% Tampering
- 1.4% Oil separation
- 1% Outboard seal
- Balance: end play, cup spall, corrosion, assembly, quality

SKF 001860

SKF

Main failure causes identified

- **SKF**
 - CFW seal
 - R-safe seal
 - Stud hardness
- **ARM**
 - Mounting without rotating
 - Stud replacements

SKF 001861

SKF

CFW seal cause sheet

- Cause: IR Seal failure / not sealing properly
- Effect: Unacceptable higher indication on premature seal failure rate in North America environment.
- Parts
 - Affects CFW parts made 1997 through April 2000
 - Replaced by Improved R-safe from May 2000 onwards
- Findings
 - Grease used as lubricant. Less grease does not mean it can't perform what it was intended to do.
 - Grease fill (in cavity between lips) amount less in Aiken compared to Luechow
 - might lead to early failures due to less contamination resistance
 - Luechow fill 1.5 g (remain 0.8 g after assembly)
 - Aiken fill 0.3 g
 - No spec's on grease fill from Freudenberg
 - Grease fill is used primarily for reducing seal lip wear
 - Average seal life shorter in NA compared to Europe
 - Operating differences
 - Maintenance differences
 - CFW seal pumping action reduces effect over time
 - Failure rate <1% lead to change from CFW to R-Safe seal
 - >1 % water will break down the grease function
- Conclusions
 - Different grease fill
 - Study show no effect on seal wear
 - Statistics to support statement
 - water immersion will reduce life if
 - Statistics to support statement
 - Question to ARM: How much water will normally spray on the bearing ?
 - Question to ARM: What's the extent of high pressure cleaning
- Recommendations
 - Evaluate Retrofit pop-out bolt from Webash (Plan timing TBD By 03 June 02)
 - To be checked by the driver min once per day
 - To be used in combination with ABS signal warning
 - R-Safe Seal Axial VS Dirt Lip Design
 - Grease Change GWZ

SKF 001882

SKF

R-safe seal cause sheet

- Cause: IR Seal failure / not sealing properly
- Effect: Unacceptable higher indication on premature seal failure rate in North America environment.
- Parts
 - Affects R-Safe parts made after July 2000
- Findings
 - Molding defects (April 5, 2002)
 - fill not completed on one lip or both lips / de-flashing not complete
 - 10 claimed parts returned from ARM
 - 6 showed defects on both lips
 - The other 4 were not seal related
 - Water intrusion only possible when both lips are defect
 - Defects on the seal lips are run out under operation due to wear
 - have seen on samples that at least one lip is repaired within 100.000 miles
 - Defect rate found is < 2% of both lips
 - note: The findings are from inspection of the last production lot. However the scrap rate was the same for the other production lots. Samples from the other production lots will be checked for verification.
 - 100 % air test already implemented in Elgin
 - Conclusions
 - Water Intrusion could happen if:
 - Both lips defected
 - Water flooding at early mileage (before lip repair itself)
 - Rig test on pre-damaged bearings shows residual life in excess of 80.000 miles.
 - Recommendations
 - Evaluate the Retrofit of pop-out bolt (Plan Timing TBD by 03June02)
 - Implement 3 extra inspections
 - at 50, 100 and 150 thousand miles
 - Complete instrumental road test for verification
 - Continuous improvement with R-Safe +

SKF 001863

SKF

Stud hardness cause sheet

- **Cause:** Studs with hardness out of spec, incl high hardness variation
- **Effect:** Fractures occurring at low mileages or during re-torque of wheel nuts
- **Parts**
 - Affects studs from supplier Ingersoll. Delivery started Feb 2001
- **Findings**
 - Bolts delivered outside SKF
 - SKF spec's in Vickers 0,3
 - NATC uses video monitoring equipment
 - Ingersoll measures with manual equipment
 - Correlation issues between NATC and Ingersoll
 - Affects shipment lot #4, and possibly #3 & #5 Verification by 14June02
 - Pending proper 8D report from Ingersoll Due 03 June 02
 - MascotTech bolts from 1997 with >500,000 miles up to 456 HV 0,3
- **Conclusions**
 - Ingersoll have not a capable HT process
 - Measurement principles different
 - SKF key spec on surface hardness
 - Ingersoll measurement principle focus core
 - Difficult translation between two meas. principles
- **Recommendations**
 - Temporary deviation to be issued to Ingersoll for slight increase in surface hardness
 - Revalidate Mascotech as supplier with new heat treat process
 - Long Term Effect Evaluation Study (Timing by 03 June 02)

SKF 001885

SKF

Unhardened IR raceway cause sheet

- **Cause:** Unhardened IR raceway
- **Effect:** Early spalling
- **Parts**
 - Affects bearings during Q1 1999 through Q2 2000
- **Findings**
 - 20 bearings were returned and evaluated with unhardened inner rings returned from field
 - Early spalling started
- **Conclusions**
 - Heat Treatment process not working properly for a short period of time
 - No further returns received after corrective actions.
 - Root cause identified and fixed.
- **Recommendations**
 - Case closed

SKF 001866

SKF


Mounting without rotating OR cause sheet

- **Cause:** Damage raceways during mounting
- **Effect:** Insufficient life for 1 million miles
- **Parts**
 - Affects units from 1997 through April 2001
- **Findings**
 - Nicks found on OR raceways during installation
 - Rotation is part of SKF mounting instructions
 - ARM introduced Controlled rotation April 2001
- **Conclusions**
 - ARM introduction of automatic device was made to ensure proper mounting.
- **Recommendations**
 - Evaluate Detectability Device
 - Closed issue for current product

SKF 001867

SKF

- The Data
 - Returned Material Review



Item Description	Corrective Action

SKF 001868

SKF

Discussion

Main Topic

Bernd Stephan/SCH/SKF
06/30 04:59 AM


Subject: 60000 miles inspection intervall rig test,- pictures after completion

Category:



KIF_0529.JPG KIF_0523.JPG KIF_0524.JPG KIF_0525.JPG KIF_0526.JPG KIF_0522.JPG

SKF 001869



SKF 001870



SKF 001871




SKF 001672



SKF 001873



SKF 001874



SKF 001875

Discussion

Main Topic

Bernd Stephan/SCH/SKF
05/30 04:58 AM

Subject: ARM Knuckle pictures

Category:




KIF_0533.JPG KIF_0518.JPG KIF_0630.JPG KIF_0531.JPG KIF_0532.JPG KIF_0515.JPG


SKF 001876




SKF 001877




SKF 001878



SKF 001879



SKF 001880



SKF 001881



SKF 001882

Discussion

Main Topic

Bernd Stephan/BCH/SKF
05/30 04:56 AM

Subject:


Main route cause "Water ingress along the spindle" and Influencing parameters

Category:



KIF_0543.JPG

SKF 001883



SKF 001884

Discussion

Main Topic

Bernd Stephan/SCH/SKF
05/30 04:44 AM

Subject: pictures from field returned parts inspected at Schweinfurt
Category:

ARM THU2 without O-Ring but with R-Safe seal 100318 miles route cause "water ingress along spindle"



KIF_0522.JPG KIF_0523.JPG KIF_0524.JPG KIF_0525.JPG KIF_0526.JPG KIF_0629.JPG

ARM THU2 with O-Ring and R-safe seal 91572 miles route cause "water ingress through seal due to molding defects on both lips"



KIF_0478.JPG KIF_0479.JPG KIF_0480.JPG KIF_0481.JPG KIF_0514.JPG KIF_0484.JPG KIF_0485.JPG



KIF_0509.JPG KIF_0510.JPG KIF_0511.JPG KIF_0483.JPG KIF_0482.JPG

ARM THU2 #9 with CFW seal



KIF_0508.JPG KIF_0487.JPG KIF_0488.JPG KIF_0489.JPG KIF_0490.JPG KIF_0491.JPG KIF_0492.JPG




KIF_0493.JPG KIF_0494.JPG KIF_0496.JPG KIF_0498.JPG KIF_0497.JPG KIF_0505.JPG KIF_0506.JPG



SKF 001885




SKF 001866




SKF 001887



SKF 001888




SKF 001689



SKF 001690




SKF 001691




SKF 001892



SKF 001893



SKF 001894



SKF 001695



SKF 001896




SKF 001897



SKF 001898




SKF 001899




SKF 001900



SKF 001901



SKF 001902




SKF 001903



SKF 001904




SKF 001905



SKF 001906




SKF 001907



SKF 001908


SKF 001909



SKF 001910



SKF 001911



SKF 001912



SKF 001913



SKF 001914



SKF 001915

SECRET//NOFORN//DFI

SKF 001916



SKF 001917



SKF 001918

Discussion

Main Topic:

Achim Mueller/SCH/SMP
05/29 10:39 AM

Subject: Engineering Statement on THU Performance
Category:

Attached document contains a statement of SKF BU Trucks Product Engineering about the potential performance of an SKF front wheel Truck Hub Unit (THU)



SKF Eng. Statement.doc

SKF 001919

Engineering Statement about the design of the THU2-FF for ARM steer application

The bearing design, as it is today, is enable to operate maintenance free for 1 Mio miles under long haul conditions as long as all components are manufactured according the existing engineering specifications and according the manufacturing practice which is established at SKF Lüchow plant.

This is valid also for the seals, grease, grease distribution and the assembly process of the entire unit.

These statements are based on SKF's

- Beacon-Calculation
- X-Ray-Diffraction-Analysis of ARM units (after 560.000 miles in service)
- Raceway qualification testing on rigs
- Inspection of seal returns from field in US and Europe

under the following preconditions:

- No handling damage during transport from SKF to ARM assembly plant. Transport of axles from ARM to truck assembly plant.
- Correct installation on the wheel end spindle and correct application of the clamp load with rotating HUB during tightening of the central wheel nut.
- Correctly machined abutment parts.
- Installation of a sufficient static seal against water ingress along the spindle.
- Correctly secured central nut against loosening.
- No disassembly during operation or service.
- Replacement of studs has to follow strictly the procedure described in ARM's Bulletin. Using any other replacement method is strictly forbidden.

Concerning product improvements:

we see some potential:

1. Adding a third lip to the R-Safe and filling the free space with a water resistant grease like SKF:LGHB2.
2. To select a more wear resistant rubber material than our present FKM-formulation.
3. Further development of the grease for even longer service life.

Discussion

Main Topic
Class
Rehmberg/GHQ/GOT/SKF
05/28 10:18 AM

Subject: Presentation to CEO May 28th
Category: Information

The following presentation was made to SKF CEO Sune Carlson, to Thore Bertilsson and Lars Behn
by Claes Rehmberg
Also present was Tom Johnstone and Gunilla Nilsson




THU2 seal issue3.ppt

THU2 issue w. ARM

Facts

- Customer Arvin Meritor
- 400.000 bearings in the market
- Mainly steer axle (to some extent used also on trailers)
- SOP Luechow March 96
- SOP Aiken August 98
- Freudenberg seals used up till April 00 (340.000 units)
- RFT (R-safe) seals used from April 00 (61.000 units ytd)
- SKF notified March 14th on 15 wheel offs / fires since beginning of the year
- As of April 8th 18 wheel offs, incl. 3 trucks on fire
- ARM claiming 117 bearings as "severely advanced parts"

P-Chart - All ARM Returns by Service Date



SKF

SKF 001923

THU2 seal issue

Facts

- Typical seal failure mode:**

Seal wear -> deteriorated sealing function -> contamination/ water ingress -->
greasing function destroyed -> metallic contact/spalling etc. --> noise/vibration.

- However:

In this case in NA it continued in a few cases with:

drastic heat/pressure increase-> melting/fire --> nut worn out --> wheel-off.

- The Freudenberg seal used in RVI truck, without problems.**

- Decision to treat the two seals as two cases:**

- Freudenberg - high milage failures
- RFTR-safe seals - early failures

Steer THU Warranty Return

3. Weeks 18 Mar 2002

530 Total Claims in SKF Database (as of 12/31/2001)

Corrective Actions Taken by SKF

	<u>Percent of Claims</u>
Switch to GW-Z Grease	10.4
Grease Egress	
Switch to R-Safe Inboard Seal	
B Seal Leak - Contaminant Ingress	15.6
Induction Hardening Equipment & Procedural Changes	
CR not hardened	3.8

Corrective Actions taken by ArvinMeritor

Increased Hubcap Torque	
Bearing Failure - Run w/o Hub Cap	2.6
Switch to MolyKote D Anti-fretting Compound/O-Ring Seal	
Removal Damage	5.7
Aladar Intrusion Along Spindle	1.9
Rotation of Hub Unit during Torque	
Low Clamp Load	6.8
Field Bulletin on Inspection Techniques	
No problem found	27.6
Tampering	1.9

Total percent Claims Addressed by Corrective Actions 69.5

Claim Categories Not Directly Addressed

	<u>Percent of Claims</u>
Root Cause Not Determined	Total 14.0
Returns too advanced to determine cause	
Customer Abuse	Total 7.5
Impact Damage	7.5

Total Percent claims above 91.0



THU2 - ARM

Current status

- **SKF related**
 - **Freudenberg seal** (mfg 1997 to April 2000) 320000 units
 - Seal shorter life in NA comp. to Europe
 - Operating differences
 - Maintenance practices
 - All wheel-offs w. F. seals
 - Grease fill in cavity between lips - influence on functional performance ?
 - Detection method
 - Pop-out bolt
 - **RFTs R-safe** (mfg from April 2000) 61000 units
 - Incorrect moulding (2-3 %)
 - influence on life
 - Implement 3x50,000 miles inspection
 - Track test starting to verify these intervals
 - Confirm inspection & detection method as sufficient or advice alternatives



THU2 - ARM

Current status

- **SKF related cont.**
 - **Unhardened Raceway** (some 20 cases) spring 2000
 - Problem was identified, process changed
 - some few units could remain in the field
 - **Studs (Supplier Ingersoll)**
 - Hardness level (too high) and large hardness variation
 - Root cause analysis pending from supplier (limited response is a major concern)
 - Supplier HT process capability ?
 - Risk evaluation on studs in the field
 - **Overall**
 - Final decision to be made latest May 30th on action steps for SKF

THU2 - ARM

Current status

- ARM related
 - **Water ingress along spindle**
 - O-ring was implemented by ARM June 2001
 - No information as to whether retrofit to be made
 - **Raceway damage due to lack of rotation during clamping**
 - Influence on life
 - **Stud replacement**
 - procedure at truck manufacturers
 - Damage while changing

Discussion

Main Topic
Class
Rahmberg/GHQ/GOT/SKF
05/13 12:44 PM

Subject: Statistical Evaluations
Category: Statistics



Response
to Main Document

Rick P Morrow/AMER/SKF
05/20 08:23 AM


Subject: Hub data from ARM
Response to: Statistical Evaluations
Category: Statistics




fr98x hub niran 4_15_02.x



PPM Trend for FF98X Hubs



Average Miles FF98X Hub Returns Failed on Progressive Incidents (PI) & Combined



Response

to Main Document

Rick P Morrow/AMER/SKF
05/20 09:10 AM

Subject: Analyses of ARM and SKF data
Response to: Statistical Evaluations
Category: Statistics



THU 2 Analysis Duane Gipe, Rick Morrow shor

THU 2 Analysis Duane Gipe, Rick
Morrow

5/15/02

Valid Claims Only (Unless
Otherwise Stated) 772 invalid, valid,
inconclusive, open ARM claims
analyzed by Bruce Weeks, Dave
Zimmerman

Notes/Assumptions

- Only one root cause was listed per warranty return. May have multiple causes and/or interactions
- Missing data for some analysis was considerable
- Immature data is expected for years 2001 and beyond thus reducing the service life mean


Count of Root Cause	
Root Cause	Total
NO PROBLEM FOUND	185
OB SEAL LEAK - INGRESS	150
UNKNOWN	73
IMPACT DAMAGE	50
LOW CLAMP LOAD	47
INSIGNIFICANT LEAK	42
REMOVAL DAMAGE	34
WATER INTRUSION ALONG SPINDLE	27
OB SEAL LEAK - EGRESS	23
OIL SEPARATION	23
UNHARDENED RW	20
HUB CAP LOST	16
INNER RING SPALL	14
OB SEAL DAMAGED	12
OPEN	11
TAMPERING	11
OB SEAL LEAK - EGRESS	7
ASSEMBLY DAMAGE	6
NOT RECEIVED	3
OUTER RING SPALL	3
COCKED SEAL	2
DIMENSIONAL ISSUE	2
ENDPLAY	2
INCONCLUSIVE	2
NO INFORMATION	2
ATTACHING HARDWARE ISSUE	1
CORROSION	1
LOW GREASE WEIGHT	1
OB SEAL LEAK - INGRESS	1
(blank)	
Grand Total	771

Count of Root Cause		Total		
Root Cause				
IB SEAL LEAK - INGRESS	38	34%	7%	
NO PROBLEM FOUND	22	20%	6%	
IMPACT DAMAGE	9	8%	4%	
WATER INTRUSION ALONG SPINDLE	9	8%	4%	
UNKNOWN	8	7%	4%	
LOW CLAMP LOAD	6	5%	4%	
OB SEAL LEAK - EGRESS	3	3%	3%	
OIL SEPARATION	3	3%	3%	
HUB CAP LOST	2	2%	2%	
IB SEAL DAMAGED	2	2%	2%	
OPEN	2	2%	2%	
UNHARDENED RW	2	2%	2%	
INCONCLUSIVE	1	1%	1%	
INNER RING SPALL	1	1%	1%	
OB SEAL LEAK - INGRESS	1	1%	1%	
REMOVAL DAMAGE	1	1%	1%	
TAMPERING	1	1%	1%	
Grand Total	111			

In Service Miles by Root Cause

ByVar4	Mean4	StDev4	Sum4	Minimum4	Maximum4	N4
COCKED SEAL	271690	211127	543380	122401	420979	2
CORROSION	92944	*	92944	92944	92944	1
DIMENSIONAL ISSUE	142255	172905	284510	19993	264517	2
ENDPLAY	180414	30961	360827	158521	202306	2
IB SEAL LEAK - EGRESS	324260	160600	7133726	11821	627378	22
IB SEAL LEAK - INGRESS	340935	147001	47390033	21309	794820	139
INCONCLUSIVE	982591	*	982591	982591	982591	1
INNER RING SPALL	235484	143019	2354837	79766	528922	10
LOW GREASE WEIGHT	2325	*	2325	2325	2325	1
na	*	*	*	*	*	0
OB SEAL LEAK - EGRESS	213474	192456	1067369	18	503928	5
OB SEAL LEAK - INGRESS	151668	*	151668	151668	151668	1
OIL SEPARATION	307662	136292	6460892	34097	558646	21
OUTER RING SPALL	432888	160829	1298665	275686	597114	3
UNHARDENED RW	80515	80569	1610300	6000	304315	20
UNKNOWN	179003	99140	1611028	53489	384093	9

All Valid Claims



Infant mortality reduces fit of any distribution

IB Seal Ingress Only



Weibull is better model

Four-way Probability Plot for Serv Life

ML Estimates - Complete Data
Valid IB - Ingress Root Cause

Weibull

Lognormal base e



Anderson-Darling (adj)

Weibull

0.46

Lognormal base e



3.32

Exponential

20.42

Normal





0.51



Valid Unhardened Raceways only

Four-way Probability Plot for Serv Life

ML Estimates - Complete Data



Anderson-Darling (adj)

Webull

0.775

Lognormal base e

0.780

Exponential

0.809

Normal


1.906

Analysis


5/15/02

Analysis from 2,122 ARM
Returns and SKF Analyzed
771 claims

ARM 2,140 data







R-Safe data is immature. < 10 units analyzed



Source: ARM with DG, SKF

SKF 001944



Return Count by Month Places in Service (Period of R-Safe)

Count of MOS	Mile	Cell											Grand Total
MOS	50000	100000	150000	200000	250000	300000	350000	450000	550000	600000	650000		
200008	2	1	1	1	2			4					11
200009	3		7	1			1						12
200010	1	3	3	8	3	1							19
200011	2		1	1									4
200012	1		1	1	2	3							8
200101	2		1	1				1					5
200102	2	2	1	1	1								7
200103	3	2			1								6
200104	1	1			3								5
200105	1	3						1					5
200106	2	1						1				1	4
200107	5	4	1							1			11
200108	5	2			1								8
200109	2	1											3
200110	2											1	3
200111	4												4
200112	2												2
200202	1												1
Grand Total	36	21	19	18	9	5	5	1	1	1	1		118

R-Safe Returns

Part No. BTF-0065

Count of Root Cause	Root Cause				
Mileage Cell	B SEAL LEAK - INGRESS	INNER RING SPALL	LOW GREASE WEIGHT	Grand Total	
10000					
50000				1	1
100000		4			4
150000		1			1
200000					
250000					
300000					
350000					
400000					
450000					
500000					
550000					
600000					
650000					
700000					
750000					
800000					
1000000					
(blank)			1		1
Grand Total		5	1	1	7

Mean Time To Return imprecise due to only 7 data points. No Progressive Incidents.
1 return < 50,000 miles in service

FNOK Count by Root Cause by Mileage

Part No. BTF-0052

Count of Root Cause	Root Cause	Mileage										Grand Total
		COCKED SEAL	DIMENSIONAL ISSUE	IB SEAL LEAK - EGRESS	IB SEAL LEAK - INGRESS	INNER SPALL	OB SEAL LEAK - EGRESS	OB SEAL LEAK - INGRESS	OIL SEPARATION	UNHARDENED RW		
10000												
50000				1	1	1	1		1	8	13	
100000					1	1	1			6	10	
150000		1			1	1				1	5	
200000						9		1	1		12	
250000						11	1			4	16	
300000			1			21		1		3	1	27
350000						6			2		1	9
400000						16			2			17
450000		1			1	6						7
500000						12				1		13
550000						5	1					6
600000						1				1		2
650000						1						1
700000						2						2
750000						1						
800000						1						1
1000000												
(blank)					1	6	3	4	1	15	18	11
Grand Total		2	2	5	98	7	4	1				152


Count by Mfg Loc By Root Cause by Mileage BTF-0049 only

Part No. BTF-0049

Count of Root Cause	Root Cause	Mfg Loc												
			ENDPLAY	ENDPLAY Total	IB SEAL LEAK - EGRESS	IB SEAL LEAK - EGRESS Total	IB SEAL LEAK - INGRESS	IB SEAL LEAK - INGRESS Total	INNER RING SPALL	INNER RING SPALL Total	OUTER RING SPALL	OUTER RING SPALL Total	Grand Total	
Mileage Cnt	Luechow	Luechow	(blank)	Aiken	Luechow	(blank)	Luechow	(blank)	Luechow	(blank)	Luechow	(blank)	Grand Total	
10000														
50000														
100000														
150000														
200000														
250000	1	1	1	1	1	1	1	1	1	1	1	1	1	
300000														
350000														
400000														
450000														
500000														
550000														
600000														
650000														
700000														
750000														
800000														
850000														
900000														
1000000														
(blank)														
Grand Total			1	1	9	1	10	1	1	1	3	2	1	19

R-Safe Return Count by Root Cause By Mileage in Service

Part No: ETRF-0085



Response
to Main Document.

Rick P Morrow\AMER\SKP
05/24 09:27 AM


Subject: C chart of claims by Alken Build Month
Response to: Statistical Evaluations
Category: Statistics



THU o-Chart.xls

SKF 001851

C-Chart - # Returns By Week (Aiken Build Date) For 1999
SKF Analyzed Returns




SKF 001952

1	1	4.519	10.9
2	0	4.519	10.9
3	4	4.519	10.9
4	14	4.519	10.9
5	6	4.519	10.9
6	3	4.519	10.9
7	1	4.519	10.9
8	2	4.519	10.9
9	2	4.519	10.9
10	10	4.519	10.9
11	4	4.519	10.9
12	10	4.519	10.9
13	11	4.519	10.9
14	2	4.519	10.9
15	0	4.519	10.9
16	1	4.519	10.9
17	20	4.519	10.9
18	11	4.519	10.9
19	28	4.519	10.9
20	7	4.519	10.9
21	7	4.519	10.9
22	0	4.519	10.9
23	2	4.519	10.9
24	7	4.519	10.9

25	4	4.519	10.9
26	8	4.519	10.9
27	2	4.519	10.9
28	0	4.519	10.9
29	2	4.519	10.9
30	2	4.519	10.9
31	4	4.519	10.9
32	1	4.519	10.9
33	1	4.519	10.9
34	1	4.519	10.9
35	0	4.519	10.9
36	1	4.519	10.9
37	7	4.519	10.9
38	6	4.519	10.9
39	3	4.519	10.9
40	7	4.519	10.9
41	1	4.519	10.9
42	0	4.519	10.9
43	2	4.519	10.9
44	2	4.519	10.9
45	1	4.519	10.9
46	6	4.519	10.9
47	6	4.519	10.9
48	6	4.519	10.9
49	4	4.519	10.9
50	2	4.519	10.9
51	2	4.519	10.9
52	1	4.519	10.9

Mileage Cell (All)



SKF 001966

Week No	Week No												Count of Week No Root Cause	Message Cell [All]
	51	52	53	54	55	56	57	58	59	60	61	62		
57	-	-	-	-	-	-	-	-	-	-	-	-	1B SEAL LEAK - INGRESS	
1	-	-	-	-	-	-	-	-	-	-	-	-	OB SEAL LEAK - INGRESS	
10	-	-	-	-	-	-	-	-	-	-	-	-	UNHARDENED RW	
10	-	-	-	-	-	-	-	-	-	-	-	-	WATER INTRUSION ALONG SPINDLE	
78	-	-	-	-	20	-	-	-	-	-	-	-	Grand Total	

Log #	Date Rec'd	Part No.	Ser No.	Shipped Date	Week No.	Qtr	Shipped Yr	Shipped Lc.	CRM	Shipped	Carrier #	Carrier Date	Shipped Date	MTD	Qtr	Shipped Yr	Months In
1457	01/20/02	BTF-0052	0018428	01/01/02	1	1	1999	Allen	Fisher	Ryder	3148266						
1456	02/26/02	BTF-0052	0075913	01/14/02	3	1	1999	Allen	Fisher	Wise Foods	E1703731	01/15/02	04/15/99	Apr-99	2	1999	34
1154	01/22/01	BTF-0052	0075815	01/14/02	3	1	1999	Allen	Navigator	Dedicated Fleet Log	0047882A	10/21/00	04/17/99	Apr-99	2	1999	18
1344	03/10/01	BTF-0052	0075827	01/14/02	3	1	1999	Allen	Navigator	FTC Trig	40591A	04/16/01	06/22/99	Jun-99	2	1999	22
7095		BTF-0052	0077033	01/15/02	3	1	1999	Allen	Fisher	Kennedy Truck Sales	E1420206	04/26/98	02/25/98	Feb-98	1	1998	6
3484	11/28/01	BTF-0052		01/17/02	4	1	1999	Allen	Fisher		E1680113	07/25/01	10/23/98	Oct-98			33
1148	12/01/00	BTF-0052	0076004	01/17/02	4	1	1999	Allen	Navigator	Walt-Mart	0011480A	05/13/00	05/05/98	Jun-98	2	1998	11
1096	10/01/01	BTF-0052	0076040	01/17/02	4	1	1999	Allen	Navigator	Walt-Mart	Unit 5575	04/10/01					
1587	08/15/01	BTF-0052	0076052	01/17/02	4	1	1999	Allen	Navigator	Walt-Mart	UPS-90310025256						0
1547	09/14/01	BTF-0052	0086204	01/18/02	4	1	1999	Allen	Fisher		NLFD00011M051T	05/16/01	04/17/99	Apr-99	2	1999	27
1087	03/26/02	BTF-0052	1098227	01/18/02	4	1	1999	Allen	Fisher		E1740047	05/16/02	04/25/99	Aug-99	3	1999	38
1246	05/17/01	BTF-0052	20738441	01/19/02	4	1	1999	Allen	Fisher		Unit 333671						0
1322	10/29/01	BTF-0052	0080579	01/20/02	4	1	1999	Allen	Navigator	Walt-Mart	WMT-509	11/21/00					
1275	11/24/01	BTF-0052	00811734	01/22/02	4	1	1999	Allen	Navigator	Walt-Mart	WMT1671	10/20/01					
1268	11/24/01	BTF-0052	00811841	01/22/02	4	1	1999	Allen	Navigator	Walt-Mart	WMT1800	09/16/01					
1507	09/14/01	BTF-0052	00811929	01/22/02	4	1	1999	Allen	Navigator	Walt-Mart	UF-98-10025247						
1628	08/14/01	BTF-0052	0082057	01/23/02	4	1	1999	Allen	Fisher	Jenlo	HOM00041H0047 1/2		12/10/98	Dec-98	4	1998	
1531	08/14/01	BTF-0052	0082065	01/23/02	4	1	1999	Allen	Fisher	Jenlo	HOM00011H0047 1/2		03/24/99	Feb-99	1	1999	
1534	08/14/01	BTF-0052	0082067	01/23/02	4	1	1999	Allen	Fisher	Jenlo	HOM00011H0047 2/2		03/24/99	Feb-99	1	1999	
1744	04/04/02	BTF-0052	1098226	01/24/02	5	1	1999	Allen	Fisher	Markland Del	E1740066	01/17/02	04/12/99	May-99	2	1999	33
1283	10/28/01	BTF-0052	01/25/02	5	1	1999	Allen	Fisher		E180918D	08/14/01	10/21/98	Oct-98	4	1998	23	
1438	11/29/01	BTF-0052	0080982	01/26/02	5	1	1999	Allen	Navigator	Aramco Transfor	1610067A	07/02/01					
1651	03/26/02	BTF-0052	1098227	01/26/02	5	1	1999	Allen	Fisher	REX	E1752420	12/08/01	04/01/99	Apr-99	2	1999	33
1429	03/26/02	BTF-0052	0080984	01/26/02	5	1	1999	Allen	Fisher		Y245224079T						0
1588	08/27/01	BTF-0052	0082040	01/27/02	5	1	1999	Allen	Navigator	Associated Lease	AS4800V00021	11/07/00	08/30/98	Jun-98	2	1998	17
1388	08/28/02	BTF-0049	1098771	02/01/02	5	1	1999	Leesburg	Fisher		CNA036704	08/27/01	07/16/99	Jul-99	3	1999	26
1124	08/23/00	BTF-0052	0087965	02/01/02	5	1	1999	Allen	Fisher		TNFD-004775	07/12/00	04/01/98	Apr-98	2	1998	18
1595	08/14/01	BTF-0052	00818129	02/05/02	5	1	1999	Allen	Fisher	Polar Inc	KOM00011A0077	05/10/01	11/13/98	Nov-98	4	1998	16
1616	11/24/01	BTF-0052	0220346	02/13/02	7	1	1999	Allen	Fisher	Racer Inn	E1623306	03/08/01	08/17/98	Mar-98	12		
1586	08/14/01	BTF-0052	00818131	02/15/02	5	1	1999	Allen	Fisher	New Pierce	212996	02/28/01	04/23/99	Apr-99	2	1999	22
1594	04/04/02	BTF-0052	00818142	02/15/02	5	1	1999	Allen	Navigator	Grimm Leasing	0638570A	11/05/98	03/02/98	Sep-98	3	1998	2
1592	07/04/02	BTF-0052	0082038	02/16/02	5	1	1999	Allen	Fisher	Houston Freightliner	E14-0002	02/13/99	08/31/99	May-99	2	1999	2
1274	08/27/01	BTF-0052	0082041	02/20/02	9	1	1999	Allen	Navigator	Stabens Trucking	7023410A	02/28/01	04/14/98	Apr-98	2	1998	23
1221	08/26/02	BTF-0052	0085787	02/20/02	10	1	1999	Allen	Fisher		E1752229	01/14/02	04/20/99	Apr-99	2	1999	33
1146	04/04/02	BTF-0052	0087864	02/20/02	10	1	1999	Allen	Fisher		CNA140301	02/05/02	05/10/99	May-99	2	1999	33
1722	03/26/02	BTF-0052	0128073	03/03/02	10	1	1999	Allen	Fisher		E1730936	02/20/02	01/08/99	Jan-99	1	1999	38
1769	04/04/02	BTF-0052	0084143	03/04/02	10	1	1999	Allen	Fisher		E1834421	04/04/01	04/16/98	Apr-98	2	1998	27
1293	01/14/02	BTF-0052	0086080	03/03/02	10	1	1999	Allen	Fisher		E1708049	04/04/01	05/02/99	May-99	2	1999	23
1308	05/27/01	BTF-0052	0086087	03/03/02	10	1	1999	Allen	Navigator	Todd W. Stiles Trig	0090072A	04/13/01	10/05/98	Oct-98	4	1998	19
1145	10/29/01	BTF-0052	01011933	03/03/02	10	1	1999	Allen	Fisher		E1811933	05/13/01	03/16/98	Mar-98	1	1998	38
1238	10/28/01	BTF-0052	01011931	03/03/02	10	1	1999	Allen	Navigator	Cannon Express	012100263	05/04/00	07/30/99	Jun-99	3	1999	12
1604	BTF-0052	01014847	03/06/02	10	1	1999	Allen	Fisher	Dick Shire	Kudzu						0	
1398	12/19/01	BTF-0052	0151284	03/06/02	11	1	1999	Allen	Mack	Morristown Express	CNA04946	05/13/01	06/20/99	Sep-99	3	2000	24
1505	11/28/01	BTF-0052	01004837	03/06/02	11	1	1999	Allen	Fisher		999595	09/27/01	01/10/01	Jan-01			0
1670	12/19/01	BTF-0052	0104083	03/06/02	11	1	1999	Allen	Navigator	Walt-Mart	WMT18047	05/18/01	04/00/98	Apr-98	2	1998	28
1287	11/28/01	BTF-0052	0104084	03/06/02	11	1	1999	Allen	Navigator	Walt-Mart	RD K1618635						0
1173	04/04/01	BTF-0052	01101471	03/14/02	12	1	1999	Allen	Navigator	West Investors	1001200A	03/04/00	05/07/98	Jun-98	2	1998	18
1378	05/03/01	BTF-0052	0109834	03/15/02	12	1	1999	Allen	Fisher	Midwest Transl	PCFD000102007 25	08/02/01	08/20/98	Aug-98	3	1998	22
1403	BTF-0052	1098332	03/16/02	12	1	1999	Allen	Fisher	Truck Centers, Inc.	E1452222	08/02/01	08/10/98	May-98	2	1998	3	
1395	10/01/01	BTF-0052	01098345	03/16/02	12	1	1999	Allen	Fisher	Midwest Transl	702	05/17/01	08/20/98	Aug-98	3	1998	21
1503	08/04/01	BTF-0052	0109844	03/16/02	12	1	1999	Allen	Fisher	Midwest Transl	PCFD000102007 1/2	08/04/01	07/11/00	Jul-00	3	2000	11
1405	05/05/01	BTF-0052	01098510	03/16/02	12	1	1999	Allen	Fisher	Midwest Transit	PCFD000102007 2/2	08/04/01	07/10/00	Jul-00	2	2000	11
1414	08/04/01	BTF-0052	01098516	03/17/02	12	1	1999	Allen	Fisher	Midwest Transit	PCTD000102007 2/2	08/04/01	07/14/00	Jul-00	3	2000	11
1398	05/05/01	BTF-0052	01098519	03/17/02	12	1	1999	Allen	Fisher	Midwest Transl	PCFD000102007 1/2	08/04/01	07/14/00	Jul-00	2	2000	11
1393	04/04/01	BTF-0052	01098523	03/17/02	12	1	1999	Allen	Fisher		PCFD000102007 2/2	08/04/01	07/14/00	Jul-00	2	2000	11
1395	04/04/01	BTF-0052	01098525	03/17/02	12	1	1999	Allen	Fisher		PCFD000102007 1/2	08/04/01	07/14/00	Jul-00	2	2000	11
1397	04/04/01	BTF-0052	01098527	03/17/02	12	1	1999	Allen	Fisher		PCFD000102007 2/2	08/04/01	07/14/00	Jul-00	2	2000	11
1398	04/04/01	BTF-0052	01098529	03/17/02	12	1	1999	Allen	Fisher		PCFD000102007 1/2	08/04/01	07/14/00	Jul-00	2	2000	11
1721	04/04/02	BTF-0052	0110102	03/23/02	13	1	1999	Allen	Fisher		33620						0
1123	08/27/02	BTF-0052	0110144	03/23/02	13	1	1999	Allen	Fisher		3365840	08/04/01	01/13/00	Jan-00	1	1999	20
1277	03/26/02	BTF-0052	01098322	03/24/02	13	1	1999	Allen	Fisher		CNA10777	02/11/02	05/14/99	May-99	2	1999	33
1746	04/04/02	BTF-0052	1100390	03/24/02	13	1	1999	Allen	Fisher	Galaxy Trans	E1702504	02/05/02	05/11/99	Aug-99	3	1999	30
1499	11/20/01	BTF-0052	01110844	03/25/02	13	1	1999	Allen	Navigator	Walt-Mart	WMT18000	10/26/01	02/17/99	May-99	2	1999	32
1772	03/26/02	BTF-0052	01111738	03/25/02	13	1	1999	Allen	Fisher		336031	12/13/01	02/21/99	Jul-99	2	1999	30
1688	10/01/01	BTF-0052	01110853	03/25/02	13	1	1999	Allen	Navigator	Walt-Mart	Unit 9988	09/04/01	03/08/98	Mar-98			0
1291																	

1000	1000004	BTF-0052	0112005	00000000	14	1	1000	Allen	Wheeler	Five Star	DM177-23	0901001	0001000	Jun-99	2	1999	27	
1001	0000002	BTF-0052	1142003	00000000	14	1	1000	Allen	Wheeler	Pride	E1762025	0117700	0701000	Jul-99	3	1999	?	
1140	0100001	BTF-0048	0210048	0411000	18	2	1000	Lanchay	Wheeler		R014820	0922000	0001000	Sep-98	3	1998	24	
1500	0000002	BTF-0052	0210004	0411000	17	2	1000	Allen	Wheeler	Wheeler	UNI 81000	0714001	0001000	Jun-99			28	
1502	0000001	BTF-0052	0120040	0411000	17	2	1000	Allen	Wheeler	Wheeler	UNI 81111	0714001	0001000	Jun-99			28	
1479	0300002	BTF-0052	0120013	0411000	17	2	1000	Allen	Kehler	Trucks Inc. of Jacksonville	CWA00200	12/12001	0207000	Feb-00	1	2000	22	
1000	0000001	BTF-0052	0217703	0421000	17	2	1000	Allen	Wheeler	Wheeler	UNI 81100	0804001	0001000	Jun-99			27	
1000	0000002	BTF-0052	0217740	0421000	17	2	1000	Allen	Peller	P.L.L.C.	E1744815	12/2001	0001000	Jun-99	2	1999	31	
1000	0000001	BTF-0052	0120002	0421000	17	2	1000	Allen	Volpe	FT-Mor Express	CWA01787	0401001	0001000	Jun-99	2	1999	23	
1000	0000002	BTF-0052	0121002	0421000	17	2	1000	Allen	Pryor	Ryder	Ryder Unit #307287	0118002	0002000	Jun-99	2	1999	31	
1000	0000001	BTF-0052	0122004	0421000	17	2	1000	Allen	Pryor	Pryor	E1744825	0110002	0001000	Jul-99	3	1999	31	
1463	0010001	BTF-0052	0121026	0421000	17	2	1000	Lanchay	Peller		NPF00001A1827	0518001	0001000	May-01	2	2001		
1167	1100001	BTF-0052	0122112	0421000	17	2	1000	Allen	Wheeler	Whitman	WM191462 24	0805003						
1283	1100001	BTF-0052	0122110	0421000	17	2	1000	Allen	Wheeler	Whitman	WM191462 12	0806001						
1700	1100001	BTF-0052	0122124	0421000	17	2	1000	Allen	Wheeler	Whitman	WM191500	0803001						
1440	0100002	BTF-0052	0122005	0421000	17	2	1000	Allen	Pryor	Pryor	340000	0501000	0001000	Jun-99	2	1999		
1000	0000002	BTF-0052	0220005	0421000	17	2	1000	Allen	Pryor	Transport Express	E1822100	0727001	0001000	Jun-99	2	1999	28	
1000	0000002	BTF-0052	0122042	0421000	17	2	1000	Allen	Pryor	Transport Express	E1720740	11/14001	0001000	Jun-99	2	1999	29	
1510	0000002	BTF-0052	0122002	0421000	17	2	1000	Allen	Pryor	Transport Express	CWA00000	0105002	0001000	Jun-99	2	1999	31	
1000	0000002	BTF-0042	0122027	0421000	17	2	1000	Allen	Pryor	Pryor	330003	0217002	0001000	Jul-99	3	1999	32	
1000	1000001	BTF-0052	0122001	0422000	17	2	1000	Allen	Wheeler	Whitman	UNI 81267	0801001	0001000	Aug-99			28	
1407	0010001	BTF-0052	0120032	0422000	17	2	1000	Allen	Wheeler	Pryor	UNI 3030							
1400	0000002	BTF-0052	0120025	0422000	17	2	1000	Allen	Pryor	Pryor	Ryder Unit #304149	35014	0227002	0001000	Jun-99	2	1999	35
1200	0010001	BTF-0052	0120145	0422000	16	2	1000	Allen	Wheeler	Wheeler	0000007A	0403001	0001000	Jun-99	2	1999	20	
1711	0000002	BTF-0052	0120002	0422000	16	2	1000	Allen	Pryor	E & B Tracking	E1744715	10/24001	0002000	Jun-99	2	1999	28	
1101	0000001	BTF-0042	0120046	0422000	16	2	1000	Allen	Pryor	Transport	RO 004040	0216001	0002000	Jun-99	2	1999	21	
1000	0000000	BTF-0052	1201238	0420000	16	2	1000	Allen	Wheeler	G.T. Group	02310778	12/07000	0003000	Sep-99	3	1999	3	
1313	0700001	BTF-0052	0120004	0422000	16	2	1000	Allen	Pryor	Transport	100121352	0200001						
1227	0000002	BTF-0052	0120005	0422000	16	2	1000	Allen			Munk 81260							
1220	0000002	BTF-0052	0120031	0422000	16	2	1000	Allen			Munk 81260							
1400	0000002	BTF-0052	0122143	0422000	16	2	1000	Allen	Pryor	Transport Company	CCL00000	0103102	0001000	Jun-99	2	1999	33	
1105	0100001	BTF-0042	0121040	0423000	12	2	1000	Allen	Wheeler	R014620	0622000	0003000	Sep-99	3	1999	24		
1311	0700001	BTF-0052	0120032	0423000	16	2	1000	Allen	Pryor	Transport	1801211/2	0203001						
1000	0000001	BTF-0052	0127246	0430000	16	2	1000	Allen	Pryor	Transport	Uni 3188						0	
1000	0000002	BTF-0052	0120005	0430000	16	2	1000	Allen	Pryor	Transport	E1744819							
1000	1100001	BTF-0052	0120110	0430000	16	2	1000	Allen	Pryor		65702	0803001	0001000	Jun-99	2	1999	36	
1714	0000002	BTF-0052	1201138	0430000	16	2	1000	Allen	Pryor	Empire Truck Sales	CWA00000	10/22010	0001000	Aug-99	2	1999	28	
1040	1100001	BTF-0052	0120019	0430000	16	2	1000	Allen	Pryor		E1602210	10/01001	0002000	Aug-99	3	1999	26	
1049	0000002	BTF-0052	0120040	0430000	16	2	1000	Allen	Pryor	Mckenzies Tank Lines	R.O. 49442	12/00001	0001000	Sep-99	2	1999	26	
1700	0000002	BTF-0052	0120021	0430000	16	2	1000	Allen	Pryor		E1741001	0304402	12/27001	Dec-01	4	2001	1	
1000	0000002	BTF-0052	0120002	0430000	16	2	1000	Allen	Pryor	C 100000000								
1000	0000002	BTF-0052	0120048	0400000	19	2	1000	Allen	Pryor	The National/CA England	E1600000	0504000	0120000	Jun-99	1	1999	25	
1704	0000002	BTF-0052	0120040	0400000	19	2	1000	Allen	Pryor	Zeman Pyle	E1762040	12/00001	0001000	Jun-99	2	1999	31	
1725	0000002	BTF-0052	0120003	0400000	19	2	1000	Allen	Pryor	Reed Transport	CWA00100	10/00001	0002000	Jun-99	2	1999	26	
1745	0000002	BTF-0052	0120001	0400000	19	2	1000	Allen	Pryor	Reed Transport	CWA00100	10/00001	0002000	Jun-99	2	1999	26	
1740	0000002	BTF-0052	0120027	0400000	19	2	1000	Allen	Pryor	Martin Lipe	851002	07/00002	0002000	Jun-99	2	1999	31	
1771	0000002	BTF-0052	0120022	0400000	19	2	1000	Allen	Pryor		E16074446	07/00001	0001000	Jul-99	3	1999	24	
1471	1100001	BTF-0052	0170010	0504000	19	2	1000	Allen	Wheeler	Tom Colley Motors	CWA00000	0800001	07/20002	Jul-99	3	1999	25	
1000	0100002	BTF-0052	0120100	0504000	19	2	1000	Allen	Pryor	RLLD								
1040	0700001	BTF-0052	0044334	0600000	19	2	1000	Lanchay	Pryor		NPF00001B1431 V2	0501000	0001000	Aug-99	0		0	
1022	1100001	BTF-0048	0120000	0600000	19	2	1000	Allen	Pryor		E1762041	05/17001	07/16000	Jul-99	2	1999	25	
1745	0000002	BTF-0052	0120013	0600000	19	2	1000	Allen	Pryor	Reed Novak	E1600002	05/16001	07/21000	Jul-99	3	1999	24	
1719	0000002	BTF-0052	0120002	0600000	19	2	1000	Allen	Pryor	New Parts	E1762047	01/20002	07/20003	Jul-99	3	1999	30	
1131	1000000	BTF-0052	0120007	0600000	19	2	1000	Allen	Pryor	James Lipo	00120000	0120000	02/01000	Aug-99	3	1999	11	
1202	0300001	BTF-0052	0120002	0600000	19	2	1000	Allen	Pryor		CWA00000	10/01001	07/00000	Jul-99	2	1999	27	
1213	1100001	BTF-0052	0120022	0600000	19	2	1000	Allen	Wheeler		00120000	07/11001	07/19000	Jul-99	3	1999	24	
1340	1100001	BTF-0052	0120018	0600000	19	2	1000	Allen	Pryor		E1600001	08/15001	07/23000	Jul-99	3	1999	25	
1000	0000002	BTF-0052	0120007	0600000	19	2	1000	Allen	Wheeler	Hazard Environmental	CWA00000	0802000	08/00000	Jul-99	3	1999	2	
1004	0020002	BTF-0052	0120022	0600000	19	2	1000	Allen	Pryor	Hark Singh	E17620322	03/11002	1M/27000	Oct-99	3	1999	26	
1442	0010001	BTF-0052	0130016	0600000	19	2	1000	Allen	Pryor	C-355 Transp	BNPFD00001ME077	12/20001	0001000	Dec-01	4	2001		
1701	0400002	BTF-0052	0120022	0600000	19	2	1000	Allen	Pryor		E1762033							
1000	0000002	BTF-0052	0120000	0600000	19	2	1000	Allen	Pryor	Pryor	E1762034	01/20002	06/24000	Aug-99	3	1999	30	
1000	0000002	BTF-0052	0120000	0600000	19	2	1000	Allen	Pryor	Reed Express	VIN 0220000	07/01001	06/26000	Aug-99	3	1999	24	
1000	0000002	BTF-0052	0120000	0600000	19	2	1000	Allen	Pryor	Reed's Truck Sales	CWA00000	10/01001	07/23000	Jul-99	3	1999	27	
1401	0000002	BTF-0052	0120008	0600000	19	2	1000	Allen	Wheeler		0010000	12/10001	06/01000	Aug-99	3	1999	26	
1252	0110002	BTF-0052	0130006	0600000	19	2	1000	Allen	Pryor	Redi Contractor	F1001003311	10/02001	02/21001	Feb-01	1	2001	8	
1070	0020002	BTF-0052	0322002	0600000	19	2	1000	Allen	Pryor	Pryor								
1000	0000001	BTF-0052	0130018	0600000	19	2	1000	Allen	Wheeler	Wheeler	Uni 91263	08/10001	06/01000	Aug-99	3	1999	25	
1000	0000001	BTF-0052	0130000	0600000	19	2	1000	Allen	Wheeler	Wheeler	Uni 91367	07/17001	06/01000	Aug-99	3	1999	24	

1725	0408002	BTF-0052	010803	05/17/99	27	2	1999	Alien	Ryder	355212	02/05/02	05/25/99	Jan-99	2	1999	32	
1817	11/24/01	BTF-0052	0110008	05/18/99	21	2	1999	Alien	Wabtec	WABT01402	05/19/00						
1303	08/27/01	BTF-0052	0110017	05/19/99	21	2	1999	Alien	Radiant	Unit 547	11/01/99	11/01/99	Nov-99			0	
1958	02/28/01	BTF-0052	0110026	05/19/99	21	2	1999	Alien	Moto	004621-01	11/04/00	07/01/99	Jul-99			17	
1126	10/20/00	BTF-0052	0110031	05/20/99	21	2	1999	Alien	Nestor	Cargos Express	0059844A	05/26/99	10/26/99	Oct-99	4	1999	9
1402	05/26/02	BTF-0052	0110037	05/21/99	21	2	1999	Alien	Prins	E1700037	01/10/02	08/13/99	Aug-99	3	1999	28	
1110	08/08/00	BTF-0052	0110041	05/22/99	21	3	1999	Alien	Nestor	All Star Internation	0026268A	01/05/00	12/21/99	Dec-99	4	1999	1
1371	07/31/01	BTF-0052	0110042	05/23/99	21	2	1999	Alien	Nestor	Towline Transp.	0103570A	08/23/01	12/20/99	Dec-99	4	1999	17
1537	05/08/02	BTF-0052	0110042	05/23/99	21	2	1999	Alien	Fries	E1700042	05/19/02	05/17/99	Aug-99	3	1999	31	
1514	11/23/01	BTF-0052	0110043	05/23/99	24	2	1999	Alien	Prins	E1700034	10/22/01	01/04/99	Sep-99	3	1999	28	
1685	06/20/00	BTF-0052	0110071	05/27/99	24	2	1999	Alien	Nestor	Capital Atlantic Transit	0031077A	03/06/00	10/22/99	Oct-99	4	1999	5
1476	11/28/01	BTF-0052	0110077	05/28/99	24	2	1999	Alien	Fries	E160021102	05/28/01	05/28/99	Aug-99	3	1999	24	
1533	11/25/02	BTF-0052	0110082	05/29/99	24	2	1999	Alien	Prins	E1720014	07/08/01	09/27/99	Sep-99	3	1999	22	
1467	6/11/00/2	BTF-0052	0110089	05/29/99	24	2	1999	Alien	Kenworth	BLW Flat Sys	CWA00312	01/06/02	02/01/00	Feb-00	1	2000	24
1501	11/27/01	BTF-0052	0110084	05/10/99	24	2	1999	Alien	Fries	Interstate	DMFD01143B	04/08/01	05/01/99	Sep-99			18
1217	06/17/01	BTF-0052	0110082	05/14/99	25	2	1999	Alien	Fries	Ryder	Unit 35300						6
1757	04/09/03	BTF-0052	0110137	05/17/99	25	2	1999	Alien	Prins	Great Coastal	E1700051	09/21/01	08/18/99	Aug-99	3	1999	23
1282	08/21/01	BTF-0052	0110182	05/18/99	25	2	1999	Alien	Knight Transportation	Jack Vestell	05/26/01						
1551	11/26/01	BTF-0052	0110183	05/18/99	25	3	1999	Alien	Fries	E1600248	10/01/01	07/30/99	Jul-99	3	1999	26	
1310	11/28/01	BTF-0052	0110205	05/20/99	25	2	1999	Alien	Nestor	8220193D	08/07/01	11/08/99	Nov-99	4	1999	21	
1102	08/04/00	BTF-0052	0110242	05/21/99	25	2	1999	Alien	Mark	H94006101271	01/01/00	11/06/99	Nov-99	4	1999	3	
1091	08/08/00	BTF-0052	0110246	05/22/99	25	2	1999	Alien	Nestor	Reynolds Oil	0210748	01/22/00	08/30/99	Sep-99	3	1999	4
1105	01/25/01	BTF-0052	0110253	05/23/99	25	2	1999	Alien	Nestor	Amoco/Mobil Eagle Coupler	016117/A	10/04/00	05/17/99	May-99	2	1999	17
1707	08/22/02	BTF-0052	0110204	05/23/99	25	2	1999	Alien	Fries	R. A. G.	E1700039	08/12/01	08/29/99	Sep-99	3	1999	24
1513	08/10/01	BTF-0052	0110273	05/24/99	25	2	1999	Alien	Fries	New P-Max	BKPD0001P1027		10/03/99	Oct-99	4	1999	
1080	11/26/01	BTF-0052	0110343	05/24/99	25	2	1999	Alien	Fries	E1600244	08/30/01						
1427	08/28/02	BTF-0052	0110348	05/25/99	25	2	1999	Alien	Fries	Wheeler Foods	E1782729	01/18/02	01/24/00	Jan-00	1	2000	24
1448	08/10/01	BTF-0052	0110354	05/26/99	27	2	1999	Alien	Fries	VHM00010GHT						0	
1082	08/26/00	BTF-0052	0110355	05/27/99	27	2	1999	Alien	Nestor	W. Central Florida Lines	0074157A	10/15/99	02/23/99	Feb-99	1	1999	9
1173	04/05/01	BTF-0052	0110350	05/27/99	27	3	1999	Alien	Nestor	Central Atlantic Transit	0024152B	01/02/01	10/22/99	Oct-99	4	1999	16
1575	10/01/01	BTF-0052	0110354	05/16/99	27	2	1999	Alien	Nestor	Wheeler	Unit 00805	07/06/01	04/01/00	Apr-00			16
1806	04/13/01	BTF-0052	0110408	05/21/99	28	3	1999	Alien	Nestor	Wheeler	Unit 31659	08/31/01	12/01/99	Dec-99			21
1151	08/05/00	BTF-0052	0110507	05/23/99	28	3	1999	Alien	Nestor	Superior Carriers	0062688A	05/18/00	12/27/99	Dec-99	4	1999	5
1374	08/03/01	BTF-0052	0110716	05/25/99	31	3	1999	Alien	Fries	SHF0001A8307	06/21/01	04/06/00	Apr-00	2	2000	15	
1324	07/23/02	BTF-0052	0110847	05/26/99	31	3	1999	Alien	Nestor	Combined Transp.	123159A	03/23/01	05/10/99	May-99	2	2000	11
1540	03/08/02	BTF-0052	100715	07/26/99	31	3	1999	Alien	Prins	E1700040	09/27/99	09/27/99	Sep-99	3	1999	25	
1702	03/28/02	BTF-0052	100718	07/29/99	31	2	1999	Alien	Fries	E1700040	09/27/99	09/27/99	Sep-99	3	1999	25	
1139	12/01/00	BTF-0052	0110718	08/04/99	32	3	1999	Alien	Nestor	Carlos Estrada	0228885A	08/18/00	04/30/99	Apr-99	2	1999	37
1488	03/26/02	BTF-0052	0112702	08/13/99	33	3	1999	Alien	Fries	Rochi Transport	CW0017832	12/07/01	10/07/99	Oct-99	4	1999	39
1419	11/26/01	BTF-0052	0112812	08/17/99	34	3	1999	Alien	Nestor	J & R Tag	90186888	05/08/01					
1158	02/26/02	BTF-0052	0110703	08/01/99	35	3	1999	Alien	Fries	Lewis Trucking	E004325A	06/02/00	10/25/99	Oct-99	4	1999	7
1313	08/26/00	BTF-0052	0110813	08/07/99	37	3	1999	Alien	Nestor	Wheeler	Unit 51134	05/08/01	12/20/99	Dec-99	4	1999	18
1653	08/10/01	BTF-0052	1044594	08/08/99	37	3	1999	Alien	Nestor	Wheeler	Unit 01535	08/25/01	01/10/00	Jan-00			16
1586	08/10/01	BTF-0052	0110442	08/09/99	37	3	1999	Alien	Nestor	Wheeler	Unit 51134	08/25/01	12/01/99	Dec-99			21
1581	08/10/01	BTF-0052	0110417	08/09/99	37	3	1999	Alien	Nestor	Wheeler	Unit 51137	08/31/01	12/01/99	Dec-99			20
1360	11/29/01	BTF-0052	0120412	08/10/99	37	3	1999	Alien	Nestor	Dakota Cabbage	1004498	05/04/99					
1507	08/10/01	BTF-0052	0110450	08/10/99	37	3	1999	Alien	Nestor	Wheeler	Unit 51134	05/08/01	12/20/99	Dec-99	4	1999	18
1888	08/10/01	BTF-0052	0110459	08/10/99	37	3	1999	Alien	Nestor	Wheeler	Unit 01535	08/25/01	01/10/00	Jan-00			16
1560	08/10/01	BTF-0052	01104671	08/10/99	38	3	1999	Alien	Nestor	Wheeler	Unit 51134	08/31/01	11/23/99	Nov-99	4	1999	16
1523	12/19/01	BTF-0052	01105412	08/10/99	38	3	1999	Alien	Nestor	Delco Cabbage	RO #4940	08/27/01	10/04/99	Oct-99	4	1999	24
1259	02/26/00	BTF-0052	01105711	08/17/99	38	3	1999	Alien	Nestor	G&P Trucking	0044467A	08/23/00	10/24/99	Oct-99	4	1999	7
1362	03/26/02	BTF-0052	0110740	08/17/99	38	3	1999	Alien	Prins	E7731474	08/16/02	01/23/00	Jan-00	1	2000	24	
1280	02/25/01	BTF-0052	0110724	08/17/99	38	3	1999	Alien	Volk	E1640208	04/26/01	12/22/99	Dec-99	4	1999	16	
1651	11/29/01	BTF-0052	0110766	08/18/99	38	3	1999	Alien	Nestor	Grand Rapids Transp.	0071644A	03/27/01					0
1658	04/03/02	BTF-0052	01107347	08/18/99	38	3	1999	Alien	OM Dominion								

SKF 001959

1247	03/28/02	BTF-0052	0105490	09/25/99	39	3	1999	Allan	Friis	F.Gough Truck	E1750096	01/26/02	04/14/03	Apr-98	2	1996	46
1257	11/26/01	BTF-0052	0705604	09/23/99	39	3	1999	Allan	Friis	E1650050	08/07/01	11/26/99	Nov-98	4	1999	22	
1144	01/18/02	BTF-0052	01052051	09/24/99	40	3	1999	Allan	Hawtator	Mansfield Inc.	00636238 1/2	02/20/01	08/08/00	Sep-99	3	2000	6
1477	01/18/02	BTF-0052	01052062	09/24/99	40	3	1999	Allan	Hawtator	Mansfield Inc.	00636238 2/2	02/20/01	08/08/00	Sep-99	3	2000	6
1461	11/26/01	BTF-0052	01051943	09/24/99	40	3	1999	Allan	Friis	E1681943 2/2	07/12/01	11/26/99	Nov-98	4	1999	20	
1464	11/26/01	BTF-0052	01052228	09/24/99	42	3	1999	Allan	Friis	E1681943 1/2	07/12/01	11/26/99	Nov-98	4	1999	20	
1444	11/26/01	BTF-0052	01052063	09/24/99	40	3	1999	Allan	Hawtator	Dion International	CNA0404341 1/2	07/25/01	01/01/00	Jan-00			18
1462	11/26/01	BTF-0052	01051153	09/24/99	40	3	1999	Allan	Hawtator	Dion International	CNA0404341 2/2	07/25/01	01/01/00	Jan-00			14
1710	03/28/02	BTF-0052	1802238	09/24/99	48	3	1999	Allan	Friis		E1752385	01/22/02	09/14/03	Sep-99	3	2000	17
1772	04/08/02	BTF-0052	1803352	10/08/99	41	4	1999	Allan	Friis		E1679900	07/03/01	12/13/99	Dec-99	4	1999	19
1258	01/18/02	BTF-0052	01050432	10/20/99	43	4	1999	Allan	Friis	CWA05341	08/25/01	10/04/00	Oct-99	4	2000	12	
1384	08/10/01	BTF-0052	02005952	10/24/99	43	4	1999	Allan	Friis	KLLAI	SPPD0001A2897						
1260	08/10/01	BTF-0052	02030993	10/27/99	44	4	1999	Allan	Hawtator	Glenda Foods	0620047A	02/19/01	01/31/00	Jan-00	1	2000	13
1691	09/16/01	BTF-0052	0205007	10/31/99	45	4	1999	Allan	Friis	Waco Trig	FTTFD01B 7A						0
1182	11/26/01	BTF-0052	01050471	11/07/99	48	4	1999	Allan	Friis		E1680940	04/03/01	01/05/99	Jan-99	1	1999	32
1287	08/01/01	BTF-0052	02005952	11/08/99	48	4	1999	Allan	Hawtator	Cocoa River Express	0219831A222	02/22/01	01/12/00	Jan-00	1	2000	14
1338	07/31/01	BTF-0052	02005883	11/08/99	46	4	1999	Allan	Friis	JTFD0001T1D08T 2/2						0	
1486	11/26/01	BTF-0052	0208074	11/10/99	48	4	1999	Allan	Friis		E1705189	12/01/01	02/05/00	Feb-00	1	2000	20
1208	08/01/01	BTF-0052	02005707	11/11/99	48	4	1999	Allan	Hawtator	Cocoa River Express	0219831A1/2	01/22/01	01/12/00	Jan-00	1	2000	13
1499	08/10/01	BTF-0052	02005829	11/11/99	48	4	1999	Allan	Friis		HBF00001C121T						0
1188	11/26/01	BTF-0052	02050059	11/15/99	47	4	1999	Allan	Hawtator		0230083A	07/20/01	02/21/00	Feb-00	1	2000	17
1488	08/28/02	BTF-0052	02111136	11/15/99	47	4	1999	Allan	Friis		E1748218	01/07/02	12/28/00	Dec-00	4	2000	13
1478	11/26/01	BTF-0052	0213262	11/15/99	47	4	1999	Allan	Friis	Max Prime	E1684903	07/20/01	01/22/00	Jan-00	1	2000	18
1587	08/28/02	BTF-0052	1800776	11/15/99	47	4	1999	Allan	Friis	Pebble Camsite	E1752726	01/28/01	10/27/00	Oct-00	4	2000	3
1512	11/26/01	BTF-0052	0216046	11/16/99	47	4	1999	Allan	Friis		E1680919	08/20/01	07/29/99	Jul-99	3	1999	23
1284	03/28/02	BTF-0052	01050952	11/20/99	47	4	1999	Allan	Friis	Ryder Supercenter, N.C.	PSLJ 323						
1685	03/28/02	BTF-0052	214528	11/23/99	46	4	1999	Allan	Friis	Bermuda Express	E1762460	01/20/02	01/20/00	Jan-00	1	2000	24
1682	03/28/02	BTF-0052	214459	11/23/99	46	4	1999	Allan	Friis	Prime	E1750068	01/22/02	04/10/00	Apr-00	2	2000	21
1262	07/18/02	BTF-0052	0214312	11/23/99	48	4	1999	Allan	Hawtator	Holt Walker	0050205A	10/24/01	04/29/00	Apr-00	2	2000	18
1138	01/18/02	BTF-0052	3225846	11/23/99	48	4	1999	Allan	Friis	BLM Diesel Sys	CNA07074	11/28/01	06/23/00	Jun-00	2	2000	17
1764	04/08/02	BTF-0052	13407	11/24/99	48	4	1999	Allan	Friis		E1680900						
1180	03/28/02	BTF-0052	0202971	11/27/99	48	4	1999	Allan	Friis	Wenco Foods	E1752730	01/10/02	10/21/99	Oct-99	4	1999	27
1521	11/26/01	BTF-0052	0216046	12/01/99	48	4	1999	Allan	Friis		E1704803 1/2	09/24/01	03/04/00	Mar-00	1	2000	19
1621	11/26/01	BTF-0052	0216067	12/01/99	48	4	1999	Allan	Friis		E1704803 2/2	09/24/01	03/04/00	Mar-00	1	2000	19
1266	01/18/02	BTF-0052	0214788	12/01/99	49	4	1999	Allan	Hawtator	Holt Walker	0050172C 3/2	10/12/01	04/29/00	Apr-00	2	2000	18
1284	01/18/02	BTF-0052	0214784	12/01/99	48	4	1999	Allan	Hawtator	Holt Walker	0050172C 1/2	10/12/01	04/29/00	Apr-00	2	2000	18
1261	08/01/01	BTF-0052	0216077	12/14/99	50	4	1999	Allan	Friis	Merlin Transport	SMC000011601T 1/2	06/03/01	04/16/00	Apr-00	2	2000	18
1408	08/01/01	BTF-0052	0220704	12/16/99	50	4	1999	Allan	Friis	Merlin Transport	SMC000011601T 2/2	05/03/01	04/16/00	Apr-00	2	2000	13
1580	08/14/01	BTF-0052	6210867	12/12/99	51	4	1999	Allan	Friis	Boyle Sales Trig	H10218	07/12/01	04/17/00	Apr-00	2	2000	15
1553	08/14/01	BTF-0052	0220900	12/12/99	51	4	1999	Allan	Friis		SFC0001B104T	08/11/01	04/28/00	Apr-00	2	2000	14
1481	08/14/01	BTF-0052	0225436	12/27/99	52	4	1999	Allan	Friis	Brian Cox	SPPD0001A288T	08/25/01	04/05/01	Apr-01	2	2001	2

SKF 001960

Config. Cell	Level 1	Critical	Start Lbs	End Lbs	Start Date	End Date	Diags	Diag Date
NO INFO			200000	300000	IS SEAL LEAK - INGRESS	Endplay 0.000", smooth quiet rotation, CB row G, IS row debris dents, IS 8.0.R, CB rollers, necessary good, IS rollers, raceway good, seal good. N	Valid	03/29/02
NON-ROTATION			422040	420000	NO PROBLEM FOUND	EP 0.000", smooth rotation, no problem found	Invalid	04/01/02
LOOSE BEARING			156200	200000	NO PROBLEM FOUND	Endplay 0.040", noisy, CB row noisy rusty debris, IS row rusty tree well	Invalid	03/31/01
ENDPLAY/LOOSE			156200	200000	IS SEAL LEAK - INGRESS	CB separation. Visible past seal in case C/S of hub unit	Valid	03/31/00
LEAK			244971	300000	IS SEAL SEPARATION	Endplay 0.000", IS IR tree spike at rollers spacing/Troy Lab determination	Invalid	11/28/01
BINDSTICK			318277	200000	IMPACT DAMAGE	Endplay 0.030", tree spike at rollers spacing/Troy Lab determination	Valid	12/01/00
LOOSE			151162	150000	UNHARDENED RW	Endplay 0.030", tree spike at rollers spacing/Troy Lab determination	Valid	10/01/01
NON-SPECIFIC			320579	400000	NO PROBLEM FOUND	Endplay 0.000", smooth quiet rotation, IS & CB Worn VG, IS seal handle	Invalid	04/01/01
NO INFO					IS SEAL LEAK - INGRESS	Endplay 0.022", noisy, IS seal lies team out, CB separation<0.5g, IS dry, N	Valid	03/16/01
BROKEN/SEPARATED BEARING	X	X	202700	300000	UNHARDENED RW	Rough vibration, no internal components, CB row badly eroded, unhardened	Valid	03/20/01
LEAK			244971	300000	NO PROBLEM FOUND	CB & IS G, no internal distress	Invalid	04/18/01
NO INFO					IS SEAL LEAK - INGRESS	Endplay 0.020", noisy, IS cage melted, IS seal wear ~2.0 mm, corrosion	Valid	03/17/01
LEAK			240770	250000	INSIGNIFICANT LEAK	No internal distress, very little seepage/Troy Lab determination	Invalid	11/29/01
LEAK			214354	250000	INSIGNIFICANT LEAK	No internal distress, very little seepage/Troy Lab determination	Invalid	11/29/01
LEAK			342004	300000	INSIGNIFICANT LEAK	No internal distress, very little seepage/Troy Lab determination	Invalid	11/29/01
NO INFO					IMPACT DAMAGE	Endplay 0.022", noisy, CB row rusty debris caused cage starting to melt, Invalid	03/15/01	
LEAK			244172	250000	INSIGNIFICANT LEAK	CB separation<0.5g, IS mil-spike criteria oil separation	Invalid	03/14/01
LEAK			240612	300000	INSIGNIFICANT LEAK	CB separation<0.5g, IS <0.5g	Invalid	03/14/01
LEAK			240612	300000	INSIGNIFICANT LEAK	CB separation<0.5g, IS <0.5g	Invalid	03/14/01
NON-ROTATION			250614	200000	LOW CLAMP LOAD	Outer end sleeve M bolts, CB row VG, IS row flat, debris, OR row fine	Invalid	04/23/02
MISSING			250108	300000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, CB row row corrosive/Troy Lab determin	Invalid	11/28/01
MISSING/BROKEN HUBCAP			146531	150000	HUB CAP LOST	Endplay 0.000", smooth rotation, CB row row corrosive/Troy Lab determin	Invalid	11/28/01
BROKEN/SEPARATED BEARINGS			320592	350000	INSIGNIFICANT LEAK	CB row VG, IS row VG, IS seal OK, no internal distress	Invalid	04/18/02
NO INFO					NO PROBLEM FOUND	No claim, S.O.R. CB rollers, necessary good, IS rollers, raceway good, no	Invalid	04/01/02
NON-ROTATION			200	60000	LOW CLAMP LOAD	Corrosion 0.500", signs freefrom noise, severe oil stretches at side faces	Invalid	03/27/01
NON-ROTATION			150000	200000	IMPACT DAMAGE	Black paint, CB row VG, IS metal debris - no rust, fine scratches/scratches	Invalid	04/01/02
NON-SPECIFIC			387587	200000	UNKNOWN	Rusty stainless, no rust, debris, oil, damage/presure evidence, cannot	Inconclusive	03/22/00
BINDSTICK			238403	300000	UNKNOWN	Food disease, no anti-seize cages or rollers, cannot accurately detect	Inconclusive	03/18/01
LOOSE			78000	100000	NO PROBLEM FOUND	No internal distress (Troy Lab determination)	Invalid	11/28/01
SEIZED	X	X	200422	300000	UNKNOWN	Food! Ghee/milk, IS IR easily refining, some rust in hubcap hole	Inconclusive	05/01/01
LEAK			7483	300000	INSIGNIFICANT LEAK	CB Pump 0.2 g, insufficient, while acceptable limits	Invalid	04/11/00
SEIZED			12000	60000	UNHARDENED RW	IS OR separation heavily eroded - Unhardened Reservoir	Valid	02/28/00
NO INFO			165250	200000	RELIEF DAMAGE	Rusty stainless, IS IR sum intact, CB long row VG, IS OR RW VG	Invalid	03/21/01
NON-ROTATION			408761	400000	IS SEAL LEAK - INGRESS	0.045 and stay, noisy and rough rotation, CB & IS rollers freefrom any	Valid	04/01/02
NON-ROTATION			580348	400000	WATER INTRODUCION ALONG SPINDLE	CB row OR RW spots - rusty, IS small side faces rust, IS row good,	Invalid	04/23/02
LEAK			405520	400000	IS SEAL LEAK - EGRESS	IS seal L50, seal apparent fractured	Valid	04/01/02
LEAK			233185	250000	INSIGNIFICANT LEAK	Copper and valve arr. bolts, CB row C weight load, IS row VG, IS seal functioning	Invalid	04/23/02
LEAK			233195	250000	INSIGNIFICANT LEAK	Brass big rows VG, signs of low clamp load but no failure	Invalid	01/16/02
SEIZED			307620	350000	NO PROBLEM FOUND	Food! difference, IS rollers missing, clip ring houses pulled, IS BR, line spot	Invalid	04/27/01
SEIZED			184650	200000	IMPACT DAMAGE	Endplay 0.000", smooth rotation, no internal distress (Troy Lab determin)	Invalid	11/28/01
BINDSTICK			394208	400000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, Let & Read RHO <0.005", no problem for	Invalid	10/20/00
NON-ROTATION			387600	200000	NO PROBLEM FOUND	Outer ring heat deteriorated grease causing bearing seizure, break life	Valid	01/11/00
FIRE			17030	50000	UNHARDENED RW	0.01 OR single line spot, IS seal VG, grease VG w/o signs of contamination	Invalid	
NON-ROTATION			450000	350000	IMPACT DAMAGE	Endplay 0.000",	Invalid	
NO INFO			103320	150000	LOW CLAMP LOAD	Endplay 0.000", rough rotation, IS IR RW has spike at roller spacing	Invalid	12/19/01
NO INFO			320570	350000	IMPACT DAMAGE	No internal distress (Troy Lab determination)	Invalid	11/28/01
LEAK					NO PROBLEM FOUND	Endplay 0.000", hard to rotate, lots of water in bearing, seals look good, Valid	04/12/01	
LEAK			161760	200000	IS SEAL LEAK - INGRESS	CB separation, IS 0.000", armrest quiet rotation	Invalid	04/03/01
LOOSE RUB	X	X	165212	100000	NO PROBLEM FOUND	IS roller set stepped, heavily eroded RW - Unhardened Reservoir	Valid	02/29/00
FIRE			43601	50000	UNHARDENED RW	Pre-pressed with ten spikes, noisy, IS IR RW spots, endplay 0.000"	Invalid	10/01/01
NON-ROTATION			547600	450000	TAMPERING	CB separation<0.5g, IS <0.5g, Endplay 0.000", Noisy, CB E, IS OR, RW	Valid	08/03/01
LOOSE			368412	400000	IS SEAL LEAK - INGRESS	CB separation<0.5g, IS <0.5g, endplay 0.000", noisy, CB E, IS OR, RW	Valid	04/04/01
LOOSE			368412	400000	NO PROBLEM FOUND	CB separation<0.5g, IS <0.5g, endplay 0.000", smooth roller rotation	Valid	04/04/01
LOOSE HUB			301374	400000	IS SEAL LEAK - INGRESS	CB separation<0.5g, IS dry, endplay 0.000", noisy rotation, CB row G, IS	Valid	04/04/01
LOOSE HUB			361374	400000	NO PROBLEM FOUND	CB separation<0.5g, IS <0.5g, endplay 0.000", smooth quiet rotation	Valid	04/04/01
MISSING/SEPARATED BEARINGS			320592	350000	IS SEAL LEAK - INGRESS	CB row VG, IS row VG, no internal	Valid	04/03/02
BINDSTICK			207251	300000	IS SEAL LEAK - INGRESS	Noisy rotation, water, break, ingress, dirt lip born away	Valid	04/01/02
NON-SPECIFIC			440191	400000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, no internal distress (Troy Lab determin)	Invalid	11/29/01
LOOSE BEARING			260194	300000	IS SEAL LEAK - INGRESS	Noisy, CB row Black, 5 sherd, IS row cage melted, IS OR spotting - IS	Valid	04/23/02
NO INFO	X	X			LOW CLAMP LOAD	Race Diameters, no rust, debris, oil, oil marks on IR faces, on ring gro	Invalid	04/22/00
LOOSE HUB			324086	350000	IMPACT DAMAGE	Noisy, No end play, CB rollers saw slight heat, IS rollers squeaking/clicking spot	Invalid	04/01/02
NON-ROTATION			361104	400000	IS SEAL LEAK - INGRESS	CB row has contact spotting, IS row IR & OR noisy & clicking spots	Valid	04/23/02
BEARING FAILURE			281080	300000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, no internal distress (Troy Lab determin)	Invalid	11/29/01
NO INFO			400391	600000	IS SEAL LEAK - INGRESS	CB row good, CB RW contact needle, IS start lip born away 50 degrees	Valid	04/01/02
MISSING/BROKEN HUBCAP			2206124	250000	NO PROBLEM FOUND	Rusty hubcap threads, endplay 0.000", rusty wet boots, rust stains around	Invalid	10/01/01
NO INFO			422016	300000	IS SEAL LEAK - INGRESS	IS shallow spots, IS ring cage broken, IS seal worn out	Valid	04/16/02
NO INFO					NO PROBLEM FOUND	No internal distress (Troy Lab determination)	Invalid	11/29/01
NO INFO			231180	250000	IS SEAL LEAK - INGRESS	End play 0.041, very noisy, CB new metallic debris, IS row cage melted	Valid	04/01/02

NOSE VIBRATION		314708	360000 WATER INTRUSION ALONG SPINDLE	Smooth 0.000", noisy & rough, OB row slight heat oxidation, rust debris	Invalid	10/01/01
NOSE VIBRATION		405078	360000 OIL SEPARATION	OB row light heat, OB seal, oily grease	Valid	04/16/01
BROKEN/SEPARATED BEARING		205161	360000 REMOVAL DAMAGE	EP 0.0000", rotation smooth, clip ring missing, damaged during removal	Invalid	01/01/00
NOSE VIBRATION		205162	360000 OB SEAL LEAK - INGRESS	Smooth 0.0000", noisy, OB rollers centered at RWL cr, OB OR RW specks	Valid	10/01/01
ENDPLAY/LOADE		241205	360000 LOW CLAMP LOAD	Noisy noisy bones, endplay 0.0000", OB row VG, OB small side faces, etc as listed	Valid	04/16/01
HORSE VIBRATION		277006	360000 OB SEAL LEAK - INGRESS	Rust'd debris, OB row G, OB rusty, OB seal worn out	Valid	04/01/02
NOSE VIBRATION		285151	360000 OB SEAL LEAK - INGRESS	Endplay 0.0000", noisy, OB row rusty and heat indications, OB row coarse	Valid	10/00/01
LEAK		304450	360000 NO PROBLEM FOUND	Endplay 0.0000", smooth quiet rotation, OB & OB big rows VG, OB seal fine/normal	Valid	04/01/02
NOSE VIBRATION		306203	400000 IMPACT DAMAGE	Fast'd debris, OB row rusty, hubless threads rusty, OB IR line spoke dimmed	Valid	05/27/01
NO INFO			400000 OB SEAL LEAK - INGRESS	OB row corrosion, rusty, metallic debris, OB also	Valid	04/01/02
SHIM STICK		306202	500000 UNKNOWN	No Shim stick and Seal. Recorded data-a-mess. Current Actually clean. Hub-conclusive	Valid	04/01/02
NO INFO			500000 NO PROBLEM FOUND	OB bearings <0.5, OB <0.3, noisy hubless threads, endplay 0.0000", smooth/normal	Valid	04/10/01
BEARING FAILURE		140540	500000 OB SEAL LEAK - INGRESS	Noisy, plumes, no OB IR or seal, OB OR corrosion specks - SLIMMED/ED?	Valid	11/23/01
BEARING FAILURE		140544	500000 IMPACT DAMAGE	OB IR line spoke at rollers specks, clearing broken? Troy Lab determined Invalid	Valid	11/23/01
BEARING FAILURE		150304	500000 OB SEAL LEAK - INGRESS	OB OR RW corrosion specks, OB seal appears functional - SLIMMED/ED?	Valid	11/23/01
NO INFO		160144	500000 OB SEAL LEAK - INGRESS	Endplay 0.0000", smooth rotation, OB & OB IR plates denting, OB row slightly noisy	Valid	01/09/02
NOSE VIBRATION		200002	500000 WATER INTRUSION ALONG SPINDLE	Note, OB row flat. Dents - noisy, OB row G, OB seal functional, noisy otherwise	Valid	04/24/02
LIP		317158	500000 OB SEAL LEAK - INGRESS	OB row condition, noisy, metallic debris, OB also	Valid	04/01/02
NOSE VIBRATION		321164	500000 OB SEAL LEAK - INGRESS	Very noisy, G rough, OB seal worn out	Valid	04/01/02
NO INFO		326334	500000 OB SEAL LEAK - INGRESS	OB row VG, OB row single line condition & speck OB IR RW, seal OK	Valid	04/00/02
NOSE VIBRATION		326103	500000 UNKNOWN	Fast'd debris, OB row debris denting, OB IR line spoke at roller spec levels	Valid	10/01/01
BROKEN/SEPARATED BEARING			500000 UNKNOWN	Fast'd debris, body damaged, No rollers -noisy/grease or metal, cannot inconclusive	Valid	09/10/01
NO INFO		326245	500000 OB SEAL LEAK - INGRESS	Noisy, rough rotation, OB rollers extremely good, OB rollers race way specked	Valid	04/01/02
NOSE VIBRATION		326243	500000 NO PROBLEM FOUND	Smooth 0.0000", smooth rotation, no problems found	Valid	05/31/01
NOSE VIBRATION		326144	500000 OB SEAL LEAK - INGRESS	Smooth 0.0000", noisy rotation, OB seal noisy	Valid	04/01/02
HUB OFF	X	326244	500000 OB SEAL LEAK - INGRESS	Smooth 0.0000", noisy rotation, OB seal noisy	Valid	05/31/01
MURKING/BROKEN HUB/CAP		326244	500000 HUB CAP LOST	Heavy Rust in cap hole, no problem found, until replaced as previously	Valid	04/11/00
NOSE VIBRATION		342627	500000 OB SEAL LEAK - INGRESS	Endplay 0.0000", smooth rotation, rusty & wet bones, OB OR RW line speck	Valid	07/30/01
NO INFO			500000 OIL SEPARATION	OB seal functional - oil separation	Valid	04/01/02
NO INFO			500000 NO PROBLEM FOUND	Endplay 0.0000", smooth quiet rotation, OB & OB big rows VG, OB seal flat	Valid	04/01/02
BEARING FAILURE		350011	500000 OB SEAL LEAK - INGRESS	OB noisy, OB - squeaking, vibration, OB ring slight corrosion speck	Valid	04/01/02
BROKEN/SEPARATED BEARING		350151	500000 PESHTAL DAMAGE	EP 0.0007", rotation smooth, one ring broken, damaged during removal	Invalid	01/01/00
NOSE VIBRATION		342627	500000 NO PROBLEM FOUND	Endplay 0.0000", smooth rotation, internal components VG, OB seal origin	Valid	07/30/01
NO INFO		370374	400000 NO PROBLEM FOUND	OB bearings <1.0, OB <1.0, endplay 0.0000", smooth quiet rotation	Valid	04/00/01
NO INFO			500000 UNKNOWN	OB seal functional - oil separation	Valid	04/01/02
BEARING FAILURE		370307	500000 OB SEAL LEAK - INGRESS	Smooth 0.0000", smooth quiet rotation, OB row OB specks - condition, east/west of seal	Valid	04/01/02
COMBINATION/ST		370302	500000 OB SEAL LEAK - INGRESS	OB noisy, OB row flat, OB good, no grease leakage (Troy Lab determined)	Valid	04/01/02
NOSE VIBRATION		306797	500000 OB SEAL LEAK - INGRESS	OB row VG, OB OR RW line spoke, OB seal origin	Valid	11/23/01
NOSE VIBRATION		391302	400000 TAMPERING	OB row VG, OB OR RW condition, OB seal appropriate functional	Valid	04/01/02
NO INFO			500000 UNKNOWN	Noisy, filled with red grease	Valid	04/16/02
ENDPLAY/LOADE	X X	304315	500000 UNHARDENED ROLL	Fast'd disintegrated, OB IR only, cannot assess. Determine before oil	Valid	04/16/02
BROKEN/SEPARATED BEARING		340060	500000 UNKNOWN	OB OR recovery heavily corroded - Unhardened RW - 304315 MIL ED - OB seal	Valid	05/30/00
NOSE VIBRATION		360257	500000 OB SEAL LEAK - INGRESS	No breakage reported, track cutter ring severe damage, damage to race	Valid	04/01/02
NOSE VIBRATION		360247	500000 WATER INTRUSION ALONG SPINDLE	Noisy, OB row noisy, White noise denting, OB RW shadow specks, OB row VG	Valid	04/00/02
NOSE VIBRATION		360051	500000 OPEN	OB row G, OB IR RW 2. wide open speck, OB small side faces noisy	Valid	04/00/02
SHIM STICK		361161	500000 WATER INTRUSION ALONG SPINDLE	White, OB row cage broken - Not. Details - DR speck, OB rusty, Not. DR speck	Valid	04/01/02
NO INFO		361094	500000 OB SEAL DAMAGED	Not breakage reported, OB row OB RW speck & condition, noisy & noisy	Valid	04/23/02
LEAK		331758	500000 NO PROBLEM FOUND	OB seal flat, OB IR sharp, rollers not pitted, cage seats grease powd. inconclusive	Valid	01/01/02
SHIM		330503	500000 OB SEAL LEAK - INGRESS	OB bearings <1.0, OB <1.0, endplay 0.0000", smooth quiet rotation	Valid	07/31/01
BROKEN/SEPARATED BEARING		330504	500000 OB SEAL LEAK - INGRESS	Smooth 0.0000", smooth rotation, OB ring greased, (Troy Lab determined)	Valid	11/23/01
AXLE HUB		330507	500000 OB SEAL LEAK - INGRESS	Smooth 0.0000", smooth rotation, OB ring greased, OB ring broken, OB OR VG	Valid	04/23/02
NOSE VIBRATION		340151	500000 NO PROBLEM FOUND	Hub recovered was not together, OB rollers recovery good, OB rollers not valid	Valid	04/01/02
SHIM/SHIM STICK		350473	500000 UNKNOWN	Smooth 0.0000", smooth rotation, no problems found	Valid	10/23/00
WORN BEARING/OILS		360051	500000 OB SEAL LEAK - INGRESS	Fast'd debris, OB IR & IR only, rusty/pit/noise/darkness/ballot	Valid	12/16/01
SHIM STICK		250707	500000 LOW CLAMP LOAD	Smooth 0.0000", rough rotation, clip ring greased, (Troy Lab determined)	Valid	11/23/01
LEAK		110221	500000 OB SEAL LEAK - INGRESS	OB seal was damaged, Ob heat about 1 long	Valid	01/14/00
WORN BEARING/HUB		405200	500000 OB SEAL LEAK - INGRESS	Noisy, sticky, OB grease thin and short - debris denting, OB cage broken	Valid	04/16/02
BEARING FAILURE		546177	500000 WATER INTRUSION ALONG SPINDLE	OB bearings 0.55, OB <1.0, endplay 0.0000", rough noisy rot, OB row def.	Valid	08/10/01
NO INFO			500000 OB SEAL LEAK - INGRESS	Noisy, OB row VG, OB row noisy -OB speck - OB seal worn out	Valid	04/23/02
NOSE VIBRATION		326103	500000 UNKNOWN	Fast'd debris, OB G, OB IR only, rusty/noise	Valid	04/01/02
SHIM STICK		326103	500000 UNKNOWN	Fast'd debris, OB row condition, OB row coarse, OB row G	Valid	04/01/02
NOSE VIBRATION		326103	500000 UNKNOWN	Fast'd debris, OB row condition, OB row coarse	Valid	04/01/02
SHIM		420	500000 WATER INTRUSION ALONG SPINDLE	OB row debris denting, OB row not. Details, OB OR condition speck, OB not invalid	Valid	01/16/02
NO INFO			500000 OB SEAL LEAK - INGRESS	Fast'd debris, OB IR functional, clip ring broken, OB seal main lip	Valid	04/23/02
NOSE VIBRATION		326103	500000 UNKNOWN	Smooth 0.0000", rough rotation, OB IR RW line speck at roller spacing, noisy/noise	Valid	10/01/01
ENDPLAY/LOADE	X	326103	500000 OB SEAL DAMAGED	Old row G, OB seal not litp gone, OB row narrow spec Engag.	Valid	04/01/02
NOSE VIBRATION		326103	500000 UNKNOWN	Shaky rotation, OB row pitted, OB OR RW corrosion speck, OB seal worn out	Valid	04/01/02
SHIM		326103	500000 UNKNOWN	Fast'd debris denting, OB IR functional, clip ring broken, OB seal main lip	Valid	04/23/02
WORN BEARING/HUB		326103	500000 UNKNOWN	Smooth 0.0000", rough rotation, OB IR RW line speck at roller spacing, noisy/noise	Valid	04/16/01
BEARING FAILURE		326103	500000 UNKNOWN	Very wet noisy bones, endplay 0.0000", noisy, OB row debris denting, OB cr Invalid	Valid	04/01/02

NO INFO		457012	250000	IS SEAL LEAK - INGRESS	Rec'd. Disassembly, OB row - G, IS row debris cleaned & shallow spots, IS & O-Rings	Valid	04/23/02	
LEAK		165074	200000	INSIGNIFICANT LEAK	No internal distress, very little leakage/Troy Lab determination)	Invalid	11/25/01	
LEAK		250000	250000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, internal components VG	Invalid	08/27/01	
LEAK		171289	200000	NO PROBLEM FOUND	IS OR housing heavily smudged - Unlubricated housing	Invalid	08/25/01	
BEARING FAILURE		78076	100000	UNHARDENED RW	IS O-Rings, OB rollers, raceways good, IS rollers, raceways good, seal good. No	Invalid	04/01/02	
LEAK		250000	500000	NO PROBLEM FOUND	IS OR housing heavily smudged - Unlubricated housing	Valid	04/06/02	
SEIZED	X	X	60837	100000	UNHARDENED RW	Endplay 0.000", slightly noisy run, fine scratches at roller spacing toward outer ring	Invalid	08/15/01
NOSE/VERIFICATION		161706	200000	IMPACT DAMAGE	Hub oily, OB row V/G, IS row VG, IS seals OK, greases oily	Valid	04/15/02	
LEAK		254521	500000	OIL SEPARATION	Rec'd. Disassembly, bent up/Troy Lab determination)	Inconclusive	11/26/01	
BINDSTICK	X	X	366294	400000	UNKNOWN	IS endplay, smooth rotation, brg OK. Cap was loose in chrome cap	Invalid	08/30/00
WORM/GEAR/OPEN HUB/CAP		62111	100000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, no internal distress/Troy Lab determination	Invalid	11/25/01	
LEAK		515000	500000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, IS & O-Rings VG, IS seal function	Valid	04/28/02	
LEAK		311922	500000	OIL SEPARATION	IS IR & OR corrosion spelling, OB row comprises	Valid	01/16/02	
NOSE/VERIFICATION		584514	400000	IS SEAL LEAK - INGRESS	Rec'd. Disassembly, IS OR RW heavily distorted, metallography confirms case N inconclusive	Invalid	08/26/01	
BROKEN HUB	X	X	220408	250000	UNKNOWN	Endplay 0.000", noisy, IS split 120 degrees	Valid	08/17/01
NO INFO				INNER RING SPALL	Heavily noisy, OB row G, IS row OR RW spalls - Med. Debris - IS RW greasy	Invalid	04/23/02	
BEARING FAILURE		330000	350000	WATER INTRUSION ALONG SPINDLE	Cap ring unseated from IS RW, seals very clean, endplay 0.000", noisy. No	Valid	08/27/01	
NO INFO		250000	250000	INNER RING SPALL	Endplay 0.000", smooth rotation, no internal distress/Troy Lab determination	Invalid	11/25/01	
BROKEN		250000	250000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, no internal distress/Troy Lab determination	Valid	11/25/01	
NOSE/VERIFICATION		241750	250000	IS SEAL LEAK - INGRESS	Endplay 0.000", smooth rotation, IS brg may corrosion, OB row G/noisy	Valid	11/26/01	
LEAK		16	50000	OB SEAL LEAK - EGRESS	Endplay 0.000", smooth rotation, OB seal leak >1.0g	Valid	08/04/00	
SMOOTH/PLAY LOOSE		594408	100000	IS SEAL LEAK - EGRESS	IS seal <1.0g, O-ring endplay, smooth rotation	Valid	08/03/00	
NOSE/VERIFICATION		263300	500000	NO PROBLEM FOUND	EP 0.001", smooth rotation, no problem found	Invalid	01/01/02	
BINDSTICK		620471	700000	IS SEAL LEAK - INGRESS	Noisy & chimes, OB row noisy. Seal Debris - grease - hard, IS cage bad	Valid	04/15/02	
BROKEN/SEPARATED BEARING		224108	250000	IMPACT DAMAGE	OB endplay <0.5g, IS no, endplay 0.000", rough noisy rd, clip ring stuck	Invalid	08/10/01	
BINDSTICK		675671	700000	IS SEAL LEAK - INGRESS	Corrosion throughout bearing (Troy Lab determination)	Valid	11/26/01	
NOSE/VERIFICATION		586087	400000	IS SEAL LEAK - INGRESS	Noisy, OB noisy, IS the seals IS roller spacing	Valid	04/01/02	
NO INFO				WATER INTRUSION ALONG SPINDLE	OB endplay <1.0g, IS dry, rusty wet brws, IS & OB rows VG, pristine rd	Invalid	08/10/01	
NOSE/VERIFICATION		250000	100000	NO PROBLEM FOUND	Smooth, smooth rotation, 0.002" lateral and radial runout - RECALL P	Invalid	08/30/00	
SMOOTH/HOT BEARING/HUB	X		250000	LOW CLAMP LOAD	Endplay 0.000", smooth rotation, circular scratches on IR and faces and I	Invalid	04/12/01	
NOSE/VERIFICATION		158220	200000	NO PROBLEM FOUND	Endplay 0.000", smooth quiet rotation, IS & OB Rows VG, IS seal function	Invalid	10/01/01	
BEARING FAILURE		241200	250000	IMPACT DAMAGE	Med noisy brws, endplay 0.000", noisy, OB row VG, IS debris cleaned, IS	Invalid	08/15/01	
SMOOTH/HOT BEARING/HUB	X	X	213000	000000	IS SEAL LEAK - INGRESS	Internal seal contamination/ingress	Valid	08/03/00
WORN BEARING/HUB		714408	100000	NO PROBLEM FOUND	OB endplay rd, IS noisy dry, endplay 0.000", smooth quiet rotation, IS	Invalid	08/03/01	
LEAK		111180	100000	INSIGNIFICANT LEAK	OB endplay <0.5g, IS rd	Invalid	07/21/01	
BROKEN/SEPARATED BEARINGS		438500	400000	IS SEAL LEAK - INGRESS	OB row VG, IS debris cleaning - no spelling, IS seal worn.	Valid	04/16/02	
BROKEN/SEPARATED BEARINGS		438500	450000	INSIGNIFICANT LEAK	OB row VG, IS row VG, IS seal function, no internal distress	Invalid	04/16/02	
LEAK		267112	200000	OB SEAL LEAK - EGRESS	OB seal leak >2.0 g	Valid	12/01/00	
NOSE/VERIFICATION		577008	400000	IS SEAL LEAK - INGRESS	Slight vibration, IS seal worn rd	Valid	04/01/02	
LEAK		135274	150000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, no internal distress/Troy Lab determination	Invalid	11/25/01	
NO INFO				NO PROBLEM FOUND	BO/R, No end play, no internal distress	Invalid	04/01/02	
LEAK		126428	100000	INSIGNIFICANT LEAK	SMOOTH 0.000", SMOOTH ROTATION, LEAK <0.00g	Valid	09/05/00	
NOSE/VERIFICATION		220303	250000	IS SEAL LEAK - INGRESS	Rusty brws, OB endplay <0.5g, IS dry, endplay 0.025" noisy, IS seal rd	Valid	09/16/01	
NOSE/VERIFICATION		297140	300000	IS SEAL LEAK - INGRESS	Endplay 0.000", noisy, IS OR RW corrosion spelling, IS gear dust lip w/o	Valid	09/16/01	
NOSE/VERIFICATION		220304	250000	NO PROBLEM FOUND	OB endplay rd, IS <0.5g, endplay 0.000", smooth quiet rotation, IS & O-Rings	Invalid	09/16/01	
BROKEN/SEPARATED BEARING	X	X	250000	LOW CLAMP LOAD	Hub bore sent burnt up (Troy Lab determination)	Invalid	11/26/01	
SEIZED	X		158632	200000	UNKNOWN	Rec'd. Disassembly, P's body fractured and spun, sol conclusive due to debris	Inconclusive	09/16/01
NOSE/VERIFICATION		158422	200000	IS SEAL LEAK - INGRESS	Well rusty brws, OB endplay increased, IS scattered rd, endplay 0.018"	Valid	09/16/01	
WORN BEARING/HUB		163760	200000	UNKNOWN	Rec'd. Disassembly, O-Ring only cleaned of grease, FB & OB rows debris cleared, inconclusive	Inconclusive	09/16/01	
WHEEL OFF	X		250000	UNKNOWN	Felt started in IS row, FB's cracked spun & forced off, popped rollers, oil	Inconclusive	12/19/01	
BURNT BEARING	X		48612	100000	UNHARDENED RW	IS OR housing heavily smudged - Unlubricated housing	Valid	10/20/00
BEARING FAILURE		368217	200000	UNKNOWN	Correct assembly determines failure origin	Valid	04/01/02	
NOSE/VERIFICATION		103108	200000	IS SEAL LEAK - INGRESS	Endplay 0.000", rough rotation, IS steel wear >5.0 mm, IS grease dent rd	Valid	09/31/01	
NO INFO		200000	200000	NO PROBLEM FOUND	Endplay 0.000", smooth rotation, no internal distress/Troy Lab determination	Invalid	11/26/01	
NO INFO				REMOVAL DAMAGE	Disassembled, snap ring noses pulled, surface removal damage, no info	Invalid	04/14/00	

LEAK		584213	60000 NO PROBLEM FOUND	Hub received was not together, OB, IB rollers, raceways, seal good. No	invalid	04/01/02	
NOISE/VIBRATION		240050	25000 IMPACT DAMAGE	OB big row fine spalls, OB row VG (Troy Lab determination)	invalid	11/28/01	
LOOSE		200444	50000 NO PROBLEM FOUND	Endplay 0.000°, smooth quiet rotation, both big rows VG	invalid	01/15/02	
LOOSE		200445	50000 NO PROBLEM FOUND	Endplay 0.000°, smooth quiet rotation, both big rows VB	invalid	01/15/02	
BANDSTICK		220454	25000 NO PROBLEM FOUND	Endplay 0.000°, smooth rotation, no internal distress (Troy Lab determination)	invalid	11/28/01	
BANDSTICK		220454	250000 NO PROBLEM FOUND	Endplay 0.000°, smooth rotation, no internal distress (Troy Lab determination)	invalid	11/28/01	
NO MPD		340226	350000 HUB CAP LOST	Endplay 0.000°, smooth rotation, OB big row VG, OB row corrosion, hubc	invalid	11/28/01	
NO INFO		340223	350000 HUB CAP LOST	Endplay 0.000°, smooth rotation, OB big row VG, OB row corrosion, hubc	invalid	11/28/01	
NOISE/VIBRATION		273721	350000 IS SEAL LEAK - INGRESS	Noise, OB row VG, OB row debris denting, grease cracked at large end.	Valid	04/16/02	
LOOSE BEARING/HUB		122401	180000 COCKED SEAL	OB row VG, OB row debris denting - OB seal dust lip visible due to oil	Valid	04/23/02	
NOISE/VIBRATION		200601	250000 IMPACT DAMAGE	OB row debris denting, OB IR, fine spalls @ roller spacing	invalid	01/16/02	
NO INFO			UNKNOWN	Plated clearance, no internal components, OB row appears to be failure origin	inconclusive	04/10/01	
LOOSE		120002	150000 IS SEAL LEAK - INGRESS	OB envelope <0.5g, IS >3.0g, endplay 0.000°, smooth quiet rotation, OB	Valid	04/05/01	
BEARING FAILURE		184802	250000 IMPACT DAMAGE	ESP 0.000°, noisy rotation, OB row fine spalls @ roller spacing	invalid	06/14/01	
NO INFO			UNKNOWN	No oil clearance, no rollers - grease Cooper seal, OB IR GF no cycloids, sign	inconclusive	08/16/01	
BANDSTICK	X	X	400452	IS SEAL LEAK - INGRESS	Plastic sleeve, corrosion throughout housing, worse at OB row/Troy Lab	Valid	11/28/01
NOISE/VIBRATION		100005	150000 NO PROBLEM FOUND	ESP 0.000°, smooth rotation, no internal distress	invalid	05/14/01	
LEAK		180001	200000 INSIGNIFICANT LEAK	OB IR, OB <0.5g	invalid	07/31/01	
BANDSTICK	X	X	350002	350000 UNKNOWN	No oil OR poly, no internal components, cannot determine origin of failure	inconclusive	11/28/01
NOISE/VIBRATION		100006	150000 NO PROBLEM FOUND	OB <0.000°, smooth rotation, no internal distress	invalid	05/01/01	
NO INFO			UNKNOWN	OB envelope <1.0g, IS ~1.0g, endplay 0.000°, possible noise, fine spalls	invalid	08/10/01	
BEARING FAILURE		157728	200000 IMPACT DAMAGE	IS big row tilted, seal broke good, no grease leakage (Troy Lab determination)	invalid	11/28/01	
LEAK		201138	300000 NO PROBLEM FOUND	S.D.R. OB rollers, raceways good, OB rollers, raceways good, seal good. M	invalid	04/01/02	
BEARING FAILURE		200005	400000 LOW CLAMP LOAD	Plastic sleeve, plastic worn, clip has removed, (Troy Lab determination)	invalid	11/28/01	
LEAK		207432	300000 OIL SEPARATION	OB seal very clean, OB pump <-2.0g, OB row VG, OB seal dust lip good	Valid	04/16/02	
NOISE/VIBRATION		220001	250000 LOW CLAMP LOAD	Endplay 0.000°, rough rotation, circ scratches on IR small side faces/Tinned	invalid	11/28/01	
LEAK		276325	500000 OIL SEPARATION	Noise, OB row circular scratches both ends faces, OB row circular scratches	invalid	04/01/02	
NOISE/VIBRATION		207433	300000 IS SEAL LEAK - INGRESS	OB row VG, worse at OB seal, OB row VG, OB seal functional, hub of	Valid	04/16/02	
LEAK		200077	200000 INSIGNIFICANT LEAK	Very noisy, OB pump > , OB row VG, OB row G, OB seal worn out	Valid	04/16/02	
NOISE/VIBRATION		202457	250000 IS SEAL DAMAGED	OB row separator, OB seal dent lip low away, OB big row good condition	OTHER	01/16/02	
NO INFO			NO PROBLEM FOUND	OB row G, OB row G, OB seal G, no internal distress	invalid	04/23/02	
NOISE/VIBRATION		320017	400000 OIL SEPARATION	SCR, oil appearance	Valid	04/01/02	
LEAK		271904	300000 NO PROBLEM FOUND	Endplay 0.000°, antifriction, no internal distress (Troy Lab determination)	invalid	11/28/01	
LEAK		271904	300000 NO PROBLEM FOUND	Endplay 0.000°, smooth rotation, no internal distress (Troy Lab determination)	invalid	11/28/01	
LEAK		272567	300000 INSIGNIFICANT LEAK	Both big rows VG, OB seal longitudinal, OB seal depth <2.0g	invalid	01/16/02	
EAR		272567	300000 OB SEAL LEAK - INGRESS	Both big rows VG, OB seal longitudinal, OB seal depth >2.0g	Valid	01/16/02	
WORN BEARING/HUB		110458	150000 NO PROBLEM FOUND	OB envelope mid, OB dry, endplay 0.000°, smooth quiet rotation	invalid	08/03/01	
WORN BEARING/HUB		110458	150000 NO PROBLEM FOUND	OB envelope >1.5g, OB dry, endplay 0.000°, smooth quiet rotation	invalid	08/03/01	
ENDDISPLAY/LOOSE		113337	150000 UNKNOWN	Used study bore, endplay 0.000°, smooth quiet rotation, OB Seawage site	inconclusive	11/11/01	
NOISE/VIBRATION		242056	250000 NO PROBLEM FOUND	OB envelope <0.5g, IS <0.5g, endplay 0.000°, smooth quiet rotation	invalid	08/14/01	
RED LIGHT		17319	60000 UNHARDENED RW	OB envelope mid, OB slight, endplay 0.000°, noisy, OB OR RW worn hubvar	Valid	08/21/01	

Response
to Main Document

Richard W Frett/ELG/SKF
05/29 01:28 PM

Subject: ARM Data for P and C Charts of Claims Per production Quantity or "In Service" Qty

Response to: Statistical Evaluations

Category: Statistics




P and C Charts from ARM Claims Against Production & Ser

SKF 001965


P & C Charts
Using Number of Claims Compared
To Product Quantity and Quantity to
Be Placed In Service (Calculated
from ARM Formula) By Month


Source is ARM Database Used to
Add to Duane Gipe's Proportion
Analysis

C Chart of Claims by Month Limits Based on Dates Up To 199910




Claims Vs Qty in Service by month
Limits Based On Dates Up To 199910





Claims by Month Limits Based on Dates Up To 199910



Response
to Main Document

Rick P Morrow/AMER/SKF
06/29 05:12 PM


Subject: THU Stud hardness by Stu and IR
Response to: Statistical Evaluations
Category: Statistics




THU Stud Hardness.ppt

SKF 001971


Process Capability Analysis for IR



Process Capability Analysis for Stu



Process Capability Sixpack for Stu



Response

to Main Document

Robert J Bendy/DET/SKF
05/30 08:42 AM

Subject: breakdown of Databases by model number Freightliner and International

Response to: Statistical Evaluations

Category: Statistics



MeritorClaimsByOEMYrModelProblemPT SKFClaimsByOEMYrModelProblemPT

SKF 001975

ArvinMeritor Claims Database
Number of Claims by Yr, Model, Problem

OEM	Model	ProblemDescr	YrsOnSale						Grand Total
			1997	1998	1999	2000	2001	2002	
		BEARING FAILURE	6	23	48	15	4		96
		BROKEN/CHIP/CRACKED/WRUPTD		1	4		1	1	7
		CHATTER/NOISE/VIBRATION		1		1			2
		EXCESSIVE ENDPLAY	4	10	4	2			20
		HUB SEIZED TO SPINDLE	2	6		1			9
		IMPROPER FIT/ALIGNMENT				1			1
		INEFFECT/INOPER/WORN OUT	1	4	10	5	1		21
		LEAKING				1			1
		LOOSE			2				2
		OTHER		3	4	1			8
		SEIZED/LOCKED UP	1	2	6	1	1		11
		STUD FRACTURED			1				1
	Total		16	50	79	28	7	1	181
	Total		16	60	79	28	7	1	181
FreightLiner	C112	BEARING FAILURE				1			1
		BROKEN/CHIP/CRACKED/WRUPTD				1			1
		LEAKING				1			1
	C112 Total					2			2
	C120	BEARING FAILURE				7	1		8
		BROKEN/CHIP/CRACKED/WRUPTD				1			1
Century class		CHATTER/NOISE/VIBRATION				3			3
		CORRODED/DIRUSTY				3			3
		IMPROPER FIT/ALIGNMENT				2			2
		INEFFECT/INOPER/WORN OUT				1			1
		LEAKING				3			3
		SEIZED/LOCKED UP				4	1		5
	C120 Total					21	2		23
	112 Conventional	BEARING FAILURE		5		1			6
		BROKEN/CHIP/CRACKED/WRUPTD		10	10				20
		CHATTER/NOISE/VIBRATION		3					3
Century class		CORRODED/DIRUSTY		1					1
		IMPROPER FIT/ALIGNMENT		4	4				8
		INEFFECT/INOPER/WORN OUT	4	9	4				17
		LEAKING	2	1	1				4
		OTHER	1						1
		SEIZED/LOCKED UP		8	6				12
	112 Conventional Total		7	29	25	1			72
	120 Conventional	BEARING FAILURE	11	67	44	2			124
		BENT/TWISTED				1			1
		BROKEN/CHIP/CRACKED/WRUPTD	26	76	105	12			219
Kenworth		BROKEN		1					1
		BURNED/OVERHEATED			1				1
		CHATTER/NOISE/VIBRATION	2	11	29	4			46
	Kenworth Total		29	100	144	18			361

ArvinMeritor Claims Database
Number of Claims by Yr, Model, Problem

Number of Claims		ProblemDescr	Yrs Of Sale						
Model	Yr		1997	1998	1999	2000	2001	2002	Grand Total
		CORRODED/RUSTY		6	6	1			15
		EXCESSIVE ENDPLAY	1	2					3
		HUB SEIZED TO SPINDLE	6	12	3				21
		IMPROPER FIT/ALIGNMENT	7	31	31	6			75
		INEFFECT/INOPER/WORN OUT	12	42	39	9			102
		LEAKING	19	61	58	9			138
		OTHER	3	18	8				30
		OUT OF POSITION			1				1
		SEIZED/LOCKED UP	11	57	90	8			166
			1						1
<u>Century class 120 Conventional Total</u>			63	387	414	51			845
Columbia 120		BRKN/CHIP/CRACKED/RIPTD				2	3		5
		CHATTER/NOISY/VIBRATION				1	2		3
		CORRODED/RUSTY					1		1
		LEAKING				1	2		3
<u>Columbia 120 Total</u>						4	8		12
CST 120 Conventional		IMPROPER FIT/ALIGNMENT				1			1
<u>CST 120 Conventional Total</u>						1			1
FL70		IMPROPER FIT/ALIGNMENT				1			1
<u>FL70 Total</u>						1			1
FL70 Conventional		BRKN/CHIP/CRACKED/RIPTD	1						1
<u>FL70 Conventional Total</u>			1						1
FL80 Conventional		SEIZED/LOCKED UP		1					1
<u>FL80 Conventional Total</u>			1						1
FL80 Glider	BENT/TWISTED					1			1
	IMPROPER FIT/ALIGNMENT					1			1
<u>FL80 Glider Total</u>						1	1		2
FL8 High COE		BEARING FAILURE		1					1
<u>FL8 High COE Total</u>			1						1
FLC112SD Med. Conventional		CORRODED/RUSTY				1			1
<u>FLC112SD Med. Conventional Total</u>					1				1
FLD112		IMPROPER FIT/ALIGNMENT					2		2
		LEAKING				1			1
		LOOSE					1		1
		SEIZED/LOCKED UP				2	1		3
<u>FLD112 Total</u>					3	4			7
FLD112SD Med. Conv. Aluminum		INEFFECT/INOPER/WORN OUT		1					1
<u>FLD112SD Med. Conv. Aluminum Total</u>			1						1
FLD112SD Medium Conv. Alumin		BEARING FAILURE	1	4	4	1			9
		BRKN/CHIP/CRACKED/RIPTD	1	2	2	1			6
		CHATTER/NOISY/VIBRATION		1	1				2

ArvinMeritor Claims Database
Number of Claims by Yr, Model, Problem

Number of Claims		ProblemDescr	Yr Of Sale						Grand Total
OEM	Model		1997	1998	1999	2000	2001	2002	
		EXCESSIVE ENDPLAY		2					2
		IMPROPER FIT/ALIGNMENT		4	1				5
		INEFFECT/NOPER/WORN OUT		17	2				19
		LEAKING		3	1	2			6
		SEIZED/LOCKED UP	1	4	6	1			12
	FLD11280 Medium Cowl, Aluminum Cab, Hwy Total		2	36	17	6			51
	FLD120	BEARING FAILURE			1				1
		BKRKN/CHP/CRACKED/RIPTRD					2		2
		CHATTER/NDSV/VIBRATION				1	1		2
		IMPROPER FIT/ALIGNMENT					1		1
		INEFFECT/NOPER/WORN OUT					2		2
		LEAKING				1			1
		LOOSE				3			3
		PART - EXTRAVOMITTED/WRON				1			1
		SEIZED/LOCKED UP				3			3
	FLD120 Total					10	6		16
	FLD120SD Long Conventional,	BKRKN/CHP/CRACKED/RIPTRD		1					1
		IMPROPER FIT/ALIGNMENT		2					2
		LEAKING			1				1
		OTHER		2					2
	FLD120SD Long Conventional, Construction Total		5	1					6
	FLD132 XL Classic	BEARING FAILURE			2				2
		BKRKN/CHP/CRACKED/RIPTRD				1			1
		EXCESSIVE ENDPLAY				1			1
		HUB SEIZED TO SPINDLE				1			1
		IMPROPER FIT/ALIGNMENT			1		1		2
		LEAKING				1			1
		OTHER				1			1
	FLD132 XL Classic Total				0	1			1
	FLH Argosy High COE	BKRKN/CHP/CRACKED/RIPTRD		2					2
		IMPROPER FIT/ALIGNMENT		1					1
		LEAKING		2					2
		SEIZED/LOCKED UP			1				1
	FLH Argosy High COE Total		5	1					6
	FLT-COE (1988 Model Year)	BEARING FAILURE		1					1
		BKRKN/CHP/CRACKED/RIPTRD		1					1
		IMPROPER FIT/ALIGNMENT		1					1
		INEFFECT/NOPER/WORN OUT		1					1
		SEIZED/LOCKED UP		1					1
	FLT-COE (1988 Model Year) Total		3	2					5
	L7500 series	BKRKN/CHP/CRACKED/RIPTRD		1					1

ArvinMeritor Claims Database
Number of Claims by Yr, Model, Problem

Number of Claims		Yr/Model	1997	1998	1999	2000	2001	2002	Grand Total
ITEM	Model	ProblemDescr							
	L7000 series Total				1				1
	Long Conventional USF-1E, Hw	BEARING FAILURE	2	18	38	1			55
		BIRKNACHIP/CRACKED/RIPTRD	8	12	27	2			47
		BURNED/OVERHEATED			1				1
		CHATTER/NOISY/VIBRATION	1	7	13	4			25
		EXCESSIVE ENDPLAY	2	3	6	1			12
		HUB FRACTURED	1						1
		HUB SEIZED TO SPINDLE		1	1				2
		IMPROPER FIT ALIGNMENT	4	3	19	3			29
		INEFFECT/INOPER/WORN OUT	1	7	21	3			32
		LEAKING		14	18	2			32
		LOOSE			3	2			5
		OTHER	1	7	2				10
		OUT OF POSITION		1	1				2
		SEIZED/LOCKED UP	1	18	60	7			74
		STUD FRACTURED			1				1
	Long Conventional USF-1E, Hwy Total		18	67	197	23			328
	Long Conventional XL	BEARING FAILURE	1	5	9				14
		BIRKNACHIP/CRACKED/RIPTRD		4	7	1			12
		CHATTER/NOISY/VIBRATION		1	2	1			4
		EXCESSIVE ENDPLAY			2				2
		HUB SEIZED TO SPINDLE		1					1
		IMPROPER FIT ALIGNMENT		1	2	4			7
		INEFFECT/INOPER/WORN OUT		2	5				7
		LEAKING		3	4				7
		OTHER			1				1
		SEIZED/LOCKED UP		3	11	1			15
	Long Conventional XL Total		2	21	44	3			70
	ST120	BEARING FAILURE				2			2
		BIRKNACHIP/CRACKED/RIPTRD			1	7			8
		CHATTER/NOISY/VIBRATION			1	1			2
		CORRODED/ROUSTY				1			1
		IMPROPER FIT ALIGNMENT				1			1
		INEFFECT/INOPER/WORN OUT				4			4
		LEAKING			1	2			3
		SEIZED/LOCKED UP				3			3
	ST120 Total				3	21			24
	XC Chassis	OTHER		1					1
	XC Chassis Total			1					1
		BEARING FAILURE			4	4			8
		BIRKNACHIP/CRACKED/RIPTRD			16				16

ArvinMeritor Claims Database
Number of Claims by Yr, Model, Problem

Number of Claims	Model	Problem Description	Yrs On Sale	1987	1988	1989	2000	2001	2002	Grand Total
		CHATTER/NOISE/VIBRATION			3					3
		CORRODED/RUSTY			1		1			2
		EXCESSIVE ENDPLAY					1			1
		IMPROPER FIT ALIGNMENT			8		1			9
		INEFFECT/INOPER/WORN OUT			5					5
		LEAKING			6					6
		SEIZED/LOCKED UP			7		1			8
	Total				50		8			58
Frightliner	Total			124	682	708	192	51		1855
Navistar Int'l	4700 4x2	OTHER			1					1
	4700 4x2 Total					1				1
	6100 4x2	BEARING FAILURE		1						1
	6100 4x2	OTHER			2					2
	6100 4x2 Total			1	2					3
	6100 6x4	BEARING FAILURE		1		1				2
	6100 6x4	EXCESSIVE ENDPLAY			1					1
	6100 6x4	INEFFECT/INOPER/WORN OUT			1					1
	6100 6x4 Total			1	2	1				4
	9100 1 SBA 4x2	BEARING FAILURE				1				1
	9100 1 SBA 4x2 Total					1				1
	9100 1 SBA 6x4	BEARING FAILURE				1				1
	9100 1 SBA 6x4	OTHER				1				1
	9100 1 SBA 6x4	SEIZED/LOCKED UP					1			1
	9100 1 SBA 6x4 Total					2	1			3
	9100 SBA 4x2	OTHER		1						1
	9100 SBA 4x2 Total			1						1
	9100 SBA 6x4	BEARING FAILURE		6	1					7
	9100 SBA 6x4	EXCESSIVE ENDPLAY			1					1
	9100 SBA 6x4	IMPROPER FIT ALIGNMENT			2					2
	9100 SBA 6x4	OTHER			1					1
	9100 SBA 6x4	SEIZED/LOCKED UP				1				1
	9100 SBA 6x4 Total			10	2					12
	9200 6x4 SBA	BEARING FAILURE		2	18	48				68
	9200 6x4 SBA	EXCESSIVE ENDPLAY			4	3				7
	9200 6x4 SBA	HUB SEIZED TO SPINDLE		3		3				6
	9200 6x4 SBA	INEFFECT/INOPER/WORN OUT			2	3	2			7
	9200 6x4 SBA	LEAKING				1				1
	9200 6x4 SBA	OTHER			6	1				7
	9200 6x4 SBA	SEIZED/LOCKED UP			1	1				2
	9200 6x4 SBA Total			8	28	60	2			98
	9200 1 SBA 4x2	INEFFECT/INOPER/WORN OUT					1			1

ArvinMeritor Claims Database
Number of Claims by Yr, Model, Problem

OEM	Model	ProblemDescr	YrOfSale						Grand Total
			1997	1998	1999	2000	2001	2002	
8800 15SA 4x2	Total				1				1
8200 15SA 6x4	BEARING FAILURE			16	7	1			24
	EXCESSIVE ENDPLAY			2	1				3
	HUB SEIZED TO SPINDLE				5				5
	INEFFECT/NOPER/WORN OUT			3	1				4
	OTHER			1	1				2
8200 15SA 6x4	Total			22	16	1			39
8300 6x4	BEARING FAILURE		1	12	2				15
	BRK/NCHP/CRACKED/ruptrd			2					2
	EXCESSIVE ENDPLAY			2	1				3
	OTHER				1				1
	SEIZED/LOCKED UP			1					1
8300 6x4	Total		1	17	4				22
9400 4x2	BEARING FAILURE				1				1
	EXCESSIVE ENDPLAY				1				1
9400 4x2	Total				2				2
9400 6x4	BEARING FAILURE		5	22	16				43
	BRK/NCHP/CRACKED/ruptrd			3	1				4
	EXCESSIVE ENDPLAY			1	1				2
	HUB SEIZED TO SPINDLE			2					2
	INEFFECT/NOPER/WORN OUT				1				1
	OTHER				3				3
	SEIZED/LOCKED UP			2	2				4
9400 6x4	Total		5	30	23				58
9400 15SA 6x4	BEARING FAILURE				6	4			10
	EXCESSIVE ENDPLAY				1				1
	INEFFECT/NOPER/WORN OUT				1	3			4
	OTHER				1				1
	SEIZED/LOCKED UP				1				1
9400 15SA 6x4	Total				10	7			17
9800 SFA 6x4	BEARING FAILURE			3					3
9800 SFA 6x4	Total			3					3
9800 15FA 6x4	ABNORMAL/EXCESSIVE WEAR					2			2
	BEARING FAILURE				8	8			16
	CHATTER/NOISY/VIBRATION				1				1
	EXCESSIVE ENDPLAY				3				3
	HUB SEIZED TO SPINDLE				1				1
	INEFFECT/NOPER/WORN OUT					3			3
	LOOSE					1			1
	OTHER				2				2
	SEIZED/LOCKED UP					1	1		2

ArvinMeritor Claims Database
Number of Claims by Yr, Model, Problem

Number of Claims		Problem/Descriptor	Yrs Of Sales						
Model	Model		1987	1988	1989	2000	2001	2002	Grand Total
9900 SFA 6X4 Total					13	13	3		29
9900 D1 SFA 6X4		BEARING FAILURE				1			1
		INEFFECT/INOPER/WORN OUT			1				1
		OTHER				1			1
9900 D1 SFA 6X4 Total					1	2			3
9900 SFA 6X4		BEARING FAILURE			17				17
		BRKN/CHIP/CRACKED/RUPTD			1				1
		CHATTER/NOISE/VIBRATION			1				1
		EXCESSIVE ENDPLAY			2	8			10
		INEFFECT/INOPER/WORN OUT				5			5
		LEAKING					1		1
		OTHER				2			2
		SEIZED/LOCKED UP				3			3
9900 SFA 6X4 Total			2	37	1				40
		BEARING FAILURE			1				1
Total					1				1
Navistar International Total			13	95	177	44	5		335
Grand Total			153	726	942	264	63	1	2171

SKF 001982

SKF Claims Database

Number of Claims by Yr, Model, Problem

Number of Claims		FailureMode	By Yr								
OEM	Model		1996	1997	1998	1999	2000	2001	2002	(blank)	Grand Total
		ASSEMBLY DAMAGE				1			24		25
		CORROSION						1		1	1
		DIMENSIONAL ISSUE			1						1
		ENDPLAY						1		1	1
		HUB CAP LOST					2		2		2
		IB SEAL DAMAGED					2		2		4
		IB SEAL LEAK - EGRESS				12	13		18		43
		IB SEAL LEAK - INGRESS						1		1	1
		IB SEAL LEAK INGRESS							1		1
		IB SEAL LEAK-EGRESS				1					1
		IMPACT DAMAGE			1	7			10		18
		INNER RING SPALL				2		1	4		7
		INSIGNIFICANT LEAK			3	8			3		14
		LOW CLAMP LOAD	1	5	4		1		4		15
		NO INFORMATION		1					2		2
		NO PROBLEM FOUND	1	1	7	12		6	19		48
		NOT RECEIVED							3		3
		OB SEAL LEAK - EGRESS				1			3		4
		OIL SEPARATION			1	1			2		4
		OPEN							1		1
		OUTER RING SPALL			1						1
		REMOVAL DAMAGE		2	1		1		7		11
		TAMPERING			1				4		5
		UNHARDENED RW							2		2
		UNKNOWN		2	0	1			14		26
		WATER INTRUSION ALONG SPINDLE			4		1		2		7
		Total	2	2	38	85	1	10	132		249
		Total	3	2	30	85	1	10	132		246
FreightLiner	C112	NO PROBLEM FOUND				1					1
	C112 Total					1					1
	Century class 112 Conventional	HUB CAP LOST			1						1
		IB SEAL LEAK - INGRESS				1					1
		IMPACT DAMAGE		1	1						2
		NO PROBLEM FOUND			2						2
		REMOVAL DAMAGE		2	1						3
		Century class 112 Conventional Total	2	5	2						9
		Century class 120 Conventional	ASSEMBLY DAMAGE					1			1
			HUB CAP LOST			1					1
			IB SEAL LEAK - EGRESS				2				2
			IB SEAL LEAK - INGRESS		5	11					16

SKF 001963

SKF Claims Database

Number of Claims by Yr, Model, Problem

Number of Claims		FailureMode	BkdYr							(Blank)	Grand Total
OEM	Model		1996	1997	1998	1999	2000	2001	2002		
		IMPACT DAMAGE			1	1					2
		INSIGNIFICANT LEAK				2					2
		LOW CLAMP LOAD			1	2					3
		NO PROBLEM FOUND			8	15	2	1			26
		OIL SEPARATION				4					4
		OPEN			1			1			2
		REMOVAL DAMAGE			1						1
		TAMPERING				1					1
		UNHARDENED RW				3	1				4
		UNKNOWN			6	4	1				11
		WATER INTRUSION ALONG SPINDLE			1						1
	Century class 120 Conventional	Total			25	45	2	5			77
	Columbia 120	IB SEAL LEAK - INGRESS						1			1
	Columbia 120 Total							1			1
	FLB High COE	UNKNOWN			1						1
	FLB High COE Total				1						1
	FLD112	IB SEAL LEAK - INGRESS					1				1
		NO PROBLEM FOUND					1				1
		OPEN					1				1
	FLD112 Total						3				3
	FLD112SD Medium Conv. Alum	IMPACT DAMAGE			1						1
		UNKNOWN				1					1
	FLD112SD Medium Conv. Aluminum Cab, Hwy Total				1	1					2
	FLD120	LORN GREASE WEIGHT						1			1
		NO PROBLEM FOUND					2				2
	FLD120 Total						2	1			3
	Long Conventional USF-1E, HWD - GREASE EGRESS				1						1
		IB SEAL DAMAGED				1					1
		IB SEAL LEAK - INGRESS			5	14					19
		IMPACT DAMAGE			3	1					4
		INNER RING SPALL			2						2
		LOW CLAMP LOAD			1	1					2
		NO PROBLEM FOUND			1	7	1				9
		OIL SEPARATION				2					2
		OPEN			1						1
		REMOVAL DAMAGE			2						2
		TAMPERING				1					1
		UNHARDENED RW				2					2
		UNKNOWN			2	1	1				4
		WATER INTRUSION ALONG SPINDLE			3						3
	Long Conventional USF-1E, Hwy Total				21	30	2				53

SKF Claims Database

Number of Claims by Yr, Model, Problem

Number of Claims		FailureMode	BldYr	1996	1997	1998	1999	2000	2001	2002	(blank)	Grand Total
OEM	Model											
	Long Conventional XL	HUB CAP LOST			1							1
		IMPACT DAMAGE				2						2
		LOW CLAMP LOAD				1						1
		NO PROBLEM FOUND			4							4
		OIL SEPARATION				1						1
		OPEN			1							1
		UNKNOWN				1						1
		WATER INTRUSION ALONG SPINDLE			1							1
	Long Conventional XL Total			7	5							12
	ST120	OB SEAL LEAK - INGRESS						1				1
		IMPACT DAMAGE				1						1
		NO PROBLEM FOUND				1						1
	ST120 Total				2		1					3
		ASSEMBLY DAMAGE					2					2
		ENDPLAY						1				1
		HUB CAP LOST					1					1
		OB SEAL LEAK - EGRESS					10					10
		OB SEAL LEAK - INGRESS					18					18
		IMPACT DAMAGE					7					7
		INCONCLUSIVE					2					2
		INNER RING SPALL					2					2
		INSIGNIFICANT LEAK					1		11			12
		LOW CLAMP LOAD						11				11
		NO PROBLEM FOUND			1	1	4		39			45
		OB SEAL LEAK - EGRESS					1		1			1
		OIL SEPARATION				1			5			6
		REMOVAL DAMAGE							10			10
		TAMPERING						1				1
		UNHARDENED RW						2				2
		UNKNOWN						18				18
		WATER INTRUSION ALONG SPINDLE						4				4
	Total			2	1	7		143				153
	Long Conv XL 46RR (1994 M) UNHARDENED RW			1								1
	Long Conv XL 46RR (1994 Model Year) Total			1								1
	FLA High COE, USF-1E	NO PROBLEM FOUND			1	2						3
		OIL SEPARATION				1						1
		UNHARDENED RW						1				1
	FLA High COE, USF-1E Total			1		3	1					5
	M8 50 Conventional (never built)	NO PROBLEM FOUND				1						1
		UNKNOWN				1						1
	M8 50 Conventional (never built any) Total			2								2

SKF Claims Database

Number of Claims by Yr, Model, Problem

OEM	Model	FailureMode	B12Vr1							(blank)	Grand Total
			1996	1997	1998	1999	2000	2001	2002		
Freightliner	Total			2	61	58	14	17	1	143	326
Nevstar Int'l	8100 4x2	DIMENSIONAL ISSUE						1			1
		NO PROBLEM FOUND					1				1
							1	1			2
		HUB CAP LOST			1						1
					1						1
		18 SEAL LEAK - INGRESS				1					1
		LOW CLAMP LOAD				1					1
						1					
		8100 4x2 Total				2					2
		8100 SBA 6x4	NO PROBLEM FOUND				1				1
		8100 SBA 6x4 Total				1					1
		8100 SBA 6x4	18 SEAL DAMAGED		1						1
			IMPACT DAMAGE			1					1
			INSIGNIFICANT LEAK			1					1
		8100 SBA 6x4 Total		1	2						3
		8200 6x4 SBA	HUB CAP LOST			2					2
			18 SEAL LEAK - EGRESS		1						1
			18 SEAL LEAK - INGRESS		1	3					4
			IMPACT DAMAGE			3					3
			LOW CLAMP LOAD		1	1					2
			NO PROBLEM FOUND		1	4	1				6
			OIL SEPARATION			1					1
			REMOVAL DAMAGE		1						1
			UNHARDENED RW			2					2
			WATER INTRUSION ALONG SPINDLE			1					1
		8200 6x4 SBA Total		6	18	1					23
		8200 182A 4x2	UNHARDENED RW				1				1
							1				1
		8200 182A 4x2 Total									
		8200 182A 6x4	HUB CAP LOST			2					2
			18 SEAL LEAK - INGRESS		3	1	1				5
			IMPACT DAMAGE		1						1
			INNER RING SPALL				1				1
			NO PROBLEM FOUND		2		3				5
			OPEN				1				1
			UNHARDENED RW		2						2
			UNKNOWN		2						2
		8200 182A 6x4 Total		12	1	5	1				19
		8300 6x4	LOW CLAMP LOAD		1						1
			NO PROBLEM FOUND		1						1
			REMOVAL DAMAGE			2					2
			UNKNOWN		1						1

SKF Claims Database

Number of Claims by Yr, Model, Problem

Number of Claims			BldYr	1996	1997	1998	1999	2000	2001	2002	(Blank)	Grand Total
Item	Model	FailureMode										
	6300 6X4 Total				3	2						5
	6400 6X4	HUB CAP LOST			1							1
		IB SEAL LEAK - EGRESS				1						1
		INNER RING SPALL			1							1
		LOW CLAMP LOAD			2							2
		NO PROBLEM FOUND			2	2						4
		OB SEAL LEAK - EGRESS				1						1
		OB SEAL LEAK - INGRESS				1						1
		UNKNOWN			1							1
		WATER INTRUSION ALONG SPINDLE				1						1
	6400 6X4 Total				7	6						13
	64001 S8A 6X4	ATTACHING HARDWARE ISSUE					1					1
		IMPACT DAMAGE				2						2
		INSIGNIFICANT LEAK					1					1
		LOW CLAMP LOAD				1						1
		NO PROBLEM FOUND			1	5						7
		OPEN					1					1
		UNKNOWN						1				1
	64001 S8A 6X4 Total				1	8	1	3				14
	6600 SFA 6X4	NO PROBLEM FOUND			1							1
	6600 SFA 6X4 Total				1							1
	66001 SFA 6X4	IB SEAL LEAK - EGRESS				1						1
		IB SEAL LEAK - INGRESS				1						1
		IMPACT DAMAGE					1					1
		INSIGNIFICANT LEAK				1						1
		NO PROBLEM FOUND				2						2
	66001 SFA 6X4 Total				3	1						4
	66001 SFA 6X4	INSIGNIFICANT LEAK				3						3
		OB SEAL LEAK - EGRESS				1						1
	66001 SFA 6X4 Total				4							4
	6600 SFA 6X4	IB SEAL LEAK - INGRESS				2						2
		IMPACT DAMAGE				2						2
		NO PROBLEM FOUND				1						1
		REMOVAL DAMAGE				1						1
	6600 SFA 6X4 Total				6							6
		ASSEMBLY DAMAGE							1			1
		HUB CAP LOST						2				2
		IB SEAL DAMAGED						4				4
		IB SEAL LEAK - INGRESS					3		18			21
		IMPACT DAMAGE							2			2
		INNER RING SPALL							1			1

SKF 001987

SKF Claims Database

Number of Claims by Yr, Model, Problem

Number of Claims		Failure Mode	SldYr							(blank)	Grand Total
OEM	Model		1996	1997	1998	1999	2000	2001	2002		
		INSIGNIFICANT LEAK							3		3
		LOW CLAMP LOAD							6		6
		NO PROBLEM FOUND					1		5		6
		OIL SEPARATION							1		1
		OPEN							1		1
		OUTER RING SPALL							2		2
		REMOVAL DAMAGE							3		3
		TAMPERING							3		3
		UNHARDENED RW							1		1
		UNKNOWN							8		8
		WATER INTRUSION ALONG SPINDLE							4		4
	Total		1	3					63		67
6300 432		NO PROBLEM FOUND					1				1
6300 432		UNHARDENED RW				1					1
6300 432 Total			1	1							2
6300 GLIDER		IB SEAL LEAK - INGRESS				1					1
6300 GLIDER		IMPACT DAMAGE				1					1
6300 GLIDER Total			2								2
Navistar International Total			22	70	5	11	1	63			172
(blank)	(blank)	(blank)									
(blank) Total											
Grand Total			2	4	118	223	20	38	2	338	745

Response
to Main Document



Robert J Bondy/DET/SKF
05/30 08:57 AM

Subject:	Date Bell's graph
Response to:	<input type="checkbox"/> Statistical Evaluations
Category:	Statistics




ff98x hub niran 4_15_02.x


SKF 001989



PPM Trend for FF98X Hubs



Average Miles FF98X Hub Returns Failed on Progressive Incidents (PI) & Combined



Response
to Main Document

Rick P Morrow/AMER/SKF
06/30 09:53 AM

Subject: Additional Proportion and count charts using ARM data from DQ analysis


Response to: Statistical Evaluations

Category: Statistics




THU Charts P, C and Mfg Location.)

P-Chart - All ARM Returns by Service Date




SKF 001993


P-Chart - ARM Returns (6 Months Cumulative)




P-Chart - ARM Returns (12 Months Cumulative)



P-Chart - ARM Returns (18 Months Cumulative)




P-Chart - ARM Returns (24 Months Cumulative)




SKF 001997

**C-Chart - # Returns By Week (Aiken Build Date) For 1999
SKF Analyzed Returns**



Mileage Call [(All)]



Response
to Main Document

Robert J Bondy/DET/SKF
08/06 05:34 PM


Subject: Dale Bellis Updated graphs as of June 9, 2002
Response to: Statistical Evaluations
Category: Statistics



ff98x hub r100 may02 data> ff98x hub wear comp data.t

SKF 002001

FF98X HUB Warranty Performance - Claims Thru May 2002



Ryder Hubs Returned for Analysis - End of May 2002

SKF 002065

SKF SERIAL #	VIN #	CLAIM #	IN SERVICE DATE	MILES	R / L	Comments
18399-0160367	1FUDDYB3YPG13975	918276	11/14/99	610,074	L	No debris denting present; some oil separation from grease; load zone is visible on cones; IB seal lip wear ~2mm
18399-0160362	-	-	-	-	R	Load zone visible on cones; IB seal lip wear ~2mm; some oil separation from grease; no debris denting
18399-0149081	1FUDDYB9YPF25768	348790	08/07/99	671,884	L	IB seal wear ~1.5mm; dust lip wear ~2mm; some oil separation from grease; load zone visible on cones; no debris denting
18399-0149084	-	-	-	-	R	IB seal lip wear ~1.2mm; dust lip wear ~2mm; load zone visible on cones; some oil separation from grease; no debris denting
20499-0185637	G13981	918282		472,258	L	Jerky during rotation; OB outer race spalled; IB components are debris dented; some oil separation from the grease
20399-0167218	-	-	-	-	R	Bearings have polished appearance; OB has minor finish; IB seal lip wear ~1mm; dust lip ~1.75mm; minor fretting on ID of cones; some oil separation from grease
18199-0158206	G13973	918274		444,064	L	Some oil separation from grease; OB race load zone discolored; OB cone and rollers discolored; IB components not discolored; IB seal lip wear ~3mm no groove in clip ring
18199-0180183	-	-	-	-	R	Both inner cone faces polished; signs of cones creeping on spindle; some oil separation from grease; no debris denting; IB seal lip worn
99032-M279237-00818	G13988	918289		589,477	L	Seal purge acceptable; some separation of oil separation; grease is migrating to large end of rollers, IB and OB; IB seal wear ~2mm; normal fretting on cone bores
00742-M279257-99030	-	-	-	-	R	Tone ring missing; inner cone face show circular marks on top of machining witness; IB seal wear ~3mm; bearing surfaces polished
25899-0185414	G13939	918290		558,290	R	Some oil separation from grease; OB race and rollers are highly polished; IB seal wear ~1.5mm; no groove in clip ring
98152-M214530-001732	A63983	317568		596,346	R	OB seal shows light lube purge; no groove in clip ring
20399-0164730	1FUDDYB5YPG13976	918277	11/04/99	806,019	L	Some oil separation from grease; IB seal wear ~3mm
13099-0131801	1FUDDYB1YPG13991	918292	12/26/99	488,150	L	Wear on IB race and ends of rollers; IB rollers show slight discoloration; OB race shows wear at center
20399-0165276	G13982	918283		615,873	L	No visual damage to brg; Load zone visible on OB cone and roller; Inner cones have been creeping
20399-0165273	-	-	-	-	R	Minor debris denting on IB inner cone on bottom half only; Inner cones show signs of creep; Some oil separation from grease
20499-0165636	-	918284		585,044	L	No visual damage to brg cones; some oil separation from grease
20499-0165631	-	-	-	-	R	Jerky rotation, OB outer race spalled; no visual damage on IB cone or race; grease on OB cone and race look oxidized
28099-0180261	G53870	382038		484,506	L	Some oil separation from grease; IB cone race and rollers are in good condition. OB cone has signs of creeping on spindle also stain on load zone; OB rollers are polished on load zone; OB race heavy stain on load zone and stain starting to flake; clip ring in good condition
28099-0186236	-	-	-	-	R	IB cone, race and rollers are in good condition; OB cone and race are in good condition; OB rollers are highly polished; clip ring no groove
98271-272-14222432	A63987	317572		680,228	L	IB cone, race and rollers are in good condition; OB cone, race and rollers are in good condition; clip ring, slight groove
001153-98271-M222432	-	-	-	-	R	Some oil separation from grease; IB cone and rollers are in good condition; IB race stain at load zone; OB oil separation from grease is more apparent; OB cone and rollers are in good condition; OB race heavy stain at load zone; clip ring in good condition
18399-0160341	G13974	918275		556,934	L	IB and OB cone and rollers are in good condition; IB and OB races are darkened at load zone; clip ring no groove; some oil separation from grease
18399-0160340	-	-	-	-	R	IB cone debris denting at load zone; IB rollers are stained and show signs of debris, denting; IB race (2) spalls, OB cone stained at load zone; OB rollers stained at load zone; OB race stained at load zone; clip ring slight groove, IB seal lip worn
20299-0184284	G13978	918280		486,773	L	IB & OB cones races & rollers are in good condition; clip ring no groove

Ryder Hubs Returned for Analysis - End of May 2002

SKF SERIAL #	VIN #	CLAIM #	IN SERVICE DATE	MILES	R/L	Comments
20299-0164562		918266		551,026	R	Did not open; suspect spelling; jerky during rotation
20499-0165726					L	IB & OB cones, races & rollers are in good condition; clip ring no groove
20499-0165728					R	IB & OB cones, races & rollers are in good condition; clip ring slight groove
30699-0205531		362037		568,199	L	Some oil separation from grease; all brg parts have a mirror finish; no visual damage
30899-0205533					R	Some oil separation from grease; all brg parts have a mirror finish; no debris/dent or visual damage
22698-0013062		918281		605,219	L	Inner cones were creeping; IB cone has corrosion between seal lips; some oil separation from grease; IB rollers look dry
20499-0165652					R	Inner cones were creeping; IB cone has corrosion between seal lips; some oil separation from grease; no visual damage to brgs
25198-0019215	A63984	317588		593,206	L	OB cone, race & rollers show signs of staining on load zone; IB cone, race & rollers are in good condition; clip ring slight groove
23998-0016020					R	IB & OB cones races & rollers are in good condition; clip ring no groove
20599-0166593	G10386	918287		591,711	L	OB some oil separation from grease; OB cone, race & rollers are in good condition; IB cone oil seal grease lip very large; IB cone, race & rollers are in good condition; clip ring slight groove
20599-0166587		918279		596,184	R	OB cone, race & rollers show load zone/ IB cone, race & rollers are in good condition
20399-0164728					L	Load zone visible on inner cones; no visual damage to brgs; some oil separation from grease
20399-0164732					R	Load zone visible on inner cones & rollers; no visual damage to brgs; some oil separation from grease
25198-0019216	A63985	317570		567,711	L	Did not open up; jerky during rotation; suspect spalled IB outer race
23998-0015754					R	Did not open; suspect spalled race; jerky during rotation
20499-0165635		918285		581,925	?	Heavy fretting on ID of inner cones; some oil separation from grease; no visual damage to brgs
20499-0165630		918285			?	Some oil separation from grease; load zone visual on both brgs; load zone has a mirror finish; no spelling
008816-98189-M214550	A63982	317587		527,000	L	Inner cones were creeping; some oil separation from grease; tone ring is caked with oils & dirt from IB seal purge; no visual damage to brgs
001730-98152-M214650					R	Inner cones were creeping; tone ring is caked with oil & dirt from IB seal purge; some oil separation from grease; no visual damage to brgs
001049-98271-M222432	A63988	317573		543,562	L	Inner cones were creeping; some oil separation from grease; no visual damage to brgs; load zone visual out OB
001052-98271-M222432					R	Some oil separation from grease; no visual damage to brgs
003473-98166-M214550	A63987	317588		598,340	L	IB & OB cones, races & rollers are in good condition; clip ring no groove
18099-0122089	1FUYSDDYB1YLF46193	33887	12/29/99	397,004	?	Wheel off; inner & outer nuts burned up; drum & hub still mounted to wheel
07899-0106956	1FUYSDDYBLYLF36862	E1775908	07/01/99	578,730	R	Front hub & knuckle; both burnt up
09199-0414274	1FUYYDDYB4YDF45896	033670	07/24/99	395,799		Progressive Incident Level 1; (1) Bearing was cut in half by cutting torch was spinning on spindle/ other bearing cone also cut off with torch but too rusty to tell if it was spinning on spindle. Clip ring grooved and broken; IB cone heavy pitting and spelling on load zone; IB race pitting and spelling; IB rollers heavy debree denting; OB cone heavy stain on load zone; OB race gold tint on load zone; OB rollers dark discoloration
N/A Aiken	1FUYYDDYB8YLB64025	33882	05/28/99	443,272		IB and OB race pitted and spelled due to corrosion caused by water ingress; IB cone was seized to spindle and had to be cut off with cutting torch; OB cone debree denting and stain on load zone; OB rollers debree denting and stain on load zone; Contamination
11299-0123089	1FUYYDDYB1YLF30942	33955	06/07/99	359,724		IB cone large area heavy pitting and spelling due to corrosion caused by water ingress; IB race and rollers stained on load zone and heavy debree denting; OB cone, race and rollers are in good condition; clip ring no groove; contamination
3349-19099-M298330	1FUYZMD84XPA7711t	33894	07/20/99	284,153		

Ryder Hubs Returned for Analysis - End of May 2002

SKF 002067

SKF SERIAL #	VIN #	CLAIM #	IN SERVICE DATE	MILES	R / L	Comments
	1FUYDSEB8YL44960	033885	07/01/99	557,293		Inner cones were rotating; inner cone faces and back faces show witness marks; ID of inner cones are polished; some oil separation from grease; rollers look visually dry; All brg parts starting to have a mirror finish
	4V4ND2JF1YN242517	33836	09/28/99	277,232		IB rollers have wear on large end of rollers; debris denting on all IB cone parts; inner cones have witness marks from creeping; load zone visible on IB parts also; IB seal lip wear present; IB cone looks very dry; some oil separation from grease.
25598-0020567	1FUYDDYB5XD867268	0356743	04/08/99	403,875		Some oil separation from grease; IB race has a spell; IB cone and rollers are in good condition; clip ring slight groove.
07499-0106326	1FUYDXYB7XLA77264	33839	12/01/99	740,386		OB race several spelling and gouge marks; IB race heavy stain on load zone; spelling came first and gouging was secondary; hub was magnaflux and found no cracks; IB cone, race and rollers are in good condition; OB cone stained on load zone; grease discoloration
07499-0106326	1FUYDXYB7XLA77264	33839	12/01/99	740,386		IB and OB cones, races and roller are in good condition; clip ring no groove
26898-0024432	1FUYBXYB3XLA77262	33887	12/01/99	608,050		IB one line around cone show signs of debris denting; IB rollers light stain at load zone; IB race light pitting and one spell starting around load zone; OB light pitting and one heavy spell at load zone; OB race (1) 1 inch spell across load zone; heavy dark stain at large rollers end; OB rollers how debris denting clip ring grooved
01999-0079551	1FUYDXYB8XLF38021	0359848	03/29/00	551,881		IB cone, race and rollers are all stained pitted, spalled; due to grease break down caused by water ingress; IB seal caked with hard grease; OB cone, race and rollers are stained clip ring slight groove; contamination
01409-0077359	1FUYDDYB6XD857273	033851	03/27/99	442,040		OB race has four evenly spaced roller spell marks; OB cone debris denting and stain at load zone; OB rollers debris denting and stain at load zone; IB cone, race and roller are in good condition; clip ring no groove.
98140 "S" M209649	1FUY5XYBXLA78330	6852442	08/26/98	500,082		IB race one inch spell; IB cones and rollers show signs of debris denting also light stain at load zone; OB and IB cones are highly polished on ID; OB cone, race and rollers slight stain end are in good condition; clip ring slight groove.
11099-0121936 004825-06172-	M268510	33854	8/17/99			IB cone heavy spelling on roller spacing at bottom; IB race pitting and spelling IB rollers debris denting and stain at load zone; OB cone, race and rollers are in good condition; clip ring broken when removing hub
M214558 004385-98171-	1FUY3WD800XLA30418	0468470	08/10/98	581,185		IB and OB cone, races and rollers are in good condition; clip ring grooved; no problems found
M214530 000213-98148-	1FUY3WDB3XLA30364	0468862	08/17/98	506,289		IB and OB cones, race and rollers are in good condition; clip ring slight groove; no problems found
M214550 0033774-98168-	1FUY3WD812XLA30369	0473242	08/13/98	506,432		IB and OB cones, races and rollers are in good condition; clip ring no groove; no problem found
M214550	XLA85581	CWA10337	08/01/98	623,549		Grease separation present on both cones; all brg parts have a mirror finish; IB seal lip wear excessive; ID of cones have no frosting and have a polished look from creeping.
11298-0123790	1FUYDSEB8YL44957	0033884	07/01/99	531,182		Load zone visible on both brgs; all brg parts besides load zone have a mirror finish; the load zone is a tan color; grease separation present on both cones
	1FUYDDYB7YMG90351	33885	09/01/00	255,281		No visual damage to brgs; IB inner cone has corrosion between seal lips; excessive wear on IB seal; no sign of water contamination but dirt has made grease on back face of IB seal gritty
Too rusty - Luechow	1FUYDWD85X198440	33770	05/23/98	405,822		Only hub was returned; HPI no inner cones or rollers; tone ring missing also
Too rusty - Aiken 001929-98176-	1FUYDDYB0XLA70929	0358717	10/14/98	274,741		OB race spelled at one location about 3 inches long the whole width of race; all OB brg parts have a mirror finish; grease has a rusty color; no visual damage to the IB brg; some oil separation from grease
M2013099	4VGJDEJFSX N885091	33698	07/17/98	194,124		No visual damage on brgs; some oil separation from grease; IB seal purge excessive
??700 0285331	1FUIJAHB001PH70783	033890	07/08/00	417,606		No visual damage to brgs; some oil separation from grease; clip ring was fractured; excessive damage was caused by a hammer when trying to remove hub; brg surfaces starting to look polished.

Ryder Hubs Returned for Analysis - End of May 2002

SKF SERIAL #	VIN #	CLAIM #	IN SERVICE DATE	MILES	R / L	Comments
24898-0015207	1FUYDDYBXXLA70940	0034011	10/19/98	654882		IB race one large & several small spalls on load zone; IB cone ok; seal lip dia 2.16 mm; med stain & debris denting; IB rollers stain & Debris denting on load zone; IB bearing all damaged due to corrosion caused by water ingress; OB race flaking; stain on load zone; OB cone & roller stain. @ load zone; clip ring; slight groove; contamination
1119-0122893 00400-0227542	4V4ND1JEBYN703196 1FUYSDYB8YLG80337	0034097 E1778403	06/18/99 05/01/00	503,443 234,987		IB cone spelling on one side evenly spalled; IB race heavy stain & pitting; IB rollers stained & debris denting; OB cone race & rollers in good condition; clip ring no groove; Impact loading IB & OB cones, races & rollers are in good condition; clip ring slight groove
29599-0201278	1FUYSD0ZBBYLG16379	0034124	12/21/99	363,881		IB cone heavy spelling in one area due to corrosion caused by water ingress; IB race & rollers debris denting; OB cone race & rollers in good condition; clip ring slight groove; contamination IB race discoloration on load zone where large and small ends of rollers ride; IB cone two spalls on surface where roller (large end) rides; IB cone one small pit mark on surface where roller (small end) rides; OB cone, race, and rollers are in good condition; IB rollers debris denting and heavy stain on small end; Contamination
25098-0018803	1FUYDXYB5XLA77263	0034118	02/11/99	608,244	2 of 2	IB oil seal lip 1.73 mm; IB cone heavy spelling in one area caused by corrosion due to water ingress; IB race and roller heavy stain and debris denting; IB grease around rollers very hard; OB cone, race and rollers are stained but are in good condition; clip ring slight groove; Contamination Hub returned disassembled; only 13 rollers & both inner cones returned; clip ring is fractured; IB inner cones spalled on bottom half; guiding flange on both inner cones show excessive wear; both outer races have fine spelling
024398-0018160	1FUYDXYB5XLA77263	0034118	02/11/99	608,244	2 of 2	REC AXLE WITH BURNED UP BEARING SEIZED TO SPINDLE; REC HUB; WHEEL OFF-5/17/02
11199-0122949	1FUYDALYB4YMF46084	39528	07/27/98	330,650		IB RACE HEAVY SPALLING AND DISCOLORATION ON LOAD ZONE; SPALLING AND PITTING AND HEAVY DISCOLORATION ON LOAD ZONE; IB ROLLERS HEAVY DEBRIS DENTING AND DISCOLORATION ON LOAD ZONE; O/B CONE AND RACE PITTING WHERE ROLLERS MEET RACE; INBOARD OIL SEAL LEAKAGE WATER INGRESS; CONTAMINATION REC, DRUM, HUB, KNUCKLE AND CD BRAKE SHOE KNUCKLE INNER AND OUTER CONES SEIZED TO SPINDLE; HUB RACES BURN UP
16599-0149087	1FUYDDYB7YPF25768	E1793326	09/01/99	667,193	B	IB OIL SEAL LIP 2.21MM; IB CONE HEAVY SPALLING ON ONE SECTION; DISCOLORATION ON LOAD ZONE; IB RACE PITTING AND DISCOLORATION; IB ROLLERS SHOW SIGNS OF DEBRIS DENTING; IB CAUSED BY WATER INGRESS; O/B CONE, RACE AND ROLLERS ARE STAINED AND SHOW SIGNS OF DEBRIS DENTING AND CLIP RING SLIGHT GROOVE; CONTAMINATION
24898-0017258	1FUYSDYB2XLB26645	0034387	12/17/99	458,000		IB CONE, RACE AND ROLLERS LIGHT DISCOLORATION ON LOAD ZONE; O/B CONE PITTING, POLISHING AND DISCOLORATION ON LOAD ZONE; O/B RACE AND ROLLERS SIGNS OF DEBRIS DENTING; ALL CAUSED BY WATER INGRESS; CLIP RING SLIGHT GROOVE; INBOARD OIL SEAL WATER INGRESS; CONTAMINATION-5/22/02
98038-1795438-035243	1FUYSDYB9XLA29086	39830	05/01/98	481,834		IB RACE HEAVY SPALLING DISCOLORATION, VERY THICK GREASE; IB OIL SEAL LIP 1.55 MM; IB CONE PITTING AND HEAVY DISCOLORATION ON LOAD ZONE; RUBBING ON FLANGE GUIDE; IB ROLLERS SIGNS OF DEBRIS DENTING; ALL CAUSED BY CORROSION DUE TO WATER INGRESS; O/B BEARING IN GOOD CONDITION; INBOARD SEAL WATER INGRESS; CONTAMINATION-5/28/02
RUSTY-AIKEN	1FUYDDYB8YLF28530	0380960	06/19/99	325,981		IB RACE 1/2" SPALL; THE REST OF THE RACE IS IN GOOD CONDITION; IB CONE AND ROLLERS ARE IN GOOD CONDITION; O/B, RACE, CONE AND ROLLERS ARE IN GOOD CONDITION; CLIP RING SLIGHT GROOVE; IB OIL SEAL LIP 1.34 MM- 5/29/02
75799-0151140		34228	06/26/99			REC HUB, INNER SEAL, BEARING GREASE VERY THICK; IB RACE HEAVY SPALLING ALL AROUND RACE LOAD ZONE; IB SEAL THICK GREASE; O/B RACE DISCOLORATION ON LOAD ZONE; INCONCLUSIVE-5/28/02
11099-0126467	1FUYDDYB7YLF50868	34098	06/04/99	443,137		

Ryder Hubs Returned for Analysis - End of May 2002

SKF SERIAL #	VIN #	CLAIM #	IN SERVICE DATE	MILES	R/L	Comments
23000-0211572	1FUYDXYBXYLG32836	0034125	06/04/98	203,562		IB & O/B CONES, RACES AND ROLLERS ARE IN GOOD CONDITION; CLIP RING-NO GROOVE; NO PROBLEM FOUND-5/28/02
00384-? Luechow	1FUYSDYB8XLA28088	33835	05/01/98	481,834		HEAVY HAMMER MARKS, CLIP RING WAS BROKEN REMOVING HUB; O/B CONE TOO HEAVY SPALLS 1" LONG; DISCOLORATION DUE TO HEAT ON GUIDE FLANGE; O/B RACE AND ROLLERS SIGNS OF DEBRIS DENTING; IB CONE SPALL 3/4" LONG, IB RACE AND ROLLERS SIGNS OF DEBRIS DENTING-5/24/02
37498-0071317	1FUYDS9EBXODP870849	E1788041	04/01/98	643,529		LIGHT OIL SEPARATION O/B, IB CONE HEAVY SPALLING ON LOAD ZONE; IB RACE, HEAVY GULLING ALL AROUND RACE ON LOAD ZONE; IB ROLLERS, HEAVY DEBRIS DENTING; IB GREASE AROUND ROLLERS VERY THICK; O/B CONE, RACE AND ROLLERS ARE IN GOOD CONDITION; CLIP RING AND GROOVE; CONTAMINATION-5/24/02
16598-0340244	1FUYDDYB3YLP50433	0034225	08/09/98			REC HUB & KNUCKLE AND O/B CONE; O/B CONE AND RACE HEAVY PITTING AND SPALLING; IB RACE HEAVY DAMAGE; INBOARD SEAL LEAKING WATER INGRESS; CONTAMINATION
27598-0028198	1FUYDMEB3XPA83966	0034353	01/25/98	572,492	B	O/B SEAL OIL SEPARATION FROM SEAL; IB AND O/B CONES, RACES AND ROLLERS ARE IN GOOD CONDITION; CLIP RING NO GROOVE; NO PROBLEM FOUND-5/23/02
25198-0019199	1FUYDMEB3XPA83966	0034353	01/25/98	572,942	B	IB CONE, RACE AND ROLLERS ARE IN GOOD CONDITION; O/B CONE, AND ROLLERS DISCOLORATION ON LOAD ZONE; O/B RACE HEAVY SIGNS OF PEELING CLIP RING- NO GROOVE; NO PROBLEM FOUND-5/23/02
Too rusty - Alkan	1FUYDCYB4YDF45505	000033886	08/15/98			HUB RETURNED DISASSEMBLED; IB INNER CONE SPALLED ON BOTTOM HALF; GREASE IS A BLACK TINT; CLIP RING FRACTURED DURING REMOVAL; NO VISUAL DAMAGE TO O/B BRG.
13898-0135839	1FUYDCYB8YL1F38160	33837	08/23/98	387,484		IB CONE LIGHT PITTING AND DISCOLORATION ON LOAD ZONE; IB RACE PITTING AND DISCOLORATION ON LOAD ZONE, IB ROLLER STAIN ON LOAD ZONE; O/B CONE LIGHT DISCOLORATION ON LOAD ZONE; O/B RACE HEAVY DISCOLORATION AND FLAKING ON LOAD ZONE; O/B ROLLERS LIGHT STAIN ON LOAD ZONE; CLIP RING-NO GROOVE-5/10/02
N/A Luechow	1FUYSDYB8XPA27789	33822	05/15/98	340,588		IB AND O/B CONES, RACES AND SEALS ARE IN GOOD CONDITION; CLIP RING NO GROOVE; NO PROBLEM FOUND
01001-0326386	1FUYSDYB8XLB08801	8880797	12/09/98	343,851		IB CONE, RACE AND ROLLERS ARE IN GOOD CONDITION; O/B RACE HEAVY DISCOLORATION ON LOAD ZONE; O/B CONE AND ROLLERS ARE IN GOOD CONDITION; CLIP RING NO GROOVE; C.R. SEAL; NO PROBLEM FOUND
22801-0351862	1FUYBXYYB2XLF38015	33812	03/24/98	546,135		C.R. SEAL; IB AND O/B CONES, RACES AND ROLLERS ARE IN GOOD CONDITION; CLIP RING NO GROOVE; NO PROBLEM FOUND
Too rusty - Alkan		E1749214				Hub returned with IB brg disassembled - spalling and contamination present; sent to SKF
14289 0138959		Unit 348313	03/01/99			Sent to SKF
004518 001711	X1A85561	CWA10337				
00214550						

Response
to Main Document

Rick P Morrow/AMER/SKF
08/09 09:06 PM

Subject: Sample Size for R-Safe In field
Response to: Statistical Evaluations
Category: Statistics



Sample size THU.doc

Duane and I have considered sample sizes to estimate if the 2% of seals with axial AND primary lip failures occurred in all Bethlehem batches. We had estimated that 2% of the seals from the last batch of Bethlehem production exhibited both defects on the same seal.

The sample sizes are large to get any degree of confidence. We provide the sample sizes based on how confident we want to be with a margin of error and probability of saying the percentage is higher when it is not. One can see the change in sample size based on the proportion of seals defective being greater than 4% and 6%. (Alternative proportion in the table below).

Testing proportion = 0.02 (versus > 0.02)

Alpha = 0.01 99% Confidence Level

Alternative Proportion	Sample Size	Target Power	Actual Power
4.00E-02	1050	0.9500	0.9500
4.00E-02	802	0.8000	0.8001
6.00E-02	321	0.9500	0.9501
6.00E-02	173	0.8000	0.8007

For example, a sample size of 173 hubs would need to be pulled across all production to have a 99% confidence level that the population of seals having both defects is no greater than 4% (2% with 2% error). The quantities should be stratified using the quantity per batch.

Another way of considering sample size is to estimate the probability in a sample of 10 hubs to find 1 or more seals with both defects. This result is 18%.

In other words, one would have to sample much more than 10 hubs to have any confidence of the true population proportion.

The purpose is to have confidence of the probability of a hub having both defects in the seal AND all other factors being present (Water at the seal prior to enough wear to repair the defect with static tolerance band).

We should consider the possibility of deducing from Bethlehem's records due to the large sample sizes suggested.

Risk

Additional Power and Sample Size

Test for One Proportion

Testing proportion = 0.02 (versus > 0.02)

Alpha = 0.2 80% Confidence level

Alternative Proportion	Sample Size	Target Power	Actual Power
4.00E-02	485	0.9500	0.9502
4.00E-02	200	0.8000	0.8001
6.00E-02	162	0.9500	0.9503
6.00E-02	64	0.8000	0.8027

Response
to Main Document

Rick P Morrow/AMER/SKF
06/28 04:00 AM

Subject: Hub High Warranty Periods Tested
Response to: Statistical Evaluations
Category: Statistics



Steer THU RM Short & 27 only picture.

SKF 002072

Chuck believes Aiken produced hubs went through two and maybe three periods of higher than normal failure rates. Julian dates 12098 -27398, 11099 - 14099 and possibly Aug and Sep 1999.

His hypothesis is an axial clearance gage cycled into a wear pattern after recalibrating. This gage was eventually permanently corrected and the higher than normal failure rates ceased. He believes this permanent correction occurred in November.

He described a peak and valley cycle in the axial clearance.

Null Hypotheses

Ho1: No time periods correlate with significantly higher warranty claims Vs Production Quantities

Ho2: Axial clearance gage performance does not affect proportion of claims

Analysis


- Mike Lewis requested analysis of Chuck Smith's suggestions that "Aiken" had several periods of high failure. In addition, Chuck and Mike have requested help in determining hubs to retrieve from high warranty production periods. These answers are possible if someone can identify hubs within vehicle.
- Duane Gipe months ago identified several time periods that had a higher proportion of claims
- This study supports both analysts using the hub production date from the SKF analyzed returns database of only those claims when production date is listed. Therefore, there may be a selection bias. The Null hypothesis H_0 is rejected.
- One or more parties (ARM, Aiken and Luechow) experienced abnormal variation during several weeks.
- I added the comments, root cause from SKF work and whether the claim was validated to support decisions on true root cause.
- Other hypotheses were tested and included. Sunday has a higher proportion of claims, for instance.
- Axial clearance hypothesis requires data on gage maintenance.
- Six Sigma analysis includes SPC and hypothesis testing. Further analysis is possible when data is available.
- FMEA is again recommended to direct root cause analysis

- Data Concerns/Notes
 - Selection bias may be present because claims missing build dates were excluded.
 - I have received no process measurement data to assist in identifying variation in Aiken.
 - Several claims were posted against hub build dates that showed zero production. Several analyses were run and this error was insignificant.
 - Immature data for periods after these studied due to Mean Time to Failure
 - Luechow hubs are included in one high proportion time period
 - Databases used were Aiken production quantities by day, the SKF analyzed returns database and the ARM database of 2,200 claims.
 - Claims were also shown for hub build dates that were identified as producing only trailer hubs.
 - No data is available from suppliers that may be tested for variation and correlation with claims.

Duane Gipe's original chart


Claims Vs Produced

Limits Based on Dates Up To 19910




Analysis Begins 6/27/02

**u Chart Count of Claims Vs Monthly Production
Steer Claims Only**




Warranty Claim Proportion by Year/Week




Warranty Claim Proportion by Day Steer Only -

Note some warranty on dates showing zero steer produced. Changeover to Steer Mentioned and Next
to Highest count warranty date (4/20)



Steer Production Dates Only

Warranty Claims by Day



Day 8/27/98

BTB-0052	0016245	08/27/98	3	1998	Aiken	Frlnr	Ryder	CWA00159
BTB-0052	0016439	08/27/98	3	1998	Aiken	Frlnr	Ryder	CWA00154
BTB-0049	0015726	08/27/98	3	1998	Luechow	Frlnr	Ryder	318273
BTB-0049	0015966	08/27/98	3	1998	Luechow	Frlnr	Ryder	318277

Noise in bearing	NOISE/VIBRATION	1FUYDDYB0XLA70915	498210	500000	IB SEAL LEAK - INGRESS
Wheel bearings were failed	BEARING FAILURE	1FUYDDYB3XLA70908	351287	400000	IMPACT DAMAGE
	NO INFO	1FUYDDYB4XLA70917	369097	400000	IMPACT DAMAGE
	NO INFO	1FUYDDYB8XLA70921	418370	450000	WATER INTRUSION ALON

IB brg row water content 0.49%, brg ctr 0.12%	Valid
Line spalling of IB IR at loaded zone	Invalid
Rec'd disasm, OB row G, IB row line spalls at roller spacing	Invalid
Endplay 0.000", jerky rotation, OB row met debris, IB row VG, IB seal fun	invalid

Week 39 1998

Day of Week	Hub Production Date		Claims	Total				Proportion of Claims
				3rd	1st	2nd	Daily	
Sunday	9/20/1998		1 No Steer * *	63	160		223	0.4484%
Monday	9/21/1998	Honer down	4 No Steer *	36	91	80	207	1.9324%
Tuesday	9/22/1998		1 No Steer *	0	0	120	120	0.8333%
Wednesday	9/23/1998		1 No Steer *	136	174	76	386	0.2591%
Thursday	9/24/1998	Drill Operation down 2nd shift	3 No Steer *	129	94	122	345	0.8696%
Friday	9/25/1998		2 No Steer *	176	7	84	267	0.7491%
Saturday	9/26/1998	Grinder & Honer down	3 No Steer *	86	72	99	257	1.1673%
Sunday	9/27/1998		3 No Steer * * *	0	0	0	0	
BTF-0052	0022910	09/20/98	0 1998	Aiken	Fritn	Ryder - Ashland City	0031499	
BTF-0052	0022921	09/21/98	3 1998	Aiken		Ryder		Unit 329665
BTF-0052	0022922	09/21/98	3 1998	Aiken		Ryder		Unit 329668
BTF-0049		09/21/98	3 1998	Luechow	Fritn	Max Trkg	CHE08413 1/2	
BTF-0049	001097	09/21/98	3 1998	Luechow	Fritn	Max Trkg		CHE08457
BTF-0049	0023434	09/22/98	3 1998	Luechow	Fritn	Max Trkg		CHE08413 2/2
BTF-0052	0024551	09/23/98	3 1998	Aiken	Neistar	Andrews Trucking		0088188A
BTF-0052	0027234	09/24/98	3 1998	Aiken	Fritn	Mike Newsome		HLFD0001E450T
BTF-0052	0024343	09/24/98	3 1998	Aiken	Neistar	Vision Transp.		089156A
BTF-0049	M222432	09/24/98	3 1998	Luechow	Neistar	G&P Trucking		0041874D
BTF-0052	0024014	09/25/98	3 1998	Aiken	Fritn	Interstate		DWFD0001F334T
BTF-0052	0023916	09/25/98	3 1998	Aiken		Ryder		Unit 329654
BTF-0052	0024707	09/26/98	3 1998	Aiken	Fritn			E1703119 1/2
BTF-0052	0024841	09/26/98	3 1998	Aiken	Fritn			E1703119 2/2
BTF-0052	0024231	09/26/98	3 1998	Aiken		Ryder		Unit 329670 2/2
BTF-0052	0024453	09/27/98	3 1998	Aiken		Ryder		Unit 329664
BTF-0052	0024430	09/27/98	3 1998	Aiken		Ryder		Unit 329668
BTF-0052	0024434	09/27/98	3 1998	Aiken		Ryder		Unit 329670 1/2

9/20 – 9/27/98 Week 199839

continued

Seized	SEIZED	1FUYSDYB6M_B08901	275378	300000	IB SEAL LEAK - INGRESS
Inspect wheel speed senso	TONE RING BROKEN AL	B08907	470504	500000	IB SEAL LEAK - INGRESS
Inspect inner bearing, front	NON-SPECIFIC	B08900	480158	500000	IB SEAL LEAK - INGRESS
Bearing Failure	BEARING FAILURE	1FUYSCB0X0L973978	587114	600000	NO PROBLEM FOUND
	NO INFO				NO PROBLEM FOUND
Bearing Failure	BEARING FAILURE	1FUYSCB0X0L973978	587114	600000	OUTER RING SPALL
Lube leaking from RF hub	LEAK	2HSPFMAMR59C025337	225063	250000	OIL SEPARATION
Noisy, Rattles	NOISE/VIBRATION	1FUYSDYBXXPA87087	348505	350000	NO PROBLEM FOUND
Loose	LOOSE	2HSPFMAMER1XCO30744	213878	250000	NO PROBLEM FOUND
Wheel seal leaking	LEAK	2HSPFMAMHR03NC025573	180681	200000	IB SEAL LEAK - EGRESS
Beds & sticks	BINDYSTICK	1FUYSDYBISIP906379	396906	400000	UNKNOWN
	NO INFO	B08908	286782	300000	IB SEAL LEAK - INGRESS
Leaks	LEAK	1FUPCS2BS5LA12820	353143	400000	NO PROBLEM FOUND
Leaks	LEAK	1FUPCS2BS5LA12820	353143	400000	NO PROBLEM FOUND
	NO INFO	B08902	808905	550000	IB SEAL LEAK - INGRESS
	NO INFO	B08905	402790	450000	IB SEAL LEAK - INGRESS
	NO INFO	B08905	318601	350000	IB SEAL LEAK - INGRESS
	NO INFO	B08902	808905	550000	IB SEAL LEAK - INGRESS

Endplay 0.000", noisy, lube sparse IB OR RW, IB seal dust lip worn out	Valid
Endplay 0.020", noisy, OB seepage ~2.0 g, oil separation, IB cage melted	Valid
Endplay 0.000", smooth rotation, very clean seals, appears to be corrosion	Valid
Endplay 0.000", smooth quiet rotation, IB & OB big rows VG, IB seal func	Invalid
Endplay 0.000", smooth quiet rotation, IB & OB big rows VG, IB seal func	Invalid
Endplay 0.000", smooth quiet rotation, OB row VG, IB OR RW single line	Valid
EP 0.000", smooth rotation, no internal distress, very little extra grease in	Valid
OB seepage ~1.5g, IB dry, endplay 0.000", smooth quiet rotation	Invalid
Endplay 0.000", smooth quiet rotation, OB seepage <2.0 g, IB <1.0 g	Invalid
Hub OD covered in grease and dirt,	Valid
IB now seized, OB heat damaged - melted cage & blurred, IB rollers ends p	Inconclusive
Endplay 0.000", rotation stiff, no noise, OB IR spall multi loc. around ring,	Valid
Endplay 0.000", smooth rotation, no internal distress(Troy Lab determinati	Invalid
Endplay 0.000", smooth rotation, no internal distress(Troy Lab determinati	Invalid
Endplay 0.000", smooth rotation, IB OR spall multi loc., appears to be cor	Valid
Rec'd disease., OB IR spall, IB seepage ~2.0 g, IB OR RW spall line 360	Valid
Endplay 0.000", smooth rotation, corrosion in OB row, OB seepage ~2.0g	Valid
Rec'd disease., IB IR missing, IB OR RW spall multi loc., appears to be co	Valid

4/18/99 – 4/24/99 Cont

Week 17 1999

		Changeov							
Monday	4/18/1999	er to Steer	3	No	Steer	*	0	0	67
Tuesday	4/20/1999		9	No	Steer	*	239	295	262
Wednesday	4/21/1999		5	No	Steer	*	340	275	294
Thursday	4/22/1999		2	No	Steer	*	320	296	180
Friday	4/23/1999		1	No	Steer	*	200	134	210
Saturday	4/24/1999		0	No	Steer	**	**	**	0 *

BTF-0052	0126613	04/19/99	2	1999	Aiken	Navistar	Trucks inc. of Janesv	CWA08206
BTF-0052	0121704	04/19/99	2	1999	Aiken	Navistar	WalMart	Unit 91069
BTF-0052	0121945	04/19/99	2	1999	Aiken	Navistar	WalMart	Unit 9711
BTF-0052	0122948	04/20/99	2	1999	Aiken	FrInr	Ryder	E17248206
BTF-0052	0127740	04/20/99	2	1999	Aiken	FrInr	KLLM	E1744815
BTF-0052	0121708	04/20/99	2	1999	Aiken	Navistar	WalMart	Unit 91058
BTF-0032	0122092	04/20/99	2	1999	Aiken	Voho	Fil-Mor Express	CWA01737
BTF-0052	0121402	04/20/99	2	1999	Aiken		Ryder	Ryder Unit # 337287
BTF-0052	M121626	04/20/99	2	1999	Luechow	FrInr		BPFD0001A182T
BTF-0052	0122112	04/20/99	2	1999	Aiken	Navistar	WalMart	WMT91492 2/2
BTF-0052	0122110	04/20/99	2	1999	Aiken	Navistar	WalMart	WMT91492 1/2
BTF-0052	0122124	04/20/99	2	1999	Aiken	Navistar	WalMart	WMT91509
BTF-0052	122933	04/21/99	2	1999	Aiken	FrInr	Heartland Express	E1692195
BTF-0052	0122545	04/21/99	2	1999	Aiken	FrInr	Heartland Express	E1720710
BTF-0052	0122935	04/21/99	2	1999	Aiken	FrInr	Ryder	348806
BTF-0052	0123027	04/21/99	2	1999	Aiken		Ryder	33623
BTF-0052	0122896	04/21/99	2	1999	Aiken	FrInr		CWA09666
BTF-0052	0123651	04/22/99	2	1999	Aiken	Navistar	WalMart	Unit 91287
BTF-0052	0123372	04/22/99	2	1999	Aiken	Navistar	Fleet Pride	Unit 3036
BTF-0052	0124026	04/23/99	2	1999	Aiken		Ryder Unit 334749	33614

4/18/99 – 4/24/99 Cont

NOISE/VIBRATION	2HSCHASR1YC068276	277648	300000	IS SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	2HSFMAMIRAYC029364	280250	300000	IS SEAL LEAK - INGRESS	Valid
ENDPLAY/LOOSE	2HSFMAMIR5YC029700	346249	350000	LOW CLAMP LOAD	Invalid
BIND/STICK	1FUYSDYBXYLF38978	588523	600000	UNKNOWN	Inconclusive
LEAK	1FUYSZYBXYL787534	304850	350000	NO PROBLEM FOUND	Invalid
NOISE/VIBRATION	2HSFMAMIRXYC029353	289151	300000	IS SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	4V4ND2UF8YN788360	356930	400000	IMPACT DAMAGE	Invalid
NO INFO				IS SEAL LEAK - INGRESS	Valid
NO INFO				NO PROBLEM FOUND	Invalid
BEARING FAILURE		146540	150000	IS SEAL LEAK - INGRESS	Valid
BEARING FAILURE		146540	150000	IMPACT DAMAGE	Invalid
BEARING FAILURE		196398	200000	IS SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	1FUYSDYB5YCA93260	248423	250000	WATER INTRUSION ALON	Invalid
LEAK	1FUYSDYBYLB91578	311918	350000	IS SEAL LEAK - INGRESS	Valid
NO INFO	1FUYSDYE3YLF38977	591544	600000	IS SEAL LEAK - INGRESS	Valid
NO INFO	4V4ND1JF1YN793198	615239	650000	IS SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	4V4ND1UF8YN788433	351894	400000	IS SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	2HSFMAMR5YC030218	260100	300000	IMPACT DAMAGE	Invalid
BROKEN/SEPARATED	EXC023080DOM			UNKNOWN	Inconclusive
NO INFO	1FUYDDYBOYP885713	526469	550000	IS SEAL LEAK - INGRESS	Valid

Week 19 5/2/99 – 5/7/99


Week 19 1999

Sunday	5/2/1999		1	No Steer	*	*	*	*	0	*
Monday	5/3/1999		6	No Steer	*	57	350	176	583	1.0292%
Tuesday	5/4/1999		8	No Steer	*	259	264	217	740	1.0811%
Wednesday	5/5/1999		5	No Steer	*	300	265	358	923	0.5417%
Thursday	5/6/1999		7	No Steer	*	302	280	289	871	0.8037%
Friday	5/7/1999		1	No Steer	*	0	251	274	525	0.1905%

BTB-0052	0128993	05/02/99	2	1999	Aiken	Frtlnr			E1748129	Valid
BTB-0052	0128110	05/03/99	2	1999	Aiken	Frtlnr			66762	Invalid
BTB-0052	128126	05/03/99	2	1999	Aiken	Frtlnr	Empire Truck Sales	CWA06549		Valid
BTB-0052	128021	05/03/99	2	1999	Aiken	Frtlnr		E1741081		Invalid
BTB-0052	0128019	05/03/99	2	1999	Aiken	Frtlnr		E1692210		Valid
BTB-0052	0128460	05/03/99	2	1999	Aiken	Frtlnr	Mckenzie Tank Lines	R.O. 49442		Valid
BTB-0052	128098	05/03/99	2	1999	Aiken	Frtlnr		C WA07488		Invalid
BTB-0052	128302	05/04/99	2	1999	Aiken	Frtlnr		E1674449		Invalid
BTB-0052	0129348	05/04/99	2	1999	Aiken	Frtlnr	Tim Mallard/CR Engle	E1525550		Valid
BTB-0052	128849	05/04/99	2	1999	Aiken	Frtlnr	Zuran Peurie	E1752443		Invalid
BTB-0052	129277	05/04/99	2	1999	Aiken	Frtlnr	Marlin Lipe	86102	OPEN	
BTB-0052	0170218	05/04/99	2	1999	Aiken	Mack	Tom Bailey Motors	CWA04353		OTHER
BTB-0052	128683	05/04/99	2	1999	Aiken	Frtlnr	Roehl Transport	CWA07839		Valid
BTB-0052	128691	05/04/99	2	1999	Aiken	Frtlnr	Roehl Transport	CWA07839		Invalid
BTB-0052	0129180	05/04/99	2	1999	Aiken	Frtlnr	KLLM			Inconclusive
BTB-0049	0130080	05/05/99	2	1999	Aiken	Frtlnr		E1689451		Invalid
BTB-0032	004339	05/05/99	2	1999	Luechow	Frtlnr		NSFD0001BT43T 1/2		Invalid
BTB-0052	129813	05/05/99	2	1999	Aiken	Frtlnr	Bar None	E1689062		Valid
BTB-0052	0129943	05/06/99	2	1999	Aiken	Frtlnr	New Prime	E1750047		Valid
BTB-0052	0129637	05/05/99	2	1999	Aiken	Navistar	James Likin	0013495A		Invalid
BTB-0052	0130818	05/06/99	2	1999	Aiken	Frtlnr		E1692211		Invalid
BTB-0052	0130082	05/06/99	2	1999	Aiken	Ptiblt		CWA05981		Inconclusive
BTB-0052	0130507	05/06/99	2	1999	Aiken	Navistar	Hazmat Environments	CCU00571		Valid
BTB-0052	0131322	05/06/99	2	1999	Aiken	Navistar		0042205B		Valid
BTB-0049	130922	05/06/99	2	1999	Aiken	Frtlnr		E1689133		Valid
BTB-0052	130862	05/06/99	2	1999	Aiken	Frtlnr	Harjit Singh	E1755522		Valid
BTB-0052	0131015	05/06/99	2	1999	Aiken	Frtlnr	CSS Transp	BNFD0001ME67T		Invalid
BTB-0052	131259	05/07/99	2	1999	Aiken	Frtlnr		E1752364		Valid

Week 19 5/2/99 – 5/7/99

	NO INFO						Valid
	NO INFO	1FUPCSZBYLA88762	273885	300000	IMPACT DAMAGE	Invalid	
Bearing failure	BEARING FAILURE	1FUYDSZB3YLF06032	385007	400000	IB SEAL LEAK - INGRESS	Valid	
Chatter, noisy, vibration	NOISE/VIBRATION	1FUYSSXYB0YLB40034	391382	400000	TAMPERING	Invalid	
Corroded & rust	CORROSION/RUST	1FUYSSXYB7YLB40032	278902	300000	IB SEAL LEAK - INGRESS	Valid	
Noise and vibration in front	NOISE/VIBRATION	M1AA12Y5YW123599	208797	250000	IB SEAL LEAK - INGRESS	Valid	
	NO INFO				UNKNOWN	Invalid	
Hub bearing binds & stick	BIND/STICK	1FUYDDYBGYLB05748	191161	200000	WATER INTRUSION ALON	Invalid	
Too much play/leaking	ENDPLAY/LOOSE	1FUYSDYB6WP917799	304315	350000	UNHARDEDENED RW	Valid	
Hub bearing broken	BROKEN/SEPARATED	1FUYSSZB5YLA92032	348050	350000	UNKNOWN	Invalid	
Hub bearing noisy & rattle	NOISE/VIBRATION	1FUYSSZBXYLB86102	460061	500000	OPEN	OPEN	
Seal leaking	LEAK	M1AA18YXYW121483	251046	300000	IB SEAL DAMAGED	OTHER	
Hub bearing rough	NOISE/VIBRATION	2HSFMAHRSYC032039	284297	300000	IB SEAL LEAK - INGRESS	Valid	
Hub bearing rough	NOISE/VIBRATION	2HSFMAHRSYC032039	284297	300000	WATER INTRUSION ALON	Invalid	
	NO INFO				UNKNOWN	Inconclusive	
Broken	BROKEN	1FUPCSZB5YPB82016	308355	350000	LOW CLAMP LOAD	Invalid	
Binds & Sticks - Leaking	LEAK	1FUYSDYB4XPA31291	331718	350000	NO PROBLEM FOUND	Invalid	
Hub bearing broken	BROKEN/SEPARATED	1FUYSSEB4YPP80354	233800	250000	IB SEAL LEAK - INGRESS	Valid	
Front axle hub loose	LOOSE HUB	1FUYSSZB1YLB54028	386207	400000	IB SEAL LEAK - INGRESS	Valid	
Noise/tire wear	NOISE/VIBRATION	2HSCTNAER8YCO53562	145715	150000	NO PROBLEM FOUND	Invalid	
Binds & sticks	BIND/STICK	1FUYSDYBXYLA55449	258767	300000	LOW CLAMP LOAD	Invalid	
Bearing failure	BEARING FAILURE	1XP5D69X44YD509427	304476	350000	UNKNOWN	Inconclusive	
Seal Leak	LEAK	2HSFHAIMRSYC024047	11821	50000	IB SEAL LEAK - EGRESS	Valid	
Worn	WORN BEARING/HUB	2HSFTAERXYC043108	188851	200000	IB SEAL LEAK - INGRESS	Valid	
	NO INFO				IB SEAL LEAK - INGRESS	Valid	
Front axle bearing worn	WORN BEARING/HUB		403200	450000	IB SEAL LEAK - INGRESS	Valid	
LS hub faulty	BEARING FAILURE		346177	350000	WATER INTRUSION ALON	Invalid	
Front axle, hub bearing nois	NOISE/VIBRATION	1FUYSSSEB3YLA80791	308528	350000	IB SEAL LEAK - INGRESS	Valid	




Steer Hubs Only

SKF 002088

Includes all weeks even when trailer hubs made

Boxplots of Warranty by YrMonth

(means are indicated by solid circles)



One-way ANOVA: Warranty vs Month
Includes all weeks even when trailer hubs made

Analysis of Variance for Warranty

Source	DF	SS	MS	F	P
YrMonth	18	98.91	5.50	4.45	0.000
Error	555	684.74	1.23		
Total	573	783.65			

Individual 95% CIs For Mean

Based on Pooled StDev

Level	N	Mean	StDev	(-----+-----)
199806	30	0.133	0.346	(-----+-----)
199807	31	0.097	0.396	(-----+-----)
199808	31	0.806	0.980	(-----+-----)
199809	30	1.167	1.234	(-----+-----)
199810	32	0.156	0.369	(-----+-----)
199811	30	0.500	0.974	(-----+-----)
199812	31	0.323	0.832	(-----+-----)
199901	29	0.862	1.187	(-----+-----)
199902	26	0.308	0.618	(-----+-----)
199903	31	1.194	1.682	(-----+-----)
199904	30	1.067	2.243	(-----+-----)
199905	28	1.500	2.317	(-----+-----)
199906	31	0.742	0.815	(-----+-----)
199907	31	0.290	0.529	(-----+-----)
199908	32	0.094	0.296	(-----+-----)
199909	31	0.806	1.014	(-----+-----)
199910	31	0.194	0.477	(-----+-----)
199911	31	0.581	1.119	(-----+-----)
199912	28	0.321	0.863	(-----+-----)

(-----+-----+-----+-----+-----)


Pooled StDev = 1.111 0.00 0.60 1.20 1.80

SKF 002080

Includes all weeks even when trailer hubs made


Boxplots of Warranty by YrWeek

(means are indicated by solid circles)




Includes all weeks even when trailer hubs made

Warranty Claim Proportion by Year/Week



Includes all weeks even when trailer hubs made




Includes all weeks even when trailer hubs made
Analysis of Warranty by Hub Production Date 6/26/02

Claims By Calendar Date

Warning - Data includes SKF analyzed with hub production date

Excludes all other data. Selection bias possible.



Response

to Main Document

Rick P Morrow/AMER/SKF
07/19 11:31 AM

Subject: R-Safe Seal yield from Bethlehem
Response to: Statistical Evaluations
Category: Statistics

 Rick P Morrow
07/18/2002 11:06 AM

To: Robert J Bondy/DET/SKF@SKF
cc: Juergen Schultheis/SCH/SKF@SKF, Christopher Jones/AMER/SKF@SKF, Bernd Stephan/SCH/SKF@SKF, William J Farrel/ELG/SKF@SKF, Aurelio Nervo/VLN/SKF@SKF, Richard W Frett/ELG/SKF@SKF, Edward F Cotter/AMER/SKF@SKF, Bruce Weeks/AMER/SKF@SKF, Michael D Lewis/DET/SKF@SKF

Subject: Re: notification to the customer of R-safe defect rate.

The potential failure rate of hubs in the future is what you are asking, I believe for Chuck. Given that water ingress is a factor and exposure to water is required for the majority of the hub failures, 2% may be reasonable. If the probability of failure of the R-Safe Bethlehem hub is no worse in the earlier lots than the lots we sampled, the failure rate is no greater than the total warranty return rate.

However, we should clarify that the yield on the R-Safe seal is different than the 2% according to Elgin's study of the Bethlehem seal.

Here is why. However, the seals themselves show a higher failure rate than the 2% mentioned. The defective seals from Bethlehem and sufficient water prior to self-healing I could not reproduce the 2% number. I believe Bob's mention of a 50 piece sample below was Hans Kirch's small sample of 50 seals of unknown origin having 1 defect.

Don Nowak, Engineering Manager at Elgin, and I estimate 12% for potential functional defects with water exposure early in the life of the seal (Bob's comment on self-healing is a very factual and important addition to any statement on potential failure rate.) I also recommend that we mention other factors must be present to result in failure. The number one factor is probably sufficient water exposure prior to self-healing.

Again - no one has been able to provide samples from earlier Bethlehem lots to project probability of failure from all Bethlehem production. Self-healing of the defects we have seen, luckily, have probably occurred by now on those seals.

Our study is below. Please call me for any clarification or support.

 Rick P Morrow
07/09/2002 08:59 AM

To: Michael D Lewis/DET/SKF@SKF, William J Farrel/ELG/SKF@SKF, David M Simms/ELG/SKF@SKF
cc: Richard W Frett/ELG/SKF@SKF

Subject: Probability of R-Safe failures in the field. Follow-up to the "2%" finding.

As you can read below, I would like to assist us in answering Chuck Smith's questions on the R-Safe Bethlehem seals in a timely manner. He specifically asked me to ensure SKF is telling him the number of R-Safe seals from Bethlehem that may cause problems. The best estimate Don Nowak and I have is 12% from the sample from Bethlehem that Elgin received. This is a higher number than what Hans and Juergen have suggested. I state that this may not represent the population of seals because we have not received samples across all production lots.

The other question you all know is when will SKF validate the root causes of the hub units? I sent my suggestions earlier.

What can I do to support us with Chuck? I will be available to discuss how Chuck may react to this info on the R-Safe and what we can do to mitigate issues.

Forwarded by Rick P Morrow/AMER/SKF on 07/09/2002 08:45 AM



Rick P Morrow
07/05/2002 11:03 AM

To: Juergen Schultheis/SCH/SKF@SKF
cc:

Subject: Probability of R-Safe failures in the field. Follow-up to the "2%" finding.

Juergen, I am afraid that Class is out and you need this latest info now. I have not sent this to Aurelio or to Hans.

Please contact me so we can discuss.

Thanks,

Forwarded by Rick P Morrow/AMER/SKF on 07/06/2002 10:58 AM



Rick P Morrow
07/03/2002 09:37 AM

To: Class Rehmberg/GHQ/GOT/SKF@SKF
cc: Richard W Frett/ELQ/SKF@SKF

Subject: Probability of R-Safe failures in the field. Follow-up to the "2%" finding. □

The 5 sample that Aurelio has was from the 100 piece random from the known bad 429 sample of the 529 population sample from the 4,000 Bethlehem inventory. 3 of the 100 samples were later eliminated from the survey because they may have been damaged during the sampling.

SKF 002096

Therefore, these seals were considered defective and Aurelio was to reproduce that finding or reject.

The greater percentage of failures evidenced from the leaktest are from the cut primary lip cause. If the leaktest best reproduces the impact on the truck performance, then cut lip alone is sufficient to cause ingress of air and presumably water.

25 of 97 seals from the Bethlehem sample noted above failed leak test.

8 of these had both axial and primary lip functional defects.

4 seals had only axial lip defects.

21 of the 25 had the cut lip defect (Note that these may also be included in the 8 with both lip defects).

If the water ingress failure mode is of major concern, then this mode is only expected for the 4 + 8 seals with the axial lip failure. Having only a primary lip failure would not be expected to result in the water ingress failure in the field when the axial lip is not defective. This suggests the more probable root cause of water ingress is an axial and/or axial and primary lip defect. The probability is 12/97 = 12.4%.

We still can not be confident of this probability across all Bethlehem production because we only sample one lot produced by Bethlehem and the axial lip defects could be set-up dependent, operator dependent and other non-random dependent.

The leaktest fills the cavity between the axial and primary lip area. This is the best known method to reproduce a sealing failure. The MSA has proven leaktest is capable knowing that severely defective seals result in discrimination issues within n MSA of this type. It is not known if all leaktest failures would 100% result in field failures. Again, it is the best reproduction known and is used by seal manufacturers and customer in a variety of applications.

Robert J Bondy



Robert J Bondy
07/18/2002 10:29 AM

To: Juergen Schultheis/SCH/SKF@SKF, Christopher Jones/AMER/SKF@SKF, Rick P Morrow/AMER/SKF@SKF, Bernd Stephan/SCH/SKF@SKF, William J Ferrell/ELG/SKF, Aurelio Nervo/VLN/SKF@SKF, Richard W Frey/ELG/SKF@SKF, Edward F Coker/AMER/SKF@SKF
cc: Bruce Weeks/AMER/SKF@SKF, Michael D Lewis/DET/SKF@SKF

Subject: notification to the customer of R-safe defect rate.

Gentlemen

Chuck Smith wants an answer to the R-safe spill rate from Bethlehem.

Unless otherwise instructed this is what I'm going to tell Mr. Smith

Our estimate of the exposure rate is 2% maximum that leaked into the field. We conducted two independent evaluations on samples of 50 and found 1 piece in each sample with a two lip defect. Because of the self healing properties of the seal we expect the number of failures related to the seal to be less than 2%. The total population is 99093 seals which means we expect a maximum of 2000 hubs to fail early.

SKF 002097

We propose that we increase inspections on these items to every 50,000 miles per TP0251. Southwest research is indicating that we will be able to detect these failures.

Bob

Forwarded by Robert J Bondy/DET/SKF on 07/18/2002 11:04 AM
Charles.Smith@ArvinMeritor.com on 07/17/2002 10:42:56 AM



To: Robert.J.Bondy@skf.com
cc: Thomas.Sanko@ArvinMeritor.com, Dale.Bell@ArvinMeritor.com
Subject: Data



FF981 Database Analysis, da.

Bob

Attached are the most recent charts for Aiken Failures. Worksheet one (charts in this sheet) and two are up to date through yesterday, the rest have not been updated.

The charts show a serious increase in R-Safe seal failures. Based on implementation date for this seal and Aiken production dates, it appears that the failures begin with the implementation date of the seal. This indicates that the degradation of the seal molding tool had little to do with the failure mode, as the failures began with the first production run. Note on the rate chart that the worst R-safe rate is approaching the worst period in May 1999 for axial clearance failures, and the data indicates that these failures are all low mileage.

I must impress on you that ArvinMeritor needs to know the exposure that this defect will give us based on the acceptance criteria used at CR Bethlehem. We need to know the estimated spill rate. We need it now, more delays can not be tolerated.

Chuck

SKF 002098

<<FF981 Database Analysis, clz.xlsx>>

SKF 002099

Response

to Main Document

Rick P Morrow/AMER/ SKF
07/22 12:04 PM

Subject: R Safe Leaktest MSA
Response to: Statistical Evaluations
Category: Statistics



THU R Safe MSA.ppt

SKF 002100

Gage R&R for Leak Test R-Safe Elgin

Results for: Worksheet 6

Attribute Gage R&R Study

Attribute Gage R&R Study for Data

Date of study: 7/16/02

Reported by: D. Nowak

Name of product: R Safe

Misc:

Within Appraiser

Assessment Agreement

Appraiser #	Inspected #	Matched	Percent (%)	95.0% CI
Don	8	8	100.0	(68.8, 100.0)
Karen	8	8	100.0	(68.8, 100.0)

Matched: Appraiser agrees with him/herself across trials.

Between Appraisers

Assessment Agreement

# Inspected	# Matched	Percent (%)	95.0% CI
8	8	100.0	(68.8, 100.0)

Matched: All appraisers' assessments agree with each other.

Response
to Main Document

Rick P Morrow/AMER/SKF
10/09 02:08 AM

Subject: THU Proportion of claims Vs Alken Production Date
Response to: Statistical Evaluations
Category: Statistics



Steer THU RM Oct 2002 and 6 27.;

THU Steer Analysis

10/8/02

Includes June 2002 analysis

Warranty Problems from 6/1/98 –
12/31/99

Data Sources

Aiken production quantities by type of hub by month

Warranty info refreshed 10/02 by Bob Bondy, Mike Lewis and
others against

Aiken Hub Production Date

Hypotheses

1. Null H_0 : There are no significantly higher proportions of warranty problems by Aiken Hub production date. Specifically highlighting July – Sept. 1998 and April, May 1999

H_a : There are significantly higher proportions


This study again confirmed reason to reject the null. These dates correlate with higher proportions of claims than other dates before and after.

1. Null H_0 : The mean miles to failure is independent of date of hub production

H_a : The mean miles to failure is not independent of date of hub production


This study again confirmed reason to reject the null. The mean miles to failure correlate with these suspect dates Vs dates before. Control Group included only dates before the Suspect Group due to probability immaturity would eventually show lower Mean miles to failure.

Count of Claims by Year and Month




Defect	Count	Percent	Cum %
1998/05	104	21	21
1998/04	50	10	31
1998/08	42	8	39
1998/03	37	7	47
1998/09	33	7	54
1998/01	31	6	60
1998/06	29	6	66
2001/02	26	5	71
1999/11	22	4	75
1999/07	21	4	79
1998/11	13	3	82
1999/10	10	2	84
2000/05	8	2	86
1998/12	8	2	87
2000/12	7	1	89
2000/03	7	1	90
1999/02	7	1	92
2000/10	6	1	93
2000/01	6	1	94
2000/11	5	1	95
Others	20	4	100

P Chart Proportion Claims Against Hub Production Qty for Aiken Production Year Month




P Chart Proportion of Claims Against Hub Production Qty for Aiken Production Year Month Week



Conclusion:
Reject null and accept
alternative that there
are weeks of
significantly higher
proportions of claims
evidenced by
proportions beyond
upper control limits.

$$\begin{aligned}UCL &= 0.006941 \\ \bar{P} &= 0.002971 \\ LCL &= 0\end{aligned}$$

P Chart Proportion Claims Against Hub Production Qty for Aiken Production Day




SKF 002108

Mean Time To Failure

Significantly

(means are indicated by solid circles)



Null Hypothesis: Mean Miles to Failure independent of Days of April 20-22 and May 3-7 of 1999 than all other Dates Prior to April, 1999

One-way ANOVA: MILES versus Group

P<.05, therefore reject Null. Mean Miles to Failure
are not independent of periods. April and May of
1999 has lower mean miles to failure than dates prior.

Analysis of Variance for MILES

Source	DF	SS	MS
Group	1	2.735E+11	2.735E+11
Error	301	6.014E+12	1.998E+10
Total	302	6.288E+12	

F	P
13.69	0.000

Individual 95% CIs For Mean


Based on Pooled StDev

Level	N	Mean	StDev	-----+-----+-----+-----	(-----*-----)	
Control	188	428466	150486	-----+-----+-----+-----	(-----*-----)	
Suspect	115	366553	124929	(-----*-----)	-----+-----+-----+-----	
				360000	390000	420000

Suspect = April 20-22 – May 3- 7, 1999

SKF 002110

Histogram of the Residuals
(response is MILES)




SKF 002111

Analysis 10/8/02

- Reject the Null Hypotheses and Accept Alternatives. Therefore, proportion of claims is not independent of Aiken production date.
- Confirms April 20, 1999, May 3, 1999 and other dates within these weeks had significantly higher proportions in claims than other periods.
- This is a correlation only with this data – does not mean causation

\bar{u} Chart Count of Claims Vs Monthly Production Steer Claims Only



Hub Production Dates


199903

● Issue Date of ARM Engineering Deviation Request
Correlation study of hubcaps under deviation with high warranty periods

● Issue date of Hub & Stud Assy ARM EDR

SKF 002113

u Chart Count of Claims Vs Monthly Production Steer Claims Only



Hub Production Dates


199903

● Issue Date of ARM Engineering Deviation Request minus one month.


Correlation study of hubcaps under deviation with high warranty periods

● Issue date of Hub & Stud Assy ARM EDR minus one month

u Chart Count of Claims Vs Monthly Production



u Chart Count of Claims Vs Monthly Production



SKF 002116

Analysis 6/27/02

- Mike Lewis requested analysis of Chuck Smith's suggestions that "Aiken" had several periods of high failure. In addition, Chuck and Mike have requested help in determining hubs to retrieve from high warranty production periods. These answers are possible if someone can identify hubs within vehicle.
- Duane Gipe months ago identified several time periods that had a higher proportion of claims
- This study supports both analysts using the hub production date from the SKF analyzed returns database of only those claims when production date is listed. Therefore, there may be a selection bias. The Null hypothesis H01 is rejected.
- One or more parties (ARM, Aiken and Luechow) experienced abnormal variation during several weeks.
- I added the comments, root cause from SKF work and whether the claim was validated to support decisions on true root cause.
- Other hypotheses were tested and included. Sunday has a higher proportion of claims, for instance.
- Axial clearance hypothesis requires data on gage maintenance.
- Six Sigma analysis includes SPC and hypothesis testing. Further analysis is possible when data is available.
- FMEA is again recommended to direct root cause analysis

Chuck believes Aiken produced hubs went through two and maybe three periods of higher than normal failure rates. Julian dates 12098 -27398, 11099 - 14099 and possibly Aug and Sep 1999.

His hypothesis is an axial clearance gage cycled into a wear pattern after recalibrating. This gage was eventually permanently corrected and the higher than normal failure rates ceased. He believes this permanent correction occurred in November.

He described a peak and valley cycle in the axial clearance.

Null Hypotheses

Ho1: No time periods correlate with significantly higher warranty claims Vs Production Quantities


Ho2: Axial clearance gage performance does not affect proportion of claims

- **Data Concerns/Notes**
 - Selection bias may be present because claims missing build dates were excluded.
 - I have received no process measurement data to assist in identifying variation in Aiken.
 - Several claims were posted against hub build dates that showed zero production. Several analyses were run and this error was insignificant.
 - Immature data for periods after these studied due to Mean Time to Failure
 - Luechow hubs are included in one high proportion time period
 - Databases used were Aiken production quantities by day, the SKF analyzed returns database and the ARM database of 2,200 claims.
 - Claims were also shown for hub build dates that were identified as producing only trailer hubs.
 - No data is available from suppliers that may be tested for variation and correlation with claims.

Duane Gipe's original chart


Claims Vs Produced

Limits Based on Dates Up To 19910




Analysis Begins 6/27/02

**u Chart Count of Claims Vs Monthly Production
Steer Claims Only**




Warranty Claim Proportion by Year/Week




SKF 002122

Warranty Claim Proportion by Day Steer Only - Note some warranty on dates showing zero steer produced. Changeover to Steer Mentioned and Next



Steer Production Dates Only

Warranty Claims by Day



Day 8/27/98

BTF-0052	0016245	08/27/98	3	1998	Aiken	Frithr	Ryder	CWA00159
BTF-0052	016439	08/27/98	3	1998	Aiken	Frithr	Ryder	CWA00154
BTF-0049	0015726	08/27/98	3	1998	Luechow	Frithr	Ryder	318273
BTF-0049	0015966	08/27/98	3	1998	Luechow	Frithr	Ryder	318277

Noise in bearing	NOISE/VIBRATION	1FUYDDYB0XLA70915	400210	500000	IB SEAL LEAK - INGRESS
Wheel bearings were failed	BEARING FAILURE	1FUYDDYB3XLA70908	351267	400000	IMPACT DAMAGE
	NO INFO	1FUYDDYB4XLA70917	369097	400000	IMPACT DAMAGE
	NO INFO	1FUYDDYB6XLA70921	418370	450000	WATER INTRUSION ALON

IB brg row water content 0.49%, brg ctr 0.12%	Valid
Line spalling of IB IR at loaded zone	Invalid
Rec'd disasm, OB row G, IB row line spalls at roller spacing	Invalid
Endplay 0.000", jerky rotation, OB row met debris, IB row VG, IB seal func	Invalid

Week 39 1998

Day of Week	Hub Production Date		Claims				Total Daily	Proportion of Claims
				3rd	1st	2nd		
Sunday	9/20/1998		1 No Steer	*	*	63	180	223 0.4484%
Monday	9/21/1998		4 No Steer	*	38	91	80	207 1.9324%
Tuesday	9/22/1998	Honer down	1 No Steer	*	0	0	120	0.8333%
Wednesday	9/23/1998		1 No Steer	*	136	174	76	386 0.2591%
Thursday	9/24/1998		3 No Steer	*	129	94	122	345 0.8896%
		Drill Operation down 2nd shift	2 No Steer	*	176	7	84	267 0.7491%
Friday	9/25/1998		3 No Steer	*	86	72	99	257 1.1673%
Saturday	9/26/1998	Grinder & Honer down	3 No Steer	*	*	*	0	0 *
Sunday	9/27/1998							
BTF-0052	0022910	09/20/98	3	1998	Aiken	Frtlnr	Ryder - Ashland City	0031499
BTF-0052	0022921	09/21/98	3	1998	Aiken		Ryder	Unit 329665
BTF-0052	0022922	09/21/98	3	1998	Aiken		Ryder	Unit 329668
BTF-0049		09/21/98	3	1998	Luechow	Frtlnr	Mox Trkg	CHE08413 1/2
BTF-0049	001087	09/21/98	3	1998	Luechow	Frtlnr	Mox Trkg	CHE08457
BTF-0049	0023434	09/22/98	3	1998	Luechow	Frtlnr	Mox Trkg	CHE08413 2/2
BTF-0052	0024551	09/23/98	3	1998	Aiken	Navistar	Andrews Trucking	0088168A
BTF-0052	0027234	09/24/98	3	1998	Aiken	Frtlnr	Mike Newsome	HLFD0001E450T
BTF-0052	0024343	09/24/98	3	1998	Aiken	Navistar	Vision Transp.	089158A
BTF-0049	M222432	09/24/98	3	1998	Luechow	Navistar	G&P Trucking	0041874D
BTF-0052	0024014	09/25/98	3	1998	Aiken	Frtlnr	Interstate	DWFD0001F334T
BTF-0052	0023918	09/25/98	3	1998	Aiken		Ryder	Unit 329654
BTF-0052	0024707	09/26/98	3	1998	Aiken	Frtlnr		E1703119 1/2
BTF-0052	0024841	09/26/98	3	1998	Aiken	Frtlnr		E1703119 2/2
BTF-0052	0024231	09/26/98	3	1998	Aiken		Ryder	Unit 329670 2/2
BTF-0052	0024453	09/27/98	3	1998	Aiken		Ryder	Unit 329664
BTF-0052	0024430	09/27/98	3	1998	Aiken		Ryder	Unit 329666
BTF-0052	0024434	09/27/98	3	1998	Aiken		Ryder	Unit 32967D 1/2

SKF 002126

9/20 – 9/27/98 Week 199839

continued

Seized	SEIZED	1FUYSDYB6XLB06901	275376	300000	IB SEAL LEAK - INGRESS
Inspect wheel speed sensor	TORQUE RING BROKEN/LC	B06907	470504	500000	IB SEAL LEAK - INGRESS
Inspect inner bearing, front	NON-SPECIFIC	B06900	490155	500000	IB SEAL LEAK - INGRESS
Bearing Failure	BEARING FAILURE	1FUYSCBXX0L973976	507114	600000	NO PROBLEM FOUND
	NO INFO				NO PROBLEM FOUND
Bearing Failure	BEARING FAILURE	1FUYSCBXX0L973976	507114	600000	OUTER RING SPALL
Lube leaking from RF hub	LEAK	2H5FMAMIR5XC025337	226063	250000	OIL SEPARATION
Noisy, Rattles	NOISE/VIBRATION	1FUYSDYB30PA97087	348506	350000	NO PROBLEM FOUND
Loose	LOOSE	2H5FMAMER1XC020744	213676	250000	NO PROBLEM FOUND
Wheel seal leaking	LEAK	2H5FMAMHR3JC0253573	180681	200000	IB SEAL LEAK - EGRESS
Bands & sticks	BANDSTICK	1FUYSDYB6XLB06901	356803	400000	UNKNOWN
	NO INFO	B06908	286792	300000	IB SEAL LEAK - INGRESS
Leaks	LEAK	1FUPCS2B5XL1A12620	363143	400000	NO PROBLEM FOUND
Leaks	LEAK	1FUPCS2B5DLA12620	363143	400000	NO PROBLEM FOUND
	NO INFO	B06902	506895	550000	IB SEAL LEAK - INGRESS
	NO INFO	B06908	402780	450000	IB SEAL LEAK - INGRESS
	NO INFO	B06906	318801	350000	IB SEAL LEAK - INGRESS
	NO INFO	B06902	506895	550000	IB SEAL LEAK - INGRESS

Endplay 0.000°, noisy, fine spalls IB OR RW, IB seal dust lip worn out	Valid
Endplay 0.020°, noisy, OB seepage ~2.0 g, oil separation, IB cage melted	Valid
Endplay 0.000°, smooth rotation, very clean seals, appears to be corrosion	Valid
Endplay 0.000°, smooth quiet rotation, IB & OB brg rows VG, IB seal func	Invalid
Endplay 0.000°, smooth quiet rotation, IB & OB brg rows VG, IB seal func	Invalid
Endplay 0.000°, smooth quiet rotation, OB row VG, IB OR RW single line	Valid
EP 0.000°, smooth rotation, no internal distress, very little extra grease in	Valid
OB seepage ~1.5g, IB dry, endplay 0.000°, smooth quiet rotation	Invalid
Endplay 0.000°, smooth quiet rotation, OB seepage <2.0 g, IB <1.0 g	Invalid
Hub OD covered in grease and dirt,	Valid
IB row seized, OB heel damaged - melted cage & blued, IB rollers ends p	Inconclusive
Endplay 0.000°, rotation stiff, no noise, OB IR spell multi loc. around ring,	Valid
Endplay 0.000°, smooth rotation, no internal distresses(Troy Lab determinati	Invalid
Endplay 0.000°, smooth rotation, no internal distresses(Troy Lab determinati	Invalid
Endplay 0.000°, smooth rotation, IB OR spell multi loc., appears to be cor	Valid
Rec'd disease., OB IR spell, IB seepage ~2.0 g, IB OR RW spell line 360	Valid
Endplay 0.000°, smooth rotation, corrosion in OB row, OB seepage ~2.0g	Valid
Rec'd disease., IB IR missing, IB OR RW spell multi loc., appears to be cor	Valid

4/18/99 – 4/24/99 Cont

Week 17 1999

		Changeov										
Monday	4/19/1999	er to Steer		3	No	Steer	*	0	0	87	87	4.4776%
Tuesday	4/20/1999			9	No	Steer	*	239	295	262	796	1.1307%
Wednesday	4/21/1999			5	No	Steer	*	340	275	294	909	0.5501%
Thursday	4/22/1999			2	No	Steer	*	320	298	180	796	0.2513%
Friday	4/23/1999			1	No	Steer	*	200	134	210	544	0.1838%
Saturday	4/24/1999			0	No	Steer	*	*	*	*	0	*

BTF-0052	0126613	04/19/99	2	1999	Aiken	Navistar	Trucks Inc. of Janesville	CWA08206
BTF-0052	0121704	04/19/99	2	1999	Aiken	Navistar	WalMart	Unit 91069
BTF-0052	0121945	04/19/99	2	1999	Aiken	Navistar	WalMart	Unit 9711
BTF-0052	0122948	04/20/99	2	1999	Aiken	Frlnr	Ryder	E17248208
BTF-0052	0127740	04/20/99	2	1999	Aiken	Frlnr	KLLM	E1744815
BTF-0052	0121708	04/20/99	2	1999	Aiken	Navistar	WalMart	Unit 91058
BTF-0032	0122092	04/20/99	2	1999	Aiken	Volvo	FII-Mor Express	CWA01737
BTF-0052	0121402	04/20/99	2	1999	Aiken		Ryder	Ryder Unit # 337287
BTF-0052	M121626	04/20/99	2	1999	Luechow	Frlnr		BPFD0001A182T
BTF-0052	0122112	04/20/99	2	1999	Aiken	Navistar	WalMart	WMT91492 2/2
BTF-0052	0122110	04/20/99	2	1999	Aiken	Navistar	WalMart	WMT91492 1/2
BTF-0052	0122124	04/20/99	2	1999	Aiken	Navistar	WalMart	WMT91509
BTF-0052	122933	04/21/99	2	1999	Aiken	Frlnr	Heartland Express	E1692195
BTF-0052	0122545	04/21/99	2	1999	Aiken	Frlnr	Heartland Express	E1720710
BTF-0052	0122935	04/21/99	2	1999	Aiken	Frlnr	Ryder	348806
BTF-0052	0123027	04/21/99	2	1999	Aiken		Ryder	33623
BTF-0052	0122896	04/21/99	2	1999	Aiken	Frlnr		CWA09666
BTF-0052	0123651	04/22/99	2	1999	Aiken	Navistar	WalMart	Unit 91287
BTF-0052	0123972	04/22/99	2	1999	Aiken	Navistar	Fleet Pride	Unit 3038
BTF-0052	0124025	04/23/99	2	1999	Aiken		Ryder Unit 334749	33614

4/18/99 – 4/24/99 Cont

NOISE/VIBRATION	2HSCHASR1YC068278	277648	300000	IB SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	2HSPFMAMR4YC029364	280250	300000	IB SEAL LEAK - INGRESS	Valid
ENDPLAY/LOOSE	2HSPFMAMR5YC029700	346249	350000	LOW CLAMP LOAD	Invalid
BIND/STICK	1FLYSDYBXYLF38978	588523	600000	UNKNOWN	Inconclusive
LEAK	1FLYSDYZBYL787534	304850	350000	NO PROBLEM FOUND	Invalid
NOISE/VIBRATION	2HSPFMAMRXYC029353	289151	300000	IB SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	4V4ND2UF6YN788380	356930	400000	IMPACT DAMAGE	Invalid
NO INFO				IB SEAL LEAK - INGRESS	Valid
NO INFO				NO PROBLEM FOUND	Invalid
BEARING FAILURE		146540	150000	IB SEAL LEAK - INGRESS	Valid
BEARING FAILURE		146540	150000	IMPACT DAMAGE	Invalid
BEARING FAILURE		195398	200000	IB SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	1FLYSDYB5YCA93280	249423	250000	WATER INTRUSION ALON	Invalid
LEAK	1FLYSDYBYLB91578	311918	350000	IB SEAL LEAK - INGRESS	Valid
NO INFO	1FLYSDYE3YLF38977	591544	600000	IB SEAL LEAK - INGRESS	Valid
NO INFO	4V4ND1JF1YN793198	615339	650000	IB SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	4V4ND1UF9YN788433	351894	400000	IB SEAL LEAK - INGRESS	Valid
NOISE/VIBRATION	2HSPFMAMR5YC030216	260100	300000	IMPACT DAMAGE	Invalid
BROKEN/SEPARATED	EX0023080DOM			UNKNOWN	Inconclusive
NO INFO	1FLYDDYBOYP885713	526459	550000	IB SEAL LEAK - INGRESS	Valid

Week 19 5/2/99 – 5/7/99


Week 19 1999

Sunday	5/2/1999	1 No Steer	*	*	*	*	0	*
Monday	5/3/1999	6 No Steer	*	57	350	176	583	1.0292%
Tuesday	5/4/1999	8 No Steer	*	259	264	217	740	1.0811%
Wednesday	5/5/1999	5 No Steer	*	300	265	358	923	0.5417%
Thursday	5/6/1999	7 No Steer	*	302	280	289	871	0.8037%
Friday	5/7/1999	1 No Steer	*	0	251	274	525	0.1905%

BTF-0052	0128893	05/02/99	2	1999	Aiken	Frtlnr		E1748129	Valid
BTF-0052	0128110	05/03/99	2	1999	Aiken	Frtlnr		86762	Invalid
BTF-0052	128126	05/03/99	2	1999	Aiken	Frtlnr	Empire Truck Sales	CWA06549	Valid
BTF-0052	128021	05/03/99	2	1999	Aiken	Frtlnr		E1741061	Invalid
BTF-0052	0128019	05/03/99	2	1999	Aiken	Frtlnr		E1682210	Valid
BTF-0052	0128460	05/03/99	2	1999	Aiken		McKenzie Tank Lines	R.O. 49442	Valid
BTF-0052	128096	05/03/99	2	1999	Aiken	Frtlnr		CWA07488	Invalid
BTF-0052	129302	05/04/99	2	1999	Aiken	Frtlnr		E1674449	Invalid
BTF-0052	0129348	05/04/99	2	1999	Aiken	Frtlnr	Tim Mallard/CR Engle	E1525550	Valid
BTF-0052	128849	05/04/99	2	1999	Aiken	Frtlnr	Zuran Petrie	E1752443	Invalid
BTF-0052	129277	05/04/99	2	1999	Aiken		Martin Lipe	86102	OPEN
BTF-0052	0170218	05/04/99	2	1999	Aiken	Mack	Tom Bailey Motors	CWA04353	OTHER
BTF-0052	128683	05/04/99	2	1999	Aiken	Frtlnr	Roehl Transport	CWA07839	Valid
BTF-0052	128691	05/04/99	2	1999	Aiken	Frtlnr	Roehl Transport	CWA07839	Invalid
BTF-0052	0129180	05/04/99	2	1999	Aiken		KLLM		Inconclusive
BTF-0049	0130080	05/05/99	2	1999	Aiken	Frtlnr		E1889451	Invalid
BTF-0032	004339	05/05/99	2	1999	Luechow	Frtlnr		NSFD00016T43T 1/2	Invalid
BTF-0052	129813	05/05/99	2	1999	Aiken	Frtlnr	Bar None	E1689062	Valid
BTF-0052	0129943	05/06/99	2	1999	Aiken	Frtlnr	New Prime	E1750047	Valid
BTF-0052	0129637	05/05/99	2	1999	Aiken	Navistar	James Lifkin	0013495A	Invalid
BTF-0052	0130818	05/06/99	2	1999	Aiken	Frtlnr		E1682211	Invalid
BTF-0052	0130092	05/06/99	2	1999	Aiken	Ptlnit		CWA05961	Inconclusive
BTF-0052	0130507	05/06/99	2	1999	Aiken	Navistar	Hazmet Environmental	CCU00571	Valid
BTF-0052	0131322	05/06/99	2	1999	Aiken	Navistar		0042205B	Valid
BTF-0049	130922	05/06/99	2	1999	Aiken	Frtlnr		E1689133	Valid
BTF-0052	130662	05/06/99	2	1999	Aiken	Frtlnr	Harjit Singh	E1755522	Valid
BTF-0052	0131015	05/06/99	2	1999	Aiken	Frtlnr	CSS Transp	BNFD0001ME67T	Invalid
BTF-0052	131259	05/07/99	2	1999	Aiken	Frtlnr		E1752364	Valid

Week 19 5/2/99 – 5/7/99

	NO INFO						Valid
	NO INFO	1FUPC8ZBYLA88762	273985	300000	IMPACT DAMAGE	Invalid	
Bearing failure	BEARING FAILURE	1FUYDS2B3YLF06032	385007	400000	IB SEAL LEAK - INGRESS	Valid	
Chatter, noisy, vibration	NOISE/VIBRATION	1FUYSXBY0YL40034	381362	400000	TAMPERING	Invalid	
Corroded & rust	CORROSION/RUST	1FUYSXBY7YL40032	278902	300000	IB SEAL LEAK - INGRESS	Valid	
Noise and vibration in front	NOISE/VIBRATION	M1AA12Y6YW123699	208797	250000	IB SEAL LEAK - INGRESS	Valid	
	NO INFO				UNKNOWN	Invalid	
Hub bearing binds & stick	BIND/STICK	1FUYDDYBGYLB05748	191161	200000	WATER INTRUSION ALON	Invalid	
Too much play/leaking	ENDPLAY/LOOSE	1FUYSDYB6WP817798	304315	350000	UNHARDENED RW	Valid	
Hub bearing broken	BROKEN/SEPARATED	1FUYSSZB5YLA92032	346050	350000	UNKNOWN	Invalid	
Hub bearing noisy & rattle	NOISE/VIBRATION	1FUYSSZBXYLB86102	460061	500000	OPEN	OPEN	
Seal leaking	LEAK	1M1AA18YXYW121483	251048	900000	IB SEAL DAMAGED	OTHER	
Hub bearing rough	NOISE/VIBRATION	2HSFMAHR5YC032039	284297	300000	IB SEAL LEAK - INGRESS	Valid	
Hub bearing rough	NOISE/VIBRATION	2HSFMAHR5YC032039	284297	300000	WATER INTRUSION ALON	Invalid	
	NO INFO				UNKNOWN	Inconclusive	
Broken	BROKEN	1FUPC8ZB5YPB62018	308355	350000	LOW CLAMP LOAD	Invalid	
Blinds & Sticks - Leaking	LEAK	1FUYSDYB4XPA31291	331718	350000	NO PROBLEM FOUND	Invalid	
Hub bearing broken	BROKEN/SEPARATED	1FUYSSSEB4YPF80354	233800	250000	IB SEAL LEAK - INGRESS	Valid	
Front axle hub loose	LOOSE HUB	1FUYSSZB1YLB54929	386207	400000	IB SEAL LEAK - INGRESS	Valid	
Noise/tire wear	NOISE/VIBRATION	2HSCNAER9YCO53562	145715	150000	NO PROBLEM FOUND	Invalid	
Blinds & sticks	BIND/STICK	1FUYSDYBXYLA55443	258787	300000	LOW CLAMP LOAD	Invalid	
Bearing failure	BEARING FAILURE	1XP5D89X44YD509427	304478	950000	UNKNOWN	Inconclusive	
Seal leak	LEAK	2HSFHAMR5YC024047	11821	50000	IB SEAL LEAK - EGRESS	Valid	
Worn	WORN BEARING/HUB	2HSFTAERXYC043108	166851	200000	IB SEAL LEAK - INGRESS	Valid	
	NO INFO				IB SEAL LEAK - INGRESS	Valid	
Front axle bearing worn	WORN BEARING/HUB		403200	450000	IB SEAL LEAK - INGRESS	Valid	
LS hub faulty	BEARING FAILURE		348177	350000	WATER INTRUSION ALON	Invalid	
Front axle, hub bearing noi	NOISE/VIBRATION	1FUYSSSEB3YLA80791	308528	350000	IB SEAL LEAK - INGRESS	Valid	



Steer Hubs Only

SKF 002132

Response
to Main Document

Rick P Morrow/AMER/SKF
10/11 12:50 AM

Subject: Proportion Claims Against Alken Prod City. 8/98 - 2001
Response to: Statistical Evaluations
Category: Statistics

This is the additional 2000 and 2001 production and claim numbers to add to the earlier analysis. This data reproduces to most days the analysis from Arvin-Meritor. Peak days include May 3-7 and February dates in 2001/ The proportions may increase as vehicles age, especially the February dates.

Add this analysis to the earlier analysis.



THU Steer Analysis Oct 10 2002 Add to Earle

SKF 002133

THU Steer Analysis

10/10/02

See file dated Oct 9 for earlier analysis

Includes 10/8/02 and June 2002 analyses

Arvin Meritor Charts Included

Warranty Problems from 6/1/98 – 2001


Data Sources

Aiken production quantities by type of hub by month

**Warranty info refreshed 10/02 by Bob Bondy, Mike Lewis and others against
Aiken Hub Production Date**

DAILY


P Chart Proportion Claims Daily Against Hub Production Qty




Claim values are the x's. x's above the red line are statistically higher than expected.
Immature data likely excludes future claims against year 2000 and other dates

WEEKLY 1998 - 2001

P Chart Proportion Claims Weekly
Against Hub Production Qty
for Aiken Production



Proportion claims to net production. Source – Arvin Meritor



This chart combines data into half months. The peak periods agree with the analysis SKF did. The peak days are noted in the SKF daily chart.

Response

to Main Document

Michael D Lewis/DET/ SKF
10/15 06:26 PM

Subject: Failure rate by hub Julian date (Chuck Smith data)
Response to: Statistical Evaluations
Category: Statistics



FF981 Database Analysis, clb.

SKF 002138

ID	ALT?	HIGHLY PROGRESSIVE INCIDENTS	SKF / PS LAB COMMENTS	MILES
1 ?	YES		Steel tank; In board long row overheated	252622
2 L	YES		Rec hub, spindle IB and OB cones are seized to spindle; hub still on spindle due to nut spacer (lock ring) and outer nuts still on; spindle rec. drum, with shoes, rim and tire	824473
3 L	YES		Hub "fell off" when vehicle was jacked up, hub was received in Troy disassembled for circular scratches on inner race and faces (indicates no relative motion between the Hub off)	460547
4 L	YES			337133
5 L	YES		Hub separation from vehicle, failed hub assembly, spindle worn under inner races, groove worn in clip ring (Indication of relative motion between inner races); Hub off	468550
6 L	YES		No paperwork received with claim, complaint unknown, not a separation, hub was received in Troy disassembled, rust in outer bearing row, high water content in both IB	
7 L	YES		Rec hub, tire, rim, drum, spindle, customer used wheel saver; sent to SKF 4/2/02	060503
8 L	YES		Rec hub; IB and OB cones; clip ring and several burned up rollers; scrap 4/9/02	666624
9 L	YES		Hub bearing seized to knuckle spindle due to excessive heat	605417
10 L	YES		Clip ring grooved; rec hub burned up; IB & OB cone show signs of spinning rollers have heavy wear on axial end; inconclusive	
11 L	YES		Rec hub only; no bearings; bearing races are all rusty; burn up - R side	433307
			Received disassembled, badly damaged, IB or bell-mouthed, no rollers, cages, seals, or grease, very rusty, cannot determine origin of failure due to lack of parts and damage	
12 L	YES		Received disassembled, IB R's cut & split, spun on spindle, badly damaged, root cause not determinable	762914
13 L	YES		Rec spindle with IB and OB cones seized to spindle; no hub was received; scrap	461480
14 L	YES		4/8/02	600202
15 L	YES		Near wheel off	507448
16 L	YES		Burnt up; wheel bearing came apart; located. Bearing failure damaging drum and brakes, truck pulled to the right, had to replace left side brakes after bearing failure	264808
17 L	YES		1996 FTL Century; Hub off right side	646830
18 L	YES		15 rollers from OB; 16 last rollers from IB returned; both inner cones forced off spindle; not all pieces of IB inner cone ring returned; cannot determine if inner cones were cracked causing loss of clamp load; ob inner cone did not crack; burn up Drv too much play; 2 gears locked; _____ lacks; complete toast - unhardened roadway? Driver steer wheel bearing has too much play; both P hubs leaking; had to press hubs off wiper	491184
19 L	YES		Front wheel loose; truck towed to shop	504315
20 L	YES		Only hub was returned; HPI no inner cones or rollers; cone ring missing also	391184
21 ?	YES		Fire	488622
			Received disassembled, OR or IR grease seals rollers cages missing, OB spindle and heat damage, suspect OB row failure, IB row G considering damage, cannot determine origin of failure due to lack of components	265183
22 ?	YES		Hub, knuckle, drum, shoes, 3-com returned; inner cones still on spindle; scrap	482701
23 A	YES		Rec, hub and a few rollers and a badly damaged cone; IB and OB hub races are burned	0600093
24 A	YES		Fire; rec spindle (IB and OB cones seized on spindle) hub (burnt up); drum, shoes, rim and tire (burnt up); inconclusive 4/5/02	499157
25 A	YES		Sent to SKF 4/1/02	586273
26 A	YES		Smooth rotation, some water ingress after removal/had mixed in lubricant; Hub off; lost in pond (AVTF98161314)	350863
27 A	YES			087140
28 A	YES		Rec Hub and knuckle; hub still on spindle because of inner and outer nuts and lock ring still on spindle; near off; WARRANTY PAYMENT APPROVED; Burnt up; near wheel off	441028
29 A	YES		Rec hub, knuckle & drum; hub bearings burnt up; knuckle bearing cones seized to spindle	614956
30 A	YES		Rec hub only; burn up	555408
31 A	YES		Rec hub and knuckle cones seized to spindle; hub burnt up; inner and outer nuts and locking ring stop hub from coming off of spindle; near wheel off	
32 A	YES		Rec hub burnt up; inconclusive	320401
33 A	YES		IB inner cone spalled on bottom 180°; sent to SKF	415198
34 A	YES		IB inner cone spalled on bottom 180°; sent to SKF	155379
35 ?	YES		Received disassembled, IB row frost-dogs melted, seal lips burned away, OB row debris denied	447853
36 A	YES		Rec hub only; no bearing; bearing races burned up; burn up - L side	501725
37 A	YES		Hub returned; still on knuckle; a few rollers were returned; both inner cones fractured	294808
38 ?	YES		Hub burnt up	268802
			King pin R&R 100K miles previous; cannot accurately assess root cause; maybe loose; IR fractured	
39 A	YES		Near wheel off	520185
40 ?	YES		Near wheel off	143083
41 A	YES			
42 ?	YES		Rec'd disassembled, OR only, appears IB row failed first, cannot assign root cause	422238

SKF 002139

43 ?	YES	IB row seized; OB heat damaged-melted cage & bled; IB roller ends pegged; IB IR RW spall in line	396808
44 ?	YES	Rac hub burned up; Inconclusive; L side front wheel smoking (towed in); bearing failure on L front wheel damaging spindle & s-cam	
45 ?	YES	R front steer axle wheel bearing failure; progressive damage to hub, brake, steering knuckle, tie rod cross tube; ABS sensor & hub cap wheel bearing failed causing R hub to wobble violently damaging additional parts	
46 ?	YES	IB & OB CONE BURNED; NO OTHER BRG PART WERE RECEIVED; INCONCLUSIVE	
47 A	YES	Bearing burn up; hub, knuckle, drum returned; scrap	
48 A	YES	Hub burn up	482228
49 A	YES	Hub off	583429
50 A	YES	Rac disassembled; could not find cause of failure; rac knuckle/hub seized on it; clip has grooves from rotation of cup; cone faces have circular rotation witness marks; brg rollers have end wear, low clamp load	429615
51 A	YES	Rac hub & half bearing burned up; Inconclusive	
52 A	YES	Knuckle, drum, shoes, hub, kingpin, brake chamber, ASA	
53 A	YES	Knuckle returned with hub still on. Both inner cones fractured; put in box.	733819
54 A	YES	Near wheel off / or no drum & knuckle. Inner & outer brg cones are burnt up and seized to spindle; no hub returned	287309
55 A	YES	Rac hub burned up; rac one bearing cone; do not know if it is IB or OB; Inconclusive	
56 A	YES	Scrap 4/8/02	270498
57 ?	YES	Shipped to SKF for further inspection / Received disassembled, no internal components. OB row badly eroded, unhardened	262756
58 A	YES	Rac hub & knuckle; hub still on knuckle because of inner & outer nuts & lock washer still threaded to spindle	481016
59 A	YES	Near wheel off	582883
60 ?	YES	Hub off	583498
61 A	YES	Knuckle, hub returned; sent to SKF	309650
62 ?	YES	Rac disassembled, OB IR easy missing, some rust in hubcap threads Loose; unhardened raceway; bearing burn up. Hubs, front bearing misadjusted; L front hub shims; removed L front tire hub & drum; wheel bearing dry on grease & fell apart	268462
63 A	YES	Rac hub and knuckle, only thing stopping hub from coming off are the locking ring and inner and outer nuts (near off)	98900
64 A	YES	Rac spindle with both IB and OB cones seized to spindle; hub and a few rollers; Inconclusive	692708
65 A	YES	Hub returned still seized on knuckle; scrap	220365
66 A	YES	Sent to SKF	344209
68 A	YES	Hub, drum and shoes, knuckle returned; scrap	346060
70 A	YES	Knuckle returned with IB inner cone still attached; hub was returned; scrap	348211
71 ?	YES	Near wheel off	306145
72 A	YES	Near wheel off	327469
73 A	YES	Right side knuckle with hub still on, drums, shoes; scrap	398398
74 ?	YES	Fire; rac spindle; IB and OB cone seized to spindle; hub stayed on only because of inner and outer locking nuts; rac drum and shoes, rim and free near off; Inconclusive	
75 ?	YES	4/8/02	398172
76 ?	YES	Fire	
76 A	YES	Hub off	638239
77 A	YES	Knuckle, drum, hub, shoes returned; inner cones still on spindle; right side BOTH INNER CONES RETURNED UNCRACKED & HUB, KNUCKLE, TONE RING; SENT TO SKF	564889
78 A	YES	Left side knuckle, shoes, drums, hub; scrap	588423
79 A	YES	Rac hub & knuckle; both burnt up	579189
80 ?	YES	Unhardened raceway; could remove hub, or hub, spindle, brakes, drum	579730
81 A	YES	Rac hub; spindle, bearing rollers & cones burnt up; cone spinning on spindle; OB cone saw more heat than IB cone; rollers are distorted & burn up; OB cone has signs of high heat; slip ring grooved; lock off tube	80860
82 A	YES	Rac spindle (IB and OB cones spinning on spindle, cone cut off with cutting torch; burn up); rac line, rim, brake, drum and shoes and hub; Inconclusive 4/8/02	367060
83 A	YES	Knuckle and hub returned; wheel off; inner cones still on spindle	
84 L	YES	Sent to SKF 4/1/02	333882
85 ?	YES	Rac hub burned up; Inconclusive	331928
86 A	YES	Rac; rusty burned up hub, (1) Bearing was cut in half by cutting torch and was spinning on spindle; other bearing cone also cut off with torch but to rusty to tell if it was spinning on spindle.	385798
87 A	YES	Hub returned disassembled; only 13 rollers & both inner cones returned; clip ring is fractured; IB inner cones spelled on bottom half; guiding flange on both inner cones show excessive wear, both outer races have fine spelling	330880
88 A	YES	Rac hub, drum & tire; hub burnt up; near wheel off	280086
89 A	YES	Rac hub & knuckle; hub still attached to knuckle because inner & outer nut & lock washer still threaded on knuckle; near wheel off	303634

90 A	YES	Cannot accountably determine failure origin; IB IR cracked; OB; Hub burn up Rec hub, bearing cones & rollers; IB & OB cone broke apart; rollers show lack of lub; burn up	341848
91 A	YES	Rec burnt up; had to cut inner cones off knuckle; inner cones were not cracked at time of return; inner cones cracked during removal; clip ring grooved from rotation; circular marks on inner cone faces	378222
92 ?	YES	Rec burnt up; inner cones cracked; clip ring grooved; inner & outer brg have equal damage & heat indicators	886312
93 A	YES	Sent to SKF	886312
94 A	YES	Hub burnt up; 38 rollers returned; IB inner cone fractured into 5 pieces; D washer deformed; tone ring fractured into several pieces; OB inner cone not fractured - shows very little damage from rotation	410001
95 ?	YES	Near wheel off	383689
96 A	YES	Rec burnt up; cones cracked; clip ring grooved; rotation witness marks on cone faces; cannot determine if low clamp load caused failure due to cones being cracked; both brgs burned in color from heat	267031
97 A	YES	Rec hub, spindle, shoes, drum, hub did not come off spindle because of inner and outer nut and locking spacer still on spindle; near off; hub and spindle are in Bob Rosenthal box	552941
98 A	YES	Received disassembled; IB OR RW badly deformed, metallurgy confirms was heat treated on	223486
99 ?	YES	Rec disassembled; IB & OB races heavy pitting; OB cone heavy; inconclusive	359264
100 A	YES	Returned hub, drum, shoes, knuckle, ABS sensor, king pin	669678
101 A	YES	REC ONLY BOTH BRG CONE SEIZED TOGETHER; ONE CONE PIECE MISSING, ONE CONE CRACKED IN TWO PLACES; INCONCLUSIVE; Rec hub and spindle; IB and OB cones seized to spindle; scrap 4/8/02	609563
102 A	YES	Hub off	374840
103 ?	YES	Rec hub burned up; rec. IB and OB cones; clip ring - both cones were cut with cutting torch; inconclusive	206555
104 ?	YES	Rec hub & both bearing cones; cones and races are burned up; near wheel off	320406
105 A	YES	Rec hub, drum; no bearings, hub burnt up; inconclusive; burn up; near off	463126
106 A	YES	Rec hub and spindle, IB and OB cones, seized to spindle; burn up; scrap 4/7/02	206555
107 A	YES	Passenger wheel bearing seized up; wheel bearing seized up; tire blew; took out underbrace for the sleeper & fender; took out AC heater; sleeper lineshock ripped up; tire & tube was damaged; brake drum & brakes were half melted; off side spring shackles were	424577
108 A	YES	Rec hub big cone burn up; low clamp load	258688
109 A	YES	Shipped to SKF for further inspection / received disassembled, rollers, cages, seals & grease gone, OR RW's badly damaged, mol cause not determinable; Hub burn up; fire	230849
110 ?	YES	Hub was returned with OB big cone in place & IB seal in place; IB big cone & clip ring missing; tone ring broken off; OB cage starting to melt; oil greasy dry & stiff; can only imagine what IB brg looks like	179052
111 A	YES	Near wheel off	279729
112 A	YES	Rec hub IB & OB cones, clip ring & some rollers; all items were burned up; lack of lubricant	326433
113 L	YES	Rec hub only; hub burn up	214024
114 A	YES	Rec hub, spindle, drum, shoes, tire and rim; hub burned up; inconclusive 4/8/02	170226
115 A	YES	Rec hub and knuckle, hub still on spindle because inner and outer nut and lock ring are still on spindle; nut and lock ring are still on spindle; near wheel off	423462
116 A	YES	Wheel off; inner & outer nuts burned up; drum & hub still mounted to wheel	367804
117 A	YES	Sent to SKF	124982
118 A	YES	Hub off	122369
119 A	YES	INNER CONES MISSING, TONE RING GONE, HUB CAP STILL INSTALLED BUT BROKEN OUT; SENT TO SKF	106217
120 A	YES	REC HUB AND SPINDLE; IB AND OB CONES SEIZED TO SPINDLE; INNER AND OUTER NUTS OR STILL THREADED ON TO SPINDLE (REAR OFF); INCONCLUSIVE	305141
121 ?	YES	Rec hub only no IB; OB brg clip ring; IB race has heavy damage due to brg failure; when caused the failure is unknown at this time because of lack of information; unknown	305142
122 A	YES	109348; Rec: disassembled; brgs destroyed; only 10 rollers from OB & from IB inner cones cracked; ? Right wheel caught fire from wheel bearing failure; also inspected left front wheel - ok; parts shipped to Troy via Yellow Freight to Rosenthal; msc is to Rec. hub, drum and side with knuckle spindle with burned up IB and OB cones; inner and outer FPR81 Lx38 nuts still on spindle; hub burn up; 510-12641-000, AVF-98233149 98340	394673
123 ?	YES	Rec hub only; no brgs; hub races are burned up	317825
124 ?	YES	IB & OB cones & races are split	334132
125 A	YES	Fire; Hub burn up	176412
126 A	YES	Ryder Truck - Albuquerque; rec hub and spindle; hub seized to spindle; scrap 4/7/02	449786
127 A	YES	Received disassembled, IB row badly damaged, poss unhardened row	173242
128 ?	YES		

SKF 002141

131 ?	YES	IR OR RW eroded badly	41412
132 ?	YES	CB row nutty w/black corrosion in OR RW; IR row same; chips in IRs @ clip ring noses; brinell lines across both IR RW; spindle head sheared off & pulled out of knuckle; corrosion in bearing appears to be post-failure (no churning); Impact load Near wheel off	120710 125268
133 A	YES		
134 A	YES	Wheel departed; inner brg row cage fractured; clip ring 2 notch monkey wrench central scratches; OB IR circular scratches IR side; small amount oil small face; brake shoe flattened one place (wheel fell off?); IR seal was F-NOK; grease with GARZ: one IR w/ HUB & ROLLERS RETURNED; NO INNER CONES; SENT TO SKF	833
135 A	YES	No rollers returned; all mounting hardware & inner cones returned; sent to SKF	53489
136 A	YES	Complete failure; worn spindle under IR; grooves worn in clip ring; low clamp load	962981
137 L	YES	Fell apart; unhardened raceway; inboard outer ring raceway heavily eroded	79574
138 A	YES	Unhardened raceway; inboard outer ring raceway heavily eroded	81806
139 A	YES	R front wheel bearing fall apart; unhardened raceway	21306
140 ?	YES	Seal leak; hub failure	
141 ?	YES	Wear/bite; unhardened raceway; IR RW balled; entire hub opened; melted shoes; knuckle @ AP end	50024
142 A	YES	Brakes burnt; bearings were hot; unhardened raceway	8702
143 A	YES	Smoking hub; hub cap ok	21308
144 A	YES	Rac hub burned up; inconclusive	654656
145 ?	YES		360736
146 L	YES		
147 ?	YES	Rac disassembled; IR inner cone cracked; no signs of rotation brg & clip ring; IR inner cones spalled; not all roller spacings; seal journal on IR race corroded; IR seal bad; race lip groove completely worn out; bearings have signs of water ingress; IR seal	260052
148 ?	YES	Rac hub burnt up; had to cut inner cones off; inner cones not cracked; when returned; outer cone cracked during removal; outer cone spun on spindle; excessive galling on spindle; clip ring grooved	
149 ?	YES	Inner cones not returned; only 20 rollers returned; half were flat; O washer shows deformity from heat; both nuts & lock washer returned; not an unhardened raceway - fire extinguisher used on hub; hub cap threads show no sign of rust; suspect hubcap was c	
150 A	YES		
151 L	YES	Rac disassembled, no rollers or cages; IR now failed first	
152 ?	YES	Looked up; unhardened raceway IR	60097
153 ?	YES		
154 A	YES	Bearing locked up; IRs fractured; IR IR spalled	
155 A	YES	Unhardened raceway; wheel off?	38186
156 ?	YES	Fire	
157 ?	YES	Received disassembled; badly damaged; no rollers-cages-grease or seals; cannot determine origin of failure due to lack of components	
158 ?	YES	Near wheel off	
159 A	YES	RETURNED KNUCKLE RIGHT SIDE; BOTH CONES & CLIP RING, NO ROLLERS RETURNED; CIRCULAR WITNESS MARKS ON CONE FACES; GROOVES ON SPINDLE FROM CONE ROTATING; LOW CLAMP LOAD	
160 L	YES		
161 A	YES		
162 ?	YES		
163 A	YES		
164 A	YES		
165 A	YES	Rac, hub, cone and pieces of other cones; hub burn up; no other information was provided.	
166 L	YES	Rac, hub, inner and outer bearing cones; both cones were cut with a cutting torch in order to remove from spindle; hub burn up.	
167 A	YES	Rac hub & knuckle; both burnt up	
168 A	YES	No rollers, seals or gears; smashed IRs; same look as #PMS; broken tone ring w/circular notch; IRs fractured; low clamp load; grooves in clip ring	
169 ?	YES	Unhardened raceway; no parts; pic only	
170 ?	YES	Fire / Brucia Ketchum	
171 A	YES	Near wheel off	360273
172 ?	YES	Hub burn up	
173 ?	YES	Hub off; unit towed in for losing R steer axle wheel assembly	335132
174 ?	YES	Fire	
175 A	YES	No claim; sent to SKF	
176 A	YES	Inner cone still attached to knuckle; both fractured; scrap	234546
177 A	YES	Only hub returned; no inner cones missing; both BRG rings damaged by failure; sent to SKF	
178 A	YES	Hub returned with no inner cones; mounting hardware returned with hub; O washer in functional shape; both outer rings have heavy damage; hub cap still on hub; customer cut hub cap open to remove hub	
179 A	YES	Only the hub was returned; HPI both brgs ring severely damaged; sent to SKF	
180 A	YES		
181 A	YES		
182 ?	YES		
183 A	YES		
184 A	YES		
185 A	YES		
186 L	YES		
187 A	YES		
188 A	YES		
189 ?	YES		
190 ?	YES		
191 A	YES		
192 ?	YES		
193 A	YES		
194 A	YES		
195 A	YES		
196 A	YES		
197 A	YES		
198 A	YES		
199 ?	YES		
200 ?	YES		
201 A	YES		
202 ?	YES		
203 A	YES		
204 A	YES		
205 A	YES		
206 A	YES		
207 A	YES		

SKF 002142

871 A	YES	REC hub & knuckle; hub races are burned up; knuckle bearing cones seized to spindle	188543
872 ?	YES	REC hub & knuckle; hub races burned up; knuckle burn up	184905
874 ?	YES	Sent to SKF-5/23/02	455497
875 ?	YES	REC HUB, KNUCKLE AND DRUM; KNUCKLE INNER AND OUTER CONES SEIZED TO SPINDLE; HUB RACES BURNT UP-5/23/02	586652
876 L	YES	Sent to SKF-5/23/02	
877 L	YES	REC, HUB, KNUCKLE, DRUM SHOES: INNER AND OUTER CONES SEIZED TO SPINDLE; HUB RACES BURNT UP-5/23/02; warranty payment approved	535852
878 A	YES	REC, HUB, KNUCKLE, 2 BURNED UP AND BROKEN: HUB RACES AND HUB CONES ARE BURNED UP; KNUCKLE BEARINGS SPINNING ON BEARING JOURNALS; BURN UP-5/28/02	338501
879 A	YES	REC, DRUM, HUB, KNUCKLE AND CO BRAKE SHOE KNUCKLE INNER AND OUTER CONES SEIZED TO SPINDLE; HUB RACES BURN UP	458000
880 ?	YES	REC HUB AND KNUCKLE ASSEMBLED; KNUCKLE INNER AND OUTER CONES SEIZED TO SPINDLE HUB RACES BURN UP; INNER AND OUTER NUT AND WASHER STOPPED HUB FROM COMING OFF; BURN UP; NEAR OFF-5/23/02	274602
881 A	YES	Sent to SKF-5/28/02	622294
882 ?	YES	REC, DRUM AND KNUCKLE INNER AND OUTER BRG CONES ARE BURN LIP AND SEIZED TO SPINDLE; NO HUB RETURNED; BURN LIP-5/20/02	287309
883 A	YES	REC, HUB AND INNER AND OUTER CONES; HUB AND BEARING BURNT UP; warranty payment approved	408632
884 A	YES	REC HUB AND KNUCKLE, HUB STILL ON SPINDLE BECAUSE INNER AND OUTER NUTS ARE STILL THREADED ON SPINDLE; BURNT UP - NEAR WHEEL OFF-5/22/02 ; warranty payment approved	407277
885 A	YES	Sent to SKF-5/28/02	308968
886 ?	YES	Sent to SKF-5/22/02	250145
887 A	YES	REC AXLE WITH BURNED UP BEARING SEIZED TO SPINDLE; REC HUB; WHEEL OFF-5/17/02	587183
888 A	YES	IB RACE HEAVY SPALLING AND DISCOLORATION ON LOAD ZONE; SPALLING AND PITTING AND HEAVY DISCOLORATION ON LOAD ZONE; IB ROLLERS HEAVY DEBRIS DENTING AND DISCOLORATION ON LOAD ZONE; O/B CONE AND RACE PITTING WHERE ROLLERS MEET RACE; INBOARD OIL SEAL LEAKAGE W	587183
889 A	YES	IN BOARD SEAL ALLOWED WATER INGRESS WHICH IN TURN CORRODED THE IN-BOARD BEARING AND CREATED CONTAMINANTS; THESE CONTAMINANTS HELPED BREAK APART THE OUTBOARD BEARING; THE O/B RACE IS DAMAGED FROM THE ROLLERS TURNING SIDEWAYS AND BLOCKING; THIS IS INCONCLUSIVE	167925
890 A	YES	REC HUB ONLY; HUB RACES BURN UP-5/28/02	412700
891 A	YES	REC, HUB, KNUCKLE, NUTS AND 1 CONE INNER AND OUTER NUT WHERE CUT OFF IN ORDER TO REMOVE HUB; 1 CONE WAS CUT WITH A TORCH TO REMOVE FROM SPINDLE; HUB BURN UP-5/20/02; warranty payment approved	491999
892 ?	YES	Sent to SKF-5/23/02	312303
893 A	YES	HPI RETURNED; HUB CAP STILL ON HUB, BUT CENTER IS BLOWN OUT; ONLY 11 FLAT LOSE ROLLERS RETURNED; NO INNER CONES	
1179 L	YES	REC HUB, KNUCKLE AND SPINDLE ASSEMBLY WITH IB AND O/B CONES STILL ATTACHED; CONES AND RACES ARE BURNED UP	267591
1180 L	YES	RBC HUB, KNUCKLE/SPINDLE ASSEMBLY; IB AND O/B CONES AND ROLLERS; CONES, ROLLERS AND RACES ALL BURNED UP; ALSO RECEIVED KINGPIN	434826
1181 L	YES	REC., HUB WITH IB AND O/B RACES, REC KNUCKLE AND SPINDLE WITH IB AND O/B CONES, IB AND O/B CONES AND RACES WERE ALL BURNED UP	520116
1182 A	YES	REC HUB ATTACHED TO SPINDLE/KNUCKLE ASSEMBLY WITH IB AND O/B CONES AND RACES; CONES AND RACES ARE BURNED UP; ROLLERS FALL OUT AND NOT RECEIVED.	463108
1183 A	YES	REC HUB, SPINDLE/KNUCKLE ASSEMBLY, BRAKE SHOES, AND BRAKE DRUM; RACES ARE BURNED UP	382974
1184 ?	YES	RBC KNUCKLE/SPINDLE ASSEMBLY WITH IB AND O/B CONES SEIZED TO SPINDLE; CONES ARE BURNED UP; HUB NOT REC	501627
1185 A	YES	REC HUB, BRAKE DRUM, BRAKE SHOES, KNUCKLE/SPINDLE ASSEMBLY WITH IB AND O/B CONES AS SPINDLE ASSEMBLY	143063
1186 A	YES	REC HUB AND KNUCKLE; HUB IB AND O/B RACES BURNED UP; KNUCKLE IB AND O/B CONES ARE BURNED AND SEIZED TO SPINDLE; BURN-UP; WARRANTY PAYMENT APPROVED	549489
1187 L	YES	REC HUB, KNUCKLE, SPINDLE AND DRUM; DRUM WAS STILL ATTACHED TO HUB; A CONE WAS CUT WITH TORCH AND INCLUDED IN BOX; HUB RACES WERE BURNED UP.	541172

SKF 002143

		REC KNUCKLE ATTACHED TO A PARTIAL AXLE THAT HAD BEEN CUT OFF. AS SPINDLE IS ATTACHED TO KNUCKLE WITH BEARING CONES ATTACHED TO IT; WHEEL IS OFF; TALK TO SERVICE MANAGER AND WAS INFORMED THAT THEY LOOKED FOR TWO HOURS FOR HUB AND WHEEL ASSEMBLY; BURN-UP: W	663187
1188 ?	YES		
1189 A	YES	REC HUB AND KNUCKLE, HUB RACES BURNED UP; KNUCKLE VB CONE BURNED UP AND SEIZED TO SPINDLE. WARRANTY PAYMENT APPROVED	673600
1190 A	YES	REC HUB, ROLLERS, RACES, AND CONES; CONES, RACES AND ROLLERS ARE ALL BURNED UP	614924
1191 A	YES	REC HUB: HUB RACES BURNED UP	570182
1192 A	YES	REC HUB AND VB AND Q/B CONES; CONES AND RACES BURNED UP	
1193 A	YES	REC HUB AND CONE, HUB VB AND Q/B SEAL RACES BURNED UP; BURN-UP: WARRANTY PAYMENT APPROVED	
1194 A	YES	REC HUB ONLY; VB AND Q/B RACES BURNED UP; BURN-UP: WARRANTY PAYMENT APPROVED	
1195 A	YES	REC HUB AND VB AND Q/B RACES; RACES ARE BURNED UP.	544150
1196 A	YES	REC HUB, KNUCKLE/SPINDLE ASSEMBLY, BRAKE DRUM, BRAKE SHOES, KINGPIN, AND VB AND Q/B CONES; VB AND Q/B CONES AND RACES ARE BURNED UP	442364
1197 A	YES	REC HUB ATTACHED TO KNUCKLE SPINDLE ASSEMBLY; CONES, RACES AND ROLLERS ARE ALL BURNED UP	368288
1198 A	YES	REC HUB, KNUCKLE/SPINDLE ASSEMBLY, VB AND Q/B CONES; RACES AND CONES BURNED UP	327469
1199 A	YES	REC HUB AND KNUCKLE/SPINDLE ASSEMBLY; VB AND Q/B CONES STILL ON SPINDLE IN A BURNED UP CONDITION; RACES (VB AND Q/B) BOTH BURNED UP.	332123
1200 ?	YES	REC KNUCKLE/SPINDLE ASSEMBLY WITH VB AND Q/B CONES SEIZED UP; CONES ARE BURNED UP	340551
1201 A	YES	REC HUB, ROLLERS, AND BRAKE SHOES; RACES AND ROLLERS BURNED UP	546651
1202 A	YES	REC HUB WITH Q/B CONE, ROLLERS, AND STILL ATTACHED; VB RACE BURNED UP	477024
1203 A	YES	REC HUB, ROLLERS, RACES, AND CONES; CONES AND RACES BURNED UP; ROLLERS ALSO BURNED UP	471882
1204 A	YES	REC HUB ONLY; HUB RACES BURNED UP	546809
1205 A	YES	REC HUB WITH Q/B CONES, ROLLERS STILL TOGETHER; VB RACE BURNED UP	298248
1206 A	YES	REC HUB, BRAKE DRUM, KNUCKLE AND SPINDLE ASSEMBLY AND CONES; CONES ARE BURNED UP AND STUCK TO SPINDLE; RACES IN HUB ARE BOTH BURNED UP.	342353
1207 A	YES	REC HUB, ROLLERS, RACES, AND CONES; RACES, ROLLERS, AND CONES ARE ALL BURNED UP	262408
1208 A	YES	REC HUB, VB AND Q/B CONES, BRAKE DRUM, AND BRAKE SHOES; VB AND Q/B CONES AND RACES BURNED UP	408672
1209 A	YES	REC HUB ATTACHED TO SPINDLE/KNUCKLE ASSEMBLY; CONES (VB AND Q/B) AND RACES BURNED UP; ROLLERS BURNED UP AND BOUND UP INSIDE HUB	312641
1210 A	YES	REC HUB STILL ATTACHED TO KNUCKLE/SPINDLE ASSEMBLY; ROLLERS MISSING WITH CONES SEIZED TO SPINDLE; BOTH CONES AND RACES BURNED UP! NEAR WHEEL OFF	570893
1211 A	YES	REC HUB RACES OF HUB BURNED UP	260358
1212 A	YES	REC HUB AND VB AND Q/B RACE; VB AND Q/B RACES ARE BOTH BURNED UP!	378487
1213 A	YES	REC HUB, VB AND Q/B CONES, AND ROLLERS; VB AND Q/B CONES AND RACES ARE BURNED UP	114676
1214 A	YES	REC HUB AND KNUCKLE, HUB AND KNUCKLE BURNED UP THE ONLY THING STOPPING HUB FROM COMING OF WAS THE INNER AND OUTER NUTS AND WASHER; BURN-UP; WARRANTY PAYMENT APPROVED	268281
1215 A	YES	REC HUB, VB AND Q/B CONES AND ROLLERS; CONES, ROLLERS, AND RACES ARE ALL BURNED UP	377144
1216 A	YES	Q/B SEAL AND BEARING IN TILT; SEVERAL MM OF GREASE LEAKAGE! FROM SEAL; Q/B CONE AND ROLLERS SHOW HIGH HEAT; VB CONE, PLATE, AND ROLLERS BURNED UP; CLIP RING SHOWS HIGH HEAT; SEAL LEAKAGE; WARRANTY PAYMENT APPROVED	360211
1217 A	YES	REC HUB, VB AND Q/B CONES, ROLLERS; ROLLERS, CONES AND RACES ARE BURNED UP	288080
1218 A	YES	REC HUB, VB AND Q/B CONES, AND ROLLERS; CONES, RACES AND ROLLERS ARE BURNED UP	213730
1219 A	YES	REC HUB, VB AND Q/B CONES, AND ROLLERS; CONES, RACES AND ROLLERS ARE BURNED UP	341900
1220 ?	YES	REC HUB ONLY; RACES OF HUB BURNED UP	253388
1221 A	YES	REC HUB WITH VB AND Q/B CONES; CONES AND RACES ARE ALL BURNED UP	298363
1222 A	YES	REC HUB AND VB CONE; CONE AND RACES WERE BURNED UP	410088

SKF 002144

		REC HUB STILL ON KNUCLE/SPINDLE ASSEMBLY WITH ROLLERS, AND BRAKE SHOES; IB AND OB CONES SEIZED TO SPINDLE ASSEMBLY; CONES AND RACES BURNED UP; NEAR-OFF	
1223 A	YES	REC HUB, SPINDLE AND KNUCLE ASSEMBLY, AND IB AND OB CONES STILL ATTACHED TO SPINDLE, CONES AND RACES BURNED UP; MISSING ROLLERS AND CAGES; NEAR WHEEL OFF	292291
1224 A	YES	REC HUB AND IB CONE; CONE AND RACES WERE BURNED UP	223606
1225 A	YES		248275
		REC HUB, BRAKE SHOES, BRAKE DRUM, ROLLERS AND IB AND OB CONES; HUB STILL HELD ON SPINDLE; IB AND OB CONES SEIZED TO SPINDLE/KNUCLE ASSEMBLY; CONES AND RACES BURNED UP; NEAR-OFF	
1226 A	YES	REC ., HUB, KNUCLE/ SPINDLE WITH IB AND OB CONES STILL ON SPINDLE, BRAKE SHOES, CONE AND RACES BURNED UP.	438123
1227 A	YES	REC HUB, KNUCLE, IB AND OB CONES AND A FEW ROLLERS, HUB RACES BURNED UP. IB AND OB CONES AND ROLLERS BURNED UP.	212000
1228 A	YES	REC HUB AND IB AND OB CONES; CONES AND RACES ALL BURNED UP; NO CLAMM TAG WAS AVAILABLE	
1229 A	YES	REC HUB, DRUM, AXLE AND THE ROD; HUB AND DRUM BURN-UP; AXLE SPINDLE BURN-UP; IB AND OB NUTS AND LOCK WASHERS STILL ON SPINDLE; BURN-UP WHEEL OFF; WARRANTY PAYMENT APPROVED	
1370 A	YES	REC HUB ONLY; HUB IB AND OB HUB RACES BURNED UP; BURN-UP	551077
1371 A	YES	REC HUB ONLY; RACES OF HUB BURNED UP	736221
1372 L	YES	REC HUB, KNUCLE/SPINDLE ASSEMBLY; IB AND OB CONES AND ROLLERS; RACES, CONES, AND ROLLERS ARE ALL BURNED UP; WARRANTY PAYMENT APPROVED	
1373 L	YES	REC HUB COMPLETE; IB SEAL BURNED UP; IB ROLLERS TURNED AND BURNED; BEARING FAILURE FROM CONTAMINATION ON THE IB SIDE OF HUB; WARRANTY PAYMENT APPROVED	466803
1374 A	YES	Rec hub, spindle assembly w/cones seized to spindle (IB & OB), brake drum & shoes; cones & races burned up; 7/24/02	376181
1431 A	YES	Rec hub, knuckle, spindle assembly with IB & OB cones still attached; brake drum & brake shoes; cones & races burned up; 7/24/02	544292
1432 A	YES	Rec spindle/knuckle assembly w/IB & OB cones still attached; cones burned up; 7/23/02	207120
1434 ?	YES	Rec hub, rollers, IB & OB cones all components burned up; 7/24/02	457001
1436 A	YES	Rec hub, IB and OB rollers and cones and brake shoe; cones, rollers and races are all burned up; 7/23/02	437629
1437 A	YES	Rec hub with IB and OB cones and rollers seized in hub; both IB and OB seals turned out; rollers on OB side turned sideways and burned up; 7/23/02	572022
1438 A	YES	Rec hub only; races in hub all burned up; 7/23/02	576629
1441 A	YES	Rec hub with brake shoes and brake drum; races in hub burned up; also rec knuckle/spindle assembly with IB and OB cones seized on spindle; cones are burned up; 7/16/02	334111
1445 A	YES	Rec hub with IB and OB cones and rollers; cones, rollers and races are all burned up; 7/16/02	689729
1446 A	YES	Rec hub with IB and OB cones cut free from spindle with Torch; rollers also included; cone, races, and rollers are all burned up; 7/16/02	288374
1449 A	YES	Rec hub and brake shoes; races in hub burned up; 7/15/02	288374
1451 A	YES	Rec hub with missing rollers; cone, races, and rollers burned up; 7/15/02	326306
1452 A	YES	Rec hub & knuckle/spindle assembly with IB & OB cones still attached; all components burned up; 7/15/02	155990
1455 A	YES	Rec knuckle/spindle assembly only; IB & OB cones seized on spindle; everything burned up; 7/15/02	
1459 ?	YES	Rec hub, drum, shoes & king pin; races in hub burned up; 7/6/02	138799
1463 A	YES	Rec hub, brake drum; spindle/knuckle assembly & IB & OB cones; IB & OB cones seized to spindle; cones & races burned up; near off; 7/6/2	446227
1464 A	YES	Rec hub; races in hub burned up; 7/6/02	715692
1466 A	YES	Rec hub, knuckle/spindle assembly, rollers & IB & OB cones; cones, races & rollers burned up; 7/3/02	246321
1468 A	YES	Rec knuckle/spindle assembly, brake shoes; king pins; a-cam & IB & OB cones; hub was not rec; IB & OB cone is seized to spindle & burned up; 7/3/02	353926
1469 ?	YES	Rec hub returned up cones, races & rollers (IB & OB) 7/2/03	446227
1470 A	YES	Rec hub only; races inside hub are burned up; 7/2/02	525116
1473 A	YES		572351
1478 A	YES	Rec hub, rim, knuckle/spindle assembly & brake drum; hub races burned up; 6/26/02	341720
1479 A	YES	Rec hub, brake drum, knuckle/spindle assembly & IB & OB cones; cones & races burned up; 6/26/02	342684
1486 L	YES	Rec hub and IB and OB bearing cones both cones are broken; hub races are burned up; Warranty payment approved; 7/17/02	722864
1489 ?	YES	Rec Knuckle and part of bearing cone; knuckle IB and OB race seized to spindle no hub was retained; Burn-up; Warranty Payment Approved 7/17/02	767591
1502 A	YES	Rec hub & knuckle; hub races burnt up; knuckle IB & OB cones seized to spindle; warranty payment approved; 7/6/02	248295
1509 L	YES	Rec hub only; races in hub burned up; warranty payment approved; 7/10/02	645438

1517 A	YES	Rac hub only; hub races burn up; 7/18/02	439489
1619 A	YES	Rac hub and 1B bearing cones; hub 1B and O8 races burned up; 1B cone shows extreme heat; burn up; 7/18/02	567487
1620 A	YES	Rac hub only; hub races burned up; 7/18/02	439499
1629 ?	YES	Rac knuckle brakcs and brake parts; knuckles 1B and O8 cones seized to spindle old not receive hub; burn up; approved; 7/9/02	643438
1530 A	YES	Rac hub, knuckle and drum; hub and knuckle burn up; the only thing sloping hub from coming off was the inner and outer nut and washer; 7/18/02	575430

ID	Hub Problem YN	VIN#	CLAIM #	IN SERVICE DATE	MILES	Date	Quantity
1088	Y		12345				
828	Y	1FUYDDYB6XLA77269	77259				
848	Y	1FUYDDYB6XLA70918	318274		417040		
1087	Y		E1749214				
849	Y	1FUYDDYB6XLA70921	318277		418370		
850	Y	1FUYDDYB6XLA70931	318287		200882		
851	Y	1FUYDDYB6XLA70931	318287		200882		
1089	Y		E1686819				
1090	Y		E1605085				
852	Y	1FUYDDYB4XLA70934	318290		268057		
850	Y	G63870	382039		484508		
1078	Y	840034	E1660846				
1101	Y		E1773776				
1079	Y		701-				
847	Y	1FUYDDYB6XLA70915	318274		400374		
1082	Y		0331597				
1081	Y		628785				
1080	Y		R0229627				
332	Y	1M1AAC8Y1WW01238	Unit 898		743004		
327	Y		Unit				
326	Y		Unit				
325	Y		Unit				
323	Y		Unit 2084		236900		
320	Y		Test hub		160000		
318	Y	1FUYD5E801PH38272	E388204		116192		
311	Y		188121		422836		
308	Y		836385		103320		
858	Y	1FUYD5E82YL44672	396885		522036		
1140	Y	ZHSPWAMR5YC028729	WMT9123		293388		
839	Y	A63865	317570		587711		
840	Y	A63866	317570		587711		
845	Y	1FUYDDYB6XLA70914	318270		310151		
848	Y	1FUYDDYB4XLA70917	318273		360057		
1184	Y	ZHSPWAMR5YL086325					
1155	Y	2HSPTAER6X023136	WO				
925	Y		STCD				
1163	Y	2HSPTWAMR7XC080538	WMT9104		301728		
1162	Y		WMT9103		244460		
1161	Y		WMT9100		195388		
1160	Y		WMT9148		146840		
1100	Y	1FUY3SE57XPA18635	E1758868		346374		
1148	Y	3HSPTWAMDYN092038	WMT9143		282456		
306	Y	1FUYDXYB2XLA77263	77263				
1145	Y	2HSPTWAMR0X029528	WMT9071		318360		
1144	Y	2HSPTWAMR7Y0871058	WMT0027		166888		
1143	Y	2HSPTWAMR5YC081878	WMT0001		215022		
1142	Y	F14703	V8FD02A				
1141	Y		VHSD0000				
1134	Y		STCD0000				
1133	Y		STCD				
1119	Y		R8AR00J		226500		
1118	Y	A73648	JHM001F				
1112	Y		E1746214				
1105	Y	A01448	E1678709				
1107	Y	1FJJACAB61LJ92898	D1104480		100316		
1149	Y		WMT9148		146840		
947	Y	2HSPTAER6X023136	WO				
897	Y		CWA0804				
800	Y	1FJJACAB61LJ92898	D1104480		100316		
903	Y	A73648	JHM001F				
911	Y		R8AR00J		226500		
934	Y		Unit		366472		
151	Y		N3FD				
152	Y		No info				
970	Y	858091	E1760012				
969	Y		0213279				
968	Y	860573	0084438				
858	Y	2HSPTWAMR2KG071467			328185		
306	Y	1FUY3DYBXYPA88387	186122		404902		
860	Y	1FUYD5EB1YP940512	ZVAR01C				
150	Y		GKF001A				
946	Y		WMT9070		285738		
842	Y	2HSPTWAMR7XC080538	WMT9104		301728		

SKF 002147

941 Y		WMT9153	244650
940 Y		WMT9150	165388
939 Y		WMT9149	146540
938 Y		WMT9149	146540
937 Y	3H8FMAMM0YNO82039	WMT9143	263466
935 Y	2HSFMMAMRHYC028723	WMT9123	203366
934 Y	2HSFMMAMR0XC020828	WMT9071	318360
933 Y	2H8CEAMR7Y0071088	WMT0027	196669
932 Y	2H8CEAMR8YC061878	WMT0001	218022
931 Y		VHM0000	
930 Y	2HSFMMAMR8YL065525		
929 Y	2HSFHAMR1XC078578	0128543A	194627
1161 Y	1FUYDSEB1YPB40512	ZVAR01C	
137 Y		51298	
302 Y	1FUYSDZBXLA14579	14579	129446
862 Y	G13974	918275	556334
860 Y	G13979	918260	466773
867 Y		918261	606219
868 Y		918261	606219
869 Y	G13981	918262	472226
872 Y	G13982	918263	615073
138 Y		0041467A	
139 Y		0056844A	78378
874 Y		918264	658044
885 Y		7 ef 8	
141 Y		0062086A	21309
894 Y	1FUYDDYB7XLA70827	318283 (1	653995
142 Y		1180555A	50024
895 Y	1XK0D89X1XR053805	02093-	
143 Y		65801	8702
893 Y	2HSFMAXR4XC048218	1610097A	145031
903 Y	1FUY1WEBZ1LH01156	UNIT	
144 Y		82056A	21309
145 Y		A64347	654456
146 Y	1FUY5DYB4XPA68868	AW33844	980736
147 Y		CDCD	
148 Y	2H8FBAER7WC06715	CWA0287	
149 Y	1FUYDCYB4YDF48178	E1562173	256962
307 Y		97780	438660
140 Y		0067486A	61800
1229 Y			128038
360 Y			
827 Y	1FUYDXYB2XLA77254	77254	
174 Y	1XPBD9X8XD480364		
173 Y	1FUY28E856YFB00000		
171 Y	1FUY52YB7Y1787491		380273
170 Y			
163 Y			
1228 Y			
175 Y	no paperwork		
160 Y			
166 Y			
107 Y			
188 Y			
186 Y			
184 Y			
1234 Y	2H8FMAMR0YC028659	WMT9106	367036
1330 Y		362181	
335 Y	1FUYNMMD83YF002774	#BAR000	195726
336 Y			404100
1337 Y		322670	
1338 Y		348618	
1336 Y		365338	
1334 Y		357008	
1157 Y		WMT997D	265758
1332 Y		340686	
351 Y			404044
1328 Y		341294	
1327 Y		358908	670906
1326 Y		R0-	343364
1324 Y	2H8CEMAR3YC040100	WMT9168	388072
1323 Y		RC	234548
178 Y	1FUY8DYBXYLF72791		234416
361 Y			

1333 Y			349610			
160 Y	WD446455		WD446455			
161 Y						
162 Y						
820 Y	M286510	33854				
821 Y	1FUPC6S2BVL466762	86762		237985		
365 Y				506682		
169 Y		Unit 379				
168 Y		Unit 3038				
157 Y		Unit 1631				
166 Y		Unit #		35106		
163 Y		RO		66087		
155 Y		TNPDX000				
154 Y		T422				
1 Y	1XKDD2BXVRL736713	CEL02203	01-Jul-97	262822	01/01/97	0
2 Y	1FUYNMD85VP795206	CWA0668	27-Jan-97	824473	01/27/97	2
363 Y	1FUYNMD85VP795206	CWA0668	27-Jan-97	842473	03/10/97	1
178 Y	1FUYNACB9VP162248	CHE0443	10-Mar-97	480400	03/17/97	2
3 Y	245FMAXR1VC034789	034789 /	17-Mar-97	460487	03/20/97	1
4 Y	245FMAXR1VC034779	CA103740	17-Mar-97	237133	04/23/97	1
5 Y	245FMAXR1VC034774	CBE2409	20-Mar-97	468600	04/26/97	2
6 Y	245FMAXR1VC034756	034756	23-Apr-97		04/30/97	1
367 Y	245FMAXR1VC033315	CWA0817	25-Apr-97		05/08/97	1
368 Y	1FUYDQYB7VP604700	E1588424	25-Apr-97	875871	05/11/97	1
874 Y	2FUYDQYB7WVA83386	E1741260	30-Apr-97	456487	05/15/97	1
370 Y	1FUYBSEBXL865687	CWA0864	08-May-97	351125	06/17/97	1
1178 Y	1FUY5S2B6WP447339	E1776332	11-May-97	267581	06/22/97	1
7 Y	1FUY5ZBY4WL863001	E1666060	15-May-97	860503	06/30/97	1
378 Y	1FUY5SEB1WB606847	E1683613	17-Jun-97	460037	07/07/97	1
1242 Y	1FUYNMD85WL74146	CWA1285	22-Jun-97	576417	07/15/97	1
179 Y	1FUY5SEB2WP780485	E1672205	30-Jun-97	413368	07/17/97	1
8 Y	1FUY5SEB5WL86076	E1700843	07-Jul-97	865624	07/21/97	1
9 Y	1FUY55ZB9WL447407	E1776417	15-Jul-97	808417	07/23/97	1
10 Y	1FUY5KXYB8WL884423	CWA0872	17-Jul-97		07/27/97	1
11 Y	1XPGDUX0XWLD44693	CWA0705	21-Jul-97	433307	07/29/97	2
385 Y	1FUYNWB8XWL88080	E1680634	23-Jul-97	817742	08/08/97	1
384 Y	2FUYDQYB5WVA80457	E1703129	27-Jul-97	485673	08/08/97	1
180 Y	1FUY5MD83WL88069	E1672185	29-Jul-97	727018	08/13/97	1
12 Y	1FUY5HDB85WL88069	E1672185	30-Jul-97	762914	08/21/97	1
181 Y	2FUPFED84XA94883	CWA0371	08-Aug-97	322880	08/28/97	1
13 Y	1FUYDQYB2WL787003	E1681844	08-Aug-97	461480	09/02/97	2
14 Y	1FUY5BZB3WVA838948	CWA0370	13-Aug-97	600202	09/09/97	1
1372 Y	1FUY5KXYB7WL824086	E1606260	21-Aug-97	736221	09/15/97	2
15 Y	1FUY5SEB4M426222	CWA0880	25-Aug-97	807448	10/03/97	1
999 Y	1FUYNMD85WL80887	E1717541	02-Sep-97		10/18/97	1
1008 Y	1FUYNMD85WL80887	E1717542	02-Sep-97		10/20/97	1
1229 Y	1FUYDQYB5WL807681	0034852	08-Sep-97	714870	10/28/97	1
16 Y	245FRAHR6WC06018	C8Y0008	15-Sep-97	284808	11/07/97	1
17 Y	1FUY5BZB6WL889451	Imvole	15-Sep-97	846830	12/10/97	1
183 Y	2FUPDSEB4WVA80139	E1672375	03-Oct-97	716893	12/31/97	0
400 Y	1FUPDSEB3WVA84470	E1664227	16-Oct-97			
401 Y	4UG7DBJH4WN751203	CWA0764	20-Oct-97	422320		
978 Y	2FUYDSEB0WVA842373	E1785102	26-Oct-97	552892		
188 Y	1FUY3MCB3WL803377	D1089970	07-Nov-97	422726		
18 Y	1FUYDQYB4WL822898	Unit	10-Dec-97	481104		
19 Y	1FUYDQYB6WP917799	E1525860	29-Jan-98	304316		
427 Y	1FUPC8E86WVA86805	E1574441	02-Feb-98			
1343 Y	2FUPDQYB4WVA877785	E1795404	12-Feb-98	861216		
1008 Y	1FUYNMD85WL827554	E175666	18-Feb-98			
994 Y	1FUY5SEB4M871848	E1785877	01-Mar-98	386606		
978 Y	2FUYDSEB6WVA868208	E1712573	20-Mar-98			
437 Y	1FUYNWEBXWFB80025	E1699193	01-Apr-98	622310	01/01/98	0
977 Y	1FUY5DQYB1WLA17838	CWA1331	01-Apr-98	836822	01/28/98	1
438 Y	1FUYNMD81WL82289	CWA0380	06-Apr-98		02/02/98	1
20 Y	1FUPDSEB4WP28654	E1662280	21-Apr-98	381184	02/12/98	1
1014 Y	1FUY5WC85WL80820	E1768074	24-Apr-98		02/18/98	1
1077 Y	1FUYDQYB8WLA975488	E1574422	26-Apr-98	337408	03/01/98	1
186 Y	1FUY5SEB5XWP985387	E1651612	26-Apr-98	442225	03/20/98	1
1180 Y	1M1AA1679WW08864	CWA0671	29-Apr-98	434820	04/01/98	2
448 Y	1XPGDUX1WN47141	CWA0697	30-Apr-98	462862	04/06/98	1
297 Y	1FUYDQYB8WLA29088	338530	01-May-98	461834	04/21/98	1
1015 Y	1FUY5DQYB80WL829088	338530	01-May-98	461834	04/24/98	1
190 Y	1FUYDQYB5XWP80189	32872	15-May-98	250087	04/28/98	2
481 Y	1FLUAV3MCAXP987112	E1699400	19-May-98	533009	04/29/98	1

21 Y	1FUYDWD8XLA98440	33770	23-May-98	485822	04/30/98	1
181 Y	1FUPDSEB1X1973300	E1781912	29-May-98	520118	05/01/98	2
486 Y	1FUPCS5B0XLA10460	E1755927	04-Jun-98	573902	05/15/98	1
457 Y	1FUYSWEB1XLA22861	E1730748	11-Jun-98		05/18/98	1
458 Y	1FUYSWEB3XLA22862	E1730747	11-Jun-98		06/23/98	1
191 Y	1FUYSWEB3XLA22862	E1730747	11-Jun-98		06/29/98	1
22 Y	1FUYDSEB7XLA33776	C8Y0015	16-Jun-98	283163	06/04/98	1
402 Y	1FUYDSEB1XLA98440	E1687553	22-Jun-98	419279	06/11/98	3
464 Y	1FUYDSEB1XPA68404	CWA0232	26-Jun-98	504209	06/18/98	1
978 Y	1FUYSDYB1YLA82864	E1785864	30-Jun-98	336501	06/22/98	1
409 Y	4VGJDEJFSX N	H065091 33096	17-Jul-98	194124	06/26/98	1
470 Y	1FUYCDYB7XLA67587	E170961	17-Jul-98	596805	06/30/98	1
471 Y	1FUY3MD84XPA77111	33894	20-Jul-98	284153	07/16/98	2
23 Y	1FUYSDYB1XPB18096	E1686498	31-JUL-98	482701	07/31/98	1
472 Y	1FUYDSEB7XPA41431	CWA0300	04-Aug-98	595034	08/04/98	1
473 Y	1FUYSSZB1XLA05404	CWA1426	06-Aug-98	747824	08/06/98	2
194 Y	1FUYSSZB1XLA06404	CWA1426	06-Aug-98	747824	08/28/98	2
479 Y	1FUYSSZBXXLA78558	8.552444*	26-Aug-98	596062	09/01/98	2
24 Y	1FUYSDZB1XPB18096	E1704740	26-Aug-98	509095	09/15/98	2
481 Y	XLA98581	CWA1033	01-Sep-98	523549	09/17/98	1
198 Y	1FUYDSEB5XPA07040	CWA1426	01-Sep-98	411300	09/21/98	2
483 Y	1XPCD80X1XN468638	CWA0802	15-Sep-98	468759	09/22/98	1
482 Y	1XPCD80X1XN468638	CWA0802	15-Sep-98	468759	09/24/98	2
1019 Y	1FUYSSZBXXLA01258	E1717654	17-Sep-98	488778	09/25/98	1
1084 Y	1FUYD3YB3KL978597	E1682202	21-Sep-98	350813	09/30/98	3
1083 Y	1FUYD3YB3KL978597	E1682202	21-Sep-98	350813	10/01/98	1
26 Y	1FUYSSZB7XPA487434	E1681698	22-Sep-98	406157	10/03/98	1
1182 Y	1FUYSDYB7XPA26787	E1778014	24-Sep-98	400109	10/05/98	4
26 Y	1FUYSDYB4XPK985346	CWA0940	24-Sep-98	588279	10/08/98	1
27 Y	1FUYCDYB4XL978608	E1682440	25-Sep-98	300543	10/08/98	2
488 Y	1FUYSSZB7XLS21614	E1702813	30-Sep-98	348980	10/13/98	1
486 Y	1FUYDDYB7XPA36198	CWA0808	30-Sep-98	388348	10/14/98	5
28 Y	1M1AA12YXW098251	CWA0707	30-Sep-98	557140	10/19/98	1
199 Y	1XKADB9KB0U799302	CWA1255	01-Oct-98	377145	10/20/98	2
29 Y	1FUYSSZB40L444932	CWA1426	02-Oct-98	441085	10/22/98	1
1020 Y	1FUYSDZB5XPB16099	E1778481	06-Oct-98	617764	10/23/98	2
30 Y	1FUYSDZB5XPB16099	E1778717	08-Oct-98	614988	10/26/98	1
1183 Y	1FUYSSZB1XPB22897	E1741078	08-Oct-98	393974	10/31/98	2
31 Y	1FUYSSZB1XLA01358	E1781278	08-Oct-98	555498	11/04/98	1
489 Y		YHCD000	08-Oct-98	509283	11/07/98	1
32 Y	2HGFHAMR1XC070482	CWA1177	08-Oct-98	320491	11/09/98	2
33 Y	1FLBSQZB7XPK985783	E1704762	08-Oct-98	415186	11/11/98	1
200 Y	1FUYSSZB9XLA01619	E1687204	13-Oct-98	364172	11/13/98	2
487 Y	1FUYSDYB7XPA87046	CWA0686	14-Oct-98	417425	11/15/98	1
494 Y	1FUYDDYB0XLA70829	0368717	14-Oct-98	274741	11/16/98	1
1289 Y	1FUYDSEB1XPA26658	E1687279	14-Oct-98	432283	11/17/98	1
201 Y	1FUYDSEB1XPA26658	E1687279	14-Oct-98	405499	11/18/98	1
34 Y	2HGFRAH4XK070296	CWA0466	14-Oct-98	168379	11/19/98	3
501 Y	1FUYDDYB0XLA70940	0034011	18-Oct-98	604482	11/21/98	3
222 Y	4VGTDBUF3XN788406	CWA0838	20-Oct-98	381658	11/23/98	2
504 Y	1FUYD3YB7XLS785518	E1682468	20-Oct-98	314612	11/24/98	2
505 Y	1FUYSSZB5XLA04987	E1700878	22-Oct-98	420080	11/25/98	2
507 Y	1FUYSDYB6XPA98810	VEH NO.	23-Oct-98		11/27/98	1
506 Y	1FUYNM090XLA927888	E1688113	25-Oct-98		12/01/98	2
509 Y	1FUYNM090XPA23409	E1700143	28-Oct-98	341022	12/03/98	1
206 Y	2HGFBAH4XK070292	CWA0273	31-Oct-98		12/04/98	1
208 Y		Unit	31-Oct-98	298792	12/05/98	1
1873 Y	1FUYSSZB0XPA07375	E1683068	04-Nov-98	488803	12/16/98	1
1001 Y	1FUYSDYB2XLA06912	0034224	07-Nov-98	409308	12/17/98	2
1184 Y	1FUYSSZB2XLA01624	E1776991	08-Nov-98	501287	12/18/98	2
36 Y	1FUYSSZB2XLA01624	E1744763	08-Nov-98	501725	12/31/98	0
37 Y	1FUYSDCYB1XLA48874	E1744771	11-Nov-98	284808		
38 Y	1FUYSSZB4XPA87443	E1674286	15-Nov-98	265802		
515 Y		Unit	13-Nov-98	263613		
39 Y	1FUYSSZB6XLA01333	CWA0609	15-Nov-98	520186		
516 Y	1FUPCSB2B1XPA67312	E1701164	16-Nov-98	409000		
209 Y		Unit	17-Nov-98	470204		
210 Y		Unit	18-Nov-98	490155		
211 Y	1FUYSDYB3XPA48884	E1684054	18-Nov-98	322243		
517 Y	1FLUHNWOA7XLB3254	E1682062	19-Nov-98	411868		
518 Y		Unit	19-Nov-98	402700		
1185 Y	1FLUWTECA3X-H3049	E1682105	21-Nov-98	143063		
40 Y	1FLUWTECA3X-H3049	E1682106	21-Nov-98	143063		
41 Y	1FLUWTECA3X-H3049	E1682106	21-Nov-98	143063		

214 Y		Unit	23-Nov-98	608696		
213 Y		Unit	23-Nov-98	508896		
42 Y	1FUYSDYBAXXP988377	CWA0112	24-Nov-98	422688		
43 Y	1FUYSDYBAXXP988379	E1845207	24-Nov-98	398606		
1188 Y	1FUY58ZB50XLA01533	CWA1575	25-Nov-98	648469		
217 Y	1FUY33ZB50XLA20441	E160085	25-Nov-98	245854		
522 Y	1FUY85ZB7XLA18133	E1778422	27-Nov-98	258014		
523 Y	1FUYTXYB3XLA77282	33887	01-Dec-98	898650		
1266 Y	1XP0DBBX4VN408850	CWA1312	01-Dec-98	632241		
1187 Y	1FUYNWDA6XLB2258	E1788984	03-Dec-98	541172		
524 Y	2HSFTAER1XC024205	CWA0485	04-Dec-98			
1344 Y	1FUYT8CB8XKB30019	E1823062	06-Dec-98	211298		
529 Y	1FUYDDYB0XDA39020	CWA0096	15-Dec-98	327684		
1287 Y	1FUYSDYB3XLB06880	0034580	17-Dec-98	380012		
879 Y	1FUYSDYB2XLB28645	0034387	17-Dec-98	458000		
218 Y	N94800YD		18-Dec-98	173		
860 Y	1FUYT5CBXKH30000	E1741117	18-Dec-98	274002		
44 Y	1FUPD8ZB7XLA84174	CWA0278	01-Jan-99			
45 Y	1FUPD8ZB7XLA84174	CWA0278	01-Jan-99			
221 Y	1PYDCYB00XLB30108	E1888178	06-Jan-99	389818		
48 Y	1FUPDXYB00XLA14617	E1688400	06-Jan-99	466486		
532 Y	1FUPDXYB00XLA14617	E1688400	06-Jan-99	466486		
1022 Y	1FUYJECBSXKH30012	E1787981	08-Jan-99	185480		
47 Y	1FUY34WE80XLA61760	CFA02893	10-Jan-99			
222 Y	1FUYNNMD8XKL972625	E1672074	14-Jan-99	389766		
223 Y	1FUY58ZB80XLA01441	E1687158	15-Jan-99	103202		
1188 Y	1FUY58ZB80XLA228673	E1797445	16-Jan-99	883157		
981 Y	1FUY33ZB2XLA406873	E1778449	18-Jan-99	822284		
1189 Y	2H9PBAER1XC037344	CFY00832	29-Jan-99			
48 Y	1FUY88ZB7XLA01440	CWA0273	29-Jan-99	462226		
49 Y	1FUYD8ZB1XLB973977	CWA0874	01-Feb-99	583429		
540 Y	1FUPDSCB0XKL973978	CHE0841	01-Feb-99	587114		
50 Y	1FUPC8ZB2XLB08121	E1688667	01-Feb-99	426615		
226 Y	1FUPDSEB0XPB50115	E1060674	04-Feb-99	572000		
544 Y	2HSFMAER8XC028294	CWA0386	10-Feb-99			
228 Y	1FUYDXYB5XLA77283	0034116	11-Feb-99	808244		
648 Y	1FUYDXYB5XLA77283	0034116	11-Feb-99	808244		
806 Y	1FUYBXYB8XLA686444	E178616	18-Feb-99			
81 Y	1FUYDWEBBX1A22942	E1710655	23-Feb-99			
1073 Y	1FUY8XYB0XLA72106	CWA1030	28-Feb-99	431268		
1204 Y	2H9PMAER5XC029046	WMT9275	28-Feb-99	313508	01/01/99	2
228 Y	1FUYDSYB2XLB88484	E1670084	01-Mar-99	284716	01/06/99	3
1104 Y		Unit	01-Mar-99		01/06/99	1
1189 Y	1FUY5XYB0XPA10374	E1767077	06-Mar-99	414824	01/10/99	1
62 Y	1FUY58E81X1B87544	E1765688	06-Mar-99		01/14/99	1
1088 Y	1FUPDSZB8XLA14612	E1745391	20-Mar-99		01/16/99	2
53 Y	1FUY33ZB80XLA42847	E1760134	22-Mar-99	733519	01/18/99	1
1272 Y	1FUYDXYB00LF98014	0034689	23-Mar-99	041871	01/20/99	2
54 Y	1FUY5XYB3XPA06251	E1716190	24-Mar-99	267300	02/01/99	3
882 Y	1FUY5XYB3XPA06251	E1716190	24-Mar-99	267300	02/04/99	1
1300 Y	2H9PHAMR2X0C03828	CWA1688	25-Mar-99	534269	02/10/99	1
1300 Y	2H9PHAMR2X0C03828	CWA1688	25-Mar-99	534269	02/11/99	2
56 Y	1FUPD8ZB80XPA68373	E1688621	25-Mar-99		02/19/99	1
654 Y	1FUPD8ZB80XPA68373	E1688621	26-Mar-99		02/23/99	1
225 Y	1FUYDDYB8XKB97276	0388601	27-Mar-99	442040	02/26/99	1
888 Y	1FUYDXYB8XLP88021	0388646	28-Mar-99	501881	02/28/99	1
56 Y	1FUPD8ZB80XLA14636	E1698401	31-Mar-99	270435	03/01/99	2
559 Y	1FUPD8ZB80XLA14636	E1703110	31-Mar-99	258164	03/02/99	1
561 Y	2HSBBAER5XC087100	CWA0386	01-Apr-99		03/08/99	1
1088 Y	1FUYDSEBXKPB70649	E1786041	01-Apr-99	543529	03/20/99	1
57 Y	1FUYSDYB8XLA61780	E1674309	01-Apr-99	252785	03/22/99	1
58 Y	1FUY88ZB80XLA42842	E1778451	03-Apr-99	491916	03/23/99	1
585 Y	2HSFTAER2X0C03833	CWA0880	05-Apr-99		03/24/99	2
608 Y	1FUYDDYB8XKB97284	0388743	05-Apr-99	403878	03/25/99	2
1181 Y	1FUYD5ZB1XPA64746	E1763685	12-Apr-99	573500	03/26/99	2
56 Y	1FUPD8ZB1XPA64743	E1717800	15-Apr-99	552883	03/27/99	1
50 Y	1FUYD8ZB8XPA64747		16-Apr-99	593468	03/29/99	1
572 Y	1FUY58ZB2XLA01672	CWA0468	18-Apr-99	406310	03/31/99	2
61 Y	1FUY8DYB8YPA69031	E1752263	20-Apr-99	303600	04/01/99	3
1027 Y	2HSFTAER2X0C043067	CWA1354	21-Apr-99	481421	04/03/99	1
1200 Y	2HSFTAER5XC090868	CWA1618	23-Apr-99		04/06/99	1
62 Y	1FUYD8ZB8XPA64333	E1633998	23-Apr-99	286462	04/09/99	1
1182 Y	1FUY88ZB8XLA42804	E1778482	25-Apr-99	570162	04/12/99	1
1183 Y	2HSFTAER5XC041893	CWA1519	03-May-99		04/15/99	1

230 Y	2H5FTASR0XC042536	E1987234	03-May-99	177990	04/16/99	1
1273 Y	2H3PAAER0XC041593	CWA1619	03-May-99	92600	04/18/99	1
63 Y	1FUY3DYB3YPA46769	E1517030	14-May-99	92600	04/20/99	1
582 Y	1FUYDDYB1YPF37320	33954	17-May-99	268703	04/21/99	1
231 Y	2HSFTA5R0XC033983	E1646525	15-May-99	191756	04/23/99	2
583 Y	2HSPMAER1XC029266	WMT9847	16-May-99	320974	04/26/99	1
1255 Y	XCO40888	CWA1355	20-May-99		05/03/99	3
1194 Y	XCO40565	CWA1355	20-May-99		05/14/99	1
1198 Y	1FUYDSZB2XPA84336	E17858930	20-May-99	544158	05/17/99	1
1277 Y	2HSFTAMR7XC041574	CWA1237	21-May-99		05/18/99	1
588 Y	1M1AE07Y1XW001201	CWA0498	26-May-99	809937	05/19/99	1
585 Y	1FUYDDYB8YLB84029	33892	26-May-99	443272	05/20/99	2
587 Y	2H5PHASR7YC037897	0823320A	28-May-99	308903	05/21/99	1
588 Y	1FUPC9S2BYLA88762	06762	01-Jun-99	273966	05/26/99	2
232 Y	1FUYSDYE3YLF38977	348805	01-Jun-99	391544	05/28/99	1
1261 Y	1FUYSB2B4YL854420	CWA1380	04-Jun-99	604662	06/01/99	2
1280 Y	2HSFMMAR2YC037026	CWA1618	04-Jun-99		06/04/99	4
1029 Y	1FUYDDYB7YLF60588	34098	04-Jun-99	443157	06/06/99	1
233 Y	1FUYSDYB8YLB867636	E1707284	04-Jun-99	456310	06/07/99	2
64 Y	1FUYSSZB2YLB854888	CWA1184	06-Jun-99	62708	06/10/99	2
589 Y	1FUYDDYB1YLF20942	338665	07-Jun-99	359724	06/11/99	3
594 Y	1FUYSDYB4YLA84213	E1895965	07-Jun-99	280000	06/12/99	1
58 Y	1FUYSDYB1YLA66413	E1748904	10-Jun-99	230565	06/14/99	2
1196 Y	1FUYSSZB8YLB854828	E1783245	10-Jun-99	442384	06/15/99	3
697 Y	4V4ND1UF0YN788434	CWA0505	11-Jun-99	291140	06/17/99	1
698 Y	1M1AA12Y6YW117312	CWA0498	11-Jun-99	182299	06/18/99	3
68 Y	4V4ND1UF0YN788434	CWA0648	11-Jun-99	344209	06/19/99	4
585 Y	1FUYSSZB8YLF02384	CWA1438	12-Jun-99	409632	06/22/99	3
1197 Y	1FUYSWD88YLA88692	E1781282	14-Jun-99	384288	06/23/99	4
854 Y	1FUYSEWE3YLA86108	CWA1400	14-Jun-99	407277	06/24/99	1
87 Y	1FUYSSZB2YLA82032	E1752443	16-Jun-99	346600	06/26/99	2
1284 Y	2HSFTA5R3X008281	CWA1452	16-Jun-99	343973	06/28/99	3
601 Y	4V4ND2UF0YN788380	CWA0173	16-Jun-99	388530	06/29/99	2
68 Y	1FUYSDYB0YLB80720	E1691102	17-Jun-99	346211	06/30/99	2
603 Y	4V4ND1J80YN788196	2034087	16-Jun-99	683443	07/01/99	5
68 Y	1M1AB08Y0XW001143	CWA0887	16-Jun-99		07/02/99	2
173 Y	1FUYDDYB0YLB897958	CWA0848	16-Jun-99	336132	07/04/99	3
1198 Y	1FUYSDYB8YPP88084	E1735901	16-Jun-99	327489	07/06/99	1
71 Y	1FUYSDYB8YPP88084	E1735901	19-Jun-99	327489	07/10/99	2
1004 Y	1FUYDDYB8YLF20930	0380880	19-Jun-99	325951	07/12/99	3
70 Y	1FUYSDYB4YPP880972	E1730988	19-Jun-99	325145	07/13/99	1
612 Y	1FUPC82B7YL891162	E1707483	22-Jun-99	371288	07/14/99	1
613 Y	1FUPC82B7YL891162	E1707483	22-Jun-99	371288	07/15/99	2
238 Y	2HSPTAER8K0C041975	40861A	22-Jun-99	182256	07/16/99	4
1031 Y	1FUYDCYB8YL1F3818	33887	23-Jun-99	367484	07/18/99	2
72 Y	1FUYSSZB8YPA88084	E1795829	23-Jun-99	364338	07/20/99	5
686 Y	1FUYSSZB0YLB887981	E1717834	25-Jun-99	306995	07/21/99	1
614 Y	1HSHCANRLYH212420	CWA1197	25-Jun-99	313533	07/22/99	2
1286 Y	1FUW3MCAY2YLB85441	CWA1290	24-Jun-99	446920	07/23/99	1
1199 Y	1FUYD8E85YPF28133	E1785948	25-Jun-99	322123	07/24/99	1
1032 Y	1FUPC82B8YPP880802	E1773098	25-Jun-99	344409	07/26/99	2
1287 Y	1FUYSDYB8YPA880877	E1786113	26-Jun-99	238000	07/27/99	2
617 Y	1XKWD8KUYJ888160	CWA1207	26-Jun-99	264734	07/28/99	3
73 Y	1FUYBDYB8YPA880883	E1780046	26-Jun-99	386172	07/29/99	5
74 Y	1FUYSDYB7YPA880847	Unit 3189	28-Jun-99		07/30/99	1
237 Y	1FUYSDYB8YPA880853	N086464	28-Jun-99	302048	08/01/99	1
78 Y	1FUYDWD81YL81792	E1641806	30-Jun-99	388239	08/02/99	1
238 Y	1FUYD800YU0	NO460070	30-Jun-99	209	08/03/99	2
76 Y	1FUYD8EB2YLF44985	8-837474*	01-Jul-99	584599	08/10/99	2
624 Y	1FUYSSZB0YLB854880	E1790074	01-Jul-99	482883	08/11/99	2
1201 Y	1FUYB02B8YLP871245	E1752349	01-Jul-99	349881	08/12/99	1
79 Y	1FUYSDYB8YLFP386812	E1772658	01-Jul-99	579730	08/13/99	1
77 Y	1FUYSDYB2YLF88798	E1744208	01-Jul-99	588583	08/14/99	2
621 Y	1FUYDSE80YLF44980	038886	01-Jul-99	367298	08/15/99	3
78 Y	1FUYSDYB8YLFP386423	E1773648	01-Jul-99	579180	08/16/99	2
1200 Y	1FUYSDZB8YLP871245	E1752349	01-Jul-99	349881	08/17/99	2
627 Y	1FUYDDYB2YDF37814	Unit 8	02-Jul-99	197412	08/18/99	1
628 Y	1FUYDDYB2YDF37814	32882	02-Jul-99	197412	08/19/99	2
1203 Y	1FUPDW8B4YDF5442	E1798214	08-Jul-99	471882	08/20/99	3
1202 Y	1FUYSSZB8YLB84203	E1772784	08-Jul-99	477024	08/23/99	2
1033 Y	1FUYDSZB8YLB88100	E1783577	08-Jul-99	367277	08/24/99	1
80 Y	1FUYSDYB8YPA467699	E1627208	08-Jul-99	90980	08/25/99	1
800 Y	1FUPC82B1YFP87244	E1682286	10-Jul-99	281740	08/26/99	1
801 Y	1FUYSSZB86XP867711	E1792489	10-Jul-99	466808	08/27/99	1

632 Y	1FUY5S7B7YLB54918	E1662020	12-Jul-99	548217	06/26/99	2
633 Y	1FUPD62B8YPA68056	E1706151	12-Jul-99	391921	06/30/99	4
240 Y	1FUT852B7YLB54844	E1793025	13-Jul-99	546809	06/31/99	3
1204 Y	2HSFTIMR0YC052688	CWA1014	14-Jul-99	367059	06/01/99	3
51 Y	1FUY39ER0YL063342	E1708888	15-Jul-99	06/07/99	1	
241 Y	1FUY39ER0YL063342	E1708888	15-Jul-99	06/07/99	1	
1290 Y	1FUV5MCA7YLB54440	CWA1357	16-Jul-99	398263	06/08/99	1
62 Y	1FUY5S8B0XLA60406	E1744738	16-Jul-99	06/08/99	3	
242 Y	1FUPL87B5YPB02016	E1669451	18-Jul-99	308355	06/11/99	1
1034 Y	1FUY5XY88YL861651	E1785035	18-Jul-99	422048	06/14/99	1
1205 Y	1FUPCSE88YL848501	E1798152	19-Jul-99	268248	06/15/99	1
638 Y	1FUY38EB2YPF20489	E1662277	19-Jul-99	272436	06/15/99	3
638 Y	2HSFTAER7Y8031728	CFW0109	19-Jul-99	198651	06/17/99	1
83 Y	1FUYDDYB7YLB64728	CWA0828	20-Jul-99	06/20/99	2	
84 Y	1FUYDDYB7YLB64743	E1663827	20-Jul-99	333962	06/24/99	1
85 Y	1FUYBSZB8YLB54822	E1708617	20-Jul-99	331928	06/28/99	1
1206 Y	1FUYEDYB9YLAD6434	E1792803	20-Jul-99	344633	06/27/99	1
1057 Y	1FUYCDYB7Y1805743	E1663827	20-Jul-99	333962	06/28/99	1
636 Y	1FUPDDYB0YL864728	CWA0828	21-Jul-99	06/30/99	1	
1292 Y	2HSFTASR3YCO24131	CWA1402	22-Jul-99	332284	10/04/99	1
1293 Y	2HSFTASR3YCO24131	CWA1402	22-Jul-99	332284	10/06/99	2
1207 Y	1FUY3SKYB3YLAD64851	E1795227	23-Jul-99	262486	10/06/99	1
86 Y	1FUYDDYB4YMF48084	033870	24-Jul-99	386799	10/08/99	1
1342 Y	1FUY8D0YB1YL11683	E1785651	26-Jul-99	273782	10/14/99	1
642 Y	1FUYDDYB3YL806788	CWA0436	26-Jul-99	291208	10/15/99	3
243 Y	Y0034837	CWA0568	27-Jul-99	388290	10/15/99	1
87 Y	1FUYDLYB4YMF48084	33626	27-Jul-99	305880	10/19/99	1
244 Y	1FUYSDYBAYLA65443	E1882211	28-Jul-99	286787	10/20/99	3
1206 Y	1FUPCZYB4YD787818	E1755096	28-Jul-99	408672	10/21/99	1
843 Y	1FUYD5ZBXYL8A60075	E1688299	29-Jul-99	474311	10/25/99	1
844 Y	1M1AA18Y20YW121463	CWA0436	29-Jul-99	251046	10/27/99	1
245 Y	1FUYSDYB3YPA50484	E1680018	29-Jul-99	222801	10/28/99	1
88 Y	1FUYSDYB0YPA50484	E1773686	29-Jul-99	380098	10/29/99	3
1003 Y	1FUYSSZB8YL864980	E1783284	30-Jul-99	382468	11/01/99	1
1294 Y	1M1AA18YSYIW116997	0034879	01-Aug-99	373876	11/03/99	1
1005 Y	1FUYSDYRXYLB861563	E1710514	05-Aug-99	286106	11/08/99	1
1209 Y	1FUPCXYB2YL870588	E1778223	08-Aug-99	312541	11/09/99	1
1038 Y	1FUYDDYB3YL860453	0334228	09-Aug-99	0	11/11/99	1
88 Y	1FUYWWQD45YLFB271	E1748140	10-Aug-99	383634	11/12/99	1
852 Y	1FUY882B80YPA68316	E1683176	10-Aug-99	225600	11/13/99	1
853 Y	1FUY5WE88YL816300	E1722504	11-Aug-99	581104	11/15/99	1
1295 Y	1FUY5WE88YL816254	E1782997	11-Aug-99	315200	11/16/99	2
1084 Y	1FUP05E888YLFB28318	E1741286	12-Aug-99	432484	11/19/99	1
1210 Y	1FUYSS8E88YLFB0188	E1798201	13-Aug-99	570993	11/25/99	1
1000 Y	1FUYSSZB0YPA78877	E1717463	14-Aug-99	302367	11/29/99	1
90 Y	1FUPCZYB4YD787519	787819	14-Aug-99	341048	12/01/99	2
856 Y	1FUYDC2B86YDF80214	32871	15-Aug-99	468620	12/03/99	1
1037 Y	1FUYDCY84YDF48084	00003385	15-Aug-99	0	12/10/99	1
246 Y	1FUYDCY82YDF80220	380811	15-Aug-99	443760	12/15/99	1
1038 Y	1FUY88EB2YL80788	E1778530	16-Aug-99	258145	12/16/99	1
906 Y	1FUY88EB2YL80788	E1778530	16-Aug-99	260145	12/17/99	1
91 Y	1FUY88EB2YL864864	E1744783	17-Aug-99	378222	12/20/99	4
1099 Y	1FUY88ZB3Y1LB34194	E1781300	17-Aug-99	637485	12/21/99	2
657 Y	1FUY20ZB4YPA88848	E1720817	18-Aug-99	374623	12/22/99	1
661 Y	2HSFTMAXR0YC032853	CWA0349	18-Aug-99	0	12/24/99	1
680 Y	2HSFTMAXR0YC032853	CWA0349	19-Aug-99	0	12/29/99	2
251 Y	1FUYSS8E88YL860451	E1680202	20-Aug-99	784620	12/29/99	1
92 Y	1FUYDW0828YL81793	E1872385	20-Aug-99	658312	12/30/99	2
93 Y	1FUYDW0828YL81793	E1872385	20-Aug-99	658312	12/31/99	0
085 Y	1FUY3XYB7YL840032	E1682210	23-Aug-99	278002		
664 Y	2HSFTAERHYC034848	034868	23-Aug-99	815808		
1041 Y	1FUYSDYB6YL84224	E1783333	24-Aug-99	343046		
94 Y	1FUYHWD48YLFB275	E1780128	25-Aug-99	410001		
1042 Y	1M1AA12Y3YW12487	CWA1483	26-Aug-99	375820		
1236 Y	2HSFTAERHYC034152	CWA1582	27-Aug-99	475886		
1043 Y		34220	28-Aug-99			
1296 Y	1FUD93E35YPB73104	0034629	28-Aug-99	662361		
670 Y	2HSFHAMR1YC030259	6347902A	30-Aug-99	288403		
671 Y	2HSFHAMR1YC030259	6347902A	30-Aug-99	288403		
95 Y	2HSFTAMR8YCO38848	0028861A	30-Aug-99			
96 Y	1FUYSDYB7YPB85730	E1717818	30-Aug-99	383860		
97 Y	1FUPD82B1YLFB9730	E1696343	31-Aug-99	287091		
673 Y	4V4ND1UFXYN787884	CWA0639	31-Aug-99	334810		
222 Y	2HSFHAMR8YCO46441	0111731A	31-Aug-99	250799		


SKF 002163

987 Y	1FUYDDYB7YPF26768	E1793325	01-Sep-99	687103
986 Y	1FUYDDYB7YPF26768	E1793325	01-Sep-99	687103
1211 Y	1FUYSDYB3YL46579	E1788808	01-Sep-99	260303
85 Y	1FUYDDYBXYYFA83374	B3374	06-Sep-99	652841
98 Y	1FUY97DB0YPAB89891	E1684132	07-Sep-99	225466
100 Y	1FUYSSB80YLA88308	E1700884	08-Sep-99	358284
1212 Y	1FUPC5ZB4YP042638	E1783378	08-Sep-99	374487
101 Y	1FUYSSZB8YPB89481	CWA0748	08-Sep-99	589878
102 Y	1FUYSSZB8YPB89481	E1698000	08-Sep-99	508663
103 Y	1FUWNNWDAZYL09263		11-Sep-99	374640
877 Y	1FUPDCZB0YPG19884	E1678135	14-Sep-99	
104 Y	1FUY3MDB4YL03456	E1691022	15-Sep-99	208535
879 Y	1M1AA12YXYW121978	CWA0637	15-Sep-99	307087
105 Y	1FUY65ZB3YPF23783	E1730671	16-Sep-99	320405
293 Y	1M1AA12YXYW121978	CWA0637	16-Sep-99	307087
106 Y	1FUPC5ZB10F88758	E1745020	17-Sep-99	463120
1213 Y	1FUY3DYB8YPB80529	E1783381	20-Sep-99	114675
1044 Y	1FUY3DYB8YL07238	E1783387	20-Sep-99	333741
107 Y	1HSCNAER3YCD5740	CWA1254	24-Sep-99	
1214 Y	1FUPCDZB8XPA16380	E1741252	26-Sep-99	266281
108 Y	1FUYSSZB4YPF23789	E1748138	27-Sep-99	424877
883 Y	4V4ND2JF1YN242617	33835	28-Sep-99	277222
884 Y	1M1AA12Y2YW123222	CWA0434	30-Sep-99	480000
109 Y	1HSCAAHNP9YJ068665	68665	04-Oct-99	256888
885 Y	2HSCNAER5YLG06141	CWA0583	05-Oct-99	248638
1046 Y	1FUPCXB8Y1887866	E1785937	08-Oct-99	552194
886 Y	2H8FTASR6XC042638	E1687954	08-Oct-99	184655
1215 Y	1FUY8SZB8YL88688	CWA1481	08-Oct-99	377144
1046 Y	1FUY3DZB24P816241	E1778408	14-Oct-99	318111
887 Y	2HSCNAER5YQ06283	CWA0389	16-Oct-99	
1216 Y	1FUY6MDR1YL603460	E1797036	16-Oct-99	360211
110 Y	1FUYD9E868YP840540	E1670070	15-Oct-99	230649
111 Y	2HSCNAER7YJ046117	1016034A	16-Oct-99	170862
112 Y	1M1AA09Y7YW019793		19-Oct-99	279729
258 Y	1FUY8S2B80YL886884	E1680596	20-Oct-99	224106
1217 Y	YC036706	CWA1329	20-Oct-99	266060
1236 Y	YC036706	CWA1329	20-Oct-99	266060
113 Y	1FUYDXB81YPB84899	E1689425	21-Oct-99	326433
1303 Y	1FUPDXZB1YL886877	CWA1584	26-Oct-99	
1304 Y	1FUYDDYB8YL088833	440971	27-Oct-99	360116
114 Y	1FUYSDZB8YP816261	CWA1015	28-Oct-99	214024
1218 Y	1FUPD8ZB1YL887483	E1781808	29-Oct-99	213730
890 Y	2HSCNAER6YLG068448	00744389	29-Oct-99	295338
891 Y	1FUYDDYB8YL886184	E1686301	30-Oct-99	174378
897 Y	1FUYSDYB6YF00200	E1703968	01-Nov-99	168382
259 Y	1M1AA3Y1YW121948	CWA0321	02-Nov-99	128457
115 Y	1FUY8XYB7YL886313	E1744786	06-Nov-99	170226
700 Y	1HSCEAHRTYJ05880	02381860	08-Nov-99	241798
267 Y	2HSCCEAMR8C040290	6383718A	11-Nov-99	285720
1002 Y	1FUY8CYR0YL7B970	E1788805	12-Nov-99	
899 Y	1FUYDDYB8YL886885	E1717878	13-Nov-99	157428
1306 Y	1KPCDR8XEXN468385	CWA1686	15-Nov-99	383643
259 Y	2H8FTAER5YQ046233	1022181A	15-Nov-99	295300
118 Y	1FUY8S2B8YL8868404	E1773870	18-Nov-99	423453
1307 Y	1FUP08ZB8YL886154	CWA1401	18-Nov-99	407216
708 Y	1FUYSDYB8YL886880	E1689080	20-Nov-99	246830
709 Y	1FUYD9E868YL886822	E1707482	20-Nov-99	204719
710 Y	1FUYDXB7XL877284	33839	01-Dec-99	740386
261 Y	2HSCCEAMR8YCD404462	9888416A	01-Dec-99	207176
1219 Y	1FUY8S2B8YL886181	E1788544	03-Dec-99	341900
262 Y	2HSCNAER5YCD6228	E1648818	10-Dec-99	41189
711 Y	2HSCNAER7YJC068800	0093084A	15-Dec-99	178143
264 Y	2HSCCEAMR3YCD71123	9884248A	16-Dec-99	270280
265 Y	1FUPDSZB7YCA14612	E1701163	17-Dec-99	
266 Y	2HSCNAER9YCD048402	0103570A	20-Dec-99	161766
1371 Y	2HSCCEAXRTYC070434	00103	20-Dec-99	
267 Y	2HSCCEAMRXYC04012	9347364A	20-Dec-99	246077
268 Y	1FUYSDYB3YPAB88784	E1686083	20-Dec-99	348177
720 Y	1FUT80ZB8YL886378	0034124	21-Dec-99	383881
721 Y	1M1AA13Y0YW127770	CBE2246	21-Dec-99	168967
269 Y	4V4NDM4UH8YN280886	E1686208	22-Dec-99	163186
723 Y	1FUY8S2B8YL886830	E1682247	24-Dec-99	105415
726 Y	1FUYD9E868YL886917	E1715674	25-Dec-99	
724 Y	1FUD0YB81YPG13891	016292	26-Dec-99	466160


117 Y	1FUY8DYB3YLF48193	33897	26-Dec-00	397604		
1220 Y	1FUY8SEB1YPG06381	E1762301	30-Dec-00	253885		
1370 Y	2HSCNAMR8YCO05885	CWA1466	30-Dec-00	551077		
118 Y	1FUY8SEB3XYPP00438	E1755635	03-Jan-00	124962		
119 Y	1FUYNEB2YYP586432	E1674330	04-Jan-00	182359	01/01/00	0
270 Y	2HSCCEAMR0YC30723	9378513A	05-Jan-00	253809	01/03/00	1
729 Y	2HSCCEAM0YC030723	9378813A	05-Jan-00	253809	01/04/00	1
730 Y	2HSCCEAH-R3YCO044585	CWA0434	11-Jan-00	346235	01/05/00	2
731 Y	2HSCBAAH-R3YCO064585	CWA0434	11-Jan-00	346236	01/11/00	2
272 Y	3HSFMAXR4Y039872	1029218	14-Jan-00	66837	01/14/00	1
880 Y	1FUY8SEB3YLA68497	E1785583	15-Jan-00	412700	01/15/00	1
120 Y	1FUY8SEB3YLB66613	E1751474	23-Jan-00	185217	01/23/00	1
735 Y	2HSCKASR3YCO71357	00265744	24-Jan-00	234268	01/24/00	1
737 Y	1FUPD0ZB8YLB856178	E1684304	25-Jan-00	388509	01/25/00	1
273 Y	1FUY87EBXYPG880320	E1687103	30-Jan-00	178571	01/30/00	1
1060 Y	1FUY8SEB1YLFL00500	E1710642	31-Jan-00	261363	01/31/00	2
274 Y	2HSCAXR2YC066617	E1849463	31-Jan-00	184963	02/01/00	1
275 Y	1XKWD09X8YTR966383	CWA0631	01-Feb-00	920390		
121 Y	1FUPD0ZB2YPB08603	E1898283	03-Feb-00	306141	02/06/00	1
122 Y	1FUPC52B7YPB62034	E1705158	05-Feb-00	308662	02/10/00	1
123 Y	1FUY85ZB7YLB66177	E1724321	10-Feb-00	384673	02/16/00	1
740 Y	1MIA007BYW005707	CWA0571	16-Feb-00	171946	02/17/00	1
278 Y	2HSCAAER4YC066639	00441484	17-Feb-00	144147	02/21/00	2
1221 Y	1FUY8ZYB6YPF48388	E1778031	21-Feb-00	266363	02/24/00	1
741 Y	2HSCNAMR8YCO5873	0288692A	21-Feb-00	167728	02/26/00	1
124 Y	1FUY85ZB2YLB66223	C8Y0046	24-Feb-00	421464	02/28/00	1
277 Y	1FUPD7EB8YPAB08128	E1672341	25-Feb-00	172104	03/04/00	1
278 Y	1FUYD82B9YLG48817	E1703150	25-Feb-00	931300		
746 Y	2HSCHAFR8YC70238	140767A	08-Mar-00	244822	03/13/00	1
748 Y	1FUPD5ZB0YLFD2878	E16882218	13-Mar-00	188797	03/22/00	1
747 Y	1FUPD5ZB0YLFD2978	E16882218	13-Mar-00	188797	03/23/00	1
761 Y	1FUY8SEB0YLB663448	E1705048	15-Mar-00	392600		
279 Y	2HSCKAER4YC071788	E16897978	22-Mar-00	82134	03/29/00	2
1222 Y	1FUY87EB2YPG028810	E1787993	23-Mar-00	410088	04/03/00	2
1223 Y	1FUY8SEB8YPB41154	E1705174	25-Mar-00	282281	04/10/00	2
125 Y	1FUY87EB0YPAB0423	E1776067	29-Mar-00	317826	04/12/00	1
1374 Y	1FUYD5ZB1YLG686590	E1683288	03-Apr-00	375151	04/16/00	1
691 Y	1XPCDU8X3DNB11397	CWA1240	03-Apr-00	491990	04/18/00	1
1224 Y	1FUYD8ZB3YLUH40384	E1786118	10-Apr-00	223668	04/20/00	1
1093 Y	1FUYD8ZB0YLH40388	E1741246	10-Apr-00	191226	04/27/00	1
1315 Y	1HSHCAHR1YH272678	C8Y0071	12-Apr-00	254936	05/03/00	1
754 Y	1FUY8SEB8YPB41272	E1707287	15-Apr-00	172807	05/12/00	1
760 Y	1FUYD5ZB3YLQ667909	E1778229	18-Apr-00	168591	05/25/00	1
1226 Y	1FUY8SEB8YLG07438	E1796183	20-Apr-00	246276	05/28/00	1
1099 Y	1FUY8ZYB8YLFB6772	E1750104	27-Apr-00	860100		
295 Y	2HSCNAMR81C076742	E142674A	03-May-00	848229	06/06/00	2
902 Y	1FUY85ZB31LG94328	E1717838	12-May-00	312203	06/08/00	2
770 Y	2HSCKAPR8YC064722	114548A	25-May-00	152075	06/15/00	1
296 Y	1FLUAABD81LG61680	E1688692	26-May-00	148820	06/21/00	1
126 Y	1FUY85ZB21LG62171	E1793074	01-Jun-00	334152	06/23/00	1
287 Y	2HSCNAMR71C0794466	83375A	06-Jun-00	160688	06/29/00	1
127 Y	1FUY8SEB31P0441378	E1679583	08-Jun-00	178412	06/27/00	1
773 Y	2HSCNAMR81C025827	0089843A	09-Jun-00	118180	07/10/00	1
1375 Y	1FUY80YBX1LH37409	E1782648	09-Jun-00	192466	07/13/00	2
1228 Y	1FUJA3CG61LG62177	E1795173	15-Jun-00	438125	07/14/00	1
128 Y	4V4N8RHH1N239287	CCV0034	21-Jun-00	43671	08/01/00	1
129 Y	1FUJA-HB81LG71191	33680	22-Jun-00	449786	08/07/00	1
298 Y	1FUPD0YB8YLG16483	CWA0707	23-Jun-00	091400		
130 Y	1FUY85ZB31LG444343	E1674311	27-Jun-00	173242	08/28/00	1
299 Y	1FUYDWB3YLB1793	E1672382	10-Jul-00	368412	10/03/00	1
1007 Y	1FLJCLCG11PG06403	E1741268	13-Jul-00	167887	10/04/00	1
777 Y	1FUYDWB3XYLB1785	E1741271	13-Jul-00	580162	10/13/00	1
291 Y	1FUYDWB37YLH1794	E1672361	14-Jul-00	381374	11/02/00	1
293 Y		17084664	01-Sep-00	118083	12/14/00	1
131 Y	1FLUJA3CG41LGW485	E1687418	07-Sep-00	41412	12/15/00	1
132 Y	2HSCAMRN21C010389	KFA03341	14-Sep-00	120710	12/18/00	1
133 Y	1FUNA3B041PG08471	E1738627	26-Sep-00	125288	12/31/00	0
134 Y		CBX00473	02-Oct-00	633		
764 Y	4V4N8D4J-BV1247818	CWA2834	04-Oct-00	230981		
1364 Y	1FLUJB8B091LH98808	E1795549	13-Oct-00	247031		
792 Y	2HSCAAER2YC0683984	01482658	22-Nov-00	138013		
1347 Y	1FLUJAHCQX1LJ20437	20437	14-Dec-00	201304		
265 Y	2HSCNAMR81C067438	64832A	15-Dec-00	157161		
1227 Y	1FLUJA3CG81PH98826		18-Dec-00	212000		

793 Y	1XPCCDR8X1YD614352	CWA0871	01-Jan-01	312710	01/01/01	1
696 Y	1FUIJBBCG71PB88710	E1871900	04-Feb-01	67367	02/04/01	1
1056 Y	1XXWDRC981R8879257	CWA1106	05-Feb-01	236253	02/05/01	1
600 Y	117991	F100	21-Feb-01	426	02/21/01	1
601 Y	2HSCCEAHR31C021236	44368A	23-Feb-01	69353	02/23/01	1
971 Y	1FUIJBBAV81LF25366	E1781270	15-Mar-01	106840	03/15/01	1
297 Y	1FUIJBBCG31LJ15204	E1674302	16-Mar-01	34988	03/16/01	2
1348 Y	1FUIJBBCGX1LJ15202	1796483	15-Mar-01	201419	03/15/01	1
1387 Y	4V4MC0RF91N328053	E1763842	21-Mar-01	74600	04/06/01	1
135 Y	1FUIJBBCG71PB88836	E1744724	00-Apr-01	63469	04/06/01	1
296 Y	1FUPUDZB01LF88348	E1662395	03-Apr-01	17810	05/03/01	1
604 Y	1FUIJBBCA21PB88019	E1663803	03-May-01	76300	05/06/01	1
1363 Y	1FUIJAHBG32PJ84114	E1781379	06-May-01	120560	07/01/01	2
1368 Y	1FUIJABLG32LK06658	E1786737	01-Jun-01	133471	07/02/01	2
1360 Y	1FUIJAACG82LK06808	E1778615	01-Jun-01	157671	07/03/01	2
806 Y	1FUIJAACG32LK08814	E1773848	02-Jun-01	182278	07/06/01	3
1351 Y	1FUIJAACG32LK06616	E1786054	02-Jun-01	229167	07/06/01	2
907 Y	2HSCCEAMR72C023268	9379713A	03-Jun-01	81284	07/07/01	2
808 Y	2HSCCEAMR72C023268	9378713A	03-Jun-01	81284	07/13/01	1
1385 Y	1FUIJAACG72LK08817	E1778619	05-Jun-01	181981	07/15/01	1
1360 Y	1FUIJAACG82LK08827	E1778616	05-Jun-01	186906	07/16/01	1
1346 Y	1FUIJAACG32LK06630	E1778620	06-Jun-01	158892	07/25/01	1
1363 Y	1FUIJAACG82LK06634	E1785738	06-Jun-01	147371	08/22/01	1
1387 Y	1FUIJAACG342LK06636	E1786257	08-Jun-01	180533	08/28/01	1
972 Y	1FUIJAACG82LK08839	E1778618	07-Jun-01	184995	08/26/01	1
1348 Y	1FUIJAACG362LK06638	E1778616	07-Jun-01	184998	08/26/01	1
1355 Y	1FUIJBBD52PL15196	E1795601	13-Jun-01	107974	10/16/01	1
1361 Y	1FUIJAACG82LF24807	E1800682	15-Jun-01	92723	12/05/01	1
1358 Y	1FUIJAHBG22PJ71412	E1773681	16-Jun-01	89500	12/31/01	0
809 Y	1FUIJARL082LJ73867	E1790131	25-Jun-01	60934		
811 Y	1FUIJAAC812LJ74358	E1752389	22-Aug-01	81672		
816 Y	1FUIJAPC3015H08489	E1662133	23-Sep-01	102247		
818 Y	1XP8080XX2H674488	C800409	25-Sep-01	38666		
817 Y		3120441A	26-Sep-01			
815 Y	2HSCCHAPR4YC048184		19-Oct-01			
136 Y	1FUPCDY80XLA94169	E1727993	04-Dec-01	862891		


1997 IBD Failures



1998 IBD Failures



1999 IBD Failures




SKF 002157

2000 ISO Fails




2001 ISO Fails



SKF 002168


Period End	Net		Period End	Fail Rate
	Fail	Produced		
03/31/98	0	0	03/31/98	#DIV/0!
04/15/98	0	0	04/15/98	#DIV/0!
04/30/98	0	0	04/30/98	#DIV/0!
05/15/98	0	0	05/15/98	#DIV/0!
05/31/98	0	0	05/31/98	#DIV/0!
06/15/98	2	0	06/15/98	#DIV/0!
06/30/98	0	0	06/30/98	#DIV/0!
07/15/98	0	0	07/15/98	#DIV/0!
07/31/98	2	1124	07/31/98	0.1778%
08/15/98	23	2771	08/15/98	0.8300%
08/31/98	19	6032	08/31/98	0.3150%
09/15/98	17	4437	09/15/98	0.3831%
09/30/98	20	3023	09/30/98	0.6098%
10/15/98	0	824	10/15/98	0.0000%
10/31/98	2	3644	10/31/98	0.0548%
11/15/98	8	5181	11/15/98	0.1737%
11/30/98	3	3255	11/30/98	0.0022%
12/15/98	0	0	12/15/98	#DIV/0!
12/31/98	8	2068	12/31/98	0.1570%
01/15/99	10	5341	01/15/99	0.1577%
01/31/99	20	7030	01/31/99	0.2888%
02/15/99	2	0	02/15/99	#DIV/0!
02/28/99	9	5817	02/28/99	0.1647%
03/15/99	14	8484	03/15/99	0.1680%
03/31/99	31	7571	03/31/99	0.4041%
04/15/99	1	0	04/15/99	#DIV/0!
04/30/99	58	6724	04/30/99	0.8328%
05/15/99	106	7269	05/15/99	1.4603%
05/31/99	10	7278	05/31/99	0.1374%
06/15/99	20	7437	06/15/99	0.2860%
06/30/99	13	8111	06/30/99	0.1608%
07/15/99	4	3598	07/15/99	0.1111%
07/31/99	12	8531	07/31/99	0.1403%
08/15/99	2	0	08/15/99	#DIV/0!
08/31/99	2	498	08/31/99	0.4274%
09/15/99	14	4032	09/15/99	0.3472%
09/30/99	12	7145	09/30/99	0.1810%
10/15/99	4	5127	10/15/99	0.0780%
10/31/99	6	5732	10/31/99	0.0891%
11/15/99	13	6795	11/15/99	0.1922%
11/30/99	12	4880	11/30/99	0.2876%
12/15/99	4	8543	12/15/99	0.0606%
12/31/99	3	3037	12/31/99	0.0688%
01/15/00	4	8350	01/15/00	0.0632%
01/31/00	2	364	01/31/00	0.0076%
02/15/00	0	0	02/15/00	#DIV/0!
02/28/00	2	3024	02/28/00	0.0661%
03/15/00	5	6617	03/15/00	0.0733%
03/31/00	2	7872	03/31/00	0.0251%
04/15/00	2	6630	04/15/00	0.0306%
04/30/00	1	5684	04/30/00	0.0178%
05/15/00	5	6638	05/15/00	0.0763%
05/31/00	3	4498	05/31/00	0.0667%
06/15/00	0	0	06/15/00	#DIV/0!
06/30/00	0	0	06/30/00	#DIV/0!
07/15/00	0	0	07/15/00	#DIV/0!
07/31/00	0	0	07/31/00	#DIV/0!
08/15/00	0	0	08/15/00	#DIV/0!
08/31/00	0	0	08/31/00	#DIV/0!
09/15/00	0	0	09/15/00	#DIV/0!
09/30/00	0	0	09/30/00	#DIV/0!
10/15/00	0	3388	10/15/00	0.0000%



55
55002
0.00065


10/31/00	6	8286	10/31/00	0.0059%	
11/15/00	4	4281	11/15/00	0.0034%	
11/30/00	2	986	11/30/00	0.0026%	212000
12/15/00	1	0	12/15/00	#DIV/0!	239253
12/31/00	0	0	12/31/00	#DIV/0!	247031
01/15/01	2	5942	01/15/01	0.0607%	167507
01/31/01	0	0	01/31/01	#DIV/0!	126285
02/15/01	3	3181	02/15/01	0.0049%	702647
02/28/01	21	1865	02/28/01	1.0687%	157181
03/15/01	4	2179	03/15/01	0.1636%	833
03/31/01	1	1080	03/31/01	0.0026%	109318
04/15/01	0	1808	04/15/01	0.0000%	120598
04/30/01	0	2435	04/30/01	0.0000%	109318
05/15/01	0	1417	05/15/01	0.0000%	201419
05/31/01	1	0	05/31/01	#DIV/0!	281304
06/15/01	1	0	06/15/01	#DIV/0!	76300
06/30/01	0	318	06/30/01	0.0000%	
07/15/01	0	0	07/15/01	#DIV/0!	69363
07/31/01	0	1993	07/31/01	0.0000%	67367
08/15/01	0	1875	08/15/01	0.0000%	733818
08/31/01	0	1908	08/31/01	0.0000%	74600
09/15/01	0	1364	09/15/01	0.0000%	107974
09/30/01	0	2002	09/30/01	0.0000%	82723
10/15/01	0	1980	10/15/01	0.0000%	61264
10/31/01	0	2180	10/31/01	0.0000%	159882
11/15/01	0	2082	11/15/01	0.0000%	133471
11/30/01	0	1691	11/30/01	0.0000%	158986
12/15/01	0	1712	12/15/01	0.0000%	188053
12/31/01	0	0	12/31/01	#DIV/0!	184993
01/15/02	0	0	01/15/02	#DIV/0!	81284
01/31/02	0	0	01/31/02	#DIV/0!	157871
02/15/02	0	2385	02/15/02	0.0000%	182270
02/28/02	0	1410	02/28/02	0.0000%	225167
03/15/02	0	2082	03/15/02	0.0000%	147371
03/31/02	0	449	03/31/02	0.0000%	181991
04/15/02	0	0	04/15/02	#DIV/0!	60334
04/30/02	0	0	04/30/02	#DIV/0!	398662
05/15/02	0	2784	05/15/02	0.0000%	91872
05/31/02	0	2260	05/31/02	0.0000%	99950
06/15/02	0	2230	06/15/02	0.0000%	
06/30/02	0	2874	06/30/02	0.0000%	5460000
07/15/02	0	0	07/15/02		46
					116844.91

SKF Alken Failure Rate Based on Hub Julian Date



SKF 002161

ates



©Pent-Rite

SKF 002162

ID	VAL?	Julian Date Translation	Hub Problem Y/N	SKF SERIAL #	VIN#	IN SERVICE DATE	FAILURE DATE	MILES
54 A		01-Jun-98 Y		15298 00142720	1FUY5XYB3XPA05251	24-Mar-98	02-Nov-01	267309
55 A		05-Jun-98 Y		015898 0067125	1FUPDS2B3XPA46373	28-Mar-98	27-Apr-01	386097
846 A		27-Jul-98 Y		23998 0015728	1FUYDDYB4XLA70917			
34 A		30-Jul-98 Y		21198 0010100	2H5FRAHR4XC070206	14-Oct-98	18-Sep-01	155379
712 A		02-Aug-98 Y		21598 0010545	1FUPDS2B3YMB4262	02-Dec-98	16-Jun-01	244682
1183 A		03-Aug-98 Y		21598 0010684	1FUY5SEB1XP923007	05-Oct-98	23-Dec-01	392974
483 A		04-Aug-98 Y		21698 0011278	1XPCD85X1XN488539	18-Sep-98	26-Oct-01	488768
1182 A		05-Aug-98 Y		21798 0010700	1FUY5DYB7XP425797	24-Sep-98	20-Feb-02	403100
195 A		05-Aug-98 Y		21798 0010881	1FUYDSEB5XPA07044	01-Sep-98	13-Mar-02	411300
462 A		05-Aug-98 Y		21798 0011003	1XPCD85X1XN488530	15-Sep-98	25-Oct-01	488758
31 A		06-Aug-98 Y		21898 0011263	1FUY58ZB1XLA01305	05-Oct-98	11-Mar-01	566496
539 A		06-Aug-98 Y		21898 0011335	1FUYD9ZB0XL037889	01-Feb-99	24-Jan-02	586016
1020 A		06-Aug-98 Y		21898 001270	1FUY8DZB5XP016009	05-Oct-98	04-Apr-02	517754
763 A		07-Aug-98 Y		21998 0011546	1FUY57EB4YP026939	23-Mar-98	07-Apr-02	4797915
33 A		07-Aug-98 Y		21998 0011535	1FUY8DZB7XP965733	06-Oct-98	19-Sep-01	415198
26 A		07-Aug-98 Y		21998 0011532	1FUY59E97XP457435	22-Sep-98	05-Jul-01	489187
32 A		08-Aug-98 Y		22098 0011512	2H5FHAMR1XC075492	06-Oct-98	04-Mar-02	320491
1188 A		10-Aug-98 Y		22298 0026193	1FUY29ZB3XLA01633	25-Nov-98	15-May-02	540489
27 A		11-Aug-98 Y		22398 0011999	1FUYD5YB4XJL976606	25-Sep-98	27-Aug-01	360683
659 A		12-Aug-98 Y		22498	1FUPDS2B5XLA14835	31-Mar-98	10-Sep-01	288184
604 A		12-Aug-98 Y		22498 0012262	1FUY5DYB7XL976615	20-Oct-98	27-Aug-01	314512
645 A		13-Aug-98 Y		22698 0020863	1FUYDDYB6XLA70914			310151
50 A		14-Aug-98 Y		22698	1FUPDS2B5XLA14835	31-Mar-98	23-Jul-01	270436
1698 A		14-Aug-98 Y		22698 0130720	1FUY58E93TYLA885417	26-Jul-98	08-Apr-02	344482
487 A		14-Aug-98 Y		22698 0012906	1FUY5DYB7XP467048	14-Oct-98	16-Jan-02	417625
488 A		14-Aug-98 Y		22798 0013327	1FUYDDYB7XP489185	30-Sep-98	24-Aug-01	388348
867 A		14-Aug-98 Y		22898 0013082				#06219
809 A		17-Aug-98 Y		22998 0013578	1FUVNMDS8XPA23400	28-Oct-98	16-Sep-01	341622
1523 A		19-Aug-98 Y		23198 0014050	2H5FHABEROC26284	23-Jan-98	21-May-02	703014
1522 A		19-Aug-98 Y		23198 0014062	2H5FHABEROC26284	23-Jan-98	21-May-02	703014
595 A		22-Aug-98 Y		23498 0014798	1M1A807Y1XW001201	28-May-98	02-Oct-01	505837
516 A		22-Aug-98 Y		23498 0014898	1FUPCS2B1XPA57312	16-Nov-98	17-Sep-01	408880
199 A		25-Aug-98 Y		23798 0013202	1X6AD99X8XJ799392	01-Oct-98	21-Mar-02	377146
1832 A		26-Aug-98 Y		23898 00167	1FUY3DYB3XP434621	08-Oct-98	26-May-02	480699
493 A		26-Aug-98 Y		23998 0015413	1FUY58ZB5XLA37985	14-Oct-98	18-Feb-02	488129
494 A		27-Aug-98 Y		23998	1FUYDDYB6XLA70929	14-Oct-98	21-Mar-02	274741
848 A		27-Aug-98 Y		23998 0016988	1FUYDDYB6XLA70921			416370
894 A		27-Aug-98 Y		23998 0016042	1FUYDDYB7XL97027			682856
840 A		27-Aug-98 Y		23998 0016764	A63645			867711
41 A		29-Aug-98 Y		24198 0015700	1FUMTCCA3XHE30468	21-Nov-98	27-Jul-01	143063
823 A		29-Aug-98 Y		24198 0016426	1FUYDDYB6XLA70914			367106
848 A		29-Aug-98 Y		24198 0016419	1FUYDDYB6XLA70918			417040
1874 A		29-Aug-98 Y		24198 0016421	1FUYDDYB2HA70916			575800
861 A		29-Aug-98 Y		24198 041777	1FUYDDYB6XLA70921			200562
226 A		31-Aug-98 Y		02498 0016160	1FUYDDYB6XLA7263	11-Feb-99		605244
928 A		31-Aug-98 Y		24398 0016621	1FUY3DYB9XP988957		07-Dec-01	384859
486 A		01-Sep-98 Y		24498	1FUY58E97XL921514	30-Sep-98	21-Sep-01	348460
978 A		03-Sep-98 Y		24698 0017228	1FUY3DYB2XLB26845	17-Dec-98		459500
136 A		03-Sep-98 Y		24698 0017229	1FUY88C371PB34830	06-Apr-01	11-Aug-01	53489
517 A		04-Sep-98 Y		24698 0016110	1FHJNNHOA7XLB32548	18-Nov-98	31-Jul-01	411855
1699 A		04-Sep-98 Y		24798 0017731	1FUYDDYB7XL98979	03-Nov-98		860841
1214 A		04-Sep-98 Y		24798 0022670	1FUPCD2B8XPA18360	20-Sep-98	03-Nov-01	368261
801 A		05-Sep-98 Y		24698 0016267	1FUYDDYB6XLA70940	19-Oct-98		864602
181 A		05-Sep-98 Y		25098 0015801				
850 A		07-Sep-98 Y		26198 0046919	1FUYDDYB6XLA70931			260862
548 A		07-Sep-98 Y		25098 0016803	1FUYDDYB5XLA77263	11-Feb-99		608244
498 A		07-Sep-98 Y		25098 0016454	4V670BLF0P0N788361	14-Oct-98	20-Jan-02	344370
829 A		08-Sep-98 Y		25198 0018210	A63665			867711
1337 A		08-Sep-98 Y		25198 0018678				
565 A		12-Sep-98 Y		25598 0020687	1FUYDDYB6XCB57265	08-Apr-99		403875
847 A		12-Sep-98 Y		25598 0020470	1FUYDDYB6XLA70915			460374
26 A		14-Sep-98 Y		25798 0021187	1FUY8DYB4XP988349	24-Sep-98	24-Jan-02	368279
1088 A		14-Sep-98 Y		25798 0021198	1FUP98EB6XP973462	09-Nov-98	02-May-02	368203
889 A		18-Sep-98 Y		25998 0027834	2H5FHAMR1XC078576		21-Jun-01	104627
202 A		18-Sep-98 Y		25998 0016762	4VG7QBLUFQXN788408	20-Oct-98	02-Nov-01	301858
1001 A		18-Sep-98 Y		26198 0022308	1FUY58ZB2KL088912	07-Nov-98		468336
39 A		18-Sep-98 Y		26198 0022811	1FUY35ZB6XLA01333	18-Nov-98	30-Oct-01	520166
1702 A		20-Sep-98 Y		26398 0023166	1FUY58EB5XLA64322	20-Jan-99	10-May-02	932399
1703 A		20-Sep-98 Y		26398 0023100	1FUY58EB5XLA64322	20-Jan-99	10-May-02	932399

SKF 002163

1554 A	20-Sep-96 Y	26488-00223341	1FKCD99X80UJ818143	21-Apr-02	29-Jun-02 475285
154 A	21-Sep-96 Y	26488-0023397			
540 A	22-Sep-96 Y	26488-0023434	1FUYD9CB004L973978	01-Feb-98	22-Jan-02 587114
1267 A	23-Sep-96 Y	26788-0024230	1FUYSDYB3XLB058989	17-Dec-98	380012
38 A	23-Sep-96 Y	26888-0023874	1FUYSSZB2XL0A01524	08-Nov-98	17-Jan-02 501725
150 A	24-Sep-96 Y	26788-0024014			
1528 A	24-Sep-96 Y	26788-0024043	ZHSFMAER8XC020832	05-Oct-98	21-Jan-02 582167
1100 A	25-Sep-96 Y	26888-0024542	1FUY86EB7XPA18633		348374
523 A	25-Sep-96 Y	26888-0024432	1FUY8XYB3XL0A77282	01-Dec-98	098850
49 A	26-Sep-96 Y	26888-0024341	1FUYDSZB1XL973977	01-Feb-99	15-Jan-02 583429
622 A	26-Sep-96 Y	26888-0024492	1FUY95ZB7XL0A18133	27-Nov-98	04-Mar-02 356014
1580 A	26-Sep-96 Y	26888-0024504	1FUY3CYB4XL0A449587	11-Nov-98	08-May-02 450979
37 A	26-Sep-96 Y	26888-0024537	1FUY3CYB1XL0A449574	11-Nov-98	29-Dec-01 294808
96 A	26-Sep-96 Y	26888-0024902	1FUYSDYB7YPB355730	30-Aug-98	02-Nov-01 385889
1448 A	20-Oct-96 Y	29388-0020975	1FUPDSEB2XPB773388	10-Dec-98	17-Apr-02 288374
531 A	22-Oct-96 Y	29388-0030283	1FUPCD2B2XP0A16485	01-Jan-99	19-Feb-02 407036
1585 A	06-Nov-96 Y	30888-0035896	1FUYSSZB8XP0A39431	10-Jan-99	30-May-02 619887
1586 A	06-Nov-96 Y	30888-0036812	1FUPCD2B2YPG73062	03-Mar-00	30-Apr-02 324120
824 A	05-Nov-96 Y	30888-0036802	1FUYD8ZB3YL0A895933		393580
507 A	09-Nov-96 Y	31388-0038622	1FUY8XYB6XP0A38610	23-Oct-98	18-Aug-01
533 A	10-Nov-96 Y	31488-0037090	1FUY88EB6XP0B28449	08-Jan-99	12-Jan-02 406968
48 A	10-Nov-96 Y	31488-0037109	1FUY83ZB7XL0A1440	29-Jan-99	03-May-01 412228
1344 A	12-Nov-96 Y	31688-0032163	1FUYTBCB6XH0B30019	03-Dec-98	10-May-02 211290
1700 A	12-Nov-96 Y	31688-0036124	1FUYDSEB0XP0A28676	28-Dec-98	00-Mar-02 500123
632 A	15-Nov-96 Y	31988-0036471	1FUPQYX88XL0A14517	08-Jan-99	08-Aug-01 466458
1108 A	16-Nov-96 Y	32088-005130	A01448		
961 A	24-Nov-96 Y	32688-0061987	1FUY8ZB2XL0A08870	18-Jan-99	10-Mar-02 822284
400 A	24-Nov-96 Y	32688-0061970	1FUYDCYB6XL0A442757	13-Jun-98	27-Apr-01 286710
542 A	16-Dec-96 Y	35088-0067614	1FUPD8ZB2XPB06121	01-Feb-99	28-Mar-01 463490
50 A	18-Dec-96 Y	35088-0067297	1FUPD8ZB2XB06121	01-Feb-99	13-Jun-01 429015
163 A	21-Dec-96 Y	36888-0020234			
1513 A	22-Dec-96 Y	36888-0069505	1M1AA13Y3XWV110883	06-Mar-98	386863
1410 A	23-Dec-96 Y	36788-0070044	2HSFMAHR4XC028000	18-Feb-00	17-Jan-02 204711
59 A	24-Dec-96 Y	36888-0070436	1FUPD8ZB1XP0A44743	16-Apr-98	552263
1461 A	24-Dec-96 Y	36888-0070464	1FUPC8EB0XP0B0118	04-Feb-99	01-Apr-02 521118
1028 A	30-Dec-96 Y	36488-0071917	1FUYDSEBXXP0870846	01-Apr-98	22-Mar-02 843628
116 A	02-Jan-97 Y	00289-0194704	1FUY8XYB7YL0A48913	08-Nov-98	23-Dec-01 170225
146 A	04-Jan-97 Y	00488-0071856	1FUYSDYB4XP0A88886		12-Oct-01 360138
595 A	05-Jan-97 Y	00688	2HSFTAER0XC023133	08-Apr-98	30-Jun-02
1468 A	05-Jan-97 Y	00688-0073040	1FUYD8ZB1XP0A12751	29-Apr-98	18-Mar-02 383820
1647 A	05-Jan-97 Y	00688-0074171	2HSFTAPR8X0C077978	19-Feb-99	06-Jun-02 584473
1552 A	10-Jan-97 Y	01088-0074612	1FUY8S2B5XL0A42888	18-Mar-98	13-Jun-02 882888
906 A	12-Jan-97 Y	01288-0036270	1FUY8XYB6XL0A88444	19-Feb-99	08-Mar-02
1230 A	14-Jan-97 Y	01488-0077296	2HSFTAIRAX0C093899	23-Apr-99	16-May-02
665 A	14-Jan-97 Y	01488-0077359	1FUYDDYB6X0D867275	27-Mar-99	442040
1260 A	14-Jan-97 Y	01488-0077279	1FUYDDYB6XL0A70036	14-Oct-98	432263
573 A	15-Jan-97 Y	01688-0096787	1FUYD8ZB7YPB39094	30-Apr-99	14-Jan-02 409761
608 A	17-Jan-97 Y	01788	1FUYHMC086XL027688	23-Oct-98	20-Jul-01
51 A	17-Jan-97 Y	01788-0054464	1FUYZYW0B0X1A22942	23-Feb-99	15-Oct-01
1294 A	18-Jan-97 Y	01888-0126879	1M1AA13Y5YVW118887	01-Aug-98	373875
666 A	19-Jan-97 Y	01988-0079821	1FUYDKYB6XL0F38021	29-Mar-99	551881
1272 A	20-Jan-97 Y	02088-0080880	1FUYDKYB0XL0F38014	23-Mar-99	641971
1487 A	22-Jan-97 Y	02288-0081917		07-May-02 457209	
1212 A	22-Jan-97 Y	02288-0082083	1FUPCS82B6YPB02036	09-Sep-98	21-Mar-02 376487
1027 A	23-Jan-97 Y	02388-0082489	2HSFTAER2X0C043087	21-Apr-98	02-Apr-02 461421
1703 A	24-Jan-97 Y	02488-0029865	2HSFBAER2Y0C083880	20-Sep-98	16-Jun-02 617414
68 A	24-Jan-97 Y	02488-0083937	1FUY88ZB5XL0A42842	03-Apr-98	03-Mar-02 491918
672 A	24-Jan-97 Y	02488-0082082	1FUY8S2B2XL0A01572	16-Apr-98	20-Sep-01 408310
681 A	24-Jan-97 Y	02488-0108288	1FUY8WE0YL0F10310	15-May-98	17-Jun-02 295814
993 A	25-Jan-97 Y	02688-0083892	2HSFMAXR4XC049219	02-Jul-01 148031	
1588 A	25-Jan-97 Y	02688-0083612	1FUY8XYB3XL0A72097	28-Feb-99	25-Jun-02 480918
63 A	25-Jan-97 Y	02688-0107771	1FUYSDYB3YPA467889	14-May-99	07-Mar-00 388803
1190 A	26-Jan-97 Y	02688-0083887	1FUY8XYB0XP0A10374	08-Mar-99	22-Apr-02 414024
1508 A	26-Jan-97 Y	02688-0084184	1FUY8SEER2XP0A06382	16-Mar-99	06-May-02 273168
1441 A	26-Jan-97 Y	02688-0084277	1FUYD8E82XP041038	24-Mar-99	03-Jun-02 334111
986 A	26-Jan-97 Y	02688-0084436	660873		
1191 A	26-Jan-97 Y	02688-0084021	1FUYD8ZB1XP0A84748	12-Apr-98	08-Mar-02 473800
136 A	27-Jan-97 Y	02788	1FUPCDYB0XL0A94189	09-Dec-01	09-Dec-01 462281
52 A	27-Jan-97 Y	02788-0084648	1FUY8SEB1X087544	08-Mar-99	13-Feb-02
1182 A	27-Jan-97 Y	02788-0085086	1FUY8ZB0XL0A42904	29-Apr-99	10-Mar-02 670162

SKF 002164

1073 A	27-Jan-99 Y	02798-0064630	1FUY8XYB0XLA72106	26-Feb-99	20-Dec-01 431565
1218 A	30-Jan-99 Y	03098-0191682	1FUPC9ZB1YL887463	29-Oct-99	16-Apr-01 213730
1470 A	01-Feb-99 Y	03298-0328498	1FUYC9ZB3YFB88121	22-Jun-99	01-May-02 525115
1493 A	07-Feb-99 Y	03698-	1M1AA13YGYW124100	19-Aug-99	31-May-02 387464
1195 A	16-Feb-99 Y	05098-0092590	1FLYD9ZB2XPAB4336	20-May-99	04-Jan-02 544159
1193 A	21-Feb-99 Y	06298	2HSPHAER0XQC041593	03-May-99	10-May-02
1273 A	21-Feb-99 Y	06298	2HSPHAER0XQC041593	03-May-99	10-May-02
328 A	23-Feb-99 Y	06498 0095702	1FUYSSB6XLA80486	16-Jul-99	16-Jan-02
62 A	24-Feb-99 Y	06598	1FUYSSB6XLA80486	02-Apr-99	01-Apr-02 453726
1569 A	24-Feb-99 Y	06599-0098645	1FUYSSB6XLA80482	05-Apr-99	16-Jan-02 578529
1438 A	25-Feb-99 Y	06599-0097122	1FUY3HIEB6XPK843082	10-May-99	05-Feb-02 360348
155 A	28-Feb-99 Y	05799 0087986	1FUYSSB6XLA80486	26-May-99	09-Nov-01 368803
587 A	27-Feb-99 Y	05899-0113190	2HSPHASR7YC037007	28-May-99	09-Nov-01 368803
577 A	02-Mar-99 Y	06198 0085784	1FUYSSB6XLB81798	10-May-99	05-Feb-02 360348
1590 A	03-Mar-99 Y	06298-0098523	1FUYSSB6XLA80486	04-Jun-99	08-Apr-02 448227
1215 A	04-Mar-99 Y	06398-0100670	1FUYSSZB6YLB65058	08-Oct-99	09-Apr-02 377144
552 A	04-Mar-99 Y	06398	1FUYSDYB1YPPF7320	17-May-99	25-Mar-02 288703
1518 A	04-Mar-99 Y	06398-0100987	1FUYSSZBXL854047	17-Jun-99	23-May-02 587487
61 A	06-Mar-99 Y	06498-0101618	1FUYSDYB6YPA86051	20-Apr-99	21-Jan-02 303850
1595 A	05-Mar-99 Y	06498-0101718	1FUYSSB6YPPF65368	14-Oct-99	22-May-02 403032
1463 A	09-Mar-99 Y	06898-0113188	1FUYB6ZB4XLB64684	04-Jun-99	08-Apr-02 448227
308 A	10-Mar-99 Y	06998 0103837	1FUYB6ZB4XLB64684	27-Sep-01 103326	388072
1323 A	10-Mar-99 Y	07098-0104907	1FUYSSB6XLA80486	19-May-99	07-Dec-01 320074
663 A	11-Mar-99 Y	07098-0104983	2HSPMAER1XC029266	19-May-99	16-Apr-02 419837
1663 A	11-Mar-99 Y	07098-0104988	1FUYDCYB6YLB10331	01-Jun-99	24-May-02 343440
1594 A	15-Mar-99 Y	07498-0105820	1FUYDCYB6YLB10331	01-Dec-99	740356
710 A	18-Mar-99 Y	07498-0105828	1FUYDXB7XLA77284	01-Jun-99	14-Jan-02 590162
777 A	16-Mar-99 Y	07598-0106878	1FUYDWDB6XYLB17038	14-Jun-00	14-Jan-02 572022
1437 A	16-Mar-99 Y	07598-0106879	1FUYDWDB6YLB17940	23-Jun-99	12-Mar-02 381853
614 A	17-Mar-99 Y	07698-0107840	1HSHCANRLYH212428	10-Jun-99	15-Oct-01 442364
1198 A	18-Mar-99 Y	07798-0107912	1FUYSSZB6YLB654626	01-Feb-00	05-Apr-02 362120
1407 A	18-Mar-99 Y	07798-0108161	1FUYNEB3YLB20170	01-Jun-99	30-Oct-01 287801
623 A	18-Mar-99 Y	07798-0108087	1FUYSSB6YPPF15665	01-Jun-99	07-Mar-02 392708
64 A	18-Mar-99 Y	07798-0108488	1FUYSSZB2YLB54588	01-Jun-99	21-May-02 408006
1640 A	18-Mar-99 Y	07798-0107615	1FUYSSB6YPPA86046	03-Apr-00	08-Mar-02 401999
991 A	19-Mar-99 Y	07898-0108958	1XPCDU6XG3XKN811397	01-Jun-99	20-Nov-01
99 A	19-Mar-99 Y	07998-0109938	1M1A605YQXW001149	18-Jun-99	13-Feb-02 571730
79 A	19-Mar-99 Y	07998-0108050	1FUYSDYBLYLP38082	01-Jul-99	17-Mar-02 330650
105 A	22-Mar-99 Y	08298 0110148	1FUYDLYB4YMF48084	27-Jul-99	28-Jan-02 330650
67 A	22-Mar-99 Y	11198-0122048	1FUYDLYB4YMF48084	19-May-99	02-May-02 343873
1101 A	22-Mar-99 Y	08198 0105092	1FUYSSB6XLA80486	12-Jun-00	04-Sep-01 288104
1284 A	22-Mar-99 Y	08198-0106508	2HSPTAER3XC0292661	11-Aug-99	06-Feb-02 351104
1201 A	22-Mar-99 Y	08198-0106480	1FUYSDZB6YPP71245	14-May-99	11-Feb-02
733 A	23-Mar-99 Y	08298 0110102	1FUYSSZBXYLB94300	26-Nov-01	28-Nov-01
653 A	24-Mar-99 Y	08398-0110696	1FUYSSWEB6YLB16300	14-Jun-00	15-May-00
1206 A	24-Mar-99 Y	08398-0110688	1FUYSSWEB6YLB16264	11-Aug-99	482815
678 A	24-Mar-99 Y	08398-0109332	2HSPTAER3XC0292664	14-May-99	10-Apr-02 407277
903 A	25-Mar-99 Y	08498 0111482	A73546	08-Feb-02	231160
1118 A	25-Mar-99 Y	08498 0111482	A73548	18-May-99	08-Jul-02 458438
1005 A	25-Mar-99 Y	08598-0112223	1M1AA12YGYW123225	31-Oct-99	29-May-01 446209
1037 A	25-Mar-99 Y	08698	1FUYDCYB4YDF48085	16-Aug-99	17-Mar-02
826 A	25-Mar-99 Y	08598-0111801	1FUYLDDYB6YLF12050	14-Jun-99	24-May-00
664 A	26-Mar-99 Y	08598-0110687	1FUYSSWEB6YLA86108	15-May-99	08-Feb-02 406076
579 A	27-Mar-99 Y	08598-0112373	1FUYDCYB4YDF18130	24-Jul-99	305709
1549 A	28-Mar-99 Y	08698-0112842	1FUY3MCAC2YLB654800	08-May-99	08-May-02 357026
175 A	30-Mar-99 Y	09098	1FUYSDYBXYLF72791	234548	146540
1653 A	31-Mar-99 Y	08998-0114086	1FUYSDYB7YFB368730	02-Nov-01 363659	146540
626 A	31-Mar-99 Y	08698-0114223	1FUYSSWEB6YLB94221	01-Jul-99	146540
69 A	01-Apr-99 Y	09198-0414274	1FUYDCYB4YDF48085	11-Jun-00	146540
1234 A	20-Apr-99 Y	11098-0121888	2HSPMAMR0YCO29359	12-Jul-99	08-Apr-02 263574
1606 A	20-Apr-99 Y	11098-0121841	2HSPMAMR0YCO29408	12-Jul-99	11-Apr-02 375526
1650 A	20-Apr-99 Y	11098-0122133	1FUYSSB6XLA80486	146540	146540
938 A	20-Apr-99 Y	11098-0122110	1FUYSSB6XLA80486	146540	146540
1150 A	20-Apr-99 Y	11098-0122112	1FUYSSB6XLA80486	146540	146540
606 A	20-Apr-99 Y	11098-0122135	1FUYSSB6XLA80486	146540	146540
1148 A	20-Apr-99 Y	11098-0122110	1FUYSSB6XLA80486	146540	146540
68 A	20-Apr-99 Y	11098	4V4ND1UF07N768434	11-Jun-99	31-Dec-01 344209
1599 A	20-Apr-99 Y	11098-0121808	2HSPMAMR7YC029357	12-Jun-99	25-Jul-02 363468
1181 A	20-Apr-99 Y	11098-0122124	1FUYSSB6XLA80486	146540	146540
1658 A	20-Apr-99 Y	11098-0122120	1FUYSSB6XLA80486	146540	146540

938 A	20-Apr-99 Y	11099-0122112			148540
940 A	20-Apr-99 Y	11099-0122124			196396
1029 A	20-Apr-99 Y	11099-0122487	1FUYDDYB7YL930669	04-Jun-99	443137
1083 A	20-Apr-99 Y	11099-0121801	1FUYD8EB1YL808842	08-Jan-00	30-Apr-02 491506
1482 A	20-Apr-99 Y	11099-0122108			03-Jul-02 448507
820 A	20-Apr-99 Y	11099-0121936	M288610		
815 A	20-Apr-99 Y	11099-0121402		24-Jun-99	19-Jan-02
1657 A	20-Apr-99 Y	11099-0122113			16-Apr-02 390290
1541 A	20-Apr-99 Y	11099-0121816	2HSPMAMR7YC029357	12-Jun-99	26-Jul-02 363456
232 A	20-Apr-99 Y	11199-0122036	1FUYSDYE3YLFL38977	01-Jun-99	581544
600 A	21-Apr-99 Y	11199-0122545	1FUYSDYB7YL891578	15-Jun-99	14-Nov-01 311918
77 A	21-Apr-99 Y	11199-0122948	1FUYSDYBXYLFL38978	01-Jul-99	10-Jan-02 588623
78 A	21-Apr-99 Y	11199-0122801	1FUYDSEB2YLFL44055	01-Jul-99	27-Jan-02 554588
599 A	21-Apr-99 Y	11199-0122143	4V4MD2RF4YN798018	01-Jun-99	31-Jan-02 388511
1148 A	21-Apr-99 Y	11199-0122188	3HSPMANDY0N052039		25-Sep-01 283455
937 A	21-Apr-99 Y	11199-0122186	3HSFMANDY0N052039		25-Sep-01 262445
620 A	21-Apr-99 Y	11199-0123027	4V4ND1JF1YN703198	10-Jul-99	816338
1521 A	21-Apr-99 Y	11199-0126770	2HSPFTAMR7YC058905	15-Jul-99	15-Apr-02 532065
804 A	21-Apr-99 Y	11199-0122696	4U4ND1UF9YN768433	18-Jun-99	03-Jan-02 351894
890 A	21-Apr-99 Y	11199-0122983	1FUYSDYB5YL893260	02-Jun-99	27-Jul-01 249423
803 A	21-Apr-99 Y	11199-0122882	4V4ND1JE8YN703198	18-Jun-99	503443
1398 A	22-Apr-99 Y	11299-0123303			26-Dec-01
78 A	22-Apr-99 Y	11299-0123377	1FUYSDYB8YLFL38423	01-Jul-99	13-Feb-02 579189
593 A	22-Apr-99 Y	11299-0123068	1FUYDDYB1YLFL20042	07-Jun-99	389724
1588 A	22-Apr-99 Y	11299-0123553	1FUYSDYB4YPA48794	09-Jul-99	29-Oct-01 304354
1830 A	22-Apr-99 Y	11299-0123190	1FUYSDYB2YLFL38453	23-Nov-99	575430
167 A	22-Apr-99 Y	11299-0123230			
1451 A	22-Apr-99 Y	11299-0124971	1FUYSDZB3YLFL1944	09-Nov-99	12-Apr-02 328305
1280 A	22-Apr-99 Y	11299-0123483	1FUM8MCA7YL884403	15-Jul-99	09-Apr-02 389353
597 A	23-Apr-99 Y	11399-0124269			
243 A	23-Apr-99 Y	11399-0124347	Y0034637	27-Jul-99	18-Oct-01 369259
907 A	23-Apr-99 Y	11399-0124025	1FUYDDYB0YPL886713	22-Jun-99	27-Feb-02 526468
1654 A	23-Apr-99 Y	11399-0123983	2HSPCEAMR3YC026097	01-Dec-99	01-Mar-02 302478
68 A	25-Apr-99 Y	11599-0124400	1FUYDSYB0YL805720	17-Jun-99	13-Mar-02 346211
241 A	25-Apr-99 Y	11699-0124091	1FUY83ER0YL986342	16-Jul-99	17-Oct-01
933 A	27-Apr-99 Y	11799-0126187	1FUYSSZB5YLPL02294	13-Jun-99	28-May-02 409632
30 A	27-Apr-99 Y	11799-0126614	1FUYSD2B5XP918099	08-Oct-99	20-Feb-02 814958
1432 A	29-Apr-99 Y	11899-0126398	1FUY88E80YP83187	22-Jul-99	21-May-02 207120
601 A	28-Apr-99 Y	11899-0125808	n0 paperwork		
802 A	28-Apr-99 Y	11899-0126000	1FUYSDYB8YLPL86787		208745
1404 A	28-Apr-99 Y	11999-0226068	1FUYSDZB4XLFL28627	08-Jul-99	18-Apr-02 716862
1207 A	29-Apr-99 Y	11999-0120070	1FUTSAYB8YL8A4851	23-Jul-99	21-Mar-02 292480
105 A	29-Apr-99 Y	11999-0126944	1FUYSSZB3YPLF23783	16-Sep-99	11-Nov-01 320405
617 A	30-Apr-99 Y	12099-0127604	1XKWDROXBYJ836190	28-Jun-99	12-Mar-02 284734
1822 A	30-Apr-99 Y	12099-0127598	1FUY88ZB5YL881452	15-Jul-99	20-Oct-01 273248
87 A	02-May-99 Y	12299-0131009	1FUPD8ZB1YLFL86730	31-Aug-99	02-Jun-01 267031
117 A	02-May-99 Y	12299-0011785		26-Sep-01	19-Oct-01
65 A	03-May-99 Y	12399-0128000	1FUY8DVB1YLA88413	10-Jun-99	22-Dec-01 230385
171 A	03-May-99 Y	12499-0126928	1FUY82YB7YL787491		16-Jan-02 380273
912 A	03-May-99 Y	12399-0128400	1M1AA12Y8YW123099		06-Dec-01 208787
160 A	03-May-99 Y	12399-0126128			
102 A	03-May-99 Y	12399-0126003	1FUY88ZB5YPL84451	09-Sep-99	14-Aug-01 508663
73 A	03-May-99 Y	12399-0128144	1FUY8DVB8YPA888853	28-Jun-99	24-Oct-01 586172
81 A	03-May-99 Y	12399-0125398	2HSPFHMPDYC062800	14-Jul-99	14-Jan-02 367058
72 A	03-May-99 Y	12399-0128217	1FUYSSZB3YPA88884	23-Jun-99	09-Feb-02 398368
698 A	03-May-99 Y	12399-0126110	1FUPC8ZB5YL88792	01-Jun-99	20-Sep-01 272985
63 A	03-May-99 Y	12399-0127879	2HSPFTAMR7Y0831728	20-Jul-99	30-Jan-02
612 A	03-May-99 Y	12399-0126303	1FUPCSZB7YL881162	22-Jun-99	19-Nov-01 371288
821 A	03-May-99 Y	12399-0126110	1FUPCSZB5YL88792		20-Sep-01 237885
603 A	03-May-99 Y	12399-0126019	1FUYSDYB7YL884082	23-Aug-99	01-Oct-01 275802
101 A	03-May-99 Y	12399-0126098	1FUY88ZB5YPL884461	09-Sep-99	03-Dec-01 558678
1460 A	03-May-99 Y	12399-0126014	1FUY88EB1YLA882944	11-Aug-99	08-Mar-02 330863
1206 A	03-May-99 Y	12399-0126363	1FUPC8E80YPL84601	16-Jul-99	08-Apr-02 206248
1203 A	03-May-99 Y	12399-0126930	1FUPDWE84YDF84528	08-Jul-99	12-Apr-02 471682
1039 A	03-May-99 Y	12399-0126369	1FUY88ZB5YL886100	08-Jul-99	11-Jan-02 367277
1199 A	03-May-99 Y	12399-0126014	1FUY88EB5YPT29133	23-Jun-99	04-Mar-02 332123
1286 A	03-May-99 Y	12399-0126114	1FUY88E80YPL873104	29-Aug-99	652381
1195 A	03-May-99 Y	12399-0126068	1FUY8DVB5YPP88844	19-Jun-99	24-Nov-01 327469
1075 A	03-May-99 Y	12399-0126024	B40034		
1494 A	03-May-99 Y	12399-0126373	1FUYDDYB8YLI88623	02-Jul-99	423225
1565 A	03-May-99 Y	12399-0127979	2HSPFTAMRTYC031728	20-Jul-99	30-Jan-02 558766
1597 A	03-May-99 Y	12399-0126297	1FUPDDYB1WL88884	29-Dec-99	30-Apr-02 488126
1666 A	03-May-99 Y	12399-0126212	1FUY8DVB5YPP88845	05-Jul-99	24-May-02 303774

885 A	03-May-99 Y	12399-0128011	1FUY562B0YLB97851	23-Jun-99	02-Nov-01 308998
1590 A	03-May-99 Y	12399-0128384	B60122		50822†
1531 A	03-May-99 Y	12399-0128116	1FUYDSEB6YPB104	26-Jun-99	582048
1579 A	03-May-99 Y	12399-0126316	1FUYDSEB1YPF29125	23-Jun-99	25-Apr-02 312457
813 A	04-May-99 Y	12499-0128294	1FUPC62B7YLB91152	22-Jun-99	19-Nov-01 371258
761 A	04-May-99 Y	12499-0181780	1FUY95ZB3YLB86004	20-Apr-00	27-Nov-01 259307
1088 A	04-May-99 Y	12499-0203118			
830 A	04-May-99 Y	12499-0128626	1FUPC3ZB1YPB67245	10-Jul-99	12-Jul-01 251745
839 A	04-May-99 Y	12499-0128302	1FUYDDY8GYLBB05748	21-Jul-99	02-Jul-01 181181
810 A	04-May-99 Y	12499-0128801	2HSPMAMR5YC032039	22-Jun-99	05-Nov-01 264297
908 A	04-May-99 Y	12499-0128277	1FUY85ZBXYLB86102	22-Jun-99	15-Jan-02 480061
1142 A	04-May-99 Y	12499-0129188	F14783		
1087 A	04-May-99 Y	12499-0129319	1FUYDDYB7YLB05743	20-Jul-99	02-Aug-01 333962
1187 A	04-May-99 Y	12499-0128830	1FUY3WD88YLBB05992	14-Jun-99	19-Feb-02 386258
609 A	04-May-99 Y	12499-0128083	ZHSPMAMR5YC032039	22-Jun-99	05-Nov-01 264297
87 A	04-May-99 Y	12499-0128849	1FUYSSZB5YLBA82032	18-Jun-99	26-Dec-01 346050
1206 A	04-May-99 Y	12499-0129191	1FUPCZYB4YD767518	22-Jun-99	09-Feb-02 408872
1660 A	04-May-99 Y	12499-0128237	2HSPMAXR4YC037024	09-Sep-99	07-Jun-02 843458
90 A	04-May-99 Y	12499-0129180	1FUPCZYBXYD767519	14-Aug-99	341846
473 A	04-May-99 Y	12499-0128779	1FUYSSZB1XLA05404	06-Aug-99	13-Apr-02 747824
1433 A	04-May-99 Y	12499-0128243	1FUYSSB81YLA87957	22-Jul-99	13-May-02 340184
832 A	05-May-99 Y	12599-0128432	1FUY557B7YLBB4918	12-Jul-99	23-Jun-01 348217
878 A	05-May-99 Y	12599-0128549	1M1AA127XYW121878	16-Sep-99	17-May-01 307087
1438 A	05-May-99 Y	12599-0129418	1FUY39ZB8YLBB4922	20-Jul-99	23-May-02 437626
845 A	05-May-99 Y	12599-0128943	1FUYSSZB1YLBB4929	29-Jul-99	22-Jun-02 386207
844 A	05-May-99 Y	12599-0170218	1M1AA15YXYW121443	29-Jul-99	30-Sep-01 281048
840 A	05-May-99 Y	12599-0129813	1FUYSSB84YPPF80354	21-Jul-99	18-Jul-01 233800
1208 A	05-May-99 Y	12599-0129417	1FUYSDYB8YLBB49434	20-Jul-99	27-Aug-02 349363
833 A	05-May-99 Y	12599-0129401	1FUY337B7YLBB4918	12-Jul-99	23-Jun-01 346217
795 A	05-May-99 Y	12599-0128834	1XPDR5K1YD814362	01-Jan-01	12-Nov-01 312719
1386 A	05-May-99 Y	12599-0129882	1FUYSSB5XYPPF80357	21-Jul-99	11-Jun-02 380866
253 A	05-May-99 Y	12599-0129851	1M1AA127XYW121978	16-Sep-99	17-May-01 307087
1208 A	05-May-99 Y	12599-0129468	2HSPFTASR3YC024131	22-Jul-99	04-Jan-02 332284
1202 A	05-May-99 Y	12599-0129421	1FUYSSZB28YLBB4920	08-Jul-99	18-Jun-02 477024
1209 A	05-May-99 Y	12599-0180160	1FUPCKYB2YLBB70888	09-Aug-99	13-Feb-02 312641
1204 A	05-May-99 Y	12599-	1FUYSSB2B7YLB54844	13-Jul-99	22-Mar-02 548806
1292 A	05-May-99 Y	12599-0129470	2HSPFTASR2YC024131	22-Jul-99	04-Jan-02 332284
242 A	05-May-99 Y	12599-0130080	1FUPL3T65YPB802010	18-Jul-99	17-Aug-01 304356
1003 A	05-May-99 Y	12599-0128024	1FUYSSZB8YLBB49480	30-Jul-99	06-Mar-02 392489
1478 A	05-May-99 Y	12599-0128049	1FYSSEB8YLBB49490	20-Jul-99	02-May-02 341720
1000 A	05-May-99 Y	12699-0138031	1FUYSSB280YPA78577	14-Aug-99	18-Nov-01 302357
883 A	05-May-99 Y	12699-0130622	1FUYSSB288YLBB49888	20-Aug-99	04-Jun-01 372781
244 A	05-May-99 Y	12699-0130818	1FUYSDYB8YLBB49443	28-Jul-99	15-Aug-01 250767
88 A	05-May-99 Y	12699-0130302	1FUYSDYB8YLBB49450	29-Jul-99	18-Oct-01 280095
1287 A	05-May-99 Y	12699-0130480	1FUYSDYB8YPA88077	28-Jun-99	11-Apr-02 239000
1623 A	05-May-99 Y	12699-0130412	1FUPCZBXYDPF88255	13-Sep-99	01-Dec-01 448789
1554 A	05-May-99 Y	12699-0130413	1FUPC8ZB1YDPF88256	15-Sep-99	28-Apr-02 616314
1428 A	07-May-99 Y	12799-0131327	1FUYSDYBXYPA88989	12-Aug-99	03-May-02 376879
1039 A	07-May-99 Y	12799-	1FUYSSZB3YLBB34184	17-Aug-99	18-Mar-02 637468
116 A	07-May-99 Y	12799-0131138	1FUYSSZB8YLBB49404	18-Nov-99	10-Feb-02 423402
635 A	07-May-99 Y	12799-0131822	2HSPFTAERUXYC0243108	19-Jul-99	11-Jul-01 186851
869 A	07-May-99 Y	12799-0131289	1FUYSSB853YLBB791	24-Aug-99	26-Jan-02 306625
811 A	07-May-99 Y	12799-0131147			225820
1452 A	07-May-99 Y	12799-0131282	1FUYSSB81YLB80780	24-Aug-99	19-Mar-02 113240
70 A	07-May-99 Y	12799-0128082	1FUYSDYB4YPPF88072	19-Jun-99	11-Dec-01 358145
592 A	07-May-99 Y	12799-0131288	1FUYSDZB8YLFB41935	27-Oct-99	11-Feb-02 403200
1118 A	07-May-99 Y	12799-0131147			225800
1460 A	08-May-99 Y	12699-0130731	1M1AA13Y8YW124100	13-Aug-99	31-May-02 307464
724 A	10-May-99 Y	12699-0131801	1FUDDYB1YPG13691	28-Dec-99	486180
1032 A	10-May-99 Y	12699-			
670 A	10-May-99 Y	13099-0131971	2HSPMAMR1YC030299	25-Jun-99	26-Feb-02 348409
671 A	10-May-99 Y	13099-0131652	2HSPMAMR1YC030299	30-Aug-99	18-Sep-01 269803
550 A	10-May-99 Y	13099-0122106	1FUYD8EB2YLFB44972	30-Aug-99	18-Sep-01 269803
908 A	10-May-99 Y	13099-0132553			522036
1607 A	10-May-99 Y	13099-0131972	2HSPMAMR8YC030297	30-Aug-99	17-Apr-02 329378
800 A	11-May-99 Y	13199-0132078	117001	31-Feb-01	22-Oct-01 428
883 A	11-May-99 Y	13199-0132882	1FUYD8BXYLF44987		
621 A	11-May-99 Y	13199-0132877	1FUYD8ZB8YLFB44980	01-Jul-99	21-Mar-02 657298
1342 A	11-May-99 Y	13199-0132751	1FUYSDYB1YLP11883	26-Jul-99	25-Mar-02 273762
1633 A	11-May-99 Y	13199-0132645	4V4ND10P4YN703220	10-Jul-99	656628
1327 A	11-May-99 Y	13199-0132044			
1330 A	11-May-99 Y	13199-0132812			27-Aug-01
1334 A	11-May-99 Y	13199-0132530			

SKF 002167

1682 A	11-May-99 Y	13199-0132747	1FUYSDYB3YLFB3434	01-Nov-99	307800
1288 A	11-May-99 Y	13199	1FLW3MCAB6YL854412	24-Jun-99	21-Dec-01 440820
1006 A	12-May-99 Y	13299 0131117	1FUYSDYRXYLB51383	05-Aug-99	17-Oct-01 288108
1044 A	12-May-99 Y	13299-0133894	1FUYSDYB9YL07230	20-Sep-99	11-Mar-02 333741
257 A	14-May-99 Y	25799 0156236	2HSCCEAMR9C040240	11-Nov-99	18-Jan-02 266720
1034 A	18-May-99 Y	13699-0138441	1FUY8XYB8YL861851	16-Jul-99	22-Apr-02 422046
1031 A	18-May-99 Y	13699-0136830	1FUYDCYB6YL1F36150	23-Jun-99	387484
618 A	18-May-99 Y	13699 0138833	1FUYDDYB4YL47384	26-Jun-99	487812
139 A	19-May-99 Y	14099 0137951			79378
1228 A	19-May-99 Y	13999	2HSFTAMRXYC034162	27-Aug-99	27-May-02 478998
1041 A	19-May-99 Y	13999-0158560	1FUYSDYB6YL85294	24-Aug-99	08-Mar-02 342048
1104 A	22-May-99 Y	14200 0138968		01-Mar-99	23-Mar-01
1449 A	24-May-99 Y	14499-0140140	1FUPDDYB4YFF70312	05-Aug-99	17-Apr-02 288374
1596 A	24-May-99 Y	14499-013649	1FUY3SEB6YPF06365	14-Oct-99	22-May-02 403032
1405 A	24-May-99 Y	14499-0140132	1FUPDDYB6YPF70312	05-Aug-99	17-Apr-02 270355
1888 A	01-Jun-99 Y	15299-1042779	1FUYSDYBZYPB35730	01-Aug-99	08-Sep-02 450008
108 A	02-Jun-99 Y	15399-0143864	1FUPC6Z910F88726	17-Sep-99	15-Dec-01 463126
1573 A	05-Jun-99 Y	15699-1441031	1FUYWWND4A4YLFB2524	14-Jul-99	14-May-02 477570
858 A	07-Jun-99 Y	15699-0146242	1FUY&SEB7YLFB0204	17-Aug-99	10-Feb-02 554027
111 A	07-Jun-99 Y	15699-0146085	2HSQNAE7YL048117	18-Oct-99	08-Sep-01 179052
1089 A	07-Jun-99 Y	15699-0145987			
100 A	08-Jun-99 Y	15699-0144483	1FUY3SEB90YLA86306	06-Sep-99	22-Oct-01 359284
275 A	08-Jun-99 Y	16099	1XKWD64X6TR95383	01-Feb-00	06-Jun-02
1210 A	08-Jun-99 Y	15999-0146491	1FUY3SEB82YLFB0196	13-Aug-99	10-Apr-02 570683
93 A	08-Jun-99 Y	16099-0147221	1FUYDWD82YL817932	20-Aug-99	22-Jun-01 588312
1445 A	09-Jun-99 Y	16099-0147016	1FUPCXYB1YL857940	01-Sep-99	04-Jun-02 589728
98 A	09-Jun-99 Y	16099-0177260	1FUYDDYBXYFA82374	06-Sep-99	652941
557 A	09-Jun-99 Y	16099-0148668	1FUY80Z84YPF88649	18-Aug-99	21-Nov-01 374523
108 A	10-Jun-99 Y	16199 0147882	1FUY58Z84YPF27280	27-Sep-99	27-Dec-01 424577
1838 A	10-Jun-99 Y	16199-0148184	1FUYSDYB7YPF061117	27-Aug-99	16-May-02 380085
1431 A	14-Jun-99 Y	16599-0148328	1FUYWWND4A1YLFB2589	24-Jul-99	10-May-02 544302
887 A	14-Jun-99 Y	16599-0148069	1FUYDDYB7YPF25768	01-Sep-99	01-Feb-02 667103
988 A	14-Jun-99 Y	16599-0148087	1FUYDDYB7YPF25768	01-Sep-99	01-Feb-02 667103
1211 A	14-Jun-99 Y	16599-0148036	1FUYSDYB8YL48578	01-Sep-99	26-Dec-01 260353
1036 A	14-Jun-99 Y	16599-0349244	1FUYDDYB3YLPS0433	09-Aug-99	
1326 A	16-Jun-99 Y	16799-0181117			03-May-02 476906
882 A	16-Jun-99 Y	16899-0151437	1FLY89EB3SYLF0451	19-Aug-99	21-Sep-01 334888
94 A	16-Jun-99 Y	16799	1FLUWWND46YLFB2700	25-Aug-99	06-Jun-02 410001
99 A	16-Jun-99 Y	16799-0142609	1FLUWWWD46YL792714	10-Aug-99	21-Oct-01 383634
129 A	16-Jun-99 Y	16799-0160683	1FLUJAHBD51LG71191	22-Jun-00	446788
884 A	17-Jun-99 Y	16899 0151264	1HMAA12Y2YW123222	30-Sep-99	13-Sep-01 450000
1213 A	18-Jun-99 Y	16899-01522275	1FUYSDYB5YPF03529	20-Sep-99	13-Feb-02 114675
700 A	21-Jun-99 Y	17299 0153005	1H5CEAHB7YJ7058800	09-Nov-99	07-Aug-01 241798
1045 A	23-Jun-99 Y	17499-0154886	1FUPCXYB9YL857958	05-Oct-99	28-Mar-02 682194
619 A	23-Jun-99 Y	17499-0105704	1FUYDWD8XYLB17919	30-Jun-99	17-Jun-01 688347
386 A	24-Jun-99 Y	17599 0160423	1FUYDXB7VPF004700	26-Apr-97	30-Aug-01 678671
1046 A	25-Jun-99 Y	17699-0165101	1FUYDZB24P978241	14-Oct-99	06-Feb-02 318111
738 A	26-Jun-99 Y	17699-0168168	1FUYDZB24YPF004096	24-Jan-00	19-Jan-02 356687
117 A	09-Jul-99 Y	19099-0122059	1FUYSDYB3YLFB48193	29-Dec-99	397804
882 A	12-Jul-99 Y	19399-0160340	G13674		556884
91 A	14-Jul-99 Y	19599-0151287	1FLY35263YL854804	17-Aug-99	20-Jul-01 376222
1080 A	14-Jul-99 Y	19599 0151505	1FLY58EB80YL805000	31-Jan-00	22-Oct-01 281393
1221 A	18-Jul-99 Y	19799-0162074	1FLY62ZB8YL0PF45300	21-Feb-00	19-Jan-02 284643
856 A	21-Jul-99 Y	20299-0164502	G13679		468773
872 A	22-Jul-99 Y	20299-0165273	G13682		616973
1644 A	23-Jul-99 Y	20499-0166037	G13681		472288
144 A	23-Jul-99 Y	20499 0165878			21300
988 A	23-Jul-99 Y	20499-0165662			000219
874 A	23-Jul-99 Y	20499-0165831			566044
888 A	23-Jul-99 Y	20499-0165837	G13681		472288
663 A	27-Jul-99 Y	20599-0166335	4V4ND2LP1YN242817	26-Sep-99	15-May-02 277232
882 A	29-Jul-99 Y	21099 0168715	1FLY58ZB8YL858043	27-Sep-99	23-Oct-01 430508
900 A	29-Jul-99 Y	21099 970032	1FLYDSE51YPF940512		
1161 A	29-Jul-99 Y	21099 970032	1FLYDSE81YPF940512		
491 A	12-Aug-99 Y	22599 0012762	1FUYHMD877LA23433	07-Oct-99	07-Dec-01 377606
600 A	14-Aug-99 Y	22698	2HSFMAHR1YC032037	21-Jun-99	13-Dec-01 330322
1429 A	16-Aug-99 Y	23199-0167013	1FLY58DYB8YL8581892	16-Dec-99	19-Apr-02 262115
1715 A	20-Aug-99 Y	24299 01138	1FUPDDYB3YL856878	08-Oct-99	16-Jul-02 897488
114 A	01-Sep-99 Y	24499-0162452	1FLYSDZB5YPF018251	28-Oct-99	24-Feb-02 214094
1307 A	01-Sep-99 Y	24499-0181799	1FUPDZB283YL85L154	19-Nov-99	09-Apr-02 407218
1500 A	01-Sep-99 Y	24499-0182417	2HSCHAER4YC0049464	14-Apr-00	09-May-02 310730
988 A	07-Sep-99 Y	25099 0183146	1FUYDDYB8YL868888	13-Nov-99	10-Oct-01 187925
128 A	08-Sep-99 Y	25199-0183090	1FUY99ZB21LG362171	01-Jun-00	12-Nov-01 334132
1470 A	08-Sep-99 Y	25199-0183697	1FUY88ZB11LG44326		542684

1376 A	08-Sep-99 Y	26100-0103806	1FUYSDYBX1LH37425	09-Jun-00	14-Feb-02 192488
112 A	10-Sep-99 Y	25300-0104419	1M1AA08Y7YW019703	19-Oct-99	29-Oct-01 279729
109 A	10-Sep-99 Y	25300-0126412	1HSCEAHNM0YJ065885	04-Oct-99	258888
270 A	10-Sep-99 Y	25400-0104508	2HSCEAHM0YC030723	05-Jan-00	13-Dec-01 253809
728 A	11-Sep-99 Y	25400-0184511	2HSCEAM0YCX030723	05-Jan-00	13-Dec-00 253809
1216 A	11-Sep-99 Y	25400-0184584	1FUY6MDR1YLB03499	16-Oct-99	18-Apr-02 380211
1543 A	13-Sep-99 Y	25700-0184904	1FUYD2YB1YPP08524	08-Nov-99	383877
605 A	14-Sep-99 Y	25700-0185318	2HSCEAER8YL058445	28-Oct-99	16-Oct-01 265335
528 A	18-Sep-99 Y	25900-0021588	1FUYDDYB8XDA39020	15-Dec-99	11-Oct-01 327584
656 A	17-Sep-99 Y	26000-0185261	G63670		484506
138 A	17-Sep-99 Y	26000-0185711			
120 A	19-Sep-99 Y	26200-0187400	1FUY66EBXYLB04813	23-Jan-00	18-Jan-02 165217
708 A	23-Sep-99 Y	26800-0188004	1FUYSDYB1YLB01850	26-Nov-99	07-Sep-01 349830
336 A	24-Sep-99 Y	26700-0190454	1FUYNM0B3YP082774		195728
818 A	25-Sep-99 Y	26800-0190899	2HSCEAHR4YC045194	18-Oct-01	08-Nov-01
1219 A	25-Sep-99 Y	26800-0191062	1FUYSSZB4YLFI1801	03-Dec-00	20-Dec-01 341900
1666 A	26-Sep-99 Y	26800-0190928	1XKH052XXYR0369404	20-Oct-99	01-Mar-02 562737
731 A	29-Sep-99 Y	27200-0192895	2HSCEAHR3YC064585	11-Jan-00	26-Jul-01 348235
730 A	29-Sep-99 Y	27200-0191153	2HSCEAHR3YC064585	11-Jan-00	26-Jul-01 348235
783 A	30-Sep-99 Y	27300-0192268	1FUY95ZB1YP084862	14-Sep-00	22-Jan-02 273721
1281 A	30-Sep-99 Y	27300-0193140	1FUYSSZB4YLB04820	04-Jun-99	09-Apr-02 504862
870 A	01-Oct-99 Y	27400-0183405	B68091		
1228 A	04-Oct-99 Y	27700-0193124			
715 A	08-Oct-99 Y	28100-0194362	1FUYSSB4YL088684	13-Dec-99	03-Jul-01 122401
741 A	12-Oct-99 Y	31000-0210859	2HSCEAM0R9YC088725	21-Feb-00	20-Jul-01 157726
755 A	18-Oct-99 Y	20100-0198978	1FUPG5ZB8YP088547	27-Oct-00	26-Jan-01 275889
784 A	20-Oct-99 Y	29300-0199852	1V4ND4LR9YN247516	04-Oct-00	28-Sep-01 230981
720 A	22-Oct-99 Y	29800-0201278	1FUYSDZB8YLG18379	21-Dec-99	383881
204 A	24-Oct-99 Y	29700-0187428	2HSCEAM0R9YC071122	15-Dec-99	26-Jun-02 270280
1186 A	28-Oct-99 Y	29600-0202486	1FUYNTCA3XH030483	21-Nov-99	27-Jul-01 143083
660 A	27-Oct-99 Y	30000-0202971	1FUYDXYB2YP084900	21-Oct-99	10-Jun-02 388017
119 A	01-Nov-99 Y	30500-0205007	1FUYMEDB2YP088432	04-Jan-00	16-Apr-01 162386
1685 A	02-Nov-99 Y	30800-0205982	2HSCEAHR3YC088016	10-Jan-00	22-Aug-00 310341
871 A	03-Nov-99 Y	30700-0319414	1FUYSSBAV1LP20368	18-Mar-01	12-Mar-02 166343
903 A	08-Nov-99 Y	31200-0206072	1FUY1W0B21LH51186		
1315 A	08-Nov-99 Y	34200-0218166	1HSCEAHR1YH272878	12-Apr-00	19-Mar-02 264936
125 A	09-Nov-99 Y	31300-0208978	1FUY97EB0YPA08423	29-Mar-00	16-Dec-01 317825
1374 A	09-Nov-99 Y	31300-0208033	1FUYD6291YLG06830	03-Apr-00	00-May-02 378161
122 A	10-Nov-99 Y	31400-0208834	1FUPC0287YP080204	05-Feb-00	01-Oct-01 302092
800 A	14-Nov-99 Y	31600-0210801	1FUYSSB9YL088407	15-Jan-00	24-Mar-02 412700
1624 A	15-Nov-99 Y	31800-02111432	1M1A05B0YBN003066	13-Jan-00	17-Nov-01 250724
1582 A	15-Nov-99 Y	31000-0210988	1FUYSSB8YL088218	22-Sep-00	12-Jun-02 467240
1835 A	15-Nov-99 Y	31800-0210810	1M1A07YK1YH004669	08-May-00	05-Jun-02 103398
1606 A	15-Nov-99 Y	31900-0210847	1FUYSSZB9YL088161	16-Dec-99	18-May-02 084633
737 A	18-Nov-99 Y	32200-0213262	1FUPD6298YL088170	25-Jan-00	26-Jul-01 388506
969 A	18-Nov-99 Y	32200-0213279			
735 A	19-Nov-99 Y	32300-0243525	2HSCKASR8YC071357	24-Jan-00	24-Jan-02 234256
1486 A	20-Nov-99 Y	32400-0210898			
1223 A	22-Nov-99 Y	32600-0214123	1FUYSSB8YP0841154	25-Mar-00	292261
734 A	23-Nov-99 Y	32700-0214328	1FUY7E7B7YL074623	20-Jan-00	20-Jan-02 275235
736 A	23-Nov-99 Y	32700-0214430	1FUYSSZB4YL0882208	10-Apr-00	02-Jun-02 267203
1222 A	25-Nov-99 Y	33000-0125448	1FUY87E7YPG028910	23-Mar-00	30-Mar-02 410088
1429 A	30-Nov-99 Y	33400-0012465	1FUYDZB8YL088404	11-Nov-99	03-Apr-02 560494
268 A	30-Nov-99 Y	33500-0222584	1FUPDDYB8YLG18483	23-Jun-00	28-Nov-01
245 A	30-Nov-99 Y	33400-0216056	1FUYSDYB2YP084044	29-Jul-99	26-Jun-01 222801
702 A	30-Nov-99 Y	33400-0215886	2HSCEAHR3YC088064	22-Nov-00	10-Dec-01 138013
1224 A	03-Dec-99 Y	33700-0217692	1FUYDSZB8YLH040264	10-Apr-00	03-Apr-02 233656
1063 A	04-Dec-99 Y	33700-0217575	1FUYDSZB8YLH040266	10-Apr-00	10-Jan-02 191229
769 A	15-Dec-99 Y	34000-0222760	1FUYSSB8YP0841212	18-Apr-00	10-Oct-01 172537
1003 A	15-Dec-99 Y	34000-0222364	1FUY7E7B7YLH3286	17-Mar-00	28-Feb-02 187977
1688 A	16-Dec-99 Y	35000-0222036	1FUY87E7YPG028879	20-Apr-00	16-Aug-01 201517
1225 A	20-Dec-99 Y	35400-0244937	1FUYSSB8YPG07496	20-Apr-00	07-May-00 348279
1503 A	20-Dec-99 Y	35400-0224714	1FUPD8EB8WP0873565	07-Apr-00	00-May-02 878433
1621 A	01-Jan-00 Y	00100-0771063	1FUCAHC081LH02728	12-Dec-00	29-Apr-02 361201
764 A	03-Jan-00 Y	00300-0227103	1FUYSSB8YPG080857	31-Mar-00	08-Jan-01 180839
178 A	04-Jan-00 Y	00400-0227802	no paperwork		
310 A	07-Jan-00 Y	00700-0225455	1FUYD2EB01PH08272		116162
1487 A	17-Jan-00 Y	01700-0232749	1FUM3MCAX1LB22120	08-Jun-00	20-Jun-02 116800
1408 A	28-Jan-00 Y	02600-0261189	2HSCEAHR41L008730	31-Aug-00	21-Mar-02 160432
143 A	22-Feb-00 Y	06300-0348000			8702
1488 A	22-Feb-00 Y	06300-0248800	1FUYDDYB6XPB22333	01-May-00	14-Dec-01 248221
320 A	03-Mar-00 Y	06300-0250419			160000
127 A	08-Mar-00 Y	06300-0260024	1FUYSSB831P041379	05-Jun-00	10-Jun-01 178412
773 A	10-Mar-00 Y	07000-0263001	2HSCEAMR51C069827	09-Jun-00	18-Aug-01 116162

1584 A	10-Mar-00 Y	07000-0263470	1FLUJSDYBXPA87119	01-May-00	20-Apr-02 293017
142 A	13-Mar-00 Y	07300-0254205			50024
1226 A	16-Mar-00 Y	07500-0255965	1FLUJA3CG51LG62177	15-Jun-00	08-Apr-02 438123
772 A	18-Mar-00 Y	07800-0256280	1FLUJA3BG51LB74838	08-Jun-00	25-Jan-02 218129
1618 A	06-Apr-00 Y	08500-0265977	1FLUJASAVB1LG96728	10-Aug-00	16-Apr-02 181803
1452 A	12-Apr-00 Y	10300-0268140	2HSCHAMR21CD12004	30-Mar-01	13-Mar-02 185060
1228 A	28-Apr-00 Y	12000-0276361			
1227 A	02-May-00 Y	12300-0278315	1FLUJA4CG51PHN625	18-Dec-00	20-Dec-01 212000
1354 A	09-May-00 Y	13000-0279465	1FLUJBBDG1LJ96506	13-Oct-00	04-Feb-02 247031
1058 A	09-May-00 Y	13000-0279171	1X0WDR9X81R878257	05-Feb-01	26-Feb-02 238263
1007 A	12-May-00 Y	13300-0280882	1FLUCLCG11PG06403	13-Jul-00	14-Jan-02 167507
133 A	15-May-00 Y	13600-0282167	1FLUNA3BG41PG88471	28-Sep-00	15-Oct-01 125288
295 A	22-May-00 Y	14300-0284469	2HSCNAHMR51C067439	15-Dec-00	04-Feb-02 167161
818 A	22-May-00 Y	14300-0284469	1FLUJAPC991H094469	22-Sep-01	24-Jun-01 102647
134 A	24-May-00 Y	14400-0285228		02-Oct-00	18-Oct-00 633
1107 A	15-Oct-00 Y	20000-0312174	1FLUJACAS61LJ92998		109318
1673 A	26-Oct-00 Y	20000-0312224	1FLUJACAS621LJ92801	01-Jan-01	273301
1672 A	26-Oct-00 Y	20000-0312114	1FLUJACAS21LK92001	01-Jan-01	273301
900 A	28-Oct-00 Y	20000-0312174	1FLUJACAS61LJ92998		109318
1383 A	28-Oct-00 Y	30000-0317037	1FLUJA-HG32PJ54114	08-May-01	12-Mar-02 120666
1502 A	29-Oct-00 Y	30300-0229317	2HSCNAMR51C068287	25-Apr-00	05-Mar-02 246206
1348 A	02-Nov-00 Y	30700-0310264	1FLUJBCGX1LJ16202	18-May-01	12-Apr-02 201418
1347 A	02-Nov-00 Y	30700-0310121	1FLUJAHCGX1LJ20437	14-Dec-00	18-Apr-02 261304
1570 A	02-Nov-00 Y	30700-0310275	1FLUVBCG51F883621	01-Feb-01	05-Sep-01 302260
504 A	14-Nov-00 Y	31000-0321695	1FLUJBBCA21PB39018	03-May-01	17-Aug-01 78300
165 A	15-Nov-00 Y	32100-0320478			
501 A	20-Nov-00 Y	32500-0321457	2HSCCEAHR21C021238	23-Feb-01	20-Dec-01 66383
866 A	07-Dec-00 Y	31200-0320980	1FLUJBBCG71PB38710	04-Feb-01	25-Jun-01 87387
53 A	10-Jan-01 Y	01001-0320630	1FLUYSSZB0XLA42847	22-Mar-00	07-Jan-02 733519
1367 A	11-Jan-01 Y	01101-0327122	4V4MC9RP91N326003	21-Apr-01	14-Mar-02 74800
1366 A	03-Feb-01 Y	03401-0328539	1FLUJB68CG52PJ13198	13-Jul-01	11-Feb-02 107874
1361 A	07-Feb-01 Y	03601-0329788	1FLUJA6CG81LF248507	15-Jul-01	04-Apr-02 92725
807 A	15-Feb-01 Y	04601-0330847	2HSCCEAMR72C023366	03-Jul-01	07-Jan-02 51284
508 A	19-Feb-01 Y	05001-0331211	2HSCCEAMR72C023366	03-Jul-01	07-Jan-02 51284
1365 A	19-Feb-01 Y	05001-0331307	1FLUJA6LG22LK06805	01-Jul-01	04-Feb-02 133471
1608 A	19-Feb-01 Y	05001-0331306	1FLUJA8CG62LK06805	08-Jul-01	17-Apr-02 170026
1349 A	19-Feb-01 Y	05001-0331313	1FLUJA7CG22LK06805	07-Jul-01	04-Mar-02 184990
1367 A	19-Feb-01 Y	05001-0331304	1FLUJA9CG42LK06806	08-Jul-01	16-Apr-02 196263
1346 A	19-Feb-01 Y	05001-0331290	1FLUJA8CG22LK06800	06-Jul-01	04-Mar-02 169692
1816 A	19-Feb-01 Y	05001-0331305	1FLUJA9CG22LK06801	05-Jul-01	15-Apr-02 203642
1360 A	19-Feb-01 Y	05001-0331298	1FLUJA9CGX2LK06807	06-Jul-01	21-Feb-02 166966
1514 A	20-Feb-01 Y	05101-0331602	1FLUJA9CG32LK06800	30-Jun-01	04-Mar-02 176236
1080 A	20-Feb-01 Y	05101-0331445		15-Feb-02	
1817 A	20-Feb-01 Y	05101-0331605	2HSCCEAMR82C023398	06-Jun-01	17-Mar-02 74661
1380 A	20-Feb-01 Y	05101-0331488	1FLUJA8CG82LK06806	01-Jul-01	16-Feb-02 157071
1051 A	20-Feb-01 Y	05101-0331605			
1608 A	20-Feb-01 Y	05101-0331511	1FLUJA6CG62LK06805	01-Jul-01	06-May-02 201289
808 A	21-Feb-01 Y	06201-0331794	1FLUJA6CG12LK06814	02-Jul-01	14-Feb-02 182279
1365 A	21-Feb-01 Y	06201-0331780	1FLUJA6CG72LK06817	08-Jul-01	04-Mar-02 161991
1353 A	21-Feb-01 Y	06201-0331786	1FLUJA6CG02LK06838	08-Jul-01	01-Feb-02 147371
1601 A	21-Feb-01 Y	06201-0331794	1FLUJA6CG12LK06814	02-Jul-01	14-Feb-02 182279
1351 A	21-Feb-01 Y	06201-0331792	1FLUJA6CG52LK06816	02-Jul-01	25-Apr-02 226167
1610 A	27-Feb-01 Y	06501-0332848	1FLUJA9A872LK47114	25-Sep-01	07-May-02 66774
808 A	27-Feb-01 Y	06501-0332852	1FLUJA8RL02LK73907	25-Jul-01	14-Jan-02 80934
810 A	01-Mar-01 Y	06601-0333248	1XP5D80X0X2N574466	28-Sep-01	27-Feb-02 36685
811 A	09-Mar-01 Y	06601-0334402	1FLUJA6CG12LK74358	22-Aug-01	16-Jan-02 91672
1816 A	18-Mar-01 Y	07401-0333379	1FLUYS9E51XP780803	28-May-00	28-May-01 553697
1448 A	18-Mar-01 Y	07401-0333324	1FLUWNWDARYLF92400	01-Sep-00	23-Apr-02 500011
1679 A	28-Mar-01 Y	06701-03358414	1FLUJACA661CH72212	01-Sep-00	22-Aug-02 321416
1358 A	17-May-01 Y	13701-0320460	1FLUJAHS22PJ71412	16-Jul-01	12-Feb-02 98680
1082 A	06-Jun-01 Y	15601-0331587			

SKF 002170

ID	A/L?	Julian Date	Translation	Hub Problem Y/N	SKF Serial number	In Service Date
1023 A		1/10/01		N	01001-0326305	12/09/98
					01300 0231668 or	
793 A		1/13/00		N	0272032?	11/20/00
947 A		1/20/00		N	02099-0080516	
948 A		1/22/00		N	02299-0081841	
949 A		1/22/00		N	02299-0081734	
600 A		1/25/00		N	02599-7	10/21/98
520 A		1/26/00		N	02599-0064213	08/20/00
580 A		1/27/00		N	02799 0031468	03/31/00
585 A		1/29/00		N	02999-0083970	04/01/00
788 A		1/4/00		N	00400-0227842	08/01/00
807 A		1/5/01		N	00801-0326003	08/22/01
801 A		10/12/00		N	26400-0311471	02/15/01
1068 A		10/12/00		N	26600-0311524	
804 A		10/16/00		N	29000-0312115	03/01/01
1061 A		10/18/00		N	29000-1312447	
1028 A		10/2/00		N	27999-0026198	01/23/00
527 A		10/22/00		N	26500-0030562	12/07/00
282 A		10/22/00		N	26500-0201638	11/30/00
295 A		10/25/00		N	30000 0317278	01/04/01
510 A		10/25/00		N	26600 0031018	10/23/00
543 A		10/26/00		N	30000-0317254	07/23/00
975 A		10/26/00		N	29000-0202760	03/04/00
829 A		10/27/00		N	30000-0001807	12/06/00
532 A		10/27/00		N	30000 0033813	12/19/00
705 A		10/9/00		N	26299 0164757	11/17/00
205 A		11/7/00		N	31599-0209918	04/23/00
800 A		11/8/00		N	30700-0319507	02/14/01
858 A		11/2/00		N	30800-0206631	
857 A		11/2/00		N	30800-0206633	
991 A		11/22/00		N	32700-0323822	
822 A		11/22/00		N	32800-0081110	
767 A		11/22/00		N	32799-0214312	04/23/00
967 A		11/26/00		N	33000-0164712	
1032 A		11/26/00		N	33099-0211572	08/04/00
773 A		11/29/00		N	33399-0216538	08/30/00
744 A		11/5/00		N	30000-0207401	08/26/00
506 A		11/6/00		N	31400-0321182	04/20/01
659 A		11/6/00		N	31300-0206679	08/26/00
751 A		12/1/00		N	33000-0216668	03/14/00
752 A		12/1/00		N	33000-0216667	03/14/00
765 A		12/1/00		N	33000-0216768	04/26/00
766 A		12/1/00		N	33000-0216784	04/26/00
888 A		12/16/00		N	38000-0057478	
668 A		2/1/01		N	04301-0330229	08/23/00
522 A		2/13/01		N	04301-0330268	11/24/00
764 A		2/13/00		N	4499-0220385	03/17/00
307 A		2/20/00		N	04199-0093448	
306 A		2/25/00		N	05600-0097704	
828 A		2/26/01		N	05601-0333070	
915 A		3/11/00		N	07000-0104604	
831 A		3/12/01		N	07101-0334961	
320 A		3/16/00		N	07600-0265668	
713 A		3/16/00		N	07499-0106328	12/01/99
791 A		3/16/00		N	07599-0265798	10/30/00
597 A		3/23/00		N	04299-0109535	08/08/00
636 A		3/23/00		N	08499 0111242	07/19/00
686 A		3/26/00		N	08599 0111194	08/21/00
607 A		3/26/00		N	08599 0111736	08/21/00
932 A		3/26/00		N	08599-0111002	
767 A		3/26/00		N	08900-0261808	10/09/00
578 A		3/26/00		N	06200-0099668	05/08/00
422 A		3/31/00		N	09099 0114207	01/11/00
504 A		3/4/00		N	06399 0100778	04/01/00
437 A		3/5/00		N	06499-0101899	03/19/00
577 A		3/5/00		N	06499 0101320	05/06/00
776 A		3/9/00		N	06900 0281902	08/16/00
777 A		3/9/00		N	06800 0253844	08/16/00
373 A		3/9/01		N	06801-0334448	05/30/01
294 A		4/11/00		N	10200-0287639	08/19/00
792 A		4/12/00		N	10300-0286538	10/20/00
760 A		4/14/00		N	10500-0283779	07/21/00
622 A		4/22/00		N	11200-0125790	07/01/00

SKF 002171

740 A	4/29/99	N	11999-0126813	02/07/00
682 A	5/10/99	N	16099-0146958	06/27/99
315 A	5/13/99	N	13999-0134207	
1058 A	5/16/99	N	13700-0282417	06/27/00
648 A	5/18/99	N	17099-0126813	07/30/99
938 A	5/18/99	N	13899-0135849	
614 A	5/20/99	N	12300-0278424	08/04/01
615 A	5/20/99	N	12300-0278548	08/04/01
518 A	5/20/99	N	12300-0278424	08/04/01
1037 A	6/2/99	N	12299-7770119	08/03/99
788 A	5/24/99	N	14499-0139659	10/12/00
315 A	5/29/99	N	14999-0160954	
504 A	5/3/99	N	12999-0128125	06/16/00
868 A	5/3/99	N	12399-0128021	08/23/99
663 A	5/5/99	N	12599-0129357	10/27/00
248 A	5/6/99	N	012000-0130890	08/01/99
249 A	5/6/99	N	12600-0130894	08/01/99
692 A	5/9/99	N	12801-0341718	10/22/99
368 A	5/1/99	N	16299-0143293	03/25/97
651 A	5/13/99	N	16699-0149061	06/07/00
622 A	5/13/99	N	15699-0149084	06/07/00
398 A	5/23/01	N	07401-0338228	09/11/07
860 A	5/23/99	N	17499-0154857	08/15/00
877 A	5/23/99	N	17899-0167386	09/01/00
918 A	5/3/99	N	16499-0164541	
861 A	5/30/99	N	18199-0168206	
882 A	5/30/99	N	18199-0100103	
252 A	6/8/99	N	16099-0147222	08/20/99
880 A	6/8/99	N	15999-0446617	08/18/99
851 A	5/6/99	N	15699-0146612	08/18/99
705 A	7/12/99	N	10300-0160387	11/14/99
704 A	7/12/99	N	19399-0160382	11/14/99
863 A	7/12/99	N	19399-0160341	
867 A	7/21/99	N	20299-0164294	
700 A	7/22/99	N	20399-0164730	11/04/00
865 A	7/22/99	N	20399-0164728	
868 A	7/22/99	N	20399-0164732	
672 A	7/22/99	N	20399-0167218	
673 A	7/22/99	N	20399-0166278	
675 A	7/23/99	N	20499-0166526	
677 A	7/23/99	N	20499-0166535	
675 A	7/23/99	N	20499-0166530	
679 A	7/23/99	N	20499-0165726	
680 A	7/23/99	N	20499-0165726	
851 A	7/24/99	N	20399-0166583	
852 A	7/24/99	N	20600-0166567	
969 A	7/26/99	N	20799-0166527	
887 A	8/11/99	N	22398-0012612	
636 A	8/15/99	N	22798-0013413	01/29/99
1027 A	8/17/01	N	22001-0351662	09/24/99
600 A	8/17/99	N	26098-0021694	10/14/99
968 A	8/22/99	N	23498-0184673	
582 A	8/24/99	N	25899-0017778	03/31/99
840 A	8/27/99	N	23698-0016020	
328 A	8/5/99	N	21598-0011238	
491 A	8/5/99	N	21798-0010812	10/05/00
885 A	8/15/99	N	25899-01665414	
659 A	8/17/99	N	26099-0166238	
730 A	8/18/99	N	28199-0166660	01/01/00
886 A	8/18/99	N	26299-0187045	
205 A	8/19/99	N	26298-0022982	10/22/99
443 A	8/22/99	N	26599-0188690	04/14/00
513 A	8/26/99	N	26699-0024707	10/22/99
514 A	8/26/99	N	26698-0024841	10/22/99
903 A	8/26/99	N	26004-0024014	
783 A	8/28/99	N	27198-0192551	08/06/00
784 A	8/28/99	N	27198-0192042	08/06/00
708 A	8/29/99	N	27298-0191943	11/26/99
709 A	8/29/99	N	27298-0192229	11/26/99
839 A	8/6/99	N	26196-0019215	
1026 A	8/6/99	N	26198-0019199	01/26/99

SKF 002172

ID	ALT?	Julien Date Translations	Hub Problem	VIN	SKF Serial number	In Service Date
31 A		Y	N/A Aiken	1040268		
48 A		Y	Too rusty - Aiken	0170268		
55 A		Y	01001 0326630	03/22/99		
68 A		Y	N/A Aiken	03/31/99		
67 A		Y	N/A Aiken	08/10/99		
66 A		Y	Too rusty - Aiken	08/11/99		
70 A		Y	71999-0124400	08/17/99		
64 A		Y	N/A Aiken	07/16/99		
96 A		Y	Too rusty - Aiken	08/26/99		
109 A		Y	N/A Aiken	08/24/99		
110 A		Y	77199 0147852	09/27/99		
120 A		Y	0209110 Aiken	01/03/00		
135 A		Y	Too rusty - Aiken	12/09/01		
168 A		Y	Too rusty - Aiken			
175 A		Y	Too rusty - Aiken			
283 A		Y	77199 01642301	12/01/99		
498 A		Y	Too rusty - Aiken	10/14/99		
587 A		Y	Too rusty - Aiken	04/05/99		
684 A		Y	Is rusty - Aiken	08/17/99		
687 A		Y	N/A Aiken	08/26/99		
826 A		Y	N/A AIKEN	07/01/99		
866 A		Y	N/A Aiken	08/29/99		
867 A		Y	Too rusty - Aiken	10/05/99		
889 A		Y	Aiken	10/15/99		
748 A		Y	0217487 77799	03/08/00		
852 A		Y	7 198-0048819			
854 A		Y	198-0016428			
935 A		Y	N/A Aiken			
944 A		Y	N/A Aiken			
955 A		Y	Too rusty - Aiken			
980 A		Y	Rusty - Aiken	08/30/99		
1008 A		Y	RUSTY-AIKEN	09/19/99		
1028 A		Y	37408-0071317	04/01/00		
1039 A		Y	Too rusty - Aiken	08/15/99		
1046 A		Y	75799-0151140	08/28/99		
1098 A		Y	Too rusty Aiken			

SKF 002173

ID	Alt?	Julian Date Translation	Hub Problem Y/N	SKF Serial number	In Service Date
521 A	N		N/A Aiken	11/21/00	
513 A	N		99 0140265	08/22/00	
525 A	N		Too nutty - Aiken	10/28/00	
721 A	N		Too nutty - Aiken	12/18/00	
778 A	N		???00 0288331	07/08/00	
795 A	N		Too nutty - Aiken	12/18/00	
812 A	N		N/A Aiken	07/26/01	
817 A	N		??99-0194800		
918 A	N		N/A Aiken		
920 A	N		??598-0195061		
921 A	N		N/A Aiken		
923 A	N		N/A Aiken		
924 A	N		N/A Aiken		
926 A	N		??99-007		
928 A	N		??99-015145		
1068 A	N		??100-0312161		

SKF 002174

ID	AH?	Julian Date Translation	Hub Problem Y/N	SKF Serial number	In Service Date
139 L	Y			1998 S M122978	
140 L	Y			000762 S N23214	
163 L	Y			000942 S8175	
162 L	Y			004617 M043166	
160 L	Y			006265 S M422979	
334 L	Y			M397790	
940 L	Y			Too rusty: Luochow	
1000 L	Y			98D98-081249-	
4 L	Y			000811-RM175843	01/27/97
385 L	Y			003544 M759438 R	01/27/97
21 L	Y			001938 M176870	01/28/98
5 L	Y			M317554	03/17/97
8 L	Y			00010? M817682	03/17/97
7 L	Y			00032 R M817534	03/20/97
978 L	Y			98040 1108803	03/20/98
439 L	Y			98026 MN157132	04/01/98
979 L	Y			001437-M169112-	04/01/98
22 L	Y			38088-M195137	04/21/98
8 L	Y			000418 R M817584	04/23/97
380 L	Y			Luochow	04/25/97
1079 L	Y			98065-08052	04/28/98
450 L	Y			98038 M1195166	04/30/98
998 L	Y			98038-1786436-	05/01/98
1017 L	Y			00384-? Luochow	05/01/98
372 L	Y			000231 R M776332	05/06/97
8 L	Y			98043 R	05/15/97
483 L	Y			98044 M189111	05/19/98
23 L	Y			Too rusty - Luochow	05/23/98
161 L	Y			000307 M874570	06/30/97
10 L	Y			000177-S-M832414	07/07/97
633 L	Y			000257-M168234-	07/13/98
11 L	Y			000658-R-M	07/15/97
12 L	Y			98017-M776332	07/17/97
471 L	Y			001928-98078-	07/17/98
472 L	Y			98045-005700	07/17/98
473 L	Y			3848-19099-	07/20/98
86 L	Y			000207 98010	07/20/98
13 L	Y			000681 R M776332	07/21/97
14 L	Y				07/25/97
15 L	Y			002808 S M087790	08/08/97
198 L	Y			000442-98174-	08/08/98
16 L	Y			No hub received	08/13/97
17 L	Y				08/25/97
20 L	Y			Too rusty - Luochow	08/28/98
481 L	Y			98140 "S" M209649	08/29/98
483 L	Y			0033774-98186-	09/01/98
18 L	Y			001484 S	09/16/97
19 L	Y			009780 R M776332	09/16/97
402 L	Y			0348-M122978	10/10/97
403 L	Y			001622 M888016 S	10/20/97
118 L	Y			107704 M776332	10/21/99
187 L	Y			M776332	11/07/97
20 L	Y			001181 S M140786	12/10/97

SKF 002176

ID	AVL?	Julian Date Transferred	Hub Problem Y/N	SKF Serial number	In Service Date
314 L	N			M0269016	
316 L	N			0225413-36500	
332 L	N			95426-M244530 S	
333 L	N			98180-M244530 R	
334 L	N			98170-M214560 S	
335 L	N			003818-88169-	
336 L	N			001730-98162-	
337 L	N			00152-M214560-	
338 L	N			003473-98168-	
343 L	N			98271-272-	
344 L	N			001153-98271-	
345 L	N			001048-98271-	
346 L	N			001052-98271-	
363 L	N			98032-M278257-	
364 L	N			00742-M278257-	
368 L	N			98138-M209670	
382 L	N			002612-M007700 S	
383 L	N			003352-M007700 S	
919 L	N			98454 ?	
929 L	N			M932414	
930 L	N			M776352	
931 L	N			M043188	
960 L	N			004829 M778632	
956 L	N			M122975 S 004638	
958 L	N			98050 M207100	
962 L	N			002330 98038-	
984 L	N			Too rusty - Luochow	
1104 L	N			Too rusty - Luochow	
419 L	N			002662 M122978 01/04/96	
434 L	N			M149799 01/15/96	
543 L	N			BTP0048 98284 02/01/96	
430 L	N			000488 M122978 02/04/96	
431 L	N			97383 M137432 03/02/96	
433 L	N			97583-33132 03/05/96	
456 L	N			006189-M776332 03/09/96	
440 L	N			98005 M187132 04/01/96	
447 L	N			98037-M198438 04/21/96	
371 L	N			0006742-M778438 04/20/97	
481 L	N			88098-13D9088 05/01/96	
482 L	N			98078-M203088 05/12/96	
1018 L	N			N/A Luochow 05/15/96	
302 L	N			M121820 05/18/91	
484 L	N			98028 M188188 05/20/96	
495 L	N			98055 M188137 05/20/96	
374 L	N			006217-M776332 R 05/30/97	
450 L	N			98055-M203089 05/30/96	
375 L	N			000099-5-M007790 06/02/97	
376 L	N			00800 M778332 06/13/97	
378 L	N			000577 M907790 06/30/97	
301 L	N			000630-M882414 07/07/97	
382 L	N			001805-M882414 07/07/97	
470 L	N			97351 M188117 07/15/96	
478 L	N			004925-98172- 08/10/96	
477 L	N			000213-98148- 08/13/96	
478 L	N			004388-98171- 08/17/96	
391 L	N			001103 M882414 08/18/97	
362 L	N			00018 M882414 08/18/97	
363 L	N			177833-0098 S 08/18/97	
479 L	N			008148- M214549 08/20/96	
460 L	N			008136-M214550 08/21/96	
394 L	N			M007790 S 001647 08/26/97	
388 L	N			003274-M0043168 08/26/97	
397 L	N			003874-M0073080 08/26/97	
389 L	N			301259-M007790 08/23/97	
1083 L	N			002012-M009018 S 10/26/97	
405 L	N			001484 M0090018 11/08/97	
406 L	N			003050-M009018 11/08/97	
415 L	N			M122978 12/11/97	

SKF 002176

ID	Alt.7	Julian Date Translated	Hub Problem Y/N	SKF Serial number	In Service Date
142	?	Y			
143	?	Y			
147	?	Y			
150	?	Y			
151	?	Y			
154	?	Y		No Info	
155	?	Y			
156	?	Y			
159	?	Y			
160	?	Y		0123372	
164	?	Y		023880 128102	
171	?	Y			
172	?	Y			
174	?	Y			
176	?	Y			
304	?	Y			
308	?	Y		0018799	
309	?	Y			
310	?	Y		0264177	
313	?	Y		0128094	
325	?	Y		0152882	
327	?	Y		00739441	
329	?	Y		0149882	
336	?	Y		1730	
341	?	Y			
353	?	Y			
357	?	Y			
352	?	Y			
363	?	Y			
828	?	Y		0018042	
830	?	Y		0018186	
927	?	Y			
933	?	Y		0106824	
934	?	Y			
936	?	Y			
937	?	Y			
943	?	Y			
946	?	Y			
960	?	Y		001057	
46	?	Y			01/01/00
47	?	Y			01/01/00
48	?	Y			01/02/00
223	?	Y			01/02/00
274	?	Y			01/14/00
224	?	Y			01/14/00
225	?	Y			01/15/00
275	?	Y			01/30/00
276	?	Y			01/31/00
428	?	Y			02/02/00
123	?	Y			02/03/00
227	?	Y			02/04/00
126	?	Y			02/10/00
545	?	Y			02/16/00
742	?	Y		12446035	02/16/00
275	?	Y			02/17/00
125	?	Y			02/24/00
279	?	Y			02/28/00
290	?	Y			02/28/00
291	?	Y			03/01/00
180	?	Y			03/10/00
749	?	Y			03/13/00
750	?	Y			03/13/00
753	?	Y			03/15/00
269	?	Y			03/18/01
281	?	Y			03/22/01
864	?	Y			03/24/01
650	?	Y			03/25/01
59	?	Y			04/01/01
663	?	Y			04/01/01
441	?	Y			04/08/01
300	?	Y			04/16/01
62	?	Y			04/16/01
54	?	Y			04/23/01

SKF 002177

191 ?	Y		04/21/96
976 ?	Y	006522	04/30/97
267 ?	Y	0229814	05/03/00
232 ?	Y		08/03/99
984 ?	Y	0163406	05/12/00
102 ?	Y	05438	05/15/96
233 ?	Y		05/18/99
772 ?	Y		05/25/00
288 ?	Y		05/26/00
236 ?	Y	0128903	06/04/99
269 ?	Y		06/06/00
596 ?	Y		06/07/99
193 ?	Y		06/11/96
459 ?	Y		06/11/96
451 ?	Y		06/11/96
596 ?	Y		06/11/99
599 ?	Y		06/11/99
603 ?	Y		06/15/99
377 ?	Y		06/17/97
24 ?	Y		06/18/04
175 ?	Y		06/18/99
73 ?	Y		06/19/99
130 ?	Y		06/21/00
464 ?	Y		06/22/98
294 ?	Y	0076297	06/22/99
466 ?	Y		06/28/98
132 ?	Y		06/27/00
78 ?	Y		08/28/99
238 ?	Y	126048	08/29/98
77 ?	Y		08/30/99
240 ?	Y	0084640	08/30/98
3 ?	Y		07/01/00
628 ?	Y	722002	07/02/98
829 ?	Y		07/02/99
674 ?	Y	7280-012984	07/07/01
82 ?	Y		07/09/98
292 ?	Y		07/10/00
242 ?	Y		07/12/99
293 ?	Y		07/14/00
638 ?	Y		07/19/99
87 ?	Y		07/20/99
840 ?	Y		07/21/99
386 ?	Y		07/23/97
544 ?	Y		07/26/99
388 ?	Y		07/27/97
845 ?	Y		07/28/99
162 ?	Y		07/29/97
28 ?	Y		07/31/98
474 ?	Y		08/04/98
163 ?	Y		08/05/97
854 ?	Y		08/10/99
250 ?	Y		08/16/99
667 ?	Y	Unit #280810	08/18/99
960 ?	Y		08/18/99
862 ?	Y		08/19/99
863 ?	Y		08/19/99
94 ?	Y		08/20/99
253 ?	Y		08/20/99
1044 ?	Y		08/20/99
87 ?	Y		08/30/99
284 ?	Y		08/31/99
675 ?	Y		08/31/99
295 ?	Y		09/01/00
133 ?	Y		09/07/00
101 ?	Y		09/07/99
105 ?	Y		09/11/99
134 ?	Y		09/14/00
679 ?	Y		09/14/99
106 ?	Y		09/18/99
185 ?	Y		10/03/97
462 ?	Y	0014749	10/08/98
888 ?	Y		10/08/98
202 ?	Y		10/13/98
203 ?	Y		10/14/98
		Not legible	

SKF 002178

112 ?	Y		10/16/99
257 ?	Y		10/20/99
507 ?	Y		10/22/99
877 ?	Y		10/28/99
694 ?	Y	000762	10/29/99
207 ?	Y		10/31/99
208 ?	Y	0023910	10/31/99
899 ?	Y		11/01/99
258 ?	Y		11/02/99
40 ?	Y		11/13/99
517 ?	Y		11/13/99
211 ?	Y	0022821	11/17/99
212 ?	Y	0022822	11/18/99
261 ?	Y		11/18/99
213 ?	Y		11/19/99
520 ?	Y	0024453	11/19/99
42 ?	Y		11/21/99
216 ?	Y	0024434	11/23/99
218 ?	Y	0024231	11/23/99
44 ?	Y		11/24/99
45 ?	Y		11/24/99
219 ?	Y		11/25/99
711 ?	Y		11/26/99
526 ?	Y		12/04/99
264 ?	Y		12/10/99
720 ?	Y		12/15/99
267 ?	Y		12/17/99
220 ?	Y	0037275	12/18/99
962 ?	Y		12/19/99
268 ?	Y	0144656	12/20/99
269 ?	Y		12/20/99
270 ?	Y		12/20/99
723 ?	Y		12/21/99
271 ?	Y		12/22/99
725 ?	Y		12/24/99
727 ?	Y		12/26/99

ID	Alt?	Julian Date Translation	Hub Problem Y/N	SKF Serial number	In Service Date
305 ?	N				
312 ?	N			0127632	
319 ?	N			002363	
321 ?	N				
323 ?	N				
324 ?	N				
326 ?	N			0127246	
330 ?	N			0270955	
331 ?	N			0287111	
332 ?	N			0887112	
333 ?	N			0314841	
335 ?	N			0136617	
338 ?	N				
340 ?	N				
342 ?	N				
343 ?	N				
344 ?	N				
346 ?	N				
348 ?	N				
349 ?	N				
350 ?	N				
351 ?	N				
352 ?	N				
354 ?	N				
355 ?	N				
356 ?	N				
358 ?	N				
359 ?	N				
360 ?	N				
361 ?	N				
364 ?	N				
585 ?	N			0011520	
604 ?	N			901608	
907 ?	N			0012510	
912 ?	N				
926 ?	N			004115	
929 ?	N			906870	
937 ?	N				
959 ?	N				
786 ?	N				01/03/01
420 ?	N				01/04/00
222 ?	N				01/04/00
273 ?	N				01/12/00
226 ?	N				01/15/00
425 ?	N				01/16/00
426 ?	N				01/16/00
427 ?	N				01/16/00
179 ?	N				01/21/07
769 ?	N			0022316	01/28/01
180 ?	N				02/04/00
741 ?	N				02/08/00
647 ?	N				02/10/00
366 ?	N				02/15/07
691 ?	N				02/23/00
522 ?	N				02/24/00
229 ?	N				02/25/00
190 ?	N				02/26/00
745 ?	N				02/28/00
746 ?	N				03/01/00
555 ?	N			02466-0062965	03/03/00
554 ?	N				03/03/00
434 ?	N				03/05/00
436 ?	N				03/23/00
231 ?	N				03/30/00
768 ?	N				04/03/00
262 ?	N				04/05/00
442 ?	N				04/07/00
263 ?	N				04/14/00
689 ?	N				04/14/00
670 ?	N				04/14/00
264 ?	N				04/16/00

SKF 002180

446 ?	N		04/18/98
301 ?	N	No marking on	04/21/01
295 ?	N		04/28/00
789 ?	N	0188747	05/10/00
457 ?	N		06/01/96
236 ?	N		06/09/99
480 ?	N		06/11/98
237 ?	N		06/11/99
485 ?	N		06/23/98
281 ?	N		06/26/00
488 ?	N		06/29/98
380 ?	N	000434	06/30/97
821 ?	N		07/7/97
241 ?	N		07/01/99
194 ?	N		07/06/98
550 ?	N		07/09/98
486 ?	N		07/13/98
636 ?	N		07/17/98
383 ?	N		07/21/97
387 ?	N		07/26/97
195 ?	N		08/03/98
782 ?	N		08/06/00
388 ?	N		08/11/97
389 ?	N		08/11/97
390 ?	N		08/16/97
281 ?	N		08/16/98
197 ?	N		08/26/98
678 ?	N		08/31/98
184 ?	N		09/03/97
395 ?	N		09/05/97
199 ?	N	001983	09/07/98
200 ?	N		09/14/98
400 ?	N		09/29/97
401 ?	N		09/26/97
286 ?	N		09/30/98
428 ?	N		10/01/98
494 ?	N		10/13/98
601 ?	N		10/14/98
602 ?	N		10/16/98
186 ?	N	004692	10/19/97
208 ?	N	0276914	10/16/00
612 ?	N		10/27/98
208 ?	N		10/29/98
209 ?	N		11/03/98
210 ?	N	0024343	11/12/98
260 ?	N		11/12/99
407 ?	N		11/15/97
408 ?	N		11/15/97
411 ?	N		11/19/97
412 ?	N		11/19/97
214 ?	N		11/22/98
186 ?	N		11/24/97
217 ?	N	0024430	11/24/98
218 ?	N		11/25/98
716 ?	N		12/03/98
626 ?	N	7-0031644	12/06/98
630 ?	N		12/10/98
268 ?	N		12/10/99
418 ?	N		12/11/97
417 ?	N		12/17/97
724 ?	N		12/21/99
221 ?	N		12/29/98
729 ?	N		12/30/99
418 ?	N		12/31/97
203 ?	N		no paperwork

ID	Alt/Julian Date/Transition	Hub Program YR/H	SKF Serial number	In Service Date
824 L		Q	0026316 M143785	
900 A		Q	Too rusty - Alken	
901 L		Q	0018840 N122978	
906 A		Q	77798-0127701	
909 A		Q	Too rusty - Alken	
910 A		Q	Too rusty - Alken	
911 A		Q	Too rusty - Alken	
954 L		Q	M778332 R 009873	
1068 L		Q	001252 S N122978	
1071 A		Q	N/A Alken	
1072 ?		Q		
1076 L		Q	004518 98171	
1080 L		Q	001398 98149	
1105 L		Q	Too rusty -	
421 L		Q	00300 Luechow	01/08/98
530 ?		Q		01/08/98
1024 ?		Q	0072140	01/08/98
734 A		Q	AIKEN	01/13/00
423 L		Q	000182 S M148785	01/15/98
1014 L		Q	006481	01/16/98
1015 ?		Q		01/16/98
426 L		Q	004828 S M148785	01/20/98
541 L		Q	98254 M222431	03/01/99
545 A		Q	Alken	03/05/99
1008 ?		Q		03/16/99
1073 L		Q	002384 R N017801	03/20/97
1053 ?		Q		02/21/00
1054 ?		Q		02/21/00
387 L		Q	N/A Luechow	02/21/97
747 A		Q	N/A AIKEN	03/01/00
898 L		Q	98006 01788	03/01/99
432 L		Q	98012 M148703	03/02/98
438 L		Q	000382-98048-	03/17/98
558 A		Q	TOO RUSTY-	03/18/99
1097 ?		Q		03/20/99
861 A		Q	Alken	03/01/99
759 A		Q	77798 0224748	04/06/00
1056 A		Q	N/A AIKEN	04/12/00
444 L		Q	98001 M33747	04/10/98
445 L		Q	98002 M168111	04/15/98
762 A		Q	77299-0204811	04/18/00
446 L		Q	Too rusty -	04/21/98
1018 ?		Q		04/24/98
1100 A		Q	N/A Alken	04/27/00
1101 A		Q	N/A Alken	04/27/00
1080 L		Q	053783 98052	04/28/98
1030 ?		Q		04/29/99
578 A		Q	Too rusty - Alken	05/03/99
770 A		Q	Too rusty - Alken	05/11/00
771 A		Q	Too rusty - Alken	05/11/00
682 A		Q	74880 0092486	05/15/99
1074 L		Q	001707 R	05/18/97
456 L		Q	Too rusty; Luechow	05/04/98
593 A		Q	Too rusty - Alken	05/04/98
1019 L		Q	N/A Luechow	05/11/98
1020 L		Q	N/A Luechow	05/11/98
900 A		Q	TOO RUSTY-	05/11/98
483 L		Q	001818-98075-	05/18/98
376 L		Q	005817 R N778332	05/20/97
1082 ?		Q		05/24/98
457 L		Q	98124 0020866	05/26/98
594 L		Q	M279237 98032	07/01/98
584 L		Q	001843-M922414 S	07/22/97
781 L		Q	0038238-M148730	07/23/98
848 A		Q	Too rusty - Alken	08/01/98
680 L		Q	98010 M148703	08/04/98
683 A		Q	Too rusty - Alken	08/04/98
1080 A		Q	N/A Alken	08/12/98
1040 ?		Q		08/16/98
870 A		Q	Too rusty - Alken	08/23/98
1077 A		Q	Too rusty Alken -	08/27/98
1068 ?		Q		08/28/98
452 L		Q	M214580 98153	08/31/98
674 ?		Q	0136450 13199	08/31/98
1001 L		Q	M043166 670-	08/32/97
1010 L		Q	00857 -0082A	08/32/97

SKF 002182

678 A		Q	728188 0147816	09/13/98
488 L		Q	M185135 98028	09/17/98
1021 L		Q	000040 BT-0048A	09/17/98
1087 L		Q	8812 M214548	09/17/98
1088 L		Q	N/A Luochow	09/21/98
1089 L		Q	N/A Luochow	09/21/98
480 T		Q		10/02/98
788 A		Q	799 0198777	10/12/00
497 A		Q	Too rusty - Alken	10/14/98
1011 L		Q	000679 STF-0032A	10/17/97
404 L		Q	001178 98105	10/20/98
506 L		Q	LUCHOW HUB	10/20/98
898 A		Q	Too rusty - Alken	10/28/98
701 A		Q	Too rusty - Alken	11/05/98
1004 ?		Q		11/12/98
408 A		Q	N/A AIKEN	11/13/97
410 L		Q	M270287 001018	11/17/97
706 A		Q	Too rusty - Alken	11/22/98
413 L		Q	Luochow	11/24/97
414 L		Q	Too rusty -	11/24/97
1012 L		Q	M068046 844-	11/24/97
1013 L		Q	000848	11/24/97
707 T		Q		11/25/98
710 A		Q	Too rusty - Alken	12/02/98
718 A		Q	TOC RUSTY-	12/14/98
719 A		Q	??889 0180840	12/14/98
720 A		Q	72189 0212732	12/30/98
897 A	1/12/98	Q	01289-0036270	02/18/98
571 A	1/14/98	Q	01489 0078913	04/15/98
575 A	1/16/98	Q	01889 0088787	04/20/98
763 A	1/24/98	Q	2488 0181780	04/20/98
868 A	1/24/98	Q	02488 0108828	05/16/98
981 A	1/28/98	Q	02889 0087984	
898 A	1/28/98	Q	02889-0883987	04/01/98
1073 A	1/27/98	Q	02789-0884880	02/26/98
798 A	1/3/98	Q	00309 0227103	02/31/00
757 A	1/3/98	Q	00309 0227116	03/01/00
1054 A	10/17/98	Q	27488-0183557	11/06/98
790 A	10/18/98	Q	29189-0198978	10/27/98
533 A	10/22/98	Q	29888 0030283	01/01/00
891 A	10/27/98	Q	30088 0222971	10/21/98
717 A	10/8/98	Q	28188-0184382	12/13/98
1061 A	11/1/98	Q	30888-02086373	12/22/98
535 A	11/10/98	Q	31488 0037080	01/06/99
537 A	11/13/98	Q	31788 0038380	01/07/99
538 A	11/15/98	Q	31888 0088738	01/07/99
795 A	11/15/98	Q	31888 02111138	12/28/98
1061 A	11/18/98	Q	32888 005128	
735 A	11/23/98	Q	32788 0214822	01/20/99
780 A	11/23/98	Q	32788-0214438	04/10/00
482 A	11/24/98	Q	32888 0081870	04/13/98
528 A	11/9/98	Q	30888 0025802	
1058 A	12/15/98	Q	34888 02222384	03/17/00
844 A	12/16/98	Q	35088-0087514	02/01/99
248 A	12/22/98	Q	35888 0088659	02/17/99
550 A	12/22/98	Q	35888 0088650	02/17/99
1060 A	12/3/98	Q	33788 0217878	04/10/00
764 A	2/28/00	Q	07700-0247824	04/27/00
1067 A	3/10/00	Q	07000-02262348	08/02/00
774 A	3/16/00	Q	07800-0255580	08/06/00
584 A	3/16/00	Q	07788-0108188	08/06/00
579 A	3/2/00	Q	08188 0088784	08/10/00
1108 A	5/22/00	Q	08188 0109002	
736 A	5/23/00	Q	08288 0110102	01/13/00
580 A	5/24/00	Q	08388 0108382	05/14/00
1064 A	5/25/00	Q	08488 211256	
627 A	5/26/00	Q	08488 0111801	
581 A	5/27/00	Q	08488 0112373	05/15/00
672 A	5/3/00	Q	08288-0108148	04/18/00
579 A	5/3/00	Q	08288-0086049	04/18/00
627 A	5/31/00	Q	08288-0114223	07/01/00

1046 A	38/99	Q	06499-0168368	11/28/99
625 A	4/1/99	Q	07789-0108097	07/01/99
817 A	4/20/99	Q	11099-0121402	06/24/99
591 A	4/21/99	Q	11199-0122143	06/01/99
592 A	4/21/99	Q	11199-0122833	06/02/99
593 A	4/21/99	Q	11199-0122345	06/15/99
598 A	4/21/99	Q	11199-0122896	06/18/99
931 A	4/21/99	Q	11199-0123027	07/10/99
608 A	4/23/99	Q	11299-0124026	06/22/99
1108 A	4/26/99	Q	11799-0125197	10/12/99
465 A	4/28/99	Q	11899-0125791	
904 A	4/28/99	Q	11899-0126090	
953 A	4/28/99	Q	11899-0125806	
601 A	4/30/99	Q	12099-0127740	06/11/99
808 A	5/10/99	Q	13099-0132359	
1067 A	5/10/99	Q	13099-0132189	
1068 A	5/10/99	Q	13099-0132188	
1034 A	5/10/99	Q	13099	06/25/99
905 A	5/11/99	Q	13199-0132852	
1007 A	5/12/99	Q	13299-0131117	06/05/99
1046 A	5/12/99	Q	13299-0133684	06/20/99
618 A	5/18/99	Q	13899-0135833	06/26/99
1036 A	5/18/99	Q	13899-0136441	07/16/99
1043 A	5/19/99	Q	13999-0136580	06/24/99
605 A	5/21/99	Q	14199-0138781	04/13/99
1108 A	5/22/99	Q	14299-0136688	03/01/99
814 A	5/3/99	Q	12399-0126480	
1078 A	5/3/99	Q	12399-0126024	
1038 A	5/3/99	Q	12399-0126309	07/08/99
1070 A	5/4/99	Q	12499-0229318	
810 A	5/4/99	Q	12499-0126277	06/22/99
811 A	5/4/99	Q	12499-0126883	06/22/99
812 A	5/4/99	Q	12499-0126881	06/22/99
1069 A	5/4/99	Q	12499-0126318	07/20/99
641 A	5/4/99	Q	12499-0126302	07/21/99
842 A	5/6/99	Q	12599-0126813	07/21/99
847 A	5/6/99	Q	12599-0126943	07/26/99
1042 A	5/6/99	Q	12699-0126375	06/18/99
1002 A	5/6/99	Q	12699-0138631	06/14/99
865 A	5/6/99	Q	12699-0130922	06/20/99
1041 A	5/7/99	Q	12799-	06/17/99
871 A	5/7/99	Q	12799-0131269	06/24/99
824 A	5/7/99	Q	12799-0131268	10/27/99
1002 A	5/1/99	Q	15299-0142628	
1088 A	5/14/99	Q	18899-0151432	10/15/99
804 A	5/16/99	Q	18899-0151437	06/19/99
821 A	5/23/99	Q	17499-0108704	06/30/99
1047 A	5/23/99	Q	17499-0154828	10/05/99
738 A	5/25/99	Q	17699-0158168	01/24/00
1048 A	5/25/99	Q	17699-0158100	10/14/99
1001 A	5/7/99	Q	16899-0148297	
568 A	5/7/99	Q	16899-0148242	06/17/99
1052 A	7/14/99	Q	19899-0161308	01/5/00
623 A	7/28/99	Q	21099-0189718	06/27/99
884 A	7/28/99	Q	21099-0189716	06/27/99
1088 A	5/12/99	Q	22499-0012181	03/31/99
493 A	5/12/99	Q	22899-0012762	10/07/99
605 A	5/14/99	Q	22998	06/21/99
449 A	5/16/99	Q	22799-0013407	04/21/99
518 A	5/17/99	Q	22899-0013587	11/13/99
714 A	5/29/99	Q	21599-0310545	12/02/99
495 A	5/29/99	Q	23699-0018413	10/14/99
522 A	5/29/99	Q	24199-0015428	
801 A	5/31/99	Q	24399-0019621	
540 A	5/31/99	Q	21899-0011938	02/01/99
1022 A	5/6/99	Q	21599-031270	10/05/99
738 A	5/7/99	Q	21999-0011540	03/23/00
986 A	5/1/99	Q	24499-0101753	
504 A	5/15/99	Q	26099-0021428	10/20/99
523 A	5/16/99	Q	26899-0021686	11/27/99
1050 A	5/21/99	Q	26499-018380	11/26/99
1095 A	5/22/99	Q	26599-0186900	04/14/99
615 A	5/24/99	Q	28799-0024011	11/05/99
1102 A	5/25/99	Q	28899-0024542	
624 A	5/26/99	Q	26899-0024402	11/27/99
785 A	5/30/99	Q	27399-0102298	09/14/00
488 A	5/7/99	Q	28099-0019454	10/14/99

SKF 002184

Response
to Main Document

Rick P Morrow/AMERISKF
10/19 07:10 PM

Subject: Torque Analysis Including Knight Descriptive Stats
Response to: Statistical Evaluations
Category: Statistics



THU Torque.ppt

THU Torque Study

**Data from Chuck Smith and Mike
Lewis with Hub Production data from
Warranty Analysis**

Includes Knight Torque data

Analysis


- There is significant variation in torques. Suggest Measurement System Analysis to ensure conclusions are valid.
- I studied mean and variance in inner and outer torques and mileage using factors including OEM, Build Dates of Trucks, Build Dates of Hubs,Luechow Vs Aiken and other analyses.
- May be some correlation to variation in torque and warranty claim, but weak and inconclusive. May be a function of timing between hub production date and truck build date.
- Difference in mileage and torque between OEM's but other factors could invalidate
- Little correlation between outer and inner nut torques
- Also include Knight Descriptive Statistics of torques.
- Suggest Mike and others review and continue hypothesis testing

Torques

OEM's	MeanOuter1	MeanInner	StDevOuter	StDevInner	N1
Freightliner	199.092	511.885	112.510	145.029	358
International	191.154	534.231	85.906	149.260	13
Mack	162.826	411.304	43.402	103.674	23
Volvo	224.464	537.500	54.964	135.243	84


Boxplots of Outer Nut Torque by Truck Build Date

(means are indicated by solid circles)



Boxplots of Inner Nut Torque by Truck Build Date


(means are indicated by solid circles)



Inner nut torque has higher variation than outer nut torque

Boxplots of Inner Nut Torque by Truck Build yearmonth

(means are indicated by solid circles)



Omitted dates prior to 199807

SKF 002191


Compare Truck Build Date Torque to Hub Build Date. Note some months missing

Boxplots of Proportion Warranty

Claims by Hub Build Date by

YearMonth


(means are indicated by solid circles)



Boxplots of Inner Nut Torque by

Truck Build yearmonth


(means are indicated by solid circles)



No difference in mileage by L or R

Boxplots of Mileage by L or R H


(means are indicated by solid circles)





Mack is LH and RH

SKF 002193

Torque varies between single L or R or LH or RH








Mack has lower mean inner nut torque


SKF 002-198



Aiken hubs have significantly lower mileage than Luechow, but Luechow hubs more likely installed on vehicles in service longer.

Boxplots of Mileage by SKF Site

(means are indicated by solid circles)



Mileage Comparison by OEM


One-way ANOVA: Mileage versus Truck OEM

Analysis of Variance for Mileage

Source	DF	SS	MS	F	P
Truck OEM	3	2.106E+12	7.019E+11	38.00	0.000
Error	474	8.755E+12	1.847E+10		
Total	477	1.086E+13			

Individual 95% CIs For Mean

Based on Pooled StDev



Pooled StDev = 135904 300000 400000 500000 600000

May differ due to time in service and other factors unknown

SKF 002199

Knight Only

Knight Year Month	Outer DS Mean	Inner DS Mean	Outer DS Std Dev	Inner DS Std Dev	Data points	Outer PS Mean	Inner OS Mean	StDev Outer PS	StDev Inner PS
199807	250	510 *	*	*	1	100	500 *	*	*
199809	200	575	0	106.066	2	250	640	0	56.569
199810	150	237.5	70.711	53.033	2	125	500	35.355	70.711
199902	250	550 *	*	*	1	250	550 *	*	*
199903	137.5	437.5	47.871	43.301	4	200	543.75	20.412	100.778
199904	164.29	351.43	85.217	176.109	7	335.71	542.86	301.336	255.65
199905	166.67	488.33	76.376	96.997	3	433.33	566.67	493.288	450.925
199906	250	350 *	*	*	1	200	700 *	*	*
199907	87.5	400	88.388	70.711	2	200	700	0	0
199908	266.67	455.56	286.138	215.703	9	219.44	611.11	72.648	194.9
199909 *		300 *	*	*	0	250	500 *	*	*
199910	75	300 *	*	*	1	150	400 *	*	*
199911	133.33	416.67	57.735	125.831	3	225	533.33	66.144	76.376
200003	1000	1000 *	*	*	1	1000	1000 *	*	*
200004	100	500 *	*	*	1	300	550 *	*	*
200005	100	250	0	70.711	2	100	250	70.711	212.132
200010	200	200 *	*	*	1	250	650 *	*	*
200101	150	450 *	*	*	1	250	550 *	*	*
200105	150	525 *	*	*	1	100	650 *	*	*
200106	200	550 *	*	*	1	200	650 *	*	*

Discussion

Main Topic

Class

Rahmberg/GHQ/GOT/SKF
05/13 12:24 PM

Subject: Actions and responsibilities of Competence Areas

Category: Projects

Response
to Main Document

Achim Mueller/BCH/SKF
05/16 06:29 AM

Subject: Visual Inspection of Returned Truck Hub Unit
Response to: Actions and responsibilities of Competence Areas
Category: Projects


visualInspection.doc



Purpose of the Inspection

To verify findings of earlier visual inspections performed by ADNA personal. In total 13 inboard inner rings, roller complements and seals of Truck Hub Units BTF-0032 were returned. These bearings have been identified earlier to be spalled, thus not reaching the expected service life of a million miles. It had been determined that the spalls are caused by lubricant film break down due to water ingress through the inboard seal.

Findings of Visual Inspection

Hereunder are listed the findings and conclusions of the visual inspection performed in the Schweinfurt test laboratory. To identify individual bearings, the findings are summarized under the respective claim number and mileage.

E1752364 308,528 miles

Two shallow spalls in roller distance over 3/4 of the inner ring raceway length. The seal main lip wear is 0.6 mm wide. No signs of corrosion on seal counterface. Corrosion is found in the clip ring groove.
Shallow raceway spalls are indicating surface distress. Such a damage is typically caused by either vibrations or lubricant film break down. The most common reason for lubricant film break down is the presence of water in the bearing. The presence of rust in the bearing bore and the appearance of the seal are indicating a leak path along the axle.

Ryder 3617 393,838 miles

Ring and roller raceways as well as the guiding flange are in good condition. The seal main lip wear is 3.1 mm wide. The seal counterface is partially corroded. No corrosion is found in the clip ring groove.
The bearing has not failed yet. The heavily worn seal indicates a reduced sealing function, allowing water and other contamination entering the bearing.

E1755559 438,508 miles

The guiding flange is heavily worn over about 90° of the circumference ("hot runner"). Ring and roller raceways are in good condition. The seal main lip wear is 0.6 mm wide. Corrosion is found in the clip ring groove. No evidence of water in the bearing. Preting corrosion in the bearing bore is indicating two load zones.
Seizing on guiding flange surfaces is considered to be an unusual occurrence. It may be caused by either heavy axial loading, extremely high preload (clamp load), lubricant film break down or misaligned mating parts (perpendicularity of spindle and shoulder). Due to the good overall appearance of the bearing components, lubricant film break down is an unlikely root cause for the damage. Two load zones typically show up when the bearing is disassembled and put back onto the spindle.

Ryder 33623 615,339 miles

Ring and roller raceways as well as the guiding flange are in good condition. The seal main lip wear is 1.6 mm wide. The seal counterface appears to be in good condition. The clip ring groove is not corroded. No evidence of water ingress is found. However, there are traces of over rolled particles.
The source of those particles could not be clarified. The findings on this bearing do not lead to a conclusion.

Ryder 33620 482,615 miles

One shallow spell over about 130° of the ring raceway. The areas close to the spell appear shiny. The seal main lip wear is 2.8 mm wide. The seal counterface is not corroded. Rust can be found in the clip ring groove. The ring and the seal are damaged by disassembly tools.
Shallow spalls and/or shiny, mirrorlike, raceways are indicating a lubricant film break down. Both, the shiny raceway surface and the heavily worn seal, are indicating water ingress into the bearing. There is, however, also evidence of a leak path along the spindle.

E1755522 403,280 miles

One shallow spell over about 160° of the ring raceway. In addition, the guiding flange is heavily worn over about 90°. The seal main lip wear is 2.7 mm wide, the main lip is torn away over about 90° of the circumference. Rust can be found in the clip ring groove.



BU Trucks Product Design

Visual Inspection of Returned Truck Hub Units

Shallow spalls are typical for lubrication problems. The heavy seal wear indicates contamination ingress into the bearing. There is also evidence of a leak path along the spindle.

E1752375 273,721 miles

The ring raceway is spalled over about 90° of its circumference. The roller raceways are shiny. A 2 cm long particle (chip?) is found in the guiding flange undercut. The seal main lip wear is 1.6 mm wide. The seal counterface appears in good condition, however, the trace of the dust lip shows some corrosion. Rust is found in the clip ring groove. Shiny raceways are evidence of lubricant film break down. Both corrosion traces, on the seal counterface and the bearing bore, indicating potential leak paths.

E1750339 689,347 miles

The ring raceway is spalled over about 90° of its circumference. The seal main lip wear is 3.8 mm wide. The seal counterface is heavily corroded. Rust is present in the clip ring groove. The roller raceways are shiny. The seal main lip exhibits several voids, up to five mm long, on the bearing side. The spall appears to be caused by lubricant film break down due to water entering the bearing. The voids in the seal lip may be explained by roller skewing as a consequence of the spall.

CWA06549 385,007 miles

The ring raceway is spalled, while the roller raceways are shiny. The seal main lip wear is 1.3 mm wide. The seal counterface is in good condition. Rust can be found in the clip ring groove. Shallow spalls and shiny raceways are indicating a lubricant film breakdown due to water ingress. A leak path along the spindle appears to be possible.

CWA07833 mileage ?

Ring and roller raceways are in good condition. The guiding flange is seized. The seal main lip wear is 3.0 mm wide. The seal counterface appears to be in good condition. The seal spring is missing. Only little rust can be seen in the bearing bore. The reason for this damage is not determined. The seal is heavily worn. However, since the mileage of the bearing is not known, a conclusion about the seal performance is hardly possible.

E1744715 268,745 miles

The appearance of the raceways and the guiding flange is good. Traces of over rolled particles are to be seen. The seal main lip wear is 0.9 mm wide. The seal counterface is in good condition. Rust can be found in the clip ring groove. The dust lip of the seal has a five mm long cut.

The source of those particles could not be clarified. The findings on this bearing do not lead to a conclusion.

E1752410 192,639 miles

The raceways are shiny, while the guiding flange is seized. The seal main lip wear is 3.5 mm wide. The seal counterface is heavily corroded. The bearing bore is also heavily corroded. Multiple dark lines on the ring raceway in roller distance are indicating contact corrosion between rollers and ring raceway.

The overall appearance of the bearing components leads to the conclusion that the bearing was submerged in water. Free water was present in the bearing, causing a lubricant film break down. Since multiple lines of contact corrosion can be seen, it can be assumed that the bearing was operating for a while after the submersion happened.

E1727708 1,161,585 km

The ring raceway is polished. Reaction layers on the roller raceways are indicating elevated operation temperatures. The seal main lip wear is 3.6 mm wide. The seal counterface is corroded.

The appearance of the bearing is typical for a lubricant film break down. The heavy seal wear supports the assumption that water passed the seal lip.



Summary

A total of 13 returned bearing cones and seals have been inspected. All of these bearings had been classified by ADNA as being damaged after inboard seal leakages.

The findings reported above do not fully support this earlier assessment.

It may be confirmed that the vast majority of the bearing damages are due to lubricant film break down caused by water intrusion into the bearing. It is, however, not verified in all cases that water entered the bearings through the seal. There is also a potential leak path along the spindle.

This conclusion is supported by the presence of rust in the inner ring's clip ring groove and the good overall appearance of the seal lips and their counterfaces in about half of the inspected bearings.

A total of five bearings out of 13 are concluded not to have seal leaks. One bearing damage is not conclusive since the service mileage is not known. The remaining seven bearings show evidence of seal leakage. It has to be pointed out, that in almost all cases, water was present in the bearing bore. Therefore it is not to be determined whether some of these seven cases may also be linked to water intrusion along the spindle.

Response
to Main Document

Achim Mueller@SCHUBKF
06/18 06:31 AM

Subject: Truck Hub Unit Assembly Test
Response to: Actions and responsibilities of Competence Areas
Category: Projects



THUassy.doc

SKF 002206

Purpose

Purpose of this investigation was to prove that clamping a Truck Hub Unit (THU) without rotating the outer ring may lead to damages on ring or roller raceways.

Test Description

A THU (BTF-0032) was disassembled and cleaned. The condition of the raceways was documented (see picture 1). After that, the unit was lubricated with a total of 61 gr. of GWZ grease.




Picture 1: Condition of inboard outer ring raceway before Assembly Test

The unit was put on a horizontally installed test spindle. The inner lock nut was torqued until a clamp load of approximately 90 kN was reached. Before respectively during clamping of the unit, it was taken care that the outer ring of the bearing was not rotated. As a second step, the outer lock nut was installed with a torque of 300 ftlb. After that, the bearing was disassembled, cleaned and inspected for damages.


Test Results

Upon disassembly of the unit, several indentations were found on the inboard outer ring raceway (picture 2).



Picture 2: Typical indentation on outer ring raceway after test


The extension of the indentation in picture 2 was determined to be 0.35 mm in circumferential direction and approximately 7.2 μm from peak to valley (picture 3).



Picture 3: Raceway surface and indentation

Conclusion

This test proves that non rotation of the THU outer ring during clamping can cause considerable damage of the bearing. This kind of damage is considered to be detrimental to the bearing performance.



Response
to Main Document

Achim Mueller/SCH/SKF
05/17 02:16 AM

Subject: X-Ray Diffraction Analysis Interim Result 1
Response to: Actions and responsibilities of Competence Areas
Category: Projects

To all,

Attached file depicts the comparison between a returned THU BTF-0052 (service life appr. 500 kmiles) and an unrun one. It is obvious that the b/B value is still close to 1, i.e. there is very little life consumed. The threshold value of b/B indicating fatigue is 0.85. It is still too early for a remaining life prediction, but it can be estimated, that this bearing could still have run for one million miles under the same operation conditions.

Best regards

Achim Mueller



XRDInterim1.xls

SKF 002209


THU #918279 LR. In HLZ

Depth (μm)	R.S. (MPa)	L.B. (deg. 2-th.)	MB	R.A. (vol.%)
0	-415	6.85	0.98	15
10	110	6.90	0.97	
25	80	6.95	0.97	21
50	100	7.05	0.98	
75	30	6.85	0.97	
100	-60	6.85	0.98	20
125	5	6.90	0.97	
150	10	6.80	0.95	
175	20	6.75	0.94	19
Core		7.15		

THU #.... LR. <unrun>

Depth (μm)	R.S. (MPa)	L.B. (deg. 2-th.)	R.A. (vol.%)
0	-835	7.00	9
10	95	7.00	
25	45	7.15	
100			
150			
175			

THU Innerring <inboard> unit 918279 withdrawn from service.
Residual stress and Line-broadening versus Depth



Response
to Main Document

Achim Mueller/SCH/SKF
05/24 04:16 AM

Subject: Steer Axle Action Items Update I, 24.05.2002
Response to: Actions and responsibilities of Competence Areas
Category: Projects



amprogrep1.doc

SKF 002211

PROJECT - PROPOSAL

Title: Investigations of ARM – THUs (field incidents)

Project-Manager: Achim Müller

Objectives:

- ➔ To make detailed visual and material inspections, inclusive THU application interfaces, to identify the root cause of the ARM Truck "wheel off" incidences on THUs which were used on trucks in North America.
- ➔ To draw conclusions, considering all our investigation results, which actions have to be taken in order to help solving the "wheel off" problems, by improving the ARM – THU or wheel end design if necessary.

Background:

Facts (acc. Minutes PLB THU, Arvin Meritor, e-mail Claes Rehmberg 050402)

- ➔ 400.000 bearings in the market
- ➔ 120.000 of those produced in Luechow
- ➔ 280.000 produced in Aiken whereof 61.000 with R-Safe seals
- ➔ Freudenberg seals were used up to April 2000
- ➔ R-Safe seals were used from April 2000 in Aiken produced bearings
- ➔ 117 bearing have been claimed by AM as "severely advanced" parts out of which 18 wheel-offs from start of the year all with Freudenberg seals
- ➔ Average service life of claimed units approx. 350 km/miles
- ➔ SKF notified around week 12 by ARM after the 15 first wheel-offs occurred

In order to get a clear and complete picture of the "wheel off" incident mode, a detailed ARM THU investigation will be done by the specific competence areas within SKF.

This project will be split into working packages linked to the investigating competences.

Actions and responsibilities of competence areas.

Working Package I Seal

Responsible: A. Müller

- ➔ Spec's on Freudenberg seal (material compound, design)
CFW compound 75FKM595 released for use in garter seals by ERC (NL89C802, A.v.d.Berg). Design (SG-BTFB 446329 E) released for RVI THU in 1989. Virtually no further documentation available.
- ➔ Spec's on R-Safe Seals (material compound, design)
CR compound SIRVENE490 released for use in R-Safe seals by ERC (NL92C815, A.v.d.Berg). Design principle tested and reported by IPD TRB (ST94T201, L.Winston) and CRA (CIC1231-102, G.Poll). Other standard tests comparing CFW and CR seal at CRA were

supporting decision. Since then, the basic VOLVO mud/slurry test has been adapted and is used as acceptance criterium.

- Approval process of both these two seals (who signed)

The approval process for the CFW seal is not documented. Approval of the CR seal was given based on comparative tests (see above), using the VOLVO seal test specification. The decision for the CFW seal to be used in the ARM front axle THU was taken, based on the field experience with the RVI unit (MEST dated 93-04-07, U. Brockmueller).

- Visit to Freudenberg to clarify design, material compound, production process
No documentation about the seal development available at CFW.
- Water splash test on defective R-Safe seals to confirm failure mode
ongoing at RFT
- Wear test on CFW seals
ongoing at CRA
- Water splash test on CFW with different grease fills
Test confirms that reduced grease fill reduces the time until water passes the main seal lip.
- Cure state analysis
SKF not equipped for analysis. CRA in charge.

Working Package II Total inspection THU

ERC activities

1 THU new

3 THU returned long mileage

Coordinator: A. Kerrigan

- Visual inspection G. de Wit

Visual inspection on long mileage bearings without unusual findings.

Inspection of additional 34 units will start in Schweinfurt on May 27.

- Investigation composition, microstructure, forging fibre flow conformance, surface quality, if necessary SEM investigation C. Viellard

Inner rings over hardened, hardness in tolerance but retained austenite content above specification.

- X-ray investigation of run and unrun (reference) THU to identify rolling contact fatigue damage accumulated in the microstructure H. Verschuur

First result on bearing 918279 (mileage 570.000 miles) shows virtually no decay of retained austenite. It is estimated that this bearing could have run for another million miles.

Schweinfurt lab activities

3 THU returned long mileage

- visual inspection (SEM if necessary) and X-ray investigation W. Nierlich

Activity ongoing

Working Package III General Application Features

Responsible: Achim Müller (M. Lewis)

- Ideas for truck drivers warning system A. Müller / M. Lewis
Definition of preferred warning system missing.
- Tensile fracture wheel bolt test
Failure mode not duplicated even at nut torques exceeding 1200 ft-lbs.
- Wheel bolt replacement
Damages on ring and roller raceways visible, measurement to be done.
- Inspection of returned seals (CFW)
Ongoing, see above activity "Visual inspection"
- Inspection returned CR seal bearings
Ongoing, see above activity "Visual inspection"
- Mounting test with and without run down (support: FEM calculation G.-J. Dop)
Test done, results reported
- Summary of release/homologation documentation
Documentation in SW already about 15 binders. Summary will take about 5 manweeks. We do not know if the documents are complete.

Working Package IV Customer Related Application Features

Responsible: M. Lewis

- Documentation of approval process B. Weeks
- Comparison European users F. Caron
Fleets contacted, search for long mileage vehicle ongoing.

Mike please define your actions for the following areas

e.g.

- Identification of vehicle set up (chassis,...) in relation to returns, claims, incidents
- Update of customer and SKF warranty/claim data base
- Application Engineering contacts to customer

Working Package V Quality

Responsible: J. Schultheis

Please define your action

e.g.

- Collect available PPAP documentation of units, seals and bolts
- Collect quality data of individual production runs from ARM 10/1998; 6,7,8/1999 in service dates

Working Package VI conclusions and identification of further actions concerning improvement of THU if necessary

Responsible: all involved participants

Project Team:

Leader:	A. Mueller
Application Engineering:	M. Lewis
Investigations:	A. Kerrigan
	W. Nierlich
Quality:	J. Schultheis

Other issues

Studs

- Issue report of failure analysis (NATC)
- Issue report of testing (tensile, impact,...) by Ingersoll
- Identification of root cause
- Identify affected quantity of bolts
- Disposition of parts in the field with supporting documentation

Business Gate:

B. Stephan, W. Farrell, A. Stubenrauch

Distribution:

Working package responsibles; PLB members

Response
to Main Document

Achim Mueller@CH/SKF
05/28 09:49 AM

Subject: Statement to Recommended Inspection Interval
Response to: Actions and responsibilities of Competence Areas
Category: Projects

The attached document contains a draft of an SKF statement about the 50,000 miles inspection intervals between "Basic Inspections" as proposed by ARM. Comments are very much appreciated.

Achim Mueller



Inspocom.doc

SKF 002216

**DRAFT**

Before publishing this statement, more data from field tests must be available and evaluated.

Background

ArvinMeritor is recommending in their Technical Bulletin TP-0251 (revision 05-02) to run "Basic Inspections" in intervals of not more than 50,000 miles after the first "Detailed Inspection" which is due after an operational time of 200,000 miles.

SKF is requested to take a stand on the length of the intervals between the "Basic Inspections".

Field and Rig Testing

Several field and rig tests are run by ArvinMeritor and SKF, with the target to support the recommended inspection interval to be a safe interval for the possible detection of progressive bearing damages.

1. SKF Test Truck (operated by Southwest)

A test truck is equipped with predamaged unitized wheel end bearings (THU). The bearing temperatures and vibration levels are monitored. The truck is operating under linehaul conditions. The test started on May 21, a mileage of approximately 1000 miles per day is accumulated.

"Basic Inspections" are performed every second day.

2. ArvinMeritor Test Truck

ARM is running a test vehicle on the Bosch proving ground under operating conditions, which are come close to linehaul conditions. The test started beginning of May, it is reported, that a mileage of more 25,000 miles has been accumulated. Unfortunately, not more details are known at SKF Schweinfurt.

3. Rig Test at SKF Schweinfurt

A THU has been predamaged due to non rotation during assembly (see report A. Mueller in database). This bearing was then put on a THU test rig and run under "Raceway Qualification Test" conditions.

These test conditions are chosen such, that heavy but realistic corner loads, which may occur under normal operation, are simulated. The dominant loading condition (85% of the test time) simulates + 0.25 g cornering load. Read recordings ("Service Condition Recordings...", NL93T035, G.-J. Scheer) are proposing that this condition occurs with a percentage of less than 0.3% under linehaul service. It is assumed that during city delivery, a similar cornering condition is present for less than 2% of the total service life of a vehicle.

Based on this information it is a safe assumption that every hour of test time, the test rig operates at 500 rpm, simulates approximately 2630 miles of operation under city delivery condition, while it represents more than 8000 miles under linehaul conditions.

The reported bearing was operating for 395 hours when a vibration level, which was twice as high as the base level of the already damaged bearing was measured. These 395 hours would be already equivalent to approximately 1,000,000 miles of city delivery condition. Upon inspection small damages on the inboard outer ring raceways were detected (see picture 1).



Picture 1: circumferential operation traces and scratches on run, predamaged THU outer ring raceway

During a Design Verification Test, these scratches would have been evaluated as bearing damage, and the test would have been terminated.

Since the target of this test was to demonstrate the feasibility of a 50,000 miles inspection interval, it has been decided to continue the test instead of investigating the observed damage in detail.

Upon restarting of the test, the bearing was overloaded by mistake. The overload was such that an axial load equivalent to approximately 1 g was acting on the THU. The bearing was immediately heavily damaged on the raceways and inner ring guiding flanges (see picture 2). Nevertheless the test was continued with this, now excessively, damaged bearing.



Picture 2: THU cone after overload

The bearing had been operating since for 32.5 hours under the earlier described test condition. The test time would translate into approximately 86,300 miles of field operation under city delivery conditions.

Conclusion

SKF BU Trucks Product Engineering supports the proposed 50,000 miles intervals between "Basic Inspections" for all unitized front wheel end bearings.

SKF BU Trucks Product Engineering considers the proposed intervals as being insufficient to detect progressive bearing damages prior to uncontrolled failure of such a wheel end bearing.

Response

to Main Document

Achim Mueller/SCH/SKF
05/26 10:36 AM

Subject: Potential Root Causes for Bearing Damages
Response to: Actions and responsibilities of Competence Areas
Category: Projects


Attached document contains a "Fishbone" Diagram prepared by A. Stubenhrauch depicting potential root causes for bearing damages



Root Causes.ppt

SKF 002219

Potential Root Causes for THU-damages



Response
to Main Document

Arno Stubenrauch/SCH/SKF
05/29 09:54 AM

Subject: Conclusions and Recommended Actions
Response to: Actions and responsibilities of Competence Areas
Category: Projects

Attached is a draft for discussion purposes



Recommended actions.pdf

SKF 002221

Recommended Actions

- Reduced inspection intervals 50.000 miles
- To follow consequently the ABS-Signal concerning THU
- To check the function of the static seal
- To retrofit the static seal
- To retrofit the heat indicator, preferable Wabash-Bolt
- To discuss improvements with ARM about the other causes for bearing damages

Dominating Root Cause for early bearing failures

Observation/Detection: too much water inside the bearing unit

There are different paths for water ingress:

- Trough the thread of the HUB-Cap (happened)
- Creeping along the OD of CRW (not detected)
- Passing the seal lip, after excessive wear and lost seal function (happened)
- Creeping along the spindle and passing the contact area of the IR side faces (this phenomenon is supported by micromovements) (happened)

Consequences due to water ingress:

- A certain amount of water will be absorbed by the grease
- Grease is loosing viscosity and lubrication capability
- Lubrication film will break through and rolling contact surface will suffer from surface distress (shallow spalling)
- After spalling the internal clearance will increase

- High stress in rolling contact
 - Pitting starting
 - Spalling develops
 - Noise and vibration develops
 - Extreme clearance
 - Damage seal perhaps push out
 - Water dust ingress
 - Acceleration of wear
 - Roller scew
 - Heating up
-
- Grease out
 - Metal to metal
 - Seizure/Blocking
 - Roller ejection
 - Raceway riding
 - Drum touches brake shoes
 - Wear off of central nut
 - Ignition possible
 - Wheel off

Overall Conclusions

- Bearing suitable, when correctly manufactured and installed
- Main problem: water ingress/water creep
- Manufacturing problems:
 - Aiken, CFW missing grease
 - CR - R-Safe moulding defects
- Other causes for bearing damages:
 - Assembly
 - Transport
 - Studs replacement
 - Disassembly

Response
to Main Document

Achim Mueller/SCH/SKF
05/30 01:40 AM

Subject: Seal Wear Comparison between Luschow and Alken Parts
Response to: Actions and responsibilities of Competence Areas
Category: Projects



sealwear.doc

**Background**

The purpose of this investigation was to determine, if there is a difference wear pattern on Freudenberg seals, depending on the assembly plant of the Truck Hub Unit.

Findings

Seven seals were inspected (Note: a out of a total of 18 inspected THUs, only seven seals were available) and the wear of the main lip was measured. Five of these seven seals were assembled in Aiken, the remaining two in Luechow. The wear width of the seals assembled in Aiken was in a range of 0.5 to 1.5 mm, while the measured values were 0.9 and 1.2 mm respectively for the seals assembled in Luechow (see table).

Manufacturing Location	Claim No.	Seal Wear	Mileage
Aiken	2821334 ?	1.5 mm	?
Aiken	918290	0.9 mm	559,290
Luechow	918289	0.9 mm	569,477
Luechow	918289	1.2 mm	569,477
Aiken	348970	0.8 mm	571,884
Aiken	918276	1.0 mm	610,074
Aiken	918274	0.5 mm	444,064

Conclusion

These results do not show a significant difference of seal wear between Aiken and Luechow assembled parts.

Response
to Main Document

Achim Mueller@CHI@KF
06/30 01:43 AM

Subject: Interim Result of XRD Investigation
Response to: Actions and responsibilities of Competence Areas
Category: Projects

Measurements done in the Schweinfurt laboratory confirm so far the earlier reported results from ERC. Band width reduction values b/B of 0.9, 0.82 and 0.96 have been reported, indicating that no major material responses occurred on these (Ryder) parts.

Final report is anticipated to be distributed by June 14.

Response
to Main Document

Achim Mueller/SCH/SKF
05/30 03:17 AM

Subject: Revised Statement on Recommended Inspection Interval
Response to: Actions and responsibilities of Competence Areas
Category: Projects



revlineprecom.doc

SKF 002229

Background

ArvinMeritor is recommending in their Technical Bulletin TP-0251 (revision 05-02) to run "Basic Inspections" in intervals of not more than 50,000 miles after the first "Detailed Inspection" which is due after an operational time of 200,000 miles.

SKF is requested to take a stand on the length of the intervals between the "Basic Inspections".

Field and Rig Testing

Several field and rig tests are run by ArvinMeritor and SKF, with the target to support the recommended inspection interval to be a safe interval for the possible detection of progressive bearing damages.

1. SKF Test Track (operated by Southwest)

A test truck is equipped with predamaged utilized wheel end bearings (THU). The bearing temperatures and vibration levels are monitored. The truck is operating under linehaul conditions. The test started on May 21, a mileage of approximately 1000 miles per day is accumulated.

"Basic Inspections" are performed every second day.

2. ArvinMeritor Test Truck

ARM is running a test vehicle on the Bosch proving ground under operating conditions, which are come close to linehaul conditions. The test started beginning of May, it is reported, that a mileage of more 25,000 miles has been accumulated. Unfortunately, not more details are known at SKF Schweinfurt.

3. Rig Test at SKF Schweinfurt

A THU has been predamaged due to non rotation during assembly (see report A. Mueller in database). This bearing was then put on a THU test rig and run under "Raceway Qualification Test" conditions.

These test conditions are chosen such, that heavy but realistic corner loads, which may occur under normal operation, are simulated. The dominant loading condition (85% of the test time) simulates +0.25 g cornering load. Road recordings ("Service Condition Recordings...", NL93T035, G.-J. Scheers) are proposing that this condition occurs with a percentage of less than 0.3% under linehaul service. It is assumed that during city delivery, a similar cornering condition is present for less than 2% of the total service life of a vehicle.

Based on this information it is a safe assumption that every hour of test time, the test rig operates at 500 rpm, simulates approximately 2650 miles of operation under city delivery condition, while it represents more than 8000 miles under linehaul conditions.

The reported bearing was operating for 395 hours when a vibration level, which was twice as high as the base level of the already damaged bearing was measured. These 395 hours would be already equivalent to approximately 1,000,000 miles of city delivery condition. Upon inspection small damages on the inboard outer ring raceways were detected (see picture 1).



Picture 1: circumferential operation traces and scratches on run, predamaged THU outer ring raceway



Picture 1a: operation traces on undamaged THU outer ring raceway

During a Design Verification Test, these scratches would have been evaluated as bearing damage, and the test would have been terminated.

Since the target of this test was to demonstrate the feasibility of a 50,000 miles inspection interval, it has been decided to continue the test instead of investigating the observed damage in detail.

Upon restarting of the test, the bearing was overloaded by mistake. The overload was such that a axial load equivalent to approximately 1 g was acting on the THU. The bearing was immediately heavily damaged on the raceways and inner ring guiding flanges (see picture 2). Nevertheless the test was continued with this, now excessively, damaged bearing.



Picture 2: THU case after overload

The bearing is operating since then for about 30 hours under the earlier described test condition. The test time would translate into approximately 80,000 miles of field operation under city delivery conditions.

Conclusion

SKF BU Trucks Product Engineering supports the proposed 50,000 miles intervals between "Basic Inspections" for all unitized front wheel end bearings.

SKF BU Trucks Product Engineering considers the proposed intervals as being sufficient to detect progressive bearing damages prior to uncontrolled failure of such a wheel end bearing.

Response
to Main Document

Achim Mueller/BCHSKF
08/08 02:15 AM

Subject: Air Leak Test on ARM Knuckle
Response to: Actions and responsibilities of Competence Areas
Category: Projects

We have done an "Air Leak Test" on one of the ARM Knuckles we have in our test lab.

A new THU BTF-0085 has been assembled onto the spindle and clamped with a torque of 800 Nm (590 ft-lbs). An air coupling was installed into a hub cap, and the cap assembled onto the unit. Pressurized air (1 bar) was then blown into the hub cap cavity. After the application of a leak detection spray onto the unit's inboard side, bubbles indicated a leak along the spindle.

Note that this test was a static test only. This is proving the presence of water leak paths along ARM's spindle.



airleaktest.jpg



airleakbubbles.jpg



SKF 002233



SKF 002234

Response

to Main Document

Achim.Mueller@SCHUSKF
06/06 02:35 AM

Subject: MAN 1,000,000 km Axle
Response to: Actions and responsibilities of Competence Areas
Category: Projects

A non driven front steer axle of MAN was received after operating for about 1,000,000 km (625,000 miles). The spindle shows dry fretting corrosion on its bottom side while the "side" faces and the transition radii are as new. This proves that no water entered the wheel end system between the knuckle and the Inboard inner ring side face.



[manetubtransition.jpg](#) [manetub2bottomview.jpg](#) [manetubside.jpg](#) [manetub1bottomview.jpg](#) [maninnerring.JPG](#)

SKF 002235




SKF 002236




SKF 002237



SKF 002238



SKF 002238



SKF 002240

Response
to Main Document

Achim Mueller/SCH/SKF
06/06 04:18 AM

Subject: Truck Hub Unit Assembly Test; Revised Report
Response to: Actions and responsibilities of Competence Areas
Category: Projects

Attached is a revised report about THU assembly tests performed in the Schweinfurt test lab.


assemblytest.doc

SKF 002241

Purpose

Purpose of this investigation was to prove that clamping a Truck Hub Unit (THU) without rotating the outer ring may lead to damages on ring or roller raceways.

Test Description

A THU (BTF-0032) was disassembled and cleaned. The condition of the raceways was documented (see picture 1). After that, the unit was lubricated with a total of 61 gr. of QWZ grease.



Picture 1: Condition of inboard outer ring raceway before Assembly Test

The unit was put on a horizontally installed test spindle. The inner lock nut was torqued until a clamp load of approximately 90 kN was reached. Before respectively during clamping of the unit, it was taken care that the outer ring of the bearing was not rotated. As a second step, the outer lock nut was installed with a torque of 300 Nm. After that, the bearing was disassembled, cleaned and inspected for damages.

This test was repeated with three different units.


Test Results

Upon disassembly of the unit, several indentations were found on the outer ring raceways. A typical appearance form is depicted in picture 2.



Picture 2: Typical indentation on outer ring raceway after test

The extension of the indentation in picture 2 was determined to be 0.35 mm in circumferential direction and approximately 7.2 μm from peak to valley (picture 3).



Picture 3: Raceway surface and indentation

Conclusion

This test proves that non rotation of the THU outer ring during clamping can cause considerable damage of the bearing. This kind of damage is considered to be detrimental to the bearing performance.

Response
to Main Document

Achim Mueller/BCH/SKF
06/08 06:01 AM

Subject: Raceway Qualification Test with Predamaged Truck Hub Unit

Response to: Actions and responsibilities of Competence Areas

Category: Projects



damagerqt.doc

Test Description

A THU has been predamaged due to non rotation during assembly (see report A. Mueller in database). This bearing was then put on a THU test rig and run under "Raceway Qualification Test" conditions.

These test conditions are chosen such, that heavy but realistic corner loads, which may occur under normal operation, are simulated. The dominant loading condition (85% of the test time) simulates + 0.25 g cornering load. Road recordings ("Service Condition Recordings...", NL93T035, G.-J. Scheers) are proposing that this condition occurs with a percentage of less than 0.3% under linehaul service. It is assumed that during city delivery, a similar cornering condition is present for less than 2% of the total service life of a vehicle.

Based on this information it is a safe assumption that every hour of test time, the test rig operates at 500 rpm, simulates approximately 2650 miles of operation under city delivery condition, while it represents more than 8000 miles under linehaul conditions.

Test Results

The reported bearing was operating for 395 hours when a vibration level, which was twice as high as the base level of the already damaged bearing was measured. These 395 hours would be already equivalent to approximately 1.000.000 miles of city delivery condition. Upon inspection small damages on the inboard outer ring raceways were detected (see picture 1).



Picture 1: circumferential operation traces and scratches on two, predamaged THU outer ring raceway

During a Design Verification Test, these scratches would have been evaluated as bearing damage, and the test would have been terminated.

Since the target of this test was to demonstrate the feasibility of a 50,000 miles inspection interval, it has been decided to continue the test instead of investigating the observed damage in detail.

Upon restarting of the test, the bearing was overloaded by mistake. The overload was such that a axial load equivalent to approximately 1 g was acting on the THU. The bearing was immediately heavily damaged on the raceways and inner ring guiding flanges (see picture 2). Nevertheless the test was continued with this, now excessively, damaged bearing.



Picture 2: THU cone after overload



The bearing is operating since then for 32.5 hours under the earlier described test condition. The test time would translate into approximately 86,000 miles of field operation under city delivery conditions.

During the test, inboard and outboard inner ring temperatures were recorded (see table 1). After test termination, the axial endplay of the Truck Hub Unit was determined to be 0.315 mm.

Test time [h]	Inboard inner ring temp. [°C]	Outboard inner ring temp. [°C]
6	130	not recorded
11.6	150	130
18.7	165	133
25	180	140
28.4	180	140
32.5	190	150

Table 1: Inner ring temperatures

Conclusion

From the above result it is concluded, that a damage caused by a wrong assembly method (i.e. no rotation during clamping) will not immediately affect the bearing performance. It is, however, to be expected that such damage will reduce the potential service life of a Truck Hub Unit.

The heavy bearing damage caused by mistake would have been noticed during a "Basic Inspection" of the wheel end. The wheel would have been considered as rotating rough and noisy. Continuing the test for another 32.5 hours (equivalent to 86,000 miles under city delivery condition) shows that the chosen 50,000 miles interval between two "Basic Inspections" is sufficient to detect bearing damages prior to a safety critical condition of the wheel end.

Response
to Main Document

Achim Mueller@CH/ SKF
06/08 07:38 AM

Subject: Comparison of Spindle Tolerances
Response to: Actions and responsibilities of Competence Areas
Category: Projects



Spindle Tolerance Comparison 06 Jun 200

Response
to Main Document


Achim Mueller/SCH/SKF
06/10 08:47 AM

Subject: European Wheel End Design
Response to: Actions and responsibilities of Competence Areas
Category: Projects

Just for comparison a picture of an European wheel end.



Man_f-1.jpg



SKF 002260

Discussion

Main Topic

Class

Rehmberg/HHQ/GOT/SKF
05/13 12:18 PM

Subject: Product Liability Minutes
Category: PLB

Minutes PLBs



PLB THU2 - Arvin Meritor 200204.c



PLB2 THU2 - Arvin Meritor 20020408.i



PLB3 THU2 - Arvin Meritor 20020412.i



PLB4 April 16.doc



PLB5 April 19.doc



PLB6 April 26.doc



PLB7 May 2.doc



PLB8 May 8.doc



PLB9 May 13.doc

Product Liability meeting April 8 2002
THU2 issue - Arvin Meritor

Participants:

Tom Johnstone chm.
Bernd Stephan
Bill Farrell
Juergen Schultheis
Achim Mueller
Claus Schultz
Rick Frett
Arno Stubenrauch
Michael Lewis
Claes Rehmberg secr.

1. ARM meeting Friday 5th

R-Safe seals reworked during last weekend.

ARM usage 200 pcs/day

Aiken is defining a process flow / approval and signoff for the reworked products. (Chris Jones)

2. Warranty Report as reported by ML:

Steer THU Warranty Return

B. Weeks 18 Mar 2002

530 Total Claims in SKF Database (as of 12/31/2001)

<u>Corrective Actions Taken by SKF</u>	<u>Percent of Claims</u>
Switch to GW-Z Grease	10.4
Grease Egress	
Switch to R-Safe Inboard Seal	
IB Seal Leak - Contaminant Ingress	15.6
Induction Hardening Equipment & Procedural Changes	
OR not hardened	3.8
<u>Corrective Actions taken by ArvinMeritor</u>	
Increased Hubcap Torque	
Bearing Failure - Run w/o Hub Cap	2.6
Switch to MolyKote D Anti-fretting Compound/O-Ring Seal	
Removal Damage	5.7
Water Intrusion Along Spindle	1.9
Rotation of Hub Unit during Torque	
Low Clamp Load	6.8
Field Bulletin on Inspection Techniques	
No problem found	27.6

Total percent Claims Addressed by Corrective Actions 89.5

<u>Claim Categories Not Directly Addressed</u>	<u>Percent of Claims</u>
Root Cause Not Determined	Total 14.0
Returns too advanced to determine cause	
Customer Abuse	Total 7.5
Impact Damage	7.5
	Total Percent claims above 81.0

By the above report it shows Sealing is the single largest reason, but there exist also other reasons for warranty issues.

- o Question: Did we specify to ARM they need to rotate bearing at mounting. The answer was yes, however sometimes they have not done so.

Investigate by calculation the potential implications if bearing not rotated. (AS)
Results to be discussed with ARM. (ML)

3. Bearings from field tested

100 units were collected for testing from the field having been used since 1997.

1/3 Had no seal wear

1/3 had moderate seal wear

1/3 had heavy seal wear (contamination between seal lips)

Basically the same wear pattern have been found on units running on trucks in Europe.

4. R-safe seal claims

The R-Safe seal was designed to have a better performance - especially due to better resistance from contamination.

R-Safe seal better performance than Freudenberg (hereafter called FB) seal

Conclusion: The failed 6 R-Safe seals returned shows following

15 returned for claims. 6 not justified. 7 justified, whereof 6 due to seal leakage.

Seal leakage due to not correct molding.

5. Detection methods

Two priorities:

Stop Wheel-offs and design and implement a reliable detector.

It was concluded that the majority, but not all, of trucks have ABS/warning lamp in cab. Since March 1st 1997 there is a law in US of 100% ABS/warning lamp must exist.

ABS signal are also warning for other errors/events.

Conclusion:

ABS is not a 100% reliable detection method. We therefore need an additional detection method.

It was decided to have a team working on creating several detection methods. (BS/AS). A time plan to be defined within 2 days; including development, testing on rigs in Detroit and approval from ARM (D. Bell). Possible solutions could include heat sensitive device, smoke creation, and marking colour the wheel (dye).

A complete solution could then include ABS instruction, smoke and dye. Information on detection solution to NHTSA to be done a.s.a.p.

6. Service life expectations

Questions:

Is FB good enough for 1 Mmiles ?

What is the calculated L10 life of the whole unit (AS)

Service test / mud & slurry test done ?

Answer was that RVI test was made in the 80-ties (mud and slurry)

R-Safe seal lasted all 13 weeks, FB failed after 2 weeks.

Based on the knowledge above what to do with the 340.000 units ?

- Changed when failing

or

- Change before failing

and

- will the R-Safe seals last for 1 Mmiles ?

(Volvo TMU spec says 650.000 Miles on a 13 week std Volvo mud & slurry)

It was concluded that L10 can only be calculated on the bearing but not on the seal. Only solution is to get high mileage units from the field for investigation. We need to renegotiate warranty terms.

7. Information to ARM

We need to answer to ARM following two questions:

(out of the required 30 days for answering we have approx 2 weeks left)

1. What do we do with the current FB seals in the field

2. Warranty terms for R-Safe seals

In other words are we happy with replacing FB with R-Safe ?

In the phone conf between ARM and Tom the following was discussed:

High failure rates in the field

High peaks of failures last 18 months

ARM want to have a vision from SKF on what to do

It was concluded that the original choice of using FB seal in the units was a mutual decision between ARM and SKF, based on the good record of field performance. These documents should be captured. (BS)

Also documentation on test. Did we show this to ARM. Capture these documents as well. (BS)

8. Actions on R-Safe seals

Get parts from the field covering the different 15 lots for investigating the occurrence of moulding defects. (ML)

How many per lot do we need. JS/CR/ML to verify the amounts.
This data is needed in 2.3 days.
Concentrate on the main moulding defects

10. Other actions

We also need to decide what to inform to Freightliner.
We need to get hold of all failed units from the field. BF will come back on how
this could be done. (BF)

Moulding in Elgin (compression) Tools mfg will take 20 weeks.
Moulding in Opladen (injection) Tools mfg might take approx 4 weeks.
Bernd and Bill to work out a solution on the mfg of the seals. Tom wants
decision/plan urgently. (BS / BF)

Next PLB meeting will be on Friday April 12 at 16:00 European time.

Secretary: Claes Rehmberg
Virtified: Tom Johnstone

Product Liability meeting no.5 April 19 2002

THU2 issue - Arvin Meritor

Participants:

Tom Johnstone chm.

Bernd Stephan

Robert Bondy

Achim Mueller

Rick Frett

Michael Lewis

Claes Rehmborg secr.

Bill Farrell

Aurelio Nervo

Info:

Juergen Schultheis

Claus Schultz

Arno Stubbenrauch

1. Current status with ARM

- Deliveries OK
- EDI deliveries started April 19.

2 Rotating / not rotating the bearing

- test made in Schweinfurt lab.
 - heavy marks shown on raceway (p.Lv. 7 micron)
 - ARM notified of outcome - but no comments from them
- life test to be started on test rig - look for early spelling AM
- one good unit to be tested for reference
this test will take approx 1,5 weeks
- Other units (20 pcs) received for testing AM
 - non rotating test
 - stud removal test
- depending the outcome of the life test we shall plan how to bring this forward to ARM BB

3 Stud issue

- no broken studs given to Ingersoll. Get these from ARM ! ML / BB
- Freightliner says over torqueing is the major problem
- Investigate how studs are dismounted and mounted ML

5 Detection method(s) development status

- ARM want to have a more clear signal to driver e.g. sound alarm and stains on the wheel
- we need to have a clear common position regarding detection/alarm from ARM, ML

- temperature threshold to be confirmed. ML confirm again
- tests of the chemical composition for the smoke generator to be finalized. A

6 R-Safe seal

- extra inspection (3'50 Tmiles) to be done through checking end play and rough rotation on bearing. We need to specify the inspection method and training package ML
 - test report from RFT to be send to PLB members AN
 - we should ask to get the 22 not failing units back (only seal). these to be send to Elgin for investigation. ML
 - the May 01 to Oct 01 units to be requested back ML/BB
 - Juergen S, Hans K, and Dave Young visit Bethlehem for investigating quality, scrap etc relating to the molding defects on some of the shipped lots
- Report next PLB JS

7 Misc.

- Information to SKF insurance company done CR²
- they will be cont. updated CR

Question:

Anything we need to do additional to what is currently ongoing for the human safety ?

- PLB unanimously agreed that we are doing the right things.
- this is also confirmed by our customers

**8 Next PLB will take place April 26 at 15:00 Euro time
(same number +46 8 500 528 01)**

**Secretary: Claes Rehnberg
Verified: Tom Johnstone**

Product Liability meeting no.6 April 26 2002

THU2 issue - Arvin Meritor

Participants:

Bemd Stephan
Robert Bondy
Achim Mueller
Rick Freit
Michael Lewis
Claes Rehmberg Chm & ascr.

Bill Farrell
Aurilio Nervo
Juergen Schultheis
Tim Gifford (partly)

Info:

Tom Johnstone
Claus Schutz
Arno Stubbenrauch

1. Current status with ARM

- Deliveries: Shipment from Alken increased due to sales increase
- Deliveries OK. (see below for stud out of conformance)

2 Rotating / not rotating the bearing

- life test started on test rig - aim to have test results for PLB7
- one good unit to be tested for reference: ongoing
- Other units (20 pcs) received for testing AM
- test results aim to be finished for PLB7

3 Stud issues

Stud hardness:

- Studs found out of conformance on hardness
- specs: 39 - 43 HRC
- found: up to 51HRC
- Ingersoll got samples last week. Awaiting their response.
- Check the ISIR in Alken, JS
- Hardness etc counter measured in connection to ISIR ? JS
- Impossible to break studs in SKF lab.

Broken Studs:

- not possible to duplicate fractured studs in SKF lab.
- questionable if over torqueing is the reason for the broken studs in the field.
- important to find the rootcause
- concluded that the fracture is impact not fatigue based.
- question: why was 8000 studs ordered by customer last year ?
- fractured studs to be send to Schweinfurt for material test ML/AM
- Challenger fleet: 115 trucks with broken studs (reported from 3 garages)
- Ingersoll to be fully involved in this issue.
- involve purchasing. They need to inform Ingersoll / letter RF
- replacement of studs May 8th
- Check stud lots in Alken / correlate with brgs. JS
- one person hurt in Canada while torqueing due to breakage
 - compensation rules in Canada to be checked RF
- point still due:
- investigate how studs are dismounted and mounted ML

- Procedure how to deal with the stud issues to be defined BF / RF
- BB to communicate with ARM BB

4 Freightliner meeting

- 7000 units on Ryder trucks with Rsafe seals. They want us to replace all.
 - (depends of the result of the track test) see below

Testing on track

Testing ordered an will start immediately. (test program was send out to PLB)

- decided to have noisy Rsafe with low mileage on test
 - conclude whether 50 Tmiles will take that.
- check test procedure with ARM and Ryder BB
 - BB to check that test conditions satisfy ourselves, ARM and Ryder
 - Speed is vital ! BB

5 Detection method(s) development status

- ARM want to have a more clear signal to driver e.g. sound alarm and stains on the wheel
 - decided to do this in 2 phases in order to quickly come to a workable solution:
 - phase 1:
 - finalize and present the smoke generator device (with HW cost and cost for adaptation)
 - phase 2:
 - look into audible / visual devices
 - we must inform our customer about this plan and get approval quickly BB
- ask ARM to put ABS signal as one warning into a ARM bulletin, BF
 - investigate feasibility of using pen with temp. Indicator to be used by the driver BF (e.g. thermocouple on key ring)

6 R-Safe seal

- no lot found in Bethlehem with increased scrap i.e. no correlations found between scrap and molding defects.
- inspection process in Bethlehem found not to be sufficient.
- ALL PLB agree on the need for the 3*50 Tmiles inspection plan
 - need to specify the inspection method and training package ML
- In the investigations on returned bearings found in several cases different reasons from customers and our findings (and in several cases no reason for return)
 - decided to make a spreadsheet showing "given customer complaint reason" in one axis and our findings in the other axis. BF

8 Next PLB will take place May 2 at 15:00 Euro time (same number +46 8 500 626 01)

Secretary: Claes Rehnberg
Verified: Bernd Stephan

16

Monday
December 2002

S	M	T	W	T	F	S
1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30					

November 2002							January 2003						
S	M	T	W	T	F	S	S	M	T	W	T	F	S
							1	2	3	4			
							5	6	7	8	9	10	11
							12	13	14	15	16	17	18
							19	20	21	22	23	24	25
							26	27	28	29	30	31	

↓ ABC Prioritized Daily Task List

Bread Crumb
 - What are next
 Steps in what to
 do with Posts in
 the Field
 100% completion
 of all 3 basic
 tasks Periodic

- 1-Johnson Review
- 2-Connexus discussion

And today
Last flight is
headed to Denver

Daily Expenses

© 1998 Franklin Covey Co.

www.franklincovey.com

Original-Cards

SKF 002260

13

Felday
December 2002

1 ABC Prioritised Daily Task List

Class Note - Aiken
Cum Laude

1. What is your goal (#1)
2. Is intent in PBL
- MAKING today
good -
#1 RS - a problem
in piece to make
good project
5. Does not want
this Burned down up
time but Only
transient coffee
Engaging Project

Daily Expenses

[View Franklin County Pa.](#)

www.shareitforever.com

Digitized by srujanika@gmail.com

Daily Record of Events

30th Day 11 Link Week

866 624 - 9381 Rate 6980

Batch Test, will be wrapped up by next
week. 131,000 units under TP0231

Patent Southwest test - when
are we going to start

Most recent failure date of
12-1995 JV Wb.

8/20/98 Failed in June 2002.
Non Freightliner claim.
300,000 plus

7/27/2002

No new incidents.

One in England was not
an highly projected incident.

A customer called Domestech
about's to order 981 Model's
-What is item calling to do
to ensure that they can use
the product.

Answer is 5000
Sticks only.

4888 - Kaptin - West Syra

14

Saturday
December 2008

S	M	T	W	T	F	S
1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30	31				

November 2002 January 2003

S	M	T	W	T	F	S
1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30	31				

! ABC Prioritised Daily Task List

Ol' Streamer
SeaStone
10 milers
1pm
~~8/15/25-3572~~
Montgomery

Daily Expenses

1. *What is the name of the author?*

© 1994 Franklin Camera Co.

www.christianitytoday.com

Digital Camera

Appointment Schedule

- 8 _____

9 _____

10 _____

Credit Memo

11 _____

12 _____

1 _____

2 _____

3 _____

4 _____

5 _____

6 _____

7 _____

8 _____

SKF 002263



Meadow Team Planning
Effective planning doesn't
just happen; effective
planning ~~processes it.~~

Doing the best at this moment puts you
in the best place for the next moment.
— Oprah Winfrey

11

Monday
November 2002

Daily Record of Events

This Day vs Last Week

NINJA (Conew) Journey

4/23/02

Project
actions plan

Canons Park, lots on the field

Next steps

Parents End of life Criteria

Final Report to APPCB

Local Authority Electricity

Friends Committee

Bluetouch

Father the Spike pencils
will need to be recalled.

58 Highly Progress Books

out of 400,000 Natives

will meet again in

mid January.



Monthly Forum:
What is at the center of
your personal vision
and purpose?

I am not afraid. . . . I was born to do this.
—Joan of Arc

15

Tuesday
October 2008

Daily Record of Events

30th Day 11 Left Work

~~1000~~
1-000 225 -58 88

Kennel-Transport - Transportieren der Patienten

Chuck Smith 23rd

Stamping of ate the object

~~Answer~~ to keep the circle on

complete procedure in TPC

Problems with coding practice

register鄉村醫生 provide
water

~~For-1st-class~~ ~~For-1st-class~~

are very jealous.

Concurrent - Field Component

to follow underlying Don Custer

Morales 2700

© 1999 Franklin Cover Co.

www.innphilosophy.com

Digitized by srujanika@gmail.com

SKF D0228e

S M T W T F S
Friday
October 2002

S	M	T	W	T	F	S
	1	2	3	4	5	
	6	7	8	9	10	11
	13	14	15	16	17	18
	20	21	22	23	24	25
	27	28	29	30	31	

APPOINTMENT PLANNER

- To Do List
- Planned Tasks
- Not Started
- ~~Completed Task~~
- In Progress

ABC Prioritised Daily Task List

① 529 miles on the
truck
.090 End pay

Field Evaluations
Descript 371 Trucks
Done 371 Trucks

Failure Rate 2%
for year 1 Italy
Order less than
5% due to maintenance
problems.

Another 1.5 more
failure rate.

Maintenance procedures
have a big effect
on production problems

\$10,000 is effect
on a company's cost.

Daily Expenses

© 2002 Franklin County Co.

www.franklincounty.org

Digital-Create

SKF 002267



Monthly Power Minutes
What is at the center of
your personal power
and purpose?

The life you have led doesn't need to be the only life you have.
—Anne Quindlen

10

Thursday
October 2002

Daily Record of Events

Min Day Min Lat Min Wkt

SST - 1 - Done. Re Receipt

CAT

Deere - 350^b

Deere 250 hrs - 133,750
Fuel 25,000
158,750

Throttle Stop - 13,500

101

172,250

© 1998 Franklin County Co.

www.franklincounty.com

Original Check

SKF 002268

Thursday
August 2002

S	M	T	W	T	F	S
				1	2	3
4	5	6	7	8	9	10
11	12	13	14	15	16	17
18	19	20	21	22	23	24
25	26	27	28	29	30	31

July 2002 September 2002

- / Not Completed
- /- Planned/Pending
- X Task Deleted
- (C) Deferred Task
- In Progress

ABC Prioritized Daily Task List

<i>Sign Subsidiary - Post Safety Class 1 - Order</i>
<i>Dry Fender - by</i>
<i>(D) Shingle - Circular all, Corrugate - flat</i>
<i>Verify Mason - Preformed drywall</i>
<i>Check Pittsburgh - Eng.</i>
<i>There may be need of order off prior to 1988.</i>
<i>* - 1. Sign to original inspection procedure of 2001 will be deactivated on June 2002.</i>
<i>Sample Goo - try for Tetra Laminated gypsum board on the first panel - Shingle - backer 3 above 1 below</i>

Daily Expenses

© 1999 Franklin Covey Co.

www.franklincovey.com

Original-Cards

SKF 002269

Daily Record of Events

7130 Day 182 Left Week 21

The Captain's Position

- 50,000 mils navigation is
not acceptable for modern life
We sold our maintenance free

- Want to progressively upgrade
stage of the product until
they believe that problems
are not repeated.

- Want maintenance on S/te
related recall or not

[A brief note: The Captain problem
had shown up as progressive
incorrect.

- The Captain wants firm navigation
or what to do - Non functional
Today 5 to expect 500 trucks

- The Captain gave plan to go to
961 Cycles

would like display check
car at Arden.

Moved to the RTA

10 weeks

2
Friday
August 2009

S	M	T	W	T	F	S
4	5	6	7	8	9	10
11	12	13	14	15	16	17
18	19	20	21	22	23	24
25	26	27	28	29	30	31

Appointment Schedule

- Topic Completed
 - Personal Reward
 - Task Deleted
 - Unassigned Task
 - To Review

星期一	星期二	星期三	星期四	星期五	星期六	星期日
1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28

1 ABC Prioritized Daily Task List

John Hoffman
J. Hoffman
248-703-8815

Bob Borden
734-441-6822

Bernard-

Cel Midget
Rape Bush
734-737-3766

Terry - mobile

Bearcat-

Daily Expenses

© 1999 Broderbund Company

www.jstor.org

8

SKF 002271

14
Friday
June 2002
Flag Day

30 1
2 3 4 5 6 7 8
9 10 11 12 13 14 15
16 17 18 19 20 21 22
23 24 25 26 27 28 29

May 2002 July 2002

- ✓ Task Completed
- Planned Forward
- ✗ Task Started
- Deferred Task
- In Progress

ABC Prioritised Daily Task List

Freightliner						
40,000 Test Miles						
S.W. TEST						
Continuing 17,000 Eric plus on RT Front LFT front 2,800						
Regular Meeting Concern - 3 week off and on 3 week Sunday Changes						
17% of return Concern for PM and 83% for Concern for Truck Driver in all fuel						
Test Miles \$5,000 & \$0,000 Miles						
Product is still One cent per mile						

Daily Expenses

© 1998 Franklin Covey Co.

www.franklincovey.com

Franklin-Covey

- 7 Payola work
- 8 Approved for a
product Change
test.
- 9 Take off spots
for Un G year
- 9 Get or take out
of Service

10 Major Concern to
Vehicle section
200,000 & 400,000
miles

- 11 Freightliner
Local Delivery
Committee
- 12 Met 6/17/02
to review items
for possible travel
- 1 - clearest talk
to youth
education
- 2 Total will go
to Payola area
and Marketing.
- 3 It is not slow
- 3 a few Maintenance
item
- 4 What is a rough
line of the
- 4 New Unit.

Open miles etc

- 5 SLP Needs to go
- 6 out and get off Shady

7

8

SKF 002272


Health
Quality Paper.
Howard—Serves as
a resource of physical, social,
emotional, mental, and
spiritual energy.

and social well-being, and not merely
the absence of disease or infirmity.
—The World Health Organization

Thursday
June 25

Daily Record of Events

Today 200 Lbs Week

Heavy Haul Data was made on May 3, 1999

Conway - April 30 to May 15

Hub manufacture Points

(at Forties along)

© 1998 Franklin Covey Co.

www.franklincovey.com

Original-Covey

SKF 002273

6

Thursday
June 2002

P M

2	3	4	5	6	7	8
9	10	11	12	13	14	15
16	17	18	19	20	21	22
23	24	25	26	27	28	29
30	31					

May 2002 July 2002

- ✓ Task Completed
- Planned Forward
- ✗ Task Deferred
- ♦ Delegated Task
- * In Progress

ABC Prioritized Daily Task List

- Traveling from -
-4 hours analysis
1495.83000 269 miles - 16% off 19-Tues = 2.3%
- the 1st 14.31% 531 miles - 1-what if Tues = 3%
out RDU/Int 39.520 1,01 - 1 Tues 32nd off 3.6%
- SKA crew 30 K miles up front
No further reports of any additional incidents
One plane 10 total catastrophic incidents
one for catastrophe 15.92
- TPO 207 Page inspection
Southern Int 200 miles
- Stuck - Hwy 80 collected to MoCo
all Head - 1 against Head
- Ryder - SKP crew - investigation in Tennessee - 2 flights of Park Due 70
Marion. 8 vehicles were looked at.
- Expended 7870 life vs States
Washington Park Franklin
- 7-866-604-9391
Code 64050

Appointment Schedule

5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	

Daily Expenses

© 1998 Franklin Copy Co.

www.franklincopy.com

Original-Quality

SKF 002274

20

Moody
May 2008

Victoria Day (Canada)

S	M	T	W	T	F	S
				1	2	3
5	6	7	8	9	10	11
12	13	14	15	16	17	18
19	20	21	22	23	24	25

April 2018 June 2018

SUN	MON	TUE	WED	THU	FRI	SAT
1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28

ABC Prioritized Daily Task List

Need to do
Air Legate Test
instituted.

Will instruct
a Service company
to inspect at 30,000
miles. - Boarding

Want to find a
clock and jointly
check them -
go back out and
find Boeing Test.

Want to do another
(Robert & mecha)

Appointment Schedule

6	
7	
8	
9	
10	
11	
12	
1	
2	
3	
4	
5	
6	
7	
8	

© 1998 Franklin Energy Corp.

www.frontiersin.org

Editorial Policies

SKF 002275

10

Friday
May 2002

S	M	T	W	T	F	S
1	2	3	4			
5	6	7	8	9	10	11
12	13	14	15	16	17	18
19	20	21	22	23	24	25
26	27	28	29	30	31	

✓ Task Completed
● Pending Review
✗ Task Deleted
④2 Deferred Task
■ In Progress

April 2002 June 2002

1 ABC Prioritized Daily Task List

1	Recall Hubs From Daimler On Re-Sorter From Borges From Payne
2	Wheel Durability ARM Test Vehicle Deliver Feedback Test
3	SKF - Southwest Research - Strategic Monday & Tuesday To Validate the 50,000 mile test
4	Wheel oil Replaced - 3 mo ago trans - 2 mo
5	Recalibration 1001 1996 - 8158 65.7% 1597 12-394 69.7% 1318 81960 36.7% 1857 32988 58.7% 2000 22980 53.7% 2001 9480 63.7%
6	Daily Expenses
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	

Appointment Schedule

The 1 Post 2000
8 Live Legal Situation

70100

9

10

11

1

2

3

4

5

6

7

8

9

SKF 002276



There is nothing like returning to a place that remains unchanged to find the ways in which you yourself have altered.
-- Nelson Mandela

9

Thursday
May 2002

Daily Record of Events

Monday 2002 Week 18

R-Safe test - when

End Side Tables -
- Still Running -

① New Brown -

① Dr. Chaitin -

TEXTRON-CAM CAR

George Riffel

7
Thursday
May 2002
Australia Day

S	M	T	W	T	F	S
5	6	7	8	9	10	11
12	13	14	15	16	17	18
19	20	21	22	23	24	25
26	27	28	29	30	31	

- ✓ Bob Chapman
- ✓ Personal Reward
- ✓ Bob Chapman
- ✓ Bob Chapman
- ✓ Bob Chapman
- ✓ Bob Chapman

April 2002							June 2002						
S	M	T	W	T	F	S	S	M	T	W	T	F	S
1	2	3	4	5	6	7	8	9	10	11	12	13	14
15	16	17	18	19	20	21	22	23	24	25	26	27	28
29	30	31											

ABC Prioritized Daily Task List

Call John Cannon
Start 90 Day Terms

Bob Brady -

Do Dingo trough

Start building Kalbar west

PP 98

Have a phone conference with NCRM

On Mon 105 mm on

Hand

(Concern) - Start west down no industry

Area application

No industry or take tips

No oil lease

Plant on May

Pre set flat areas

Greater than half

Search until after

Freight lines under 10th level of th

ppm

Freight lines because

Provide all the compensation

100,000 cut-in price

Daily Expenses

25

Monday
March 2009

S	M	T	W	T	F	S
31				1	2	
1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30	31				

February 2009 April 2009

✓ Task Completed
→ Planned Review
✗ Task Deferred
BG: Deliberate Task
● In Progress

S	M	T	W	F	S
1	2	3	4	5	6
7	8	9	10	11	12
13	14	15	16	17	18
19	20	21	22	23	24
25	26	27	28	29	30

↓ ABC Prioritized Daily Task List

FF9.8

- 3 Components
- USA factory performance Rate of 2%
- do not see any improvement in performance
- 10 occurrences of fine oil wheel out
- SKF ready to come back in 30 days with a comprehensive plan to fix the problem to an Acceptable Level
- 16 other lots - 12-13 since Jan

- 1 Remove
- 2 Change supplier
- 3 Contact LSC with current situation

Looking at other Suppliers

Market share has dropped from 30% to 15%.

SKF has not been as responsive as expected

Daily Expenses

New 2 Starling Cranes today,
Farewell Rate must be
150 or less

Appointment Schedule

will come to us to
Play Son Thursday
brought up about
\$60,000 per unit.

* Prime warranty
9 Rated fit \$5.00
franchise

RLLA - units
Deliverments
- Why will pay for
Added maintenance?

7.5 FLS time
claims
90 previous sources

1

2

3

4

5

6

7

8

Original-Cards

© 2009 Franklin Covey Co.

www.franklincovey.com

SKF 002279

= 4/17/03

70,000 Vehicles thru 2001250,000 Units2.4% incidents90% have no problem (6.23 miles)80% 3rd issues105% in Progression GrowthJuly 2000 - New Seats in vehicles.Bulletin 0751 - Specific inspectionEvery 50,000- Inspection extract from MentorCustomer high.* Freightliner concern of portion of the
Customers are not notified - small customer
glitches etc.* Response - Customer Backwards to inspection
Schedule.90% of progression incidents around the right hand sideLocal Warrens inspection requirement beginning May 1st.Concern need to ensure that all customers
are notified. - Safety Campaign - auditsRyan - returned 20 vehicles for inspection50 have been inspected - 3 have heavy Spalling
WearbookCR England Inc - 3 vehiclesSpangler - initial inspection due to July 2000
incidents concentration of failure in concentratedFreightliner Dexys301,000 - 1999-2000 (561 claims)

Concern - Unintended reengaging
pounder - Could still be out in field
Pm in my Unintd. Thread Sighting on
Lotus. (1999-2000)

Concern - more than one bullet
in the - left not clear
concern - with many ongoing Positive
in the field to Notify Customer
with information enough to protect
the Customer.

Concern - as soon as Customer notified
in the field will be notified automatically
Concern - US Notification by Bulletin
or Service Campaign notification enough
to Protect Customer & U.S.

Campaign Bulletin will go to Nitro

Concern - How Much Differing would
be Not Cape Retention System give.

Wilson Trophy - too incorporated
turkey pop up in a hub.

SEM - Needs to communicate with Parker
about

Parker -
P.C. - Small in Field - what do
we do about the current population?

Parker needs to know what they do about
injection
Supposed Scales.

No Lot 1 \$2 Side found

↳ Parker will want to know who will pay for the

Daily Record of Events

Initial inspection

Steel

- Everything seems that Skid does fine due to overage of 10%
- Common - CR slippage material gets in the bush

Traveling wire standard practice for Skid going from high strength steel - would like Skid to break rather than upshift

Ryder - needs estimate 50,000

will request inspection at 50,000 miles confidence limit with final bill after 7/2003.

Ryder currently paying 200 miles per month with SKF hub.

→ Repair Task

Steel - Jammed out - Damaged
Porous segment

→ Repair
Procedure

Who pays?

50,000 miles

① Driver responsible - 200 miles

② NEED to confirm 50,000 miles instead
interval. Will issue items Restimated
from Ryder with Right Rotation.

18

Thursday
April 2009

S	M	T	W	T	F	S
	1	2	3	4	5	6
7	8	9	10	11	12	13
14	15	16	17	18	19	20
21	22	23	24	25	26	27
28	29	30				

Appointment Schedule

Task Completed
 Prompt Forwarded
 Task Deleted
 Integrated Task
 In Progress

↓ ABC Prioritized Daily Task List

Dale Bell
Reydon
- Mead marsh
Speaker white
Running by end of
Mead marsh
048 - 435 - 1031

0000 off Nylon
Wool 50°
Chart

(6)

Daily Express

© 1999 Franklin Camera Co.

www.elsevier.com

DRAFT

E

EMBASSY SUITES
HOTELS

Friant

400 Miles - 200 Miles -
Ridge & Valley (Forest)
Line Draw $\frac{1}{2}$ of all Miles
Not problems
Message Box # (New to F)

Rock Cut 15,000 Miles on
45° Shds. S. West

S.W. Cut

77,000 Miles and .025° End Pl.
250° Spike - Drift. Consisting
of vibration with breaking
processes to the rock

1-800-EMBASSY
www.embassysuites.com

2 more fires (Prim)
1 wheel off
no injuries

PLT

4/25/02

Rockwell Hardware —
39-43 - Ring, 40-48

1. Deliveries OK

accruals - Debts

Inventory Replaced.

2. Rotating

life Test - in process - some information possible
actual failed parts show inner ring Spalling.

20 parts in Schenectady - slope to new results by
end of next week.

3. Rotating Aug of 2000 in production

4. Detection - Warnings - Contain Risk

5. Stock issues

out of Spec with Hardware

Both in inventory and in the Field.

180 per ship to Nern (400 to 500 Ft/Lbs - Spec)

Challenger - 115 trucks - want the Stock Changed out
- on (7/2001 - 1/2002)

Cost of replacing Stock

2 hrs per truck x 75.00 per Hour

6. Paul will work with Purchasing to Make Inquiries

Paul agreed to change Stock

- Challengers.

~~7.~~ Thermal Cycle - Key Odein

Hub UNIT - IT problem exists at 25,000
will the unit last 50,000

ISSUE - 3 Rydse Parts

Outboard Roller ISSUE -

stop in the Raceway of Boeing

What does Ryder Really want
from our truck ~~test~~ as compared
to Part Bell

tom Quattro

Root Cause

Corrective Action

1) plan to go out and get more parts

2) 99 & 2000 vintage

1.25

1) Lube oil 2000

2) Lube oil 2000

3) Lube oil 2000

PLT

5/2/02

Delivery - New Steel Problem

Ingersoll is shipping Parts that are harder than Spec
appreciate Shipment stated July 2001 (SKF lots)
currently Shipping on Deviation
Spec. 43 Parts 44.5. we need to validate these
Parts for Aeron to accept the deviation.

* Dave Zimmerman - 3/05

- Take pictures of crats that the stocks
show witness Marks of Hammer Blows.

Ryder - is 50,000m.la sufficient to
~~check~~ should it be less?

DAVE SONS - Time Line for DAVCO
TEST 100/1625

OK * Compare Seal Port with Nitrile
Port with High Mileage.
- Call Dave Zimmerman

OK * Send 120 units to Harmony
↓
Unusual High Miles
Fischer & Silon
✓ R Soft Seals

Ed Cotter - Ingersoll
- New Army - 8D - corrective action
Shipments going fine

PLT

5/7/02

- ① 199810 - increase in IB Seal leak a no problem found
② 199906 } Need to Study what happened
199907 } during these dates at both
199908 } Aiken and ARMT.

- analyze Seals for above dates as well vs
Seals from another dates. — look for
Cure State:
 Ludlow Seals vs Aiken Seals
- vs others.

R Sofe - changed out all Bethlehem &
Aiken Inventory.

Started sections for Southwest Truck
Tool.

Need to talk to:

- * ~~2 programs~~ ~~Doug Bayors~~ - Contact Aurelio Verno
1. What can we do to reduce Scrap rate
2. How we enhance Design & Material

↓
what does it take new tools Etc.

- * Need to call Brad Arnold.

Monday - PLT 900.

O.200g Dispenser & Rotator -

Action Items

I Branch Handel in on Friday)

II Fresh Soils - Dark Currant Test in progress

III Boysen in Vachoban.

5/15/02

Studs from Ingersoll

Soft on the Core? - ~~Rockwell C~~ Rockwell C (33-39 espd)

Hard on the outside 45-48 39-43

lot size. 450+ Vickers (380-420 spc)

Core is ok as is. off it goes again it would affect the core.

All A's & B's have been within Spec.

Except the Port Received under elevation.

Ingersoll has a continuous flow furnace

Batch Size is Heat of Steel

A. NTC and Nikon both showing the same measurements. Ingersoll is showing difference.

Nikor cut of B's

will be out of A's showing 450+

When is Ingersoll expecting to have Vicks 2

Product - would be May 27 if we change lower surface to 354.

Ingersoll can run parts at lower spec to see if scratches cut into the groove's Retempering to run test.

All studs that have been reduced have been over 50 RC., all parts in house are below 50

~~Parts made during 5/13-9/9~~

Parts received under elevation were 423-431

What is the best outside lot we can get another steel source up and running?
— wire diameter 2.6 mm.

Option 4 - Ship parts to OEM and have
OEM change them out in rework area.

- ★ If we contact our customers the Stud issue
comes out and everyone knows become aware
Then we must Notify NHTSA
Wire diameter:
410 - 424
26mm
- ★ Who owns the tooling at Ingersoll?
If SKF owns the tooling can
we move the tooling from Ingersoll
to another Vendor (Masco Tech)
- ★ Can we have Masco Tech Heat Treat
Ingersoll Virgin product?
ARM will have Parts until 5/22 -
- ★ Pull Studs from SKF Allentown and Take out
Studs that are longer. Use them temporarily
Pennia. to SC - Blow out Change out.

5/30/02

Europe - what is the amount used in Europe.

- Amount of Grease in R-Jobs - How was

- What is the technique of grease installation
between NA & Luster

Bathishura

WORK INSTRUCTION

what was criteria used for inspection
what is Quality Blend into the field.

SALT Spray

5/31/02

Water intrusion along the Spindle -

- Inner Ring Seal w/ O Ring -

~~pop off~~

Temp Bolt - problem Paint 400°?

Seal lip pattern -

Low Clamping - Disputed.

Bowl Stopper - coming over next week
to meet with ARM.

M. Hunter

T. Bogen

K. Plemon

J. Moore

~~Doorless~~

Freightliner

Customer closing Pm's at 25,000 Miles Findley
(+P0251) Hubs showing End play without
clicking and play.

Service Parts Elements

	1997	98	99	2000	01	02
Units	105	352	1022	1758	3291	3517
Wks.	14	133	568	1654	2024	2462
%	13.3%	32.8%	55.5%	66.4%	61.5%	70%

Freight
1999 APR total sales \$6,941 (\$92,902)

Faylen variety 2-3% range

- Apache -

Service Campaign -

200,000 (50,000)

17,000 Decrnt 77,000

847-742-7845

Service Campaign

ARM - Contact Name & Number

Targeted Units - Need information from ARM
& Freightliner.

Chuck Smith - TPO 251 ()

Units for replacement:

Co-ordinate

- 200 replacement units

60,000 trucks ?

How Many Units

2nd
global

13,000 - Stat up

15,000 - April May June
plus "R Sope"

15,000 Trucks

Cleveland

- 120 Units Build or WOP - no repairs yet. (60 at Freyhan 60 at Arivany Cosco
3,000 stock on hand.

Santiago

- 4 trucks in years - on hold
- X -

Correspondence

12/02 Cleveland Cosco

- Santiago MX - 5 truck get out
- Replaced 100 Steel or 47 Trucker.

Steel lots -

- Need to change out all slot for lot superstructure data
- 7,000 slot not break away torque of less than
600 lbs/bbl.

OK

* H



- Steel observed
- Sporadic Spinning of Steel on Tongue
1 or 2 Sticks per Job. (Short Sticks)

Mentor has been retrofitting sticks at Cleveland Plant.

Sticks that have been pulled out
Show that the steel is not biting

2805
2801

- Holes are in round
- Clamp is in spec.

2802

on Hold

- 61 Trucks at Transfatory Surface Trucks.
31 at CB Plant

\$300 to \$500 a day for holding trucks up



Call Mtns -

91 Trucks on Hold

will send 3800 sticks to start changing
out sticks. 100 to Santiago MX
8,500 on Hold

16 Trucks have been shipped over
will need

~~500 lbs~~ 2 Batches of sticks 9/23 - 10/7

1,500 older Mexican

Sticks - Min 4.02 a Disc - 1200 Newton Motors
needed 3.

410 - 450 sticks

SOP
2001
2071

2002
~~700~~
1299

PP
1651
2084



more Production Back to Lucknow

Temporary 400-450 VICKERS
Change

Clear manufacturing Problem.

Total improvment system - ^{need to change -} wash & Nut.

Freightline

7/24

Southwest test

42,000 miles

End play detected

1 to 2 ounces of water detected in HubCap.

Do not know source of water ingress

Bush Test

71 923 miles to date - no
change in status reported

Temperature has risen but
no end play detected.

Inspection device

Mid West at Ryer location in
La Vergne Tenn. Mileage varied from
730,000 up to 880,000. One Vehicle out
of 8 had bad bush bush replaced.

7/4 CR England Vehicle that Burned out
week - NO details - 275,000 miles 96/00 as service ad
KCM Vehicle reported some incident
last Friday.

SKF Building Box of 5,000 Hubs based
on Hub Analysis to replace increased
Hubs that may come in due to new
inspection device.

1,400 Hub Failures to date.

SKF 002300


Freightliner

- 981 sale has no confidence in current production being any better than past production.
- Feeling at Freightliner is that they will shut off usage of 981 axle.
 - Decision will be made in a few days.

Southwest Tex

38,580 miles as of yesterday 7/1/02
Bush 57,898 miles

- CR England Tuesday - Tractor
Pur up end track.
- LAVERNE TEND - 10L tax out. (20 hubs)
- Need to increase the service - 2,000 per + 2,000 more.



4236 Hubs Sold as replacements.

40% of Hubs returned for no
Valid reason.

Combiatic builds Increase

4,000 to 5,000



25%

Tom Sando

Clark Smith

- Campaign issued

500 - Vehicles

November - New Hub Cap. ?

200,000 mils

Root Cause and Inspection -

Go back to other OEM's and give
same presentation.

E-mail says 10 weeks

need to understand the decision

- Other issues

- make sure how we play on the production

981 - Loss of Profit

{ Is our hub & system adequate for the
Application?

- Com Met

Metric 6,000,000 Cost reduction
to Freightliner

8/29/02

- 1) Units Made Shipped in Spec. one still showing End Play at 1 RPM 10-50 microns currently Run 15 to 44 microns.
- 2) Will run 10 units and measure the same and take them to SRA install them to see what if any variation is.
- 3) Need to get 6 units to do a clearance test.
- 4) 150 truck = 3,000 wheel and 9 resets. 27 replacements have already been done on these vehicles.

* - Order working thru 6th Weekend
- need a number

8/30/02

Freightliner 866-624-8391

Batch Test - upsets no change - no end

Play detected. Come of SKF lab test

- so we know it had a spall.
Start with,

500 Unit Field test - 100,000 to 700,000 ave 400,000

3C4 Hale shelf (264 in Data Base)

12 units reported at greater than 2.0
loose & over threshold.
Should be set.

no noise or End Play detected.

5 of the 12 are in Troy.

only one showed up at PM

3 units located show no problem
found.

2 units show damage (4.0 or better)

- 1 failing

- 1 does not show failure stat

Most of the population registers below 1

1) More & det for End play & noise

2) look at George

3) look at Cam & Rollers

4) look at Seal.

NO reported additional incidents

CR England - Satisfied with information
given won't the units checked by
the monitor.

1-866-624-9391
4351406

Monday the 9th

350 Trailers

8 hr Set up

Need

16 hrs to run the

Grinding) seen if Florence can
) handle) grind & hone Posts

Assembly

Need to prioritize

Trailer 100 Day

a lot

Router 300 Day

Is Order working over the weekend:

<u>Address</u>	<u>Florence</u>	<u>estimated</u>
Working Weekends	32 - 1200 Part per <u>Day</u> (600-order)	
200 of each per day.	34 - 700 Part per <u>Day</u> (150-order)	

* 32 - 890 - thru tomorrow

** 34 - 387 - thru tomorrow 650 replacing 345 to Florence

Steel Build note

Working -
270 - 315 per per day. 10 hrs per day
and over at weekend
- Could make 315 per shift. 2nd Shift Trains
by Mid September
1) Work full shift plus 2nd shift for
Assembly.
2) Problem is people power.

Need Plan

PLB

Add

10/22/02

title -
page 4

objection FFSI and SKF hub unit.

- Service Fan Lube - Replace with

page 5 - product designed to operate in packed To flight Clearance,
OD pre load 0.001 clearance

page 9 Last Bullet is at Title to page 12

page 9 Root causes

center ingress

- missing Spindle

- Hub Cap

slide 10 - Add - increase insulating bows
increase insulation thickness

slide 12 non/step ground calculated?

slide 13 - Last point - Phase I & Phase II

page 14 - Driver (vision etc.)

* Can we see the final draft of your
agreement to our changes

Patricia Barkley -

46308 - 5544 Scotland

Bethany Barkley -

For Rings - Oct 21, 600 + 800 per
due to not getting

✓ to Reht at 10 - 9.54 - 12.09 - AA 1701
rebs Oct 11 ~~2.58~~ 3.18 AA 1430
5:00 170"

Omero Santos Leonis

① Mike Rich
Tom Soaks - Due distribution

Class Reimbursable
10/06/2002 08:11 AM

To: Bernd Stephan/SCH/USKF@SKF, William J Farrell/ELG/SKF@SKF, Juergen Schultheis/SCH/SKF@SKF,
Achim Mueller/SCH/akf@SKF, Richard W Frett/ELG/SKF@SKF, Amp Stubennach/sch/SKF@SKF,
Michael D Lewis/DET/SKF@SKF, Robert J Bondy/DET/SKF@SKF, Rick P Morrow/AMER/SKF@SKF,
Edward F Coker/AMER/SKF@SKF
cc: Tom Johnstone/GHQ/GOT/SKF@SKF
Subject: PLB Agenda Oct 9th

PLB Oct 9th 15:00 - 17:00
THU2 - ARM

Tel: +46 8 500 526 01

To be able to keep the meeting to max 2 hours, please report the status brief and concisely.

Agenda

1. Warranty analysis update (Lewis) 240 highly progressive - 21 ~~Fires~~ - 80 wheel offs
Update of failure rate vs production dates (new info only) (Morrow)
Rate updates > may 3 High Failure Rate
Field incidents Lower mileage to failure
2. Alken Process/Product improvement activities (Coker) as of Aug. 15 process in control
Clearance gage performance update mid-JULY (Question Aug 26)
Correlation/confidence of clearance measurement between Alken, Luashow, and Schweinfurt?
Training of Alken personnel
Raceway form improvement
End drop change (Mueller) - C/N start ordering as of today (Diamond)
New Inner Ring Diamond Dresser delivery date - end of November
Second gear bearing info. Scouting people from Luebeck for training after plant
3. Vibration Pen Production (Lewis) - First production pens RECEIVED
Kit plan - 4000
Field test results - 270 Ryder Trucks = 7% Failure Rate - Pending using TPA51 (\$9.90 each)
Will be reviewed with Freightliner on Nov 1. - CIR (England) failure rate 15%
4. Schweinfurt investigation into mating components (Mueller / Stephan) monitor Paying for 1st SOOKIT today
Retaining hardware
Spindle/knuckle
N/C'd to understand authorizing supplier
Review of drawings along with tightness of system
5. Conditions (Stephan, Lewis, Mueller)
Main cause of failure update
Update on measurements on the peaks
Communication to ARM
— Krist & Thibaut & co. will receive soon to verify NMEA
6. Studs (Weeks) - ~~in progress~~
Test results summary 2 more Bx's at abbey - were they Bad or
Aftermarket stud sales (as an indication of field issues)
Expected performance of parts in the field 10,600 hrs
Forward plan 6 wks to complete test 42,000 hrs
LAKC ERIC is now APPROVED. 9,000 hrs
~~5,000 hrs~~
7. Reporting requirements (Frett/AJ)
"Driver education"
Draft letter
Forward Plan

Regards,
Chris

SKF 002310

PLB

4/4/02

- Safety #1 objective

F. Scale used until May of 2000

12,000 - 13,000 on

→ 14,000 LB Rule - Need to find out what
Rules weights are used on these trucks

Gasoline Pack amount

Luchow vs Riken

1998 - ABS Required

which Vehicles have warning lights - Law says March 2001

Does ABS Pick up the STEE Rule?

IS ABS a reliable detection device?

MARCH 1, 1997 - ABS Law

July 1998 to April 2000 - what changes
have taken place.

- Dave Simms - NEED pictures of failed R-Safe Scale

Gatien's original production site at R-Safe. Early 1990's

start of production

*

Re-work limit part - 3-4000 loose seal

- Reassemble

- Clean Seal

- Inspect

green paint

Second set of Metals & Mold Domes Spray Etc

SKF 002311

P-Safe Seal

2 Issues

Identified correctable issues with the mold.

- Eliminate Tapers

- Eliminate wrinkles

- Grease pull can be corrected

3 weeks to do all work.

Total 5 weeks to supply Volumetric

Pickers - Does not work well - Tapers

- Change fill ports

- Change Metals

- Recommendation - Port needs to be redesigned

PLB

4/8/02

Friday Meeting at ARM

Shutting down New & Old Customers would kill
the product line.

CR Reworked Parts to keep production going
at AKJEW & ARM.

200 per per day.

180 → added 500 Skived
%

Molded new Parts yesterday

Heels marked a series number recorded.

clerk repairs per cycle.

Hub rotation - New not doing constantly prior
to 6/2001. 6.8% of current failures.

Problem

inboard seal problems 16% seal related failures.

Need to develop Primary detection system.

Warranty Terms - May need to renegotiate mileage of
Contract.

What do we do with the units in the field with R Safe Units

Broad Channel

Integrity

Supply issue

Note -

Field Sales people to call on a number of New Port Shipyards
but did not necessarily sell by one fleet

Sufficient Volume

* Need to add all information on New griff of Octons.

PLT

4/19/02

- Deliveries - ahead of schedule
- Rotating vs/rad Rotating - A Mueller
 - ... Found some damage on first test
 - ... Second test 1K miles to see if damage affects life.
- Steel Replacement - APR recommends removing the unit to replace the steel.
 - ... SKF Steel a modified 10.9 - Higher Case Hardened.
- Is SKF steel replacement higher than normal?
 - ... what is the norm?
- Current Steel Situation
 - ... Higher than Normal Hardness
 - ... Material Yield Strength vs coating
 - ... Need Coefficient of Friction Test.
- Ingersoll Largest Steel Supplier
 - ... Prior to 5
- Inspection - up to 20,000 miles the first two we should probably be responsible

- * Talk to Rosenthal about preferred detection sense
 - 1) Grade 2) Audit 3) Staining the wheel
- * Production centers with extra grease 3,000
 - Roll Bell goes into gear in a few.
- * After Novelt Steels are marked with an X
- * Mike Lewis & Prejov Document to response to Meritor.

6/7/02

NHTSA - Request - THUZ

Paragraph

1- Bob will do

2- NRM - Data Base

(a) SKF

b. - Field Reports?

(c) SKF

d.

e.

f.

3. Provide

4. NRM - Data Base

Munson 2 Parts

5. - need to discuss further (see fit below vs after)

6. changes that were made were not related to the defect.

7. Plant

8. Freightliner Conference Calls - Notes -

9. no changes (Not Cap A20n)

10. Start up Problem

a) housing problem

11.

Mark Wagner - Freightliner
will not ~~take~~ buy More Unitized Product.
6.5 mm - Product

Brown Monitor Data Base

4 - Proportion

Product Out until Friday → R 100 with all
1988-10 could be Data Acumulated.
start up problems

Below line

% of Part that showed up in SKF Data Base

Box Chart

Shows Spike Rod Case vs the entire
population of failures - From SKF Data
Base.

(I) = 95% confidence charts

- Possible Parts of out of Spec. Bearing Spindle
Tolerance Stack up Min Min vs Max MAX.

Motors 5 6 7 8 total Population of Spikes

Open

3-motor 1